



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD HONDA FREED (SMA9411D)
Date of Loss	27 March 2019
Time of Loss	9.00
Loss Description	SMA9039X (INSD) C/W SMA9411D (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMA9411D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

22/06/2018



Mileage

15287

Age of Vehicle

0

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

Make

TPVD HONDA

HONDA

Model

FREED

FREED HYBRID 1.5G AU*

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

NG YEONG HUA EILEEN

Date of Birth

23 July 1981

dd/mm/yyyy



Age

37

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No		GB71068163
Engine No		LEB5601610
Engine Capacity		1496
Sum Insured		0
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	74 UPPER SERANGOON VIEW, #11-52, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Unknown	
Marital status	Unknown	
Identification #	S8121974E	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

31/05/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/55R15

Rear Tyre Size

185/55R15

Front left side

DUNLOP6mm

Rear left side

DUNLOP6mm

Front right side

DUNLOP6mm

Rear right side

DUNLOP6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
☐		0	1		TAILGATE	Replaced	0	1208	No		20			966.4	Reviewing	
☐		0	1		TAILGATE LOCK	Replaced	0	112.3	No		20			89.84	Reviewing	
☐		0	1		TAILGATE LOCK CATCH	Serviceable	0	0	No		20			0	Deny	
☐		0	1		TAILGATE INNER GARNISH	Serviceable	0	0	No		20			0	Deny	
☐		0	1		TAILGATE WEATHERSTRIP	Replaced	0	198	No		20			158.4	Reviewing	
☐		0	1		TAILGATE LOGO	Replaced	0	35	No		20			28	Reviewing	
☐		0	1		TAILGATE EMBLEM "FREED"	Replaced	0	59	No		20			47.2	Reviewing	
☐		0	1		TAILGATE EMBLEM "HYBRID"	Replaced	0	82	No		20			65.6	Reviewing	
☐		0	1		TAILGATE OUTER CHROME MOULDING	Serviceable	0	0	No		20			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
		0	2		TAILGATE SHOCK ABSORBER	Serviceable	0	0	No		20			0	Deny	
		0	2		TAILGATE REFLECTOR	Serviceable	0	0	No		20			0	Deny	
		0	1		TAILGATE WINDSCREEN GLASS MOULDING	Replaced	0	174.5	No		20			139.6	Reviewing	
		0	1		TAILGATE WIPER MOTOR	Serviceable	0	0	No		20			0	Deny	
		0	1		TAILGATE PULL POCKET	Replaced	0	27	No		20			21.6	Reviewing	
		0	1		REAR BUMPER	Replaced	0	1120	No		20			896	Reviewing	
		0	2		REAR BUMPER REFLECTOR	Serviceable	0	0	No		20			0	Deny	
		0	2		REAR BUMPER BRACKET	Replaced	0	45.8	No		20			73.28	Reviewing	
		0	2		REAR BUMPER SIDE RETAINER TOP	Serviceable	0	0	No		20			0	Deny	
		0	2		REAR BUMPER SIDE RETAINER BOTTOM	Serviceable	0	0	No		20			0	Deny	
		0	1		REAR FENDER LH	Repair	0	0	No		20			0	Deny	
		0	1		REAR FENDER INNER SHIELD LH	Serviceable	0	0	No		20			0	Deny	
		0	2		TAILLAMP	Serviceable	0	0	No		20			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
		0	2		TAILLAMP PANEL	Repair	0	0	No		20			0	Deny	
		0	1		REAR END PANEL	Replaced	0	712.5	No		20			570	Reviewing	
		0	1		REAR END PANEL TOP GARNISH	Replaced	0	203	No		20			162.4	Reviewing	
		0	1		REAR BUMPER TOWING COVER	Serviceable	0	0	No		20			0	Deny	
		0	2		REAR FENDER INNER GARNISH	Serviceable	0	0	No		20			0	Deny	
		0	1		REAR FLOOR PANEL	Repair	0	0	No		20			0	Deny	
		0	1		REAR FLOOR PANEL SIDE	Serviceable	0	0	No		20			0	Deny	
		0	1		REAR FLOOR PANEL TOP BOARD (CARPET)	Serviceable	0	0	No		20			0	Deny	
		0	1		REAR NUMBER PLATE LAMP	Serviceable	0	0	No		20			0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMC
		0		TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS	0	750	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMC
		0		PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	0	800	0	0	Reviewing		
		0		APPLY RUST PROOFING ON THE ADJACENT PANELS	0	60	0	0	Reviewing		
		0		WIRING AND BULB CHECKING	0	24	0	0	Reviewing		
		0		REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	0	60	0	0	Reviewing		
		0		REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS (2-MAN JOB)	0	120	0	0	Reviewing		
		0		REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	0	60	0	0	Reviewing		
		0		SPECIALIST CHARGES - CONDUCT REAR CHASSIS ALIGNMENT	0	0	0	0	Deny		
		0		TRANSFER OF EXISTING TAILGATE MECHANISM TO NEW TAILGATE	0	60	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 6 DAYS	Reviewing			
		0	REAR BUMPER CLIP-10PCS	Reviewing	30	REPLACED	
		0	SET REAR BUMPER REVERSE SENSOR (AFTER MARKET)	Reviewing	220	MALFUNCTION	

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	REAR END PANEL TOP GARNISH CLIPS-3PCS	Reviewing		15	NECESSARY	
		0	REAR WINDSCREEN GLASS SEALANT	Reviewing		50	NECESSARY	
		0	LAMBENCY CERAMIC	Deny			SERVICEABLE	
		0	REAR FLOOR PANEL INSULATION	Reviewing		80	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount		\$5,547.32
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$3,218.32				
Labour		\$0.00		\$1,934.00				
Miscellaneous		\$0.00		\$395.00				

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FINAL LUMP SUM	Reviewing	4400		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$4,400.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$4,400.00

Submit for Review