

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TP/AIG

SGZ1199J

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG
Claim Type: Third Party
Accident Date: 08/05/2019
TP Veh Reg No: GBE9294J

Estimate No: ES1991531/WS

Date: 21 May 2019

Policy No: 5103759141

Veh Reg No: SGZ1199J

Make/Model: TOYOTA LEXUS IS250
AUTO STD

Chassis No: JTHBK262005046758

Engine No: 4GR0360502

Reg. Date: 26/09/2007

Estimate Repair Cost to Vehicle No :SGZ1199J

Description	U/Price	Quantity	List Price	Amount
List Price			S\$	S\$
1 FRONT BUMPER	706.80	1 PC	706.80	
2 FRONT BUMPER RH SIDE RETAINER	63.63	1 PCS	63.63	
3 FRONT BUMPERRH FOG LAMP	338.20	1 PC	338.20	
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	
			1,129.63	
		Less 25%	282.41	847.22
Labour				
5 REMOVE AND REFIX FRONT BUMPER ASSY, KNOCK AND REPAIR FRONT BUMPER REINFORCEMENT, FRONT RH FENDER AND REALIGN THE SAME	400.00	1 LA	400.00	25d
6 PUTTY AND RESPRAY ON FRONT BUMPER, REINFORCEMENT, FRONT RH FENDER	600.00	1 LA	600.00	20d
			1,000.00	1,000.00
			Total	S\$ 1,847.22
			Add GST @ 7%	129.31
			Total Amount Payable	S\$ 1,976.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE