

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0638/2019NK
Date : 18-May-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : SKT 7807 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chua Kian Tiong Peter
Address : 28B Jalan Lempeng
: Singapore 288917
: # 21-19
Telephone : HP +65 92711433
Type of Claim : Third Party Claims
Policy No. : 1800070073
Vehicle No : **SKT 523 7** ✓
Model Code : A3 Sedan 1.0 TFSI
Model / Year : 16-06-2018
Engine No : CHZ907563
Chassis No : WAUZZZ8V0J1057518
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-May-19
Place of Accident : CTE Braddle Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 523 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle rhs front panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00 ✓	
3	To dismantle and renew front bumper, rhs headlight and rhs front fender. Reorganise crash management components. Reinstall all parts removed.	\$ 2,450.00 ✓	1000
4	To respray front bumper, rhs front fender and rhs front door.	\$ 2,700.00 ✓	1650
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,282.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 523 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	\$ 1,830.00	X
2	FRONT BUMPER FIXING SETS	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION RHS	\$ 35.00	+
4	FRONT BUMPER COVER TRIM RHS	\$ 148.00	+
5	WHEEL HOUSING LINER ADAPTER RHS <i>new</i>	\$ 34.00	+
6	AIR GUIDE GRILLE - BLACK RHS	\$ 171.00	X
7	FRONT FENDER RHS <i>Dented</i>	\$ 778.00	✓
8	FRONT FENDER ATTACHEMENTS PARTS ?	\$ 65.00	?
9	FRONT FENDER BRACKET LOWER/ UPPER RHS ?	2 \$ 60.00	?
10	FRONT FENDER BRACE ?	\$ 88.00	?
11	WHEEL HOUSING LINER SEAL RHS <i>new</i>	\$ 31.00	+
12	WHEEL HOUSING LINER RHS <i>new</i>	\$ 158.00	+
13	WHEEL HOUSING LINERS ATTACHMENTS PARTS <i>new</i>	\$ 81.00	+
14	ALUMINIUM RIMS FRONT RHS <i>new set</i>	\$ 666.00	✓
15	RUBBER VALVE <i>new</i>	4 \$ 13.00	+
16	LED HEADLIGHT RHS <i>new</i>	\$ 5,029.00	+
17	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		: \$ 9,857.00	
TOTAL LABOUR CHARGES		: \$ 6,282.00	
GRAND TOTAL		: \$ 16,139.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling.
Surveyed Date : 21/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS Pays.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant