

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19008719/KPS3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMJ3369K	Insured Vehicle No :	SHC3912M
Date of Loss: 13/05/2019	Nature of Claim: TP	Claim No: MCT19050817

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ3369K	Engine No:	2NR5322344
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3001165183
Reg. Date:	28/02/2019 (Man. Year: 2019)	Odometer:	6584 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,099.04	1,555.29	543.75	25.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,320.00	290.00	18.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,709.04	2,875.29	833.75	22.48
+ GST 7.00/7.00% (S\$)	259.63	201.27	58.36	22.48
Nett Amount (S\$)	3,968.67	3,076.56	892.11	22.48
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
		3,556.56		

INSPECTION

Date of Assignment:	15/05/2019	
Date Inspected:	27/05/2019	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2020)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ3369K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	452.50 FL	*452.50 FL
2	1		*REAR BUMPER RH REFLECTOR	Cracked	102.20 FL	*102.20 FL
3	1		*REAR BUMPER SIDE RETAINER	Serviceable	122.90 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	301.60 FL	*301.60 FL
5	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
6	1		*REAR BOOT	Bent	672.70 FL	*672.70 FL
7	1		*REAR BOOT EMBLEM (VIOS)	Necessary	43.60 FL	*43.60 FL
8	1		*REAR BOOT EMBLEM E	Necessary	31.30 FL	*31.30 FL
9	1		*REAR BOOT LOGO	Necessary	50.25 FL	*50.25 FL
10	1		*REAR PANEL	Repair	602.10 FL	*- FL
11	1		*REAR RH REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
12	1		*REAR BUMPER BRACKET RH	Bent	131.90 FL	*131.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,732.05	2,007.05
- List Item Discount on L Items 25.00/25.00% (\$\$)	633.01	451.76
Total Parts (\$\$)	2,099.04	1,555.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	540.00
2	PUTTY & RESPRAY PAINTING	New	800.00	700.00
3	RMEOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	New	50.00	50.00
4	RUSTPROOFING	New	60.00	30.00
			Gross Labour Cost (\$\$)	1,320.00
			1,610.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >