

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SMJ3369K
 TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

WS Ref: TP/INDIA
 Claim Type: Third Party
 Accident Date: 13/05/2019
 TP Veh Reg No: SHC3912M

Not Authored
Resurvey B4 paint
82875.28 3 days

Estimate No: ES1991557/YISHUN
 Date: 27 May 2019
 Policy No: 5107599703
 Veh Reg No: SMJ3369K
 Make/Model: TOYOTA VIOS 1.5 E (AUTO)
 Chassis No: MR2B23F3001165183
 Engine No: 2NR5322344
 Reg. Date: 28/02/2019

Estimate Repair Cost to Vehicle No :SMJ3369K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	452.50	1 PC	452.50	✓
2 REAR BUMPER RH REFLECTOR	102.20	1 PC	102.20	✓
3 REAR BUMPER SIDE RETAINER	122.90	1 PC	122.90	✓
4 REAR BUMPER REINFORCEMENT	301.60	1 PC	301.60	✓
5 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
6 REAR BOOT	672.70	1 PC	672.70	✓
7 REAR BOOT EMBLEM (VIOS)	43.60	1 PC	43.60	✓
8 REAR BOOT EMBLEM €	31.30	1 PC	31.30	✓
9 REAR BOOT LOGO	50.25	1 PC	50.25	✓
10 REAR PANEL	602.10	1 PC	602.10	✓
			2,400.15	
		Less 25%	600.04	1,800.11
Special Net				
11 REAR RH REVERSE SENSOR	200.00	1 PC	200.00	✓
			200.00	200.00
Labour				
12 PANEL BEATING	700.00	1 LA	700.00	754d
13 PUTTY & RESPRAY PAINTING	800.00	1 LA	800.00	700d
14 REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	50.00	1 LA	50.00	✓
15 RUSTPROOFING	60.00	1 LA	60.00	30d
			1,610.00	1,610.00

Total SS 3,610.11
 Add GST @ 7% 252.71
 Total Amount Payable SS 3,862.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd
 CoR-
 Turpin CAR-624100-600
 AUTHORIZED SIGNATURE
 [Signature]

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

Supp 1
SMJ 3369K

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711
 TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

Estimate No: ES1991557/YISHUN
Date: 28 May 2019
Policy No: 5107599703
Veh Reg No: SMJ3369K
Make/Model: TOYOTA VIOS 1.5 E (AUTO)
Chassis No: MR2B23F3001165183
Engine No: 2NR5322344
Reg. Date: 28/02/2019

WS Ref: TP/INDIA
 Claim Type: Third Party
 Accident Date: 13/05/2019
 TP Veh Reg No: SHC3912M

Estimate Repair Cost to Vehicle No :SMJ3369K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
	Supplementary 1			
List Price				
1 REAR BUMPER BRACKET RH	131.90	1 PC	131.90	131.90
		Less 25%	32.98	98.93
		Total		S\$ 98.93
		GST Amount		S\$ 6.92
		Total Amount Payable		S\$ 105.85

For Cheng Hoe Motor Pte Ltd



 AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____