



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19008724/Uha3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 08-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 7911Y	Veh. Inspected	SLE 6711Z
Policy No.	DMCVSN1809301801	Coverage (\$)	0.00
Claim No.	SNM19D202109C02/	Excess (\$)	0.00
Assign From		Assign Date	16/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707040297	Colour	WHITE
Odometer	44141	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	HABILEAD	6 mm
L/H Front Tyre	195/50 R16	HABILEAD	6 mm
R/H Rear Tyre	195/50 R16	HABILEAD	6 mm
L/H Rear Tyre	195/50 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/05/2019	Inspection Date	16/05/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------