

ASS. REC. BY:

REF: CS/SMO19008732 / KH d3n2

Special Instruction:

SURVIVOR: KALIN

ASSIGNMENT (Office)

From (Person): Thelma choo

of

SMO

Date/Time: 16.5.14 1627 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SG 5080Z

Insured:

CB 6808B

at Workshop m/s Lexbuild International

Tel:

90296574

of 2 Woodland Sector 1 #05-12

Policy No: DIBMTSEBU000726

Claim No:

CMTD1902374

Sum Insured:

Excess:

Make of Veh:

D.O.A 9.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.5.14 439 p.m

Person Contacted:

Yong Shun

Vehicle: IN / OUT

Date/Time:

Action/Instruction (✓) Estimate Inspection: Loyang Bus Depot 2 Loyang Way

SG 5080Z - X

CB 6808B - CCB / AXA 13006814 / UH63C3

D.O.A - 09/04/2013

21/5-

Rented via merimen.

Attended: Kolvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

ODITPINSITPRESIODRESIEVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s Leobail / Zulu

id 9737763x

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vtc: _____

(Policy Condition)

Remark: The vch had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Vch No: SH 5002 Yr Regn: 28 Apr 2016

Type: M.Car / M.Cycle / 6 / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo B97C cc 936x

Colour: Green AJC: Ins 0 / Std / NI / NA

Sp. Reading: 209 + 68 T/Radio: Insured / Std / NI / 6

Eng/No: _____

C/No: YV354P9224A177228

Gen. Cond: Good / 0 / Poor / Burnt

Steering: Inord 0 / Jammed / Leaked / Burnt or

Brake: Inord 0 / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD 0 / Rim or

Tyre Size: F: 275/70R225

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Conti

Front 4 mm Rear 4,4 mm

R/Bal. 4 mm L/Bal. 4,4 mm

D.O.A. 9/5/19 D.O.L. 17/3/19

Survey held at h. - Aked

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ren.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/6/19 Chk 4/5 & 1km/2h. Ured: 980-21; 41% 5mo

RECEIVED 18 JUN 2019

Date/Time, File Pres to?

19/6 Typist ☐ : Prel. Report

Date/Time, File Return to?

0 ☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp / (\$

☐ : Interview / (\$

☐ : Tech. Insp / (\$

Survey Fee:

Transportation:

3 + RS \$

Fuel:

CRS:

TOTAL

250

11

261

0

1400/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Theima Choo

Date: 21 May 2019

Preliminary Advice

Insured Vehicle No	: CB6808B	Accident Date	: 09/05/2019
TP Vehicle No	: SG5080Z	Assignment Date	: 16/05/2019
Make	: VOLVO B9TL	Est. Duration of Repair	: 2.00
Date of Inspection	: 17/05/2019		
Inspection At	: LEXBUILD INTERNATIONAL PTE LTD (HQ) 2 WOODLANDS SECTOR 1 (WOODLANDS SPECTRUM 1), #05-12 SINGAPORE 738068		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,380.21
Revised Amount	:S\$	1,820.21
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,820.21

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2019		16 May 2019 16:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		SKY TRANSPORT SERVICES PTE LTD, Co. Reg. No.: 201009064K							
Main Claimant:		GO AHEAD SINGAPORE PTE LTD, Co. Reg. No.: 201541900C							
Vehicle Reg. No.:		SG5080Z	Date of Loss:	09/05/2019 08:00 - :59					
Claim Type:		TP / CMTD1902374	Policy/Cover Note No.:	D18MTSCBU000726 (Comprehensive)					
Vehicle Reg. No. (Insured):		C86808B	Policy No. (Claimant):						
		Excess:							
Repairer:		LexBuild International Pte Ltd (HQ) 2 Woodlands Sector 1 (Woodlands Spectrum 1), #05-12, 738068 Woodlands - Tel: 6456 3533							
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/05/2019]							
Adj Asg. Remarks:		WS: Yong Shun - 9029 6574 Vehicle located: Loyang Bus Depot 2 Loyang Way, S(508776) -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 16 May 2019 4:24 PM
To: Tien Yong Shun; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: LBI Claims; Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1902374/THE - LKK/ CB6808B(nr) & SG5080Z ACC ON 09/05/2019

Without Prejudice

Our Reference: CMTD1902374/THE
Your Reference: SG5080Z

Hi Yong Shun,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63324 681.

Please be informed, we have appointed **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SG5080Z on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompoo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Tien Yong Shun [mailto:yongshun@lexbuild.com]
Sent: Thursday, May 16, 2019 11:49 AM
To: Claims - Motor Survey
Cc: LBI Claims
Subject: ACCIDENT CLAIM FOR SG5080Z / CB6808B ON 09/05/2019

Good afternoon Sir/Mdm,

Attached please find the documents for the above case, our client is filing for a third party claim against your insurer **CB6808B**

- 1) Accident Report
- 2) Notice of Accident (AC19/028)
- 3) Insurance Certificate
- 4) Authorization to Act

Please contact us to arrange for survey of the above vehicle, vehicle may station at Go-Ahead Loyang depot, out for service or LexBuild premises

Vehicle located:
Loyang Bus Depot
2 Loyang Way, S(508776)

Yong Shun – 9029 6574

Thank you.

Best Regards,
Tien Yong Shun (田永順)
Senior Operation Executive (Capability)
Mobile : +65 9029 6574
Email : yongshun@lexbuild.com


LexBuildTM
LexBuild International Pte Ltd
2 Woodlands Sector 1
#05-12 (Woodlands Spectrum 1)
Singapore 738068
Tel : +65 6456 3533
Fax : +65 6456 3353
Website : www.LexBuild.com
a new train of thoughts



 Save a tree...please don't print this e-mail unless you really need to.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2019 14:29
Date Of Accident	09/05/2019 08:50
Exact Location Of Accident	P'GGOL FIELD X P'GGOL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5080Z
Insured/Policyholder	
Name Of Registered Owner	GO AHEAD SINGAPORE PTE LTD
Co Reg No	201541900C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63847169

Vehicle Particulars

Manufacturer	VOLVO
Model	B9TL-9.4 D AUTO TURBO ABS (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-18091603MFBP
Cover Note Number	

Driver

Name of Driver	LOO POH CHUN
Work Permit No	G2964099N
Date Of Birth	25/12/1986
Occupation	OUTDOOR
Date Of Driving Pass	31/03/2017
Driving Experience	2 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93740268
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	267B P'GGOL FIELD #03-123
Postcode	822267
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY BUS WAS THE 2ND VEHICLE QUEUING & WAITING STATIONARY ON THE 2ND LANE FROM THE EXTREME RIGHT OF A 4-LANE RD ALONG P'GGOL RD BEFORE THE SIGNALIZED JUNCTION OF P'GGOL FIELD WHEN I FELT A STRONG IMPACT FROM THE REAR OF MY BUS. I ALIGHTED MY BUS & REALIZED THAT A WHITE TOYOTA COASTER BUS BY SKY TRANSPORT SERVICES PTE LTD REAR-ENDED MY BUS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DIFFERENT FORMAT
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB6808B
Vehicle Make/Model/Colour	WHITE TOYOTA COASTER SUPER LWB
Details Of Properties	FRONT BUMPER
Vehicle Category	BUS
Name of Driver	TOH
NRIC/Passport Number	
Contact Number	91184540
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SG-5080Z



CB6808B

Accident Photo



Accident Photo



Accident Photo



9th May 2019

Quotation No.: Q18-OPS-0617

Sompo Insurance Singapore Pte. Ltd.

05-01/06 Land Tower, Raffles Place,
Singapore Land Tower,
Singapore (048623)

Attn: Claims Department

Dear Sir/Mdm

Estimated Cost of Repair job for SG5080Z (Accident on 09/05/19, along Punggol Field x Punggol Rd involving SG5080Z & CB6808B)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour to remove & replace rear RHS bumper bar with sealant	1 day	\$880.00	\$880.00 600
2	Supply skilled painter & paint material to putty, grinding & spraypaint rear RHS affected area (1-color - green)	1 day	\$880.00	\$880.00 600
3	Rear RHS bumper	1 pc	\$320.21	\$320.21
4	Advertisement	1 lot	\$300.00	\$300.00
Total				\$2,380.21
GST				\$166.61
Sub-Total				\$2,546.82

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 2 working day
Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive



Handwritten notes:
Kali 1 day
17/5/19 1426
2 Bys.
45
After 17/5/19

Approval by

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.
Tel: (65) 6456 3533, Fax: (65) 6456 3353
Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008732/K1TD3N2

Date: 19/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000726
Claimant Vehicle No :	SG5080Z	Insured Vehicle No :	CB6808B
Date of Loss:	09/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902374

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5080Z	Engine No:	D9195105
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Chassis No:	YV3S4P922GA177228
Reg. Date:	28/04/2016 (Man. Year: 2015)	Odometer:	209968 km
Colour:	Green		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Continental 4 mm	Rear Left Side:	Continental 4/4 mm
Front Right Side:	Continental 4 mm	Rear Right Side:	Continental 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	620.21	620.21	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,200.00	560.00	31.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,380.21	1,820.21	560.00	23.53
Approved Total (Overridden) (\$\$)		1,400.00		
(S\$)	2,380.21	1,400.00	980.21	41.18
+ GST 7.00/7.00% (S\$)	166.61	98.00	68.61	41.18
Nett Amount (\$\$)	2,546.82	1,498.00	1,048.82	41.18

INSPECTION

Date of Assignment:	16/05/2019	
Date Inspected:	17/05/2019 Inspected At:	LexBuild International Pte Ltd (HQ) 2 Woodlands Sector 1 (Woodlands Spectrum 1), #05-12 Singapore 738068
Estimated Period of Repair:	2.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Jun 2019)	
Parts:	N/A	VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5080Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RHS BUMPER	Cracked	320.21 FS	*320.21 FS
2	1		*LOT ADVERTISEMENT	Necessary	300.00 FS	*300.00 FS
				Total Parts (S\$)	620.21	620.21

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY SKILLED LABOUR TO REMOVE & REPLACE REAR RHS BUMPER BAR WITH SEALANT	New	880.00	600.00
2	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY,GRINDING & SPRAYPAINT REAR RHS AFFECTED AREA (1-COLOR-GREEN)	New	880.00	600.00
Gross Labour Cost (S\$)			1,760.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >