

ASS. REC. BY:

REF:

CS/FCI/19008742/Rld3/12

Special Instruction:

Labour

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

4:25pm @ 16/5/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 7015Y

Insured:

SHC 38972

at Workshop m/s

Premium

Tel:

G888 2233 / 87779612

of

281 Alexandra Road

Policy No:

Claim No:

D19003258MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/5/2019

CA / REV / REP. / REV 24 HRS

(up)

17/5/19 @ 10:45am @ meeting

H.O.D. Endorsement:

Date/Time:

4:53pm @ 16/5/19

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate

✓

SKP 7015Y - X

SHC 38972 - CS/FCI/18017071/11/4/3n2

DOA: 15/9/2019

28/05/19

@ 11:05 am received PN to Joanne Yong via email.

25/11/19

@ 16:33 pm Kee Sang informed us that owner has withdrawn his claim via email.

DATE

Paul

REF: FCI

77582

ASSIGNMENT

Form

Date

21/5/19

Estimated Cost

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SKP 70154

at Workshop no

Premium

at

281 Alexandra Road

Insured

Policy No

Claim No

Sum Insured

Excess


(Client's Record)

Make of Veh.

10:30am
ng kenji

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection



Est. of Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

days Res. Yes or No

Lump Sum:

% JVil Yes or No

CA / REV / REP. / 24 HRS

1up

Vehicle IN / OUT

Date:

Person Contacted:

Veh No

SKP 70154

Veh Type

2014 SEP

Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 1.8 TFSI

CC 1798

Colour:

BLACK

ACC Insured / Std / RI / RA

Sp Reading

45946

T/Gadio Insured / Std / RI / RA

Eng No

CINo:

WAUZZ28K0FA007571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or

Tyre Size:

F:

225/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Ral

6

mm

R/Ral

6

mm

L/Ral

6

mm

L/Ral

6

mm

D.O.A

14/05/19

D.O.A

21/05/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/5 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 26 NOV 2019

Date/Time, File Path (s)

11

Date/Time, File Path (s)

75

Report Format :

Print

Lump Sum / L.B.L: (\$)

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

G + RS: \$

Fuel

Others

TOTAL

4x15 = 60

170 + 60
50

25

305

MOTOR SURVEY ASSIGNMENT

Date	16-05-2019	Our Ref No. D19003258MFSH
Accident Date	14-05-2019	Claim Type. Third Party
Insured Vehicle	SHC3897Z	Third Party Vehicle. SKP7015Y
Survey Location	281 ALEXANDRA ROAD	
Contact Person.	NG KENJI	
Contact No.	63882233/ 0	Fax No. 64751023
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 25 November 2019 4:33 pm
To: 'Joanne Yong Lai fong'; Admin A; Admin-D (LKKAuto)
Cc: claims@premiumauto.com.sg; Rasul (LKKAuto)
Subject: RE: ACCIDENT INVOLVING SKP 7015 Y AND YOUR INSURED SHC 3897 Z DATED ON 15/05/2019
Attachments: SKP 7015 P 14052019 GIA ADDENDUM.PDF

Dear Joanne and LKK,

Kindly be-informed that our client has withdrawn his claim from our end.

Attached is the GIA for your reference.

Best Regards,
Kee Siang
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 8826 8736 p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Joanne Yong Lai fong [mailto:JoanneYong@msfirstcapital.com.sg]
Sent: Monday, 27 May, 2019 2:31 PM
To: Claims <claims@premiumauto.com.sg>
Subject: RE: ACCIDENT INVOLVING SKP 7015 Y AND YOUR INSURED SHC 3897 Z DATED ON 15/05/2019

WITHOUT PREJUDICE

Dear Sir,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 28 May 2019 11:05 AM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19003258MFSH/1
Attachments: SKP 7015Y - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SKP 7015Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 16 May 2019 5:45 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003258MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 17/05/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 16 May 2019 4:25 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003258MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7758I
Vehicle Details	
Vehicle No.:	SKP7015Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU (EU6)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CJE085115
Chassis No.:	WAUZZZ8K0FA007571
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$28,952.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$22,533.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$16,899.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,403.00
COE Rebate Amount:	\$38,958.00
Total Rebate Amount:	\$55,857.00

The information contained herein is correct as at 28 May 2019

OK

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 4, 4th Floor, 401-405 Singapore Street
 Tel: (65) 6223 8888 Fax: (65) 6223 8889
 Operating Hours: Monday to Friday 9.00 AM - 5.00 PM
 Sat: 9.00 AM - 5.00 PM Sun: 9.00 AM - 5.00 PM

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorized Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA119063420 Vehicle Registration No: SKP7015Y
 Name (as on NIC): PERIAKARUPPAN NRIC/FIN/Passport No: S13177581
 [*Vehicle Driver / Vehicle Owner] [*] Please delete as appropriate
 Address: BLK 7 TONG WATT ROAD #08-03 Singapore (238002)
 Contact (Tel): 83227047 Mobile No.: _____
 Email Address: CHARAN703324@GMAIL.COM
 Date of Accident: 14/05/2018 Time of Accident: 2215HRS
 Place of Accident: PENANG ROAD IN FRONT OF PARK MALL
 Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMENDMENT CLAIM FROM TP CLAIM TO Reporting Only

 Policyholder / Driver's Signature
 Date: _____

 Reporting Centre Personnel's Signature
 Name: Ng Kai Si
 Date: 591443410

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0634/2019/KK
Date : 16-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SHC 3897 Z**

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr. Periakaruppan
Address : 7 Tong Watt Road
#08-03
Singapore 238002
Telephone : (HP)+65 93835877
Type of Claim : Third party Claims
Policy No. : 1700041180-01
Vehicle No : **SKP 7015 Y**
Model Code : Audi A4 1.8T FSI MU
Model / Year : Sep-14
Engine No : CJE 085115
Chassis No : WAUZZZ8K0FA007571
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-May-19
Place of Accident : Penang Road In Front Of Park Mall

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 7015 Y

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs headlight and lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 / 250
3	To respray front bumper and lhs front fender.	\$ 1,800.00 1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>4,802.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 7015 Y

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER <i>repair</i>	\$	2,100.00
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	234.00
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>? new</i>	\$	207.00
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>? new</i>	\$	123.00
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>?</i>	\$	177.00
6	RADIATOR GRILLE <i>? new</i>	\$	1,005.00
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	\$	123.00
8	FRONT WHEEL SPOILER - LH <i>?</i>	\$	45.00
9	FOAM FILLER PIECE <i>?</i>	\$	113.00
10	FRONT BUMPER REINFORCEMENT <i>?</i>	\$	802.00
11	FRONT BUMPER COVER <i>X new</i>	\$	115.00
12	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	\$	33.00
13	FRONT BUMPER GRILLE SUPPORT <i>?</i>	2 \$	23.00
14	SIGN "CAUTION" <i>X new</i>	\$	13.00
15	AIR CONDITIONER STICKER <i>X new</i>	\$	22.00
16	FRONT FENDER - LH <i>repair</i>	\$	904.00
17	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	52.00
18	FRONT FENDER BRACKET - LH <i>new</i>	\$	48.00
19	REAR DEFORMATION ELEMENT BRACKET - LH <i>?</i>	\$	45.00
20	FRONT LOWER FENDER BRACE - LH <i>X new</i>	\$	107.00
SUB SPARE PARTS		\$	6,291.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 7015 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	STONE CHIP GUARD ?	\$	67.00
22	ADHESIVE TAPE ?	\$	50.00
23	HEADLAMP MOUNTING BEAM - LH ?	\$	107.00
24	HEADLAMPS BRACKET - LH ?	\$	96.00
25	HEADLIGHT GAS DISCHARGE - LH BCL ✓	\$	2,152.00
26	HALOGEN FOG LAMP - LH X S/L ✓	\$	242.00
27	HEADLIGHT LIFT CYLINDER - LH repair	\$	312.00
28	FRONT NUMBER PLATE X S/L ✓	S/N \$	40.00
29	SUNDRIES ?	\$	600.00 ?
TOTAL SPARE PARTS		:	\$ 9,957.00
TOTAL LABOUR CHARGES		:	\$ 4,802.00
GRAND TOTAL		:	\$ 14,759.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Rasuk - Hp 90010068
: 21/05/19 @ 1045
: 5 days
: Reay after repair


28/5/19

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19008742/R1sd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-11-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3897Z	Veh. Inspected	SKP 7015Y
Policy No.		Coverage (\$)	0.00
Claim No.	D19003258MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	16/05/2019

2. Vehicle Particulars & Condition

Make & Model	AUDI A4 1.8 TFSI	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WAUZZZ8K0FA007571	Colour	BLACK
Odometer	45946	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R16	GOODYEAR	6 mm
L/H Front Tyre	225/55 R16	GOODYEAR	6 mm
R/H Rear Tyre	225/55 R16	GOODYEAR	6 mm
L/H Rear Tyre	225/55 R16	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/05/2019	Inspection Date	21/05/2019
Survey held at	281 ALEXANDRA ROAD		
Repairer	PREMIUM AUTOCARE CENTRE		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 7015Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (SN)	TO REPAIR SEE LABOUR	2,100.00	-
1	FRONT BUMPER FIXING PARTS (SN)	NECESSARY	234.00	234.00
1	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE (SN)	* CHECK	207.00	-
1	FRONT BUMPER GRILLE-LOWER CENTRE (SN)	* CHECK	123.00	-
1	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE (SN)	* CHECK	177.00	-
1	RADIATOR GRILLE (SN)	SERVICEABLE	1,005.00	-
1	FRONT BUMPER AIR GUIDE GRILLE-LH (SN)	* CHECK	123.00	-
1	FRONT WHEEL SPOILER-LH (SN)	* CHECK	45.00	-
1	FOAM FILLER PIECE (SN)	* CHECK	113.00	-
1	FRONT BUMPER REINFORCEMENT (SN)	* CHECK	802.00	-
1	FRONT BUMPER COVER (SN)	SERVICEABLE	115.00	-
1	FRONT BUMPER GUIDE SECTION-LH (SN)	* CHECK	33.00	-
2	FRONT BUMPER GRILLE SUPPORT (SN)	* CHECK	23.00	-
1	SIGN "CAUTION" (SN)	NOT NECESSARY	13.00	-
1	AIR CONDITIONER STICKER (SN)	NOT NECESSARY	22.00	-
1	FRONT FENDER-LH (SN)	TO REPAIR SEE LABOUR	904.00	-
1	FRONT FENDER ATTACHMENT PARTS (SN)	NECESSARY	52.00	52.00
1	FRONT FENDER BRACKET-LH (SN)	NECESSARY	48.00	48.00
1	REAR DEFORMATION ELEMENT BRACKET-LH (SN)	* CHECK	45.00	-
1	FRONT LOWER FENDER BRACE-LH (SN)	SERVICEABLE	107.00	-
1	STONE CHIP GUARD (SN)	* CHECK	67.00	-
1	ADHESIVE TAPE (SN)	* CHECK	50.00	-
1	HEADLAMP MOUNTING BEAM-LH (SN)	* CHECK	107.00	-
1	HEADLAMPS BRACKET-LH (SN)	* CHECK	96.00	-
1	HEADLIGHT GAS DISCHARGE-LH (SN)	SCRATCHED	2,152.00	2,152.00
1	HALOGEN FOG LAMP-LH (SN)	SERVICEABLE	242.00	-
1	HEADLIGHT LIFT CYLINDER-LH (SN)	TO REPAIR SEE LABOUR	312.00	-

Report Ref No. CS/FCI19008742/R1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	40.00	-
1	SUNDRIES (SN)	* CHECK	600.00	-
			9,957.00	2,486.00
	LABOUR			
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY,		360.00	360.00
	TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT AND LHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT FENDER-LH AND HEADLIGHT LIFT CYLINDER-LH.		2,450.00	1,250.00
	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.		1,800.00	1,100.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			4,802.00	2,902.00
	GRAND TOTAL		14,759.00	5,388.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,611.00 NETT)			5,388.00

Report Ref No. CS/FCI19008742/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.