

J

not Affected
2/88 2150
4 days
Telephone. Heli
Apr

ABWIN 諭輝

Date : 17/05/2019
 TP Vehicle No. : XE -4382-K
 To : QBE INSURANCE (SINGAPORE) PTE LTD
 Attn : Motor Claim Department

YVONNE
 ABWIN SERVICE PTE LTD
 DID:
 Fax:
 HP:

Owner : FA YEW CONSTRUCTION PTE LTD
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5091598958-01
 Vehicle No. : SKT-9301-L
 Make & Model : NISSAN NOTE 1.2 (A) JN1TBAE12

Accident Date: 11/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>Nett Item</u>			
1	BONNET <i>654.60</i>	<i>20/50</i> \$780.00	
10	BONNET CLIPS	11 \$60.00	X
2	BONNET HINGE	12 \$84.00	X
1	BONNET LOCK CATCH	11 \$150.00	X
1	BONNET LOCK	7m \$132.00	✓
1	BONNET LOCK CABLE	11 \$60.00	X
1	BONNET GARNISH	0m \$105.00	✓
1	FRONT BUMPER	12 \$980.00	X
10	FRONT BUMPER CLIPS	11 \$60.00	X
1	FRONT BUMPER REINFORCEMENT	12 \$360.00	X
2	FRONT BUMPER RETAINERS	11 \$90.00	X
10	FRONT BUMPER RETAINER CLIP	12 \$60.00	X
2	FRONT BUMPER TOW COVERS	12 \$100.00	X
1	FRONT BUMPER SPONGE	11 \$250.00	X
1	FRONT GRILLE	0m \$280.00	✓
1	FRONT GRILLE CHROME	11 \$280.00	X
1	FRONT GRILLE EMBLEM	1m \$70.00	✓
2	FRONT FOGLAMPS	11 \$700.00	X
2	FRONT FOGLAMP COVERS	11 \$160.00	X
1	HEADLAMP RH	12 \$1,550.00	X
1	HEADLAMP LH	12 \$1,550.00	X
10	HEADLAMP CLIPS	11 \$60.00	X
1	HEADLAMP PANEL RH	11 \$90.00	X
1	HEADLAMP PANEL LH	12 \$90.00	X
1	FRONT FENDER (RH)	12 \$550.00	X
1	FRONT FENDER LH	12 \$550.00	X
1	FRONT SUPPORT PANEL	12 \$240.00	X
1	FRONT SUPPORT PANEL TOP	11 \$350.00	X
	Sub Total	\$9,791.00	

Date : 17/05/2019
 TP Vehicle No. : XE -4382-K
 To : QBE INSURANCE (SINGAPORE) PTE LTD
 Attn : Motor Claim Department

YVONNE
 ABWIN SERVICE PTE LTD
 DID:
 Fax:
 HP:

Owner : FA YEW CONSTRUCTION PTE LTD
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5091598958-01
 Vehicle No. : SKT-9301-L
 Make & Model : NISSAN NOTE 1.2 (A)

Accident Date: 11/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Discount 10% on Parts <i>502</i>	(\$979.10)	
		\$8,811.90	

Special Nett

1	FRONT NO PLATE WITH CASING	<i>502</i> \$65.00	<i>40</i>
	Sub Total	\$65.00	

Labour & Misc

	TO CHECK HEADLAMP WIRING	\$150.00	<i>30</i>
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	<i>11</i> \$180.00	<i>X</i>
	TO APPLY TUFF KOTE ON AFFECTED AREA.	\$150.00	<i>50</i>
	TO PANEL BEATING & STRAIGHTEN ACCIDENT ALL NECESSARY ETC	\$1,500.00	<i>520</i>
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA.	\$1,200.00	<i>900</i>
	Sub Total	\$3,180.00	

Sub Total \$12,056.90
 GST 7% \$843.98
 Total \$12,900.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

p- 1241.6
502
p- 620.80
S.N 40.00
1060 - 1500
2160.80