



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

CHEW KAILI

15/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA.

Xiao Tong.

WBAJA120X0WC08999

Accident date: 15/05/2019

Estimated repair cost for vehicle no: SCU1918A BMW 520i 2.0 A '18

CHASSIS: WBAJA120X0WC08999

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented.</i>		\$2,655.00	✓ 2451
2	2	Rear Boot Lid Hinge <i>3 new</i>	\$158.00	\$316.00	+
3	2	Rear Boot Lid Hinge Cover <i>new</i>	\$122.00	\$244.00	+
4	2	Rear Boot Lid Side Reflector <i>cut</i>	\$427.00	\$854.00	✓
5	1	Rear Boot Lid Emblem Logo <i>new</i>		\$71.00	✓
6	1	Rear Boot Lid Camera <i>Damaged.</i>		\$890.00	✓
7	1	Rear Bumper Number Plate <i>3 new</i>		\$50.00	+
8	2	Rear Boot Lid Number Plate Lamp	\$55.00	\$110.00	+
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$282.00	✓
10	1	Rear Boot Lid Inner Lock Switch <i>new</i>		\$281.00	+
11	1	Rear Boot Lid Inner Inner Rubber <i>cut</i>		\$197.00	✓
12	1	Rear Boot Lid Inner Trim Board <i>3 new</i>		\$525.00	+
13	8	Rear Boot Lid Inner Trim Board Clip	\$8.00	\$64.00	+
14	2	Rear Tail Lamp <i>cracked</i>	\$692.00	\$1,384.00	✓
15	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
16	2	Rear Tail Lamp Lower Bracket <i>new</i>	\$82.00	\$164.00	+
17	2	Rear Tail Lamp Panel <i>new</i>	\$833.00	\$1,666.00	+
18	1	Rear Bumper <i>Damaged</i>		\$2,355.00	✓ 182
19	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	50
20	2	Rear Bumper Side Retainer <i>cracked</i>	\$138.00	\$276.00	✓
21	2	Rear Bumper Side Reflector <i>cracked</i>	\$58.00	\$116.00	✓
22	1	Rear Bumper Lower Moulding <i>missing</i>		\$284.00	✓
23	1	Rear Bumper Towing Cover <i>damaged</i>		\$60.00	✓
24	6	Rear Bumper Reverse Sensor <i>2 pieces damaged</i>	\$305.00	\$1,830.00	520
25	1	Rear Bumper Inner Top Bracket <i>cracked</i>		\$225.00	✓
26	1	Rear Bumper Inner Center Cover <i>cracked</i>		\$246.00	✓
27	1	Rear Bumper Lower Bottom Cover (Small) <i>cracked</i>		\$214.00	✓

28	1	Rear Bumper Lower Bottom Cover (Big)	cracked		\$355.00	✓
29	1	Rear Bumper Smart Opener Sensor	damaged		\$193.00	✓
30	1	Rear Bumper Reinforcement	Bent		\$729.00	✓
31	1	Rear End Panel	Dented.		\$883.00	✓
32	1	Rear End Panel Top Garnish	cracked.		\$310.00	✓
33	2	Rear Fender	Repair	\$2,209.00	\$4,418.00	+
34	2	Rear Fender Inner Trim Board	2 new	\$302.00	\$604.00	x
35	16	Rear Fender Inner Trim Board Clip	1 new	\$6.50	\$104.00	x
36	1	Rear Spare Tyre Panel Top Cover	2 new		\$342.00	x
37	1	Rear Spare Tyre Panel & End Panel Sealant	1 new		\$450.00	+
38	2	Rear Exhaust	Repair	\$1,874.00	\$3,748.00	+
39	4	Rear Exhaust Mounting	Not new	\$73.00	\$292.00	x
40	2	Rear Exhaust Chrome Pipe	Not new	\$204.00	\$408.00	+
41	1	Rear Exhaust Center Aluminium Cover	cracked.		\$195.00	✓
42	2	Rear Exhaust Side Aluminium Cover	cracked.	\$212.00	\$424.00	✓
43	1	Rear Center Exhaust	Repair		\$2,926.00	x

Subtotal :- \$31,837.00

1342
13132
924
12475.40

Labour charges

To remove & refit cushion & trim board

~~\$380.00~~ 80

To remove & refit rear camera

~~\$280.00~~ 80

To remove & refit reverse sensor

~~\$180.00~~ 60

To remove & refit rear windscreen

~~\$120.00~~ X

Gum

~~\$60.00~~ X

To remove & refit rear & center exhaust

~~\$380.00~~ 120 X

To reset computer

~~\$280.00~~ 150

To check wiring

~~\$120.00~~ 30

Tuff kote

28W
~~\$200.00~~ 80

Panel beating

~~\$2,000.00~~ 1200

Spray painting

~~\$2,000.00~~ 1000

Subtotal :- \$6,000.00

Total:- \$37,837.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 1527540

h/s: 12-2K

07 Days

12-2K