

Signature: Hwee Jie

REF:

NTUC NS/IR 19008764/5cd302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: SLZ 29935

Policy No: 5108249855 (20/03/2019-19/03/2020)

Claims No: MT/1044567-005


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHL 4605 T Yr Regn: 10 Sep 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: maroon A/C: Insured / Std / NI / NA

Sp. Reading: 557360 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U505748865

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 6/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/5/19 D.O.A. 15/5/19

Survey held at Surt

Des. of Damages: Frs / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	SHL 4605 T - N/S / INC 17001205 / Kich 3m2 D.O.A - 13/01/2017
	SLZ 29935 - N/S / INC 19003643 / 124 D.O.A - 14/07/2019
19/11/19	Finalize Confir \$4700, 6 days (Poh Sur) (\$15,123.50 Red - 76%)
	RECEIVED 2 NOV 2019
	21/11/2019

Date/Time. File Pass to?

22/11/19

1) Typ. 4

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.T: \$ 4,700/- 4/5

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

☐ \$ + PG. \$

☐ Photos

☐ Other:

TOTAL

160

160

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	14/05/2019 10:19
Vehicle No.(For Motor)	SLZ29935	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	S108249855		SUNRITA PRIVATE LIMITED	196800361G	GPC	drive CLASSIC	SLZ29935	SLZ29935	20/03/2019	19/03/2020

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4605T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6132612
Chassis No.:	JTDKN36U505748865
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	10 Sep 2014
First Registration Date:	10 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	09 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$20,995.00
Total Rebate Amount:	\$27,061.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 May 2019

OK

TP Claims against NTUC Income: Follow-Through Survey

Date : 21/11/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1069899-002	SMRT TAXI PTE LTD	SHB 5063E	SMN 7910A	02/11/2019	4:30	\$ 11,390.64
2	MT/1044567-005	SMRT TAXI PTE LTD	SHC 4605T	SLZ 2993S	14/05/2019	14:20	\$ 19,823.50
3	MT/1070570-002	SMRT TAXI PTE LTD	SHD 6222X	PC 5240K	06/11/2019	10:15	\$ 5,017.40

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 19 November 2019 4:20 pm
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHC4605T

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Tuesday, 19 November 2019 2:48 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: SHC4605T

Dear Poh Suan,

We confirm the finalize \$4700 (L/S, before GST). 6 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, November 18, 2019 1:18 PM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2019 08:29
Date Of Accident	14/05/2019 14:20
Exact Location Of Accident	GUILLEMARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4605T
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD.
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-80000000
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197 MFSH
Cover Note Number	

Driver

Name of Driver	CHUA GIONG KO
NRIC No	S1782458I
Date Of Birth	25/05/1966
Occupation	OUTDOOR
Date Of Driving Pass	21/09/1987
Driving Experience	31 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	102
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : BAO QUAN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190514/2161

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FLIE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ2993S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YUN AIK LIN EDLIN
NRIC/Passport Number	S0574144J
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJV3272C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHUA GIONG KO
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHC4605T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name BAO QUAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHC4605T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address

Postcode

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Diagram illustrating the accident scene at the intersection of Lor 20 Geylang and Guillemard Road.

Legend:

- A - SHC 4605T
- B - SLZ 2993S
- C - UNKNOWN LORRY
- D - JYV 3272C

Accident Description: The diagram shows a four-way intersection. Lor 20 Geylang runs horizontally, and Guillemard Road runs vertically. A dashed line indicates the path of vehicle B, which was traveling north on Guillemard Road and turning left onto Lor 20 Geylang. At the moment of the accident, vehicle B was in the middle of the turn, having crossed the path of vehicle A, which was traveling south on Guillemard Road. Other vehicles (C and D) were traveling west on Lor 20 Geylang, and two vehicles (X) were traveling south on Guillemard Road.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

GUILLEMARD RD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper. At the very bottom left corner, there is some faint, partially visible text that appears to say "DECLARATION".

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time _____

Driver's Signature: [Signature]
(If driver is not the policyholder)
Date & Time: 14/5/17

Reporting Centre Personnel's Signature
Name _____
Unit/File No. _____



**SINGAPORE
POLICE FORCE**



T/20190514/2161

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 4

Report No. T/20190514/2161

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/05/2019 18:51		Vide Report No.:		Station Diary No.: 144
Informant's Particulars				
Name of Informant: CHUA GIONG KO		Address: APT BLK 102 RIVERVALE WALK #11-82 SINGAPORE 540102		
ID Type / ID No.: NRIC NO / S17824581		Contact No.: Home/Office: Mobile: 96997741		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 52	Date of Birth: 25/05/1966	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 14/05/2019 14:20	Type of Location: X-Junction
Location: Along Road 1 GUILLEMARD ROAD Junction of Guillemard Road and Lorong 20 Geylang				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC4605T	Car	TOYOTA	Prius	Maroon	Slightly Damaged	1
SJV3272C	Car	TOYOTA	Altis	Black	Slightly Damaged	0
SLZ2993S	Car	HONDA	vezel	Silver	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190514/2161

2 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20190514/2161

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	GOH POH QUAN	ID No.	S8729875B
Related Vehicle	SHC4605T (Car)	Contact No.	97717895
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	CHUA GIONG KO	ID No.	S1782458I
Related Vehicle	SHC4605T (Car)	Contact No.	96997741
Hospital/Clinic	DOCTORS INC. MEDICAL GROUP	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/05/2019	Date Discharge	14/05/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Driver			
Name	YUN AIK LIN EDLIN	ID No.	S0574144J
Related Vehicle	SLZ2993S (Car)	Contact No.	0
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/05/2019 at about 1420 hrs, I was travelling along Guillemard Road at the left most lane with a passenger namely Goh Poh Quan (S8729875B). I was driving a company's vehicle bearing SHC4605T from SMRT.

Subsequently, a vehicle bearing SLZ2993S turning from the opposite direction into Lorong20 Gyalang. As there were vehicles on my right lane blocking my view and when I noticed the said vehicle turning, I immediately applied my brakes however it was too late.



**SINGAPORE
POLICE FORCE**



T/20190514/2161

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 4

Report No. T/20190514/2161

CONTINUATION OF REPORT

The front portion area of my vehicle sustained damages due to the impact with the said vehicle. Thereafter, the said vehicle could not stop and lost control causing it to hit onto the unknown parked lorry (unknown bearing plate number) and a vehicle in front of the lorry bearing SJV3272C due to the impact.

I wish to state that my vehicle is installed with a car camcorder and was on recording mode. The footage was extracted by my company for claiming purposes. There are no government property damaged and no ambulance was activated.

My passenger and I then went to see a doctor and was given 4 days of MC by Dr Kevin Loy.

I am lodging this report to facilitate the matter for insurance claims and record purposes.



**SINGAPORE
POLICE FORCE**



T/20190514/2161

4 of 4

Report No. T/20190514/2161

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 AHMAD MUHAJMIN AMZAR BIN MOHD YUSOF	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/05/2019 18:51
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case: SN 168
Authentication Stamp NP168	NATURE



Case Details

Case Reference Number :

TAX/05/19/2065

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4805T

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6880-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 14/05/2019 06:20 AM

Vehicle Age(In Months) : 56

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	✓ OR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ N/A
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace	✓ OR
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	✓ CNT
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	✓ OR
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	✓ CNT
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check	✓ X N/A
One Time Key In	Main			EMBLEM FRONT	1	66.50	66.50	25.00	64.88	Replace	1	64.88	Replace	✓ N/A
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	✓ MIS CR4
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	✓ MIS
Total Spare Part Cost									11,367.62	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									9,094.10	Final Sur Total				
										923.95				
										20				
										739.16				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X NAI
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BUMPER SUPPORT FLH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	OR
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	OR
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	X NAI
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	0	Repair	X R
One Time Key In	Main			HOOD PANEL INSULATOR	1	390.50	390.50	25.00	292.88	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOOD HINGE LH	1	55.90	55.90	25.00	41.92	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	0	0	Check	X NAI

Total Spare Part Cost 11,367.82

Surveyor Total 923.86

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 9,094.10

Final Sur Total 739.16

SMRT Recommendation												Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Check	X NAI	
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	Check	X NAI	
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check	X NAI	
One Time Key In	Main			RADIATOR ASSY	1	1,496.90	1,496.90	25.00	1,122.68	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			RADIATOR ASSY, UPPER	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			A/C CONDENSER	1	1,181.90	1,181.90	25.00	886.43	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	X NAI	
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	X NAI	
Total Spare Part Cost									11,367.62	Surveyor Total					923.95
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)					20
Final Spare Part Cost									9,094.10	Final Sur Total					739.16

[Labour's Cost Detail](#)

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	200	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
6	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
Total:			1,872.00	400.00	

~~1,872.00~~
2000 + 190 (Supp) = 500

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
3	Main	TO TOP UP A/C GAS	120.00	0	
4	Main	TO REMOVE AND REFIT WIRE HARNESS	200.00	0	
5	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	

Total: 880.00 20.00 + 280 (Supp) = 300
1650

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	9,094.10	739.16
Total Labour Cost	1,014.00	400.00

23896.14

Estimator Assessment(\$)

Surveyor Assessment(\$)

Total Spray Painting

1,872.00

400.00

Other

880.00

20.00

Overall Total

12,860.10

1,559.16

Lump Sum Repair Option

Lump Sum Total

12,850.00

1,550.00

Surveyor Approved Amount

1,550.00

No of Repair Days

7

3

Remarks

L/S repair, photo before paint.

Surveyor Name

Hwee Jie

Signature



Save

Clear

23/5/19

Survey Date

15/05/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4605T
Case Reference Number	TAX/05/19/2085
Registration Date	10/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA GIONG KO
Type of Accident	Head To Side
Accident Date and Time	14/5/2019 2:20 PM
Accident Reported Date and Time	14/5/2019 4:11 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101509
Special Instruction to ARC, if any	TP
Prepared Date and Time	15/5/2019 11:49 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$2,052.00	\$500.00
Total Spare Part Cost	\$15,107.50	\$4,663.86
Total Other Cost	\$1,550.00	(\$863.86)
TOTAL COST	\$19,823.50	\$4,700.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jia (LKK) / NTUC
ARC / Surveyor Sign Off Date	15/05/2019 2:54 PM	15/05/2019 2:24 PM
Signature		
Remarks		L/S repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1911-0249	Invoice Number	
Quotation Date	18.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,014.00	\$400.00
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00 (Supp)
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT PORTION	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,052.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REPLACE FRONT SUPPORT PANEL	\$350.00	\$120.00 (Supp)
TO TOP UP A/C GAS	\$120.00	\$50.00 (Supp)
TO CONDUCT RADIATOR PRESSURE CHECK	\$180.00	\$60.00 (Supp)
TO REMOVE & REFIX AIR-CON CONDENSER	\$120.00	\$50.00 (Supp)
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,183.86)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$80.00	\$0.00
Total Other Costs	\$1,650.00	(\$863.86)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52181-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace

		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	✓
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	✓
	53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	✓
	53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	✗
	75310-47010	EMBLEM FRONT	1.00	\$68.50	25.00	\$64.68	Replace	Replace	✓
	52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	✓
	52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	✓
	81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given	✗
	81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	✗
	81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	✗
	81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	✗
	52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	✓
	52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	✓
	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	✓
	52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check	✗
	57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check	✗
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check	✗
	52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$499.40	0.00	\$0.00	Replace	Check	✗
	53301-47080	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair	✓
	53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Not Given	✓
	53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given	✗
	53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	✗
	53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Check	✗
	53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given	✗
	81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check	✗
	81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Check	✗
	53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check	✗
	16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Not Given	✗
	G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	✗
	53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Not Given	✗
	88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Not Given	✗
		COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Not Given	✗
	53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	✗
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	✗
	53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	✗
	53802-47050	FENDER FRT/LH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	✓
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	✗
	53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	✗
Total				\$14,431.33		\$923.95			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		53111-47040	GRILLE, RADIATOR	1.00	\$310.80	25.00	\$232.95	Replace	Replace
		81210-12230	FOG LAMP RH	1.00	\$295.20	10.00	\$265.68	Replace	Replace
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace
		53420-47070	HOOD HINGE LH	1.00	\$55.90	25.00	\$41.93	Replace	Replace
		53410-47070	HOOD HINGE RH	1.00	\$55.90	25.00	\$41.93	Replace	Replace
		53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	25.00	\$1,095.30	Replace	Replace
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
		53289-47032	COVER, RADIATOR	1.00	\$122.80	25.00	\$92.10	Replace	Replace
			COOLANT	1.00	\$12.32	0.00	\$12.32	Replace	Replace
		53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace
		53851-47040	FENDER LINER PAD, FR WHEEL, RH	1.00	\$49.30	25.00	\$36.98	Replace	Replace
		53852-47020	FENDER LINER PAD, FR WHEEL, LH	1.00	\$49.30	25.00	\$36.98	Replace	Replace
Total					4,734.32		3,739.91		

Supp

CRA
 CRA
 CRA
 BT
 BT
 BT
 ST
 BT
 DEF
 CRA
 CRA
 NEC
 CUT
 MIS
 MIS

$$\begin{array}{r}
 4663.86 \\
 + 400.00 \\
 + 800.00 \\
 \hline
 \end{array}$$

$$\begin{array}{r}
 5863.86 \\
 \hline
 \end{array}$$

$$\begin{array}{r}
 - 207 \\
 \hline
 \end{array}$$

$$\begin{array}{r}
 4691.06 \\
 \hline
 \end{array}$$

$$\begin{array}{r}
 415 \$4700/- \\
 \hline
 \end{array}$$

REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX/05/19/0065	Date of Collection	1 / 1
Vehicle No	SHC 4605 T	Date of Request	16/05/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	7 3

S/N	Part Number	Part Description	Quantity	Unit Price
		GRILLE RADIATOR	1pc	CRA -
		FOG LAMP RH	1pc	CRA -
		BUMPER FRONT ABSORBER LOWER	1pc	CRA -
		BUMPER ENERGY ABSORBER FRONT	1pc	CRA -
		ARM SUB ASSY, FRONT BUMPER LH	1pc	- BT
		ARM SUB ASSY, FRONT BUMPER RH	1pc	- BT

\$232.95
 \$265.68
 \$95.78
 \$59.10
 \$187.80
 \$187.80

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 (to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

PO/s

REQUEST FOR SUPPLYMENT PARTS

Contractor:		Date of Collection	1 1
Accident Case Number	TAX/05/19/2065	Date of Request	16/05/2019
Vehicle No	SAC 4605 T	Number of Days to Extend (If any)	83
Vehicle Model	TOYOTA PRIUS		

S/N	Part Number	Part Description	Quantity	Unit Price
		BOMPER REINFORCEMENT FRONT L/R	BT	✓
		HOOD HINGE LH	BT	✓
		HOOD HINGE RH	BT	✓
		SUPPORT SUB ASSY	DEF	✓
		HEAD LAMP LH	CRA	✓
		COVER RADIATOR	CRA	✓

\$373.80
 \$41.93
 \$41.93
 \$1095.30
 \$850.68
 \$92.10

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
 (to be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / TO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

P97/5

REQUEST FOR SUPPLEMENT PARTS

Contractor:			Date of Collection:	1 1
Accident Case Number	TAX 05/19/2065		Date of Request	16/05/2019
Vehicle No	SHC 4605 T		Number of Days to Extend (if any)	8 3
Vehicle Model	TOYOTA PRIUS			

S/N	Part Number	Part Description	Quantity	Unit Price
		COOLANT	4 L	/ rel
		FRONT FENDER LINER RH	1 pc	/ CUT
		FRONT FENDER LINER PAD RH	1 pc	MISSING
		FRONT FENDER LINER PAD LH	1 pc	MISSING
		Labour to REMOVE & REPLACE SUPPORT PANEL		\$ 350
		Labour to SPRAY SUPPORT PANEL		\$ 180

\$ 12.32
 \$ 128.78
 \$ 36.98
 \$ 36.98
 \$ 20
 \$ 100

<<Please submit photographs for damaged parts>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are rated for replacement for the aforesaid vehicle.

Signature of person making this declaration
 (to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

PG 3/5

REQUEST FOR SUPPLYMENT PARTS

Contractor:		Date of Collection	1 1
Accident Case Number	TAK/05/19/2065	Date of Request	16 05/2019
Vehicle No	S/H 4605 7	Number of Days to Extend (If any)	73
Vehicle Model	TOTOTA PRIUS		

S/N	Part Number	Part Description	Quantity	Unit Price	
		Labour to top up AIR-COND GAS		\$120	\$50
		Labour to conduct RADIATOR PRESSURE TEST		\$180	\$60
		Labour to REMOVE & REFIT AIR-COND CONDENSER, RADIATOR		\$120	\$50
		FRONT WINDSCREEN	1pc	X n.c	
		FRONT WINDSCREEN MOUNTING	1pc	X n.c	
		FRONT WINDSCREEN SEALANT	2pc	X n.c	

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

PG 4/5

REQUEST FOR SUPPLYMENT PARTS

Contractor:		Date of Collection	1 / 1
Accident Case Number	TAX/25/19/2065	Date of Request	16/05/2009
Vehicle No	SHE 4605 T	Number of Days to Extend (If any)	3
Vehicle Model	TOYOTA PRIUS		

S/N	Part Number	Part Description	Quantity	Unit Price
	Labour	TO REMOVE & REFIX WINDSCREEN		\$ 200
	Labour	TO REPAIR SOLAR FILM		\$ 450
		TO REQUEST ADDITIONAL REPAIR DAYS		

<<Please submit photographs for damaged parts>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Pg 3/5

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19008764/Esd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 03-12-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLZ 2993S	Veh. Inspected	SHC 4605T	
Policy No.	5108249855	Coverage (\$)	0.00	
Claim No.	MT/1044567-005	Excess (\$)	0.00	
Assign From		Assign Date	15/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U505748865	Colour	MAROON	
Odometer	557360	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/05/2019	Inspection Date	15/05/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4605T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	BROKEN	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BRACKET, FR BUMPER (DISC 25%)	BROKEN	110.40	82.80
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CUT	311.10	233.33
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	COVER, FR BUMPER HOLE LH (DISC 25%)	CRUSHED	18.50	13.88
1	COVER, FR BUMPER HOLE RH (DISC 25%)	MISSING	18.50	13.88
1	BUMPER SUPPORT F/LH (DISC 25%)	BROKEN	76.40	57.30
1	BUMPER SUPPORT F/RH (DISC 25%)	BROKEN	76.40	57.30
1	NUMBER PLATE (SN)	CUT	15.00	15.00
1	NUMBER PLATE FRAME (SN)	BROKEN	12.00	12.00
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	FOG LAMP RH	NOT NECESSARY	295.20	-
1	LENS & BODY, FR TURN RH	NOT NECESSARY	511.80	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-
1	LENS & BODY, FR TURN LH	NOT NECESSARY	511.80	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	BUMPER ENERGY ABDORBER FRT	NOT NECESSARY	78.80	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	HOOD PANEL INSULATOR	NOT NECESSARY	390.50	-
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	HOOD HINGE LH	NOT NECESSARY	55.90	-
1	HOOD HINGE RH	NOT NECESSARY	55.90	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	HEAD LAMP LH	NOT NECESSARY	945.20	-
1	HEAD LAMP RH	NOT NECESSARY	945.20	-
1	COVER, RADIATOR	NOT NECESSARY	122.80	-
1	RADIATOR ASSY	NOT NECESSARY	1,496.90	-

Report Ref No. NS/INC19008764/Esd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR ASSY, UPPER	NOT NECESSARY	679.60	-
1	DEFLECTOR, RADIATOR RH	NOT NECESSARY	83.50	-
1	A/C CONDENSER	NOT NECESSARY	1,181.90	-
1	COOLANT	NOT NECESSARY	12.32	-
1	FENDER FRT / RH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER LINER FRT / RH	NOT NECESSARY	171.70	-
1	FENDER FRT / LH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER LINER FRT / LH	NOT NECESSARY	171.70	-
1	HOOD PANEL	TO REPAIR SEE LABOUR	748.10	-
1	GRILLE, RADIATOR (DISC 25%)	CRACKED	310.60	232.95
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	CRACKED	127.70	95.78
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	ARM SUB-ASSY, FR BUMPER LH (DISC 25%)	BENT	250.40	187.80
1	ARM SUB-ASSY, FR BUMPER RH (DISC 25%)	BENT	250.40	187.80
1	BUMPER REINFORCEMENT FRT (DISC 25%)	BENT	498.40	373.80
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.93
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.93
1	SUPPORT SUB-ASSY (DISC 25%)	DEFORMED	1,460.40	1,095.30
1	COVER, RADIATOR (DISC 25%)	CRACKED	122.80	92.10
1	FENDER LINER FRT / RH (DISC 25%)	CUT	171.70	128.78
1	FENDER LINER PAD, FR WHEEL. RH (DISC 25%)	MISSING	49.30	36.98
1	FENDER LINER PAD, FR WHEEL. LH (DISC 25%)	MISSING	49.30	36.98
1	FOG LAMP RH (DISC 10%)	CRACKED	295.20	265.68
1	HEAD LAMP LH (DISC 10%)	CRACKED	945.20	850.68
1	COOLANT (SN)	NECESSARY	12.32	12.32
			19,180.14	4,663.86
	LABOUR			
	PANEL BEATING & BODY WORK, INCLUSIVE OF THE REPAIR OF HOOD PANEL		1,014.00	400.00
	SPRAY PAINT		2,052.00	500.00

Report Ref No. NS/INC19008764/Esd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 8315

Reg. No: 52983358E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REMOVE AND REPLACE FRONT SUPPORT PANEL.		350.00	120.00
	TO TOP UP A/C GAS.		120.00	50.00
	TO CONDUCT RADIATOR PRESSURE CHECK.		180.00	60.00
	TO REMOVE & REFIX AIR-CON CONDENSER.		120.00	50.00
			4,716.00	1,200.00
GRAND TOTAL			23,896.14	5,863.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,700.00

Report Ref No. NS/INC19008764/Esd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.