	22/03/2002 ASS. REC. BY	R	EF: (S/	FUD 1900877	7/ 1+0302	Special Instructi	on:	
	= roporinz	Hwa sie	ASS	SIGNMENT (	Office)			
mimn	From (Person	is Lione Tan	of	Fly.		Date/Time	17.5.19	9.369.1
	Estimated Cost:			Bill to	Bill to:			
	To Inspect Ve	StTPRESTODRES chicle No: Sot	1EVA/INV 3/37]	// MV / CS	Insu	red;		
	of 30 Woodland Inclustral Part El #05			A 05-18	Tel: 64683834			
	Policy No: PN PV 2012-0000 9664				Claim No: 1201900012966			
	Sum Insured:				Excess: \$3000.00			
	Make of Veh (Client's Becor					_ D.O.A	4.5.19	
	CA / REV	REP. / REV 24 HR	S 1 Person C	ontacted; Shu	Juan	H.O.D. E	OUT	
	Date/Time	Action/Instruction (						
		SGK 3/377 - 0	C4/ FWD	190086237	4263	D.04 -	14/05/20	19
		Owner with	draw	Claim,	QubmH	pveli	report.	•
9								

25	SIGNMENT
From: Date:	Veh No. SGK 3187J Yr Regn: 4 Aug 2006
Estimated Cost:	Type: M.Car)/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	3 1
at Workshop m/s	- 149.7
of	- Grad
Insured:	Eng/No: T/Radio: Insured / Std / NI / NA
Policy No.	
Claims No.	Gen. Cond/Good / Fair / Poor / Burnt
Sum Insured: Excess: \$3000/-	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / S/Rim / STD A/Rim or
(Palicy Condition)	Tyre Size: F: 185/60 214
Remark: The veh had commenced its N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value:	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. ( Rear
GIA / PR Seen: Consistent? : Yes or No	6 mm
Est. Repairs: days Res.: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Lum Sum: % 3 Val.: Yes or No	
	Survey held at ARC
CA / REV / REP / 24 HRS  Vehicle: IN / OU	Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
2330439 (1)07420	
MV-\$15000	
PV-\$10942	
NU-84058 - RECEIV	ED 2 1 MAY 2019
Deta/Time File Provide	
. Freil. Report	Days Of Repair:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 200
2.	Transportation: 50
Add Fee	: Site Insp (\$ )s +Pssi
Report Format :	:Interview (\$ ) Photos
Lump Sum / LB I; (S	Tech. Invs (\$ ) Others 10
r a sould be a second	2) bnekseVV
	77.741

FWD

· Firmin Have Je

\* Merimen e-Claims

1 450 . ...

# ...CLAIM SUBFOLDER...(New Assignment)

		Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Case	Notified 16 May 2019 Sendback Est	16 May 2019 18:06 \$\$5,788.00	17 May 2019 09:36 Assign	,				Cancel Cas	
	Main	Refere	nce	Claim	Details		Documents	-	Show All
CLAIM S	UBFOLDER DETAI	LS			8166056	F			
nsured: /ehicle Re	eg. No.:	SGK318	RAMINIYAN PERU 7J		of Loss:	-	[153 Mo LTA Reg	19 00:00 - :59 nths and <b>10</b> Da Date (Man Yr)]	ys From
Claim Typ			OD / 1201900012966		Policy/Cover Note No.:		(Compre	PNPV2018-00009664 (Comprehensive)	
Claim Typ		- International Contraction			Excess:		S\$3,000	S\$3,000.00	
Repairer:		Automotiv Tel: 64688	ve Repair Centre 834	Pte Ltd (HC	) 38 Woo	dlands Indust	rial Park E1, #05	-18, 757700 W	oodiands
Handling	Insurer:	FWD Sing	Tel: 64688834  FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 [Handled by Lionel Tan]  LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 29/05/2019]						
Adjuster:		LKK Auto	Consultants Pte	Ltd (HQ) -	rel: 6256-	3501 [Fill	ai Rpt due 25	11	
	ATED MAIL RECE	TVED					View All	Compose C	ase Mail
	no mail for this cas								
inere are	e no man for this cas			_					
Ξ					View All	Search Ta	sks Create	New Task	Complete
Due D		Type Task Gro	oup Subject	Handler	Assign	ed By C	ompleted On	Created On	Done

# Denise Tay (LKKAuto)

From:

lionel.tan@fwd.com

Sent:

Tuesday, 21 May 2019 12:56 PM

To:

assignments; SUR

Subject:

RE: OD Claim for SGK3187J | Accident Date 14/05/2019

Hi

Please close case & upload invoice.

Regards,

Lionel

From: Lin Shu Juan [mailto:shujuan@automotiverepaircentre.com.sg]

Sent: Tuesday, May 21, 2019 11:55 AM

To: Lionel Tan Tian Pei - SGUser

Cc: 'SUR'; assignments@lkkauto.com; raymond@automotiverepaircentre.com.sg

Subject: OD Claim for SGK3187J | Accident Date 14/05/2019

Dear Lionel / LKK,

Kindly note the above vehicle has cancel his repair under Own Damage, to which he will proceed repair within his own means.

Therefore we would like to withdraw the above OD claim pertaining to vehicle SGK3187J. Addendum submitted in Merimen for your kind perusal.

Thank you.

Regards, Lin Shu Juan

# Automotive Repair Centre Pte Ltd

38 Woodlands Industrial Park E1

#05-18

Singapore 757700 Tel: +65 6468 8834 Fax: +65 6462 2278

#### ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

# Denise Tay (LKKAuto)

From:

Lin Shu Juan <shujuan@automotiverepaircentre.com.sg>

Sent:

Tuesday, 21 May 2019 11:55 AM

To:

lionel.tan@fwd.com

Cc:

SUR; assignments; raymond@automotiverepaircentre.com.sg

Subject:

OD Claim for SGK3187J | Accident Date 14/05/2019

Dear Lionel / LKK,

Kindly note the above vehicle has cancel his repair under Own Damage, to which he will proceed repair within his own means.

Therefore we would like to withdraw the above OD claim pertaining to vehicle SGK3187J. Addendum submitted in Merimen for your kind perusal.

Thank you.

Regards, Lin Shu Juan

Automotive Repair Centre Pte Ltd 38 Woodlands Industrial Park E1 #05-18

Singapore 757700 Tel: +65 6468 8834 Fax: +65 6462 2278

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
	ACCIDENT STATEMENT
Date Of Report	14/05/2019 15:41
Date Of Accident	14/05/2019 13:30
Exact Location Of Accident	ALONG CTE TOWARDS TPE/SLE
Country/State of Loss	SINGAPORE
開發表了全角形式。2000年的基本是 D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SGK3187J
Insured/Policyholder	
Name Of Registered Owner	PALASUBRAMINIYAN PERUMAL
NRIC No	S8166056E
Email Address	MAILTOSHARATHK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81410483
Alternative Phone No	OTHERS-81410483
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS 1.5E A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00009664
Cover Note Number	

Driver

Name of Driver KANNAIYAN SHARATH KUMAR

Passport No/FIN G3271468X Date Of Birth 06/04/1993 Occupation INDOOR Date Of Driving Pass 05/08/2016

2 YEARS AND 9 MONTHS Driving Experience

Gender MALE

(LOCAL) +65-81410483 Mobile Number

Fax Number Contact Number

**EMail Address** MAILTOSHARATHK@GMAIL.COM Address

7 GAMBAS CRESCENT #04-14 ARK@GAMBAS

Postcode

757087

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - EMPLOYEE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SHB6365C

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims:
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

NRIC/FIN No.

LOCHTION :				
CTE TOWNSONDS TH	lere			
REFORE PIETUMS		IPNE 4	ADIBD	
		LENNE 3		->
A-SGK31877				-7
B - SHEE365C.		THUE 3		$\rightarrow$
		LANE 1		->
ESCRIBE CIRCUMSTANCES OF T	THE ACCIDENT			
Vas driving along	the abov	e menhaned	Insolion when	Mille
ehicle collided in	lo the from	nt vehicle.		
ECLARATION We declare the foregoing particulars		spect.	USEN INC. TO SERVICE T	
	Driver's Signature (If driver is not the		9 on	* A Signature

# > Back to OneMotoring

ehicle Owner Particulars	C: MINIC
wner ID Type:	Singapore NRIC
wner ID:	6056E
ehicle Details	CC//24071
ehicle No.:	SGK3187J
ehicle to be Exported:	No South
ntended Deregistration Date:	15 May 2019
ehicle Make:	TOYOTA
ehicle Model:	VIOS 1.5E A
rimary Colour:	Silver
Manufacturing Year:	2006
ngine No.:	1NZX462989
hassis No.:	MR053HY4204199229
Naximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,347.00
Original Registration Date:	04 Aug 2006
irst Registration Date:	04 Aug 2006
ransfer Count:	4
Actual ARF Paid:	\$13,582.00
ntended PARF Rebate Details	
PARF Eligibility:	Forfeited
ARF Eligibility Expiry Date:	
ARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
COE Expiry Date:	31 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,760.00
COE Rebate Amount:	\$10,942.00
Total Rebate Amount:	\$10,942.00
Message	

The information contained herein is correct as at 15 May 2019

OK

# Automotive Repair Centre Pte Ltd (Co.Reg.No:201312913C) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700 Tel: 64688834 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

INSURER:

Present Location:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CL	AIM		
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	PNPV2018-00009664	Date of Loss:	14/05/2019
Vehicle Reg. No.:	SGK3187J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PALASUBRAMINIYAN PERUMAL		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	04/08/2006
Vehicle Colour:	Silver		
Engine No:	1NZX462989	Chassis No:	MR053HY4204199229
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair	(day) 10		
Remarks:	VEHICLE AT WORKSHOP READY	FOR SURVEY.	

AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		3,148.00
Miscellaneous Items		70.00
Labour		2,570.00
Paintwork Labour		0.00
Towing		0.00
	Calculated Gross Total (S\$)	5,788.00
	- Excess (S\$)	500.00
	(S\$)	5,288.00
	+ GST 7.00% (S\$)	370.16
	Nett Amount (S\$)	5,658.16

This claim is handled by: RAYMOND TAN KOK LEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2019)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Automotive Repair Centre Pte Ltd/SGK3187J/16/05/2019 18:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

Particulars	%Disc	%Depr	Amount
*FRONT BUMPER PEF /	0.00	0.00	*100.00 F
*FRONT BUMPER CLIP X 10 YOU.	0.00	0.00	*10.00 F
	0.00	0.00	*10.00 F
*FRONT BUMPER RETAINER LH WELL	0.00	0.00	*10.00 F
*FRONT BUMPER LOWER GRILLE (CENTER) SCR/	0.00	0.00	*18.00 F
*FRONT BUMPER UNDER COVER RH MIS	0.00	0.00	*20.00 F
*FRONT BUMPER UNDER COVER LH MIS	0.00	0.00	*20.00 F
	0.00	0.00	*90.00 F
	0.00	0.00	*110.00 F
*FRONT REINFORCEMENT ARM RH ?	0.00	0.00	*15.00 F
*FRONT REINFORCEMENT ARM LH ?	0.00	0.00	*15.00 F
	0.00	0.00	*15.00 F
	0.00	0.00	*15.00 F
	0.00	0.00	*100.00 F
	0.00		*100.00 F
			*25.00 F
			*170.00
			*180.001
	0.00		*350.00
0 ( /			*70.001
			*100.001
			*80.00
			*20.001
This was interested to the Argent American Supplies (March 1970)			*20.001
			*10.00
*RADIATOR UPPER BUSH LH M/ Am.			*10.001
			*20.001
			*20.001
			*20.001
			*20.001
			*150.00
			*120.001
			*100.001
			*100.001
			*70.00
			*30.00
THE COURT OF THE C			*30.00
			*150.00
			*160.00
0(-			*20.00
			*25.00
			*25.00
AFFORM POLICIES MICH. AFFOR ALLE ALLE			*45.001
			*15.00
*EPONT PONNET STOPPED UPDED UI			*10.00 F
AFRONIT PONNET NOTTI F			*10.00
FRONT BONNET NOZZLE CRA	0.00	0.00	*15.00
	*FRONT BUMPER CLIP X 10  *FRONT BUMPER CLIP X 10  *FRONT BUMPER RETAINER RH  *FRONT BUMPER RETAINER LH  *FRONT BUMPER LOWER GRILLE (CENTER)  *FRONT BUMPER UNDER COVER RH  *FRONT BUMPER UNDER COVER LH  *FRONT BUMPER UNDER COVER LH  *FRONT GRILLE ASSY  *FRONT REINFORCEMENT ARM RH  *FRONT REINFORCEMENT ARM RH  *FRONT FOGLAMP COVER LH  *FRONT FOGLAMP COVER LH  *FRONT FOGLAMP COVER LH  *AIR INTAKE DUCT  *AIR FILTER/GLEANER BOX ASSY  *RADIATOR FAN BLADE  *RADIATOR FAN BLADE  *RADIATOR FAN BHOUD  *RADIATOR FAN BHOUD  *RADIATOR FOF BRACKET RH  *RADIATOR TOP BRACKET RH  *RADIATOR UPPER BUSH RH  *RADIATOR UPPER BUSH RH  *RADIATOR UPPER BUSH RH  *RADIATOR SIDE GARNISH RH  *RADIATOR SIDE GARNISH RH  *RADIATOR SIDE GARNISH RH  *A/C CONDENSER  *A/C CONDENSER  *A/C CONDENSER OUTLET PIPE  *A/C COMPRESSOR SUCTION PIPE  *A/C CONDENSER  *A/C CONDENSER	FRONT BUMPER CLIP X 10  FRONT BUMPER CLIP X 10  FRONT BUMPER RETAINER RH  FRONT BUMPER RETAINER RH  FRONT BUMPER LOWER GRILLE (CENTER)  FRONT BUMPER LOWER GRILLE (CENTER)  FRONT BUMPER UNDER COVER RH  MIS  FRONT BUMPER UNDER COVER LH  FRONT GRILLE ASSY  MIS  FRONT REINFORCEMENT  FRONT REINFORCEMENT ARM RH  FRONT REINFORCEMENT ARM LH  FRONT FOGLAMP COVER RH  FRONT FOGLAMP COVER RH  FRONT FOGLAMP COVER LH  MIS  FRONT HEADLAMP LH  FRONT HEADLAMP LH  FRONT BUMPER UNDER COVER RH  FRONT FOGLAMP COVER LH  MIS  FRONT FOGLAMP COVER LH  MIS  OOO  FRONT FOGLAMP COVER LH  MIS  OOO  FRONT FOOL MAP COVER LH  MIS  OOO  FRONT BUPPORT PANEL  BUC  OOO  FRONT SUPPORT PANEL  BUC  OOO  FRADIATOR FAN BLADE  (RADIATOR FAN BLADE  (RADIATOR FAN BLADE  (RADIATOR FAN BLADE  RADIATOR FAN BLADE  RADIATOR TOP BRACKET RH  MIS  OOO  RADIATOR TOP BRACKET RH  MIS  OOO  RADIATOR UPPER BUSH RH  CRA  OOO  RADIATOR UPPER BUSH RH  CRA  OOO  RADIATOR LOWER HOSE  RADIATOR LOWER HOSE  RADIATOR SIDE GARNISH RH  RADIATOR SIDE GARNIS	FRONT BUMPER PET

	nitra de <b>s</b> ecultos			Total Parts (S\$)			3,148.00
F=Fran	chise part.						
54	1	*FRONT HORN	CRA/		0.00	0.00	*45.00 F
53	1	*WIPER TANK	201		0.00	0.00	*25.00 F
52	1	*FRONT FENDER CLIP X 20	MX		0.00	0.00	*20.00 F
51	1	*FRONT FENDER SHIELD LI	1 nn x		0.00	0.00	*20.00 F
50	1	*FRONT FENDER SHIELD RI	+ nnx		0.00	0.00	*20.00 F
49	1	*FRONT FENDER LH	BUCI		0.00	0.00	*90.00 F
48	1	*FRONT FENDER RH	BUC -		0.00	0.00	*90.00 F

Automotive Repair Centre Pte Ltd/SGK3187J/16/05/2019 18:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

No	Qty	Particulars	Section Assessed that		Amount
Mis	cellan	eous Items			
1	1	COOLANT FLUID	nec /		35.00
2	1	FRONT LICENSE PLATE	mis/	and the same of the same	35.00
				Sub Total (S\$)	70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount	
Lab	our Items		,	
1	SPRAY PAINTING WHOLE FRONT INCLUDE FRONT DOORS	New	1,900.00	
2	REMOVE, REPAIR AND REFIT AFFECTED ACCIDENT AREA	New	1,100.00	1000
3	REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDE REFILL A/C GAS	New		1 100
4	REMOVE AND REFIT ENGINE AND TRANSMISSION TO FACILIATE REPAIR	New	350.00	250
5	CHECK AND REPAIR HEADLAMP RH WIRING	New	20.00	/
	Gross La	bour Cost (S\$)	2,570.00	

Automotive Repair Centre Pte Ltd/SGK3187J/16/05/2019 18:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to fina, approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hurs Da-Ckk 17/5/19

Lls 8days.

2)

Not Authorise

Excess: \$3000/-

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpi	. A	dj Submitted	Ins Auth'ed	Status	
Main	16 May 2019 Sendback Est	16 May 2019 18:06 <b>\$\$5,788.00</b>	17 May 2019 09:36 Edit Adj Rpt	<b>S\$4,7</b> 2	stimates	\$\$4,718.00 View Rpt		Pending for Survey Report Cancel Case	
	Main	Refe	erence	C	aim Details		Documents	Show All	
CLAIM S	SUBFOLDER DET	AILS	The state of the s		THE RESERVE				
Insured:	PALASUBR	AMINIYAN PERU	MAL, ID: S81660	56E					
Vehicle R	eg. SGK3187	J			Date of Loss:	14/05/2019 ( [ <b>153</b> Months		LTA Reg Date (Man Yr)]	
Claim Typ	oe: <b>OD</b> / 1201	<b>OD</b> / 1201900012966			Policy/Cover Note No.:	PNPV2018-00009664 (Comprehensive)			
					Excess:	S\$3,000.00			
Repairer:	Automotive	Repair Centre P	te Ltd (HQ) 38 Wo	oodlands 1	ndustrial Park	E1, #05-18, 7	57700 Woodlands -	- Tel: 64688834	
Handling Insurer:			<b>Q)</b> - Tel: 6727 570		THE OWN TO SEE THE	00250000000000000000000000000000000000			
Adjuster:	LKK Auto C	onsultants Pte L	td (HQ) - Tel: 6256	5-3561	[Handled by	ONG HWEE JI	E] [Final Rpt	due 29/05/2019]	
ASSOCI	ATED MAIL REC	EIVED					View A	Compose Case Mail	
There are	no mail for this c	ase.							
ALL ASS	SOCIATED TASK	s⊟				View All   Se	arch Tasks   Crea	ite New Task   Complete	
Due Da		Type Task G	roup Subject	Handl	er Assig	ned By C	Completed On	Created On Done	

# **Claim Documents**

# SGK3187J (1201900012966) OD May 14 2019 12:00AM [PALASUBRAMINIYAN PERUMAL] Automotive Repair Centre Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser			
Ass	essment Reports		1 per page V			
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)	Thumbna	-		
1	16/05/19 18:06	Repairer Estimates	1 Load HTM			
Pho	tos/Images		3 per page   ✓			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	100		
1	21/05/19 09:22	General View	Load JPG	V		
2	21/05/19 09:22	General View	Load JPG	~		
3	21/05/19 09:22	General View	Load JPG	V		
4	21/05/19 09:22	General View	Load JPG	V		
5	21/05/19 09:22	General View	Load JPG	V		
5	21/05/19 09:22	General View	Load JPG	V		
7	21/05/19 09:22	General View	Load JPG	~		
8	21/05/19 09:22	General View	1 Load JPG	¥		
9	21/05/19 09:22	General View	Load JPG	V		
10	21/05/19 09:22	General View	Load JPG	V		
11	21/05/19 09:22	General View	Load JPG	<b>₩</b>		
12	21/05/19 09:22	General View	1 Load JPG	V		
13	21/05/19 09:22	General View	1 Load JPG	V		
14	21/05/19 09:22	General View	1 Load JPG	V		
15	21/05/19 09:22	General View	1 Load JPG	-		
16	21/05/19 09:22	General View	1 Load JPG	V		
17	21/05/19 09:22	General View	1 Load JPG	-		
18	21/05/19 09:22	General View	1 Load JPG	V		
19	21/05/19 09:22	General View	■ Load JPG	2		
20	21/05/19 09:22	General View	1 Load JPG	-		
21	21/05/19 09:22	General View	1 Load JPG	-		
22	21/05/19 09:22	General View	<b>⑥</b> Load JPG	₩.		
23	21/05/19 09:22	General View	1 Load JPG	₩.		
24	21/05/19 09:22	General View	1 Load JPG			
25	21/05/19 09:22	General View	1 Load JPG	V		
26	21/05/19 09:22	General View	1 Load JPG	-		
27	21/05/19 09:22	General View	1 Load JPG	Ę.		
28	21/05/19 09:22	General View	1 Load JPG	V		
29	21/05/19 09:22	General View	1 Load JPG	V		
30	21/05/19 09:22	General View	1 Load JPG	V		
31	21/05/19 09:22	General View	1 Load JPG	V		
32	21/05/19 09:22	General View	1 Load JPG	Į.		
33	21/05/19 09:22	General View	1 Load JPG	V		
34	21/05/19 09:22	General View	1 Load JPG	· ·		
35	21/05/19 09:22	General View	■ Load JPG			

Ass	essment Reports		1 per p	page 🗸	V
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)		Thumbnail	Print
36	21/05/19 09:22	General View	0	Load JPG	<b>√</b>
37	21/05/19 09:22	General View	Ð	Load JPG	V
38	21/05/19 09:22	General View	0	Load JPG	V
39	21/05/19 09:22	General View	0	Load JPG	~
40	21/05/19 09:22	General View	Ð	Load JPG	V
41	21/05/19 09:22	General View	0	Load JPG	~
42	21/05/19 09:22	General View	0	Load JPG	V
43	21/05/19 09:22	General View	0	Load JPG	V
44	21/05/19 09:22	General View	0	Load JPG	V
45	21/05/19 09:22	General View	0	Load JPG	✓
46	21/05/19 09:22	General View	0	Load JPG	<b>✓</b>
47	21/05/19 09:22	General View	0	Load JPG	V
48	21/05/19 09:22	General View	0	Load JPG	~
49	21/05/19 09:22	General View	0	Load JPG	V
50	21/05/19 09:22	General View	0	Load JPG	V
51	21/05/19 09:22	General View	0	Load JPG	~
52	21/05/19 09:22	General View	0	Load JPG	V
53	21/05/19 09:22	General View	0	Load JPG	~
54	21/05/19 09:22	General View	0	Load JPG	V
55	21/05/19 09:22	General View	0	Load JPG	V
56	21/05/19 09:22	General View	0	Load JPG	V
57	21/05/19 09:22	General View	0	Load JPG	<b>V</b>
58	21/05/19 09:22	General View	0	Load JPG	<b>V</b>
59	21/05/19 09:22	General View	0	Load JPG	V
60	21/05/19 09:22	General View	0	Load JPG	<b>✓</b>
61	21/05/19 09:22	General View	0	Load JPG	V
62	21/05/19 09:22	General View	0	Load JPG	V
63	21/05/19 09:22	General View	0	Load JPG	V
64	21/05/19 09:22	General View	0	Load JPG	V
65	21/05/19 09:22	General View	0	Load JPG	~
66	21/05/19 09:22	General View	0	Load JPG	V
					1 —
Doc	umentation		1 per		V
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)		Thumbnail	_
1	17/05/19 16:07	Driver NRIC & DL	0	Load JPG	<u></u>
2	17/05/19 16:07	Driver NRIC & DL	0	Load JPG	V
3	17/05/19 16:07	Certificate of Insurance	0	Load JPG	V
4	17/05/19 16:07	Certificate of Insurance	0	Load JPG	V
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	0	Load PDF	Print
1	17/05/19 09:22	E-filed GIA report		LUGU PDF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V

Merimen e-Claims Page 3 of 3

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower 4

Singapore 038986

Our File No:

CS/FWD19008777/JTD3E2

Date:

22/05/2019

REFERENCE

Date of Loss:

Insured/Claimant: PALASUBRAMINIYAN PERUMAL

14/05/2019

Policy No:

PNPV2018-00009664

Nature of Claim: OD

Claim No: 1201900012966

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SGK3187J

Make & Model:

TOYOTA VIOS, 1.5 E (A)

Engine No:

1NZX462989

Reg. Date:

04/08/2006 (Man. Year: 2006)

Chassis No: Odometer:

MR053HY4204199229 188542 km

Colour: Engine Capacity: Grey

1497 cc

Market Value/New Car Price: S\$15,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable): Yes

Pre-accident Condition:

Yes

Handbrake (Serviceable): **CONDITION OF TYRES** 

Front Tyre Size:

185/60 R14

Rear Tyre Size:

185/60 R14

Front Left Side:

Michelin 6 mm

Rear Left Side:

No

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,148.00	2,378.00	770.00	24.46
Miscellaneous Items	70.00	70.00	0.00	0.00
Labour	2,570.00	2,270.00	300.00	11.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,788.00	4,718.00	1,070.00	18.49
- Excess (S\$)	500.00	3,000.00	-2,500.00	-500.00
(S\$)	5,288.00	1,718.00	3,570.00	67.51
+ GST 7.00/7.00% (S\$)	370.16	120.26	249.90	67.51
Nett Amount (S\$)	5,658.16	1,838.26	3,819.90	67.51

INSPECTION

Date of Assignment:

17/05/2019 Present Location:

Automotive Repair Centre Pte Ltd (HQ)

17/05/2019 Inspected At: Date Inspected:

Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Estimated Period of Repair:

8.0 days

Adjuster: ONG HWEE JIE

DENISE TAY KWEE CHENG Manager:

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_... 22/5/2019

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS \$\$500.00 NETT)

# REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 May 2019)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGK3187J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	100.00 F	*100.00 F
2	1		*FRONT BUMPER CLIP X 10	Necessary	10.00 F	*10.00 F
3	1		*FRONT BUMPER RETAINER RH	Necessary	10.00 F	*10.00 F
4	1		*FRONT BUMPER RETAINER LH	Necessary	10.00 F	*10.00 F
5	1		*FRONT BUMPER LOWER GRILLE (CENTER)	Scratched	18.00 F	*18.00 F
3	1		*FRONT BUMPER UNDER COVER RH	Missing	20.00 F	*20.00 F
7	1		*FRONT BUMPER UNDER COVER LH	Missing	20.00 F	*20.00 F
В	1		*FRONT GRILLE ASSY	Missing	90.00 F	*90.00 F
9	1		*FRONT REINFORCEMENT	Bent	110.00 F	*110.00 F
10	1		*FRONT REINFORCEMENT ARM RH	* Check	15.00 F	*- F
11	1		*FRONT REINFORCEMENT ARM LH	* Check	15.00 F	*- F
12	1		*FRONT FOGLAMP COVER RH	Missing	15.00 F	*15.00 F
13	1		*FRONT FOGLAMP COVER LH	Missing	15.00 F	*15.00 F
14	1		*FRONT HEADLAMP RH	Cracked	100.00 F	*100.00 F
15	1		*FRONT HEADLAMP LH	Cracked	100.00 F	*100.00 F
16	1		*AIR INTAKE DUCT	Buckled	25.00 F	*25.00 F
17	1		*AIR FILTER/CLEANER BOX ASSY	Not Necessary	170.00 F	*- F
18	1		*FRONT SUPPORT PANEL	Buckled	180.00 F	*180.00 F
19	1		*RADIATOR	Bent	350.00 F	*350.00 F
20	1		*RADIATOR FAN BLADE	Cracked	70.00 F	*70.00 F
21	1		*RADIATOR FAN MOTOR	* Check	100.00 F	*-F
22	1		*RADIATOR FAN SHROUD	Cracked	80.00 F	*80.00 F
23	1		*RADIATOR TOP BRACKET RH	Missing	20.00 F	*20.00 F
24	1		*RADIATOR TOP BRACKET LH	Missing	20.00 F	*20.00 F
25	1		*RADIATOR UPPER BUSH RH	Necessary	10.00 F	*10.00 F
26	1		*RADIATOR UPPER BUSH LH	Necessary	10.00 F	*10.00 F
27	1		*RADIATOR UPPER HOSE	Not Necessary	20.00 F	*-F
28	1		*RADIATOR LOWER HOSE	* Check	20.00 F	*-F
29	1		*RADIATOR SIDE GARNISH RH	Cracked	20.00 F	*20.00 F
30	1		*RADIATOR SIDE GARNISH LH	Cracked	20.00 F	*20.00 F
31	1		*A/C CONDENSER	Bent	150.00 F	*150.00 F
32	1		*A/C CONDENSER OUTLET PIPE	* Check	120.00 F	*-F
33	1		*A/C COMPRESSOR SUCTION PIPE	Bent	100.00 F	*100.00 F
34	1		*A/C PIPE DISCHARGE HOSE	* Check	100.00 F	*- F
35	1		*ENGINE MOUNTING RH	* Check	70.00 F	*-F
36	1		*ENGINE MOUNTING LH	* Check	30.00 F	*- F
37	1		*ENGINE MOUNTING REAR	* Check	30.00 F	*- F
38	1		*ENGINE MANIFOLD	Cracked	150.00 F	*150.00 F
39	1		*FRONT BONNET	Buckled	160.00 F	*160.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT BONNET LOCK	Bent	20.00 F	*20.00 F
41	1		*FRONT BONNET HINGE RH	Bent	25.00 F	*25.00 F
42	1		*FRONT BONNET HINGE LH	Bent	25.00 F	*25.00 F
43	1		*FRONT BONNET INSULATOR	Deformed	45.00 F	*45.00 F
44	1		*FRONT BONNET INSULATOR CLIP X 10	Necessary	15.00 F	*15.00 F
45	1		*FRONT BONNET STOPPER UPPER RH	Not Necessary	10.00 F	*- F
46	1		*FRONT BONNET STOPPER UPPER LH	Not Necessary	10.00 F	*-F
47	1		*FRONT BONNET NOZZLE	Cracked	15.00 F	*15.00 F
48	1		*FRONT FENDER RH	Buckled	90.00 F	*90.00 F
49	1		*FRONT FENDER LH	Buckled	90.00 F	*90.00 F
50	1		*FRONT FENDER SHIELD RH	Not Necessary	20.00 F	*-F
51	1		*FRONT FENDER SHIELD LH	Not Necessary	20.00 F	*- F
52	1		*FRONT FENDER CLIP X 20	Not Necessary	20.00 F	*- F
53	1		*WIPER TANK	Dented	25.00 F	*25.00 F
54	1		*FRONT HORN	Cracked	45.00 F	*45.00 F
F=Fra	anchise	part.		Total Parts (S\$)	3,148.00	2,378.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellan	eous Items			
1	1	(NECESSARY)		35.00	35.00
2	1	FRONT LICENSE PLATE (MISSING)		35.00	35.00
			Sub Total (S\$)	70.00	70.00

# Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
SPRAY PAINTING WHOLE FRONT INCLUDE FRONT DOORS	New	1,000.00	900.00
REMOVE, REPAIR AND REFIT AFFECTED ACCIDENT AREA	New	1,100.00	1,000.00
REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDE REFILL A/C GAS	New	100.00	100.00
REMOVE AND REFIT ENGINE AND TRANSMISSION TO FACILIATE REPAIR	New	350.00	250.00
CHECK AND REPAIR HEADLAMP RH WIRING	New	20.00	20.00
Gross Labou	r Cost (S\$)	2,570.00	2,270.00
	SPRAY PAINTING WHOLE FRONT INCLUDE FRONT DOORS REMOVE, REPAIR AND REFIT AFFECTED ACCIDENT AREA REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDE REFILL A/C GAS REMOVE AND REFIT ENGINE AND TRANSMISSION TO FACILIATE REPAIR CHECK AND REPAIR HEADLAMP RH WIRING	SPRAY PAINTING WHOLE FRONT INCLUDE FRONT DOORS New REMOVE, REPAIR AND REFIT AFFECTED ACCIDENT AREA New REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDE New REFILL A/C GAS REMOVE AND REFIT ENGINE AND TRANSMISSION TO New FACILIATE REPAIR	SPRAY PAINTING WHOLE FRONT INCLUDE FRONT DOORS New 1,000.00 REMOVE, REPAIR AND REFIT AFFECTED ACCIDENT AREA New 1,100.00 REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDE New 100.00 REFILL A/C GAS REMOVE AND REFIT ENGINE AND TRANSMISSION TO New 350.00 FACILIATE REPAIR CHECK AND REPAIR HEADLAMP RH WIRING New 20.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >