(03)	MSG19008783/Ugd3n2	
(08/11/13) wef REF:	MS/4/	
ASS. REC. BY: March	, , , , , ,	
₩	ASSIGNMENT	1 19
From: Date:  Estimated Cost:  OD/TP/WS/TP RES/OD RES/EVA/INV/MV  To Inspect Vehicle No: SLN 122  at Workshop m/s of Insured:  Policy No. 80459593	Sp.Reading 12388	/ Taxi / Prime Mover /
Claims No. 593768	Gen. Cond: Good / Fair / Poor / Burnt	
Sum Insured: Excess;	Steering: Inorde/ Jammed / Leaked / B	urnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / E	burnt or
Make of Veh:	Modi: Nil /S/R/m / STD A/Rim or	/
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  10AC Accident Rport: Consistent?: Yes or No  Consistent?: Yes or No  Est. Repairs: Adays Res.: Yes or No  Lum Sum: Which is a second contacted:  Date:  Person Contacted:  Date / Time Action / Instruction  Action / Instruction	R:  BS / DUN / EXNOVA / GY / FS / LIZA / M  TOYO / YOKO or  Front R/Bal. mm  L/Bal. mm  D.O.A. / 6/C// 9  Survey held at  Des. of Damages: Frt / Rear / O/S /  The U/C / Chassis frame / Body	Structure affected due to collision.
	RECEIVED 2-6 JUL 2019	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	Approximation Technology
1) 15 (2 MMH : Final Report  Date/Time, File Return to?	Resurvey No. of Trip:	Survey Fee: Transportation: 250
	Add Fee: : Site Insp (\$	)S+RSSI 11
7	: Interview (\$	) Photos
Report Format : MER-TP	: Tech. Invs (\$	) Others
'Lump,Sum / I.B.d: (\$   12600 )	:Weekend (\$	)
	- 1	TOTAL 261

## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

25 Jul 2019 Date: Irene Tan Gek Ing Attn:

# **Preliminary Advice**

Insured Vehicle No : SLL3002U

: 16/05/2019 Accident Date : SLN122R TP Vehicle No : 24/05/2019 Assignment Date : HYUNDAI AVANTE Make Est. Duration of Repair : 12.00 Date of Inspection : 17/05/2019

Inspection At

: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY

SINGAPORE 417883

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,618.00
Revised Amount	:S\$	15,817.84
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,817.84
Lump Sum Repair	:S\$	12,600.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

(	) The vehicle	is	economical/not eco	nomical	for	repair.
---	---------------	----	--------------------	---------	-----	---------

( X ) The above survey was conducted on a 'without prejudice' basis.

# Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 21 May 2019 1:33 PM

To:

motorsurvey@sg.msig-asia.com; Irene Tan

Cc:

KKLau; Accounts (LKKAuto); SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

16/05/2019, SLN 122R (TP VEHICLE), SLL 3002U (OI VEHICLE)

Attachments:

SLN122 PR.pdf; SLN122 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLN 122R at M/s: FASTECH AUTO PTE LTD,1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 17/05/2019.

Enclosed herewith a copy of TP's GIA report and police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1081B
/ehicle Details	
ehicle No.:	SLN122R
'ehicle to be Exported:	No
ntended Deregistration Date:	17 May 2019
ehicle Make:	HYUNDAI
ehicle Model:	AD AVANTE 1.6 GLS (A)
rimary Colour:	Silver
Manufacturing Year:	2018
ingine No.:	G4FGJU044798
Chassis No.:	KMHD841CMKU816157
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,270.00
Original Registration Date:	08 Jan 2019
First Registration Date:	08 Jan 2019
ransfer Count:	0
Actual ARF Paid:	\$12,270.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2029
PARF Rebate Amount:	\$9,202.00
ntended COE Rebate Details	
COE Expiry Date:	07 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$24,582.00
Total Rebate Amount:	\$33,784.00

The information contained herein is correct as at 17 May 2019

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACC	DEN	T STA	11 - 144.0	-176-6
AUU	DEN	IOIA		-1011

Date Of Report 16/05/2019 15:54 Date Of Accident 16/05/2019 08:10

Exact Location Of Accident ALONG ROAD 1 BUANGKOK DRIVE

Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLN122R

Insured/Policyholder

Name Of Registered Owner

FONG MOTORS CAR RENTAL

Co Reg No 53371081B Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-90000000

Vehicle Particulars

Manufacturer HYLINDAL

Model AD AVANTE 1.6 GLS (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5101257742

Cover Note Number

Driver

Name of Driver CHOON YIH KOONG

NRIC No. S1780920B Date Of Birth 22/02/1966 Occupation OUTDOOR Date Of Driving Pass 05/05/2003

16 YEARS AND 0 MONTHS Driving Experience

Gender FEMALE

Mobile Number (LOCAL) +65-93805931

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK 257A COMPASSVALE ROAD #11-505

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

PUNGGOL N.P.C

Police Station Name Police Station Address

ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20190516/2061

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLL3002U

Vehicle Make/Model/Colour

MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

### No. Of Passenger (Including Driver)

## **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SHD391E

Vehicle Make/Model/Colour

RENAULT LATITUDE 2.0L DCI AUTO D/AB 4DR

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

the second series			
$D = T \wedge I$	1005	IN III IDEE	PERSON 1
111-1141		INTURE	IPERSUNT

Name CHOON YIH KOONG

Approximate Age 53

Injuries Sustain

Injured person in which vehicle? SLN122R
Were seat belts worn? YES

Was this injured conveyed to hospital by

ambulance?

Address BLK 257A COMPASSVALE ROAD #11-505

Postcode 541257

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this eccident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (1) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (a) the information so collected under (d) above may be shared / disclosed:

011014000

ress "Seas

Policyhold

Date & Time:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any qualitions, laws or court orders.

1 6 MAY 2019

IDAC KARE BUKIT (VAC)

23 WAKI BUNKY AVE 4

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre of Prince aggregations
Name: Part 97492305

NRIC/FIN NO.: Vuckbarsingnet.com.sg

SKETCH PLAN	
	to the control of the
*****	
Angel Colored Colored Color	A.GLN IDDR
	A
	A
	C 840 3201 B
	- R
ren in the commence of the com	***************************************
	and the second s
The state of the s	The second control of
SCRIBE CIRCUMSTAN	CES OF THE ACCIDENT
0	
KEFFE TO	POLICE REPORT NO: 1/20190516/9001
	1 - 1 400
AURIO CONTRACTOR OF THE PROPERTY OF THE PROPER	
Was Stiffelionar data of	
	ticulars are true in every respect
	rticulars are true in every respect. 1 6 MAY 2019
declare the foregoing par	HDAC KAKEBUKITIYAC
declare the foregoing par	1 D MAI ZURF COLUMN
declare the foregoing par	IDAC KAKEBUKTI VAC 23 KAKEBUKTI VAC 23 KAKEBUKTAVE 4  Driver's Signature  Reporting Conference (1997)
( STONE DE LEGIS )	IDAC KAKEBUKITIVAC 23 KANEBUKITIVAC 23 KANEBUKITAVE 4

## Accident Sketch Plan Pg. 1





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

1 of 3 Report No. T/20190516/2061

REPORT	OF A TRAFFI	CACCIDENT				
Date/Time Report Made: 16/05/2019 13:42			Vide Report No.: Station Diary			
Informa	nt's Partic	ulars				
	f Informant: I YIH KUON		Address: APT BLK 257A COMPASSV/ 541257	ALE ROAD #11-505 SINGAPORE		
ID Type / ID No.: NRIC NO / S1780920B			Contact No.: Home/Office: Mobile: 93805931			
Nationality: SINGAPORE CITIZEN		EN	Email:			
Sex: Age: Date of Birth: Male 53 22/02/1966			Type of Informant:			
Race: Chinese			Language:	Institution / School Name:		
Occupation: GRAB DRIVER			Driving Licence Information: Class; 2B,3	ation: Date of Expiry:		

General Infor	mation of the Acc	dent		
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/05/2019 08:10	Type of Location:
Location: Along Road 1 BUANGKOK towards Tamp	DRIVE			
Weather:	ZIIIGO TKOGO	Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collis	ion:		1	Anyone conveyed by ambulance:

Details of V	ehicle Invo	ived				
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SHD391E	Car					0
SLL3002U	Car			1		0
SLN122R	Car					1





Police Station Of Origin: Punggol N.P.C

21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

2 of 3 Report No. T/20190516/2081

CONTINUATION OF REPORT

Details of Perso	on involved				-	
Any Pedestrian I	nvolved: No					
No. of Pedestrian	ns Injured: NIL		Use of Pa	adactric	n Cross	she as 51.6
Driver				Judati Ha	II CIUSS	sing: NA
Name	CHOON YIH KUONG			ID No	).	\$1780920B
Related Vehicle	SLN122R (Car)			Contact No.		93805931
Hospital/Clinic	LTD.				of g ce & / Date	Class: 2B,3 Date of Expiry: NIL.
Date Treatment	16/05/2019		Date Disc		16/05	/2010
No. of Days grant	ed Medical Leave	03	Degree o			Proposition and the second

## Brief Details.

On 16/05/2019 at about 0811hrs, I was along Buangkok Drive and the traffic was heavy. I was following the car in front of me and when I stopped my car as there was heavy traffic and the car in front of me stopped. I heard a screeching sound from behind and subsequently, my car was hit from the back. The impact caused my car (SLN122R) to move forward to hit the car (SHD391E) in front of me.

We alighted to take photo of the accident. I have a passenger in my car. She told me that she will see doctor after she go to work. I do not know what injury she suffered. I suffered back pain and chest pain and had went to Sengkang General Hospital to see a doctor. I was given 3 days medical leave.

My car was badly damaged.

### Accident Sketch Plan Pg. 1



T/20190516/2061

Police Station Of Origin: Punggol N.P.C 21A Teoing Lane SINGAPORE 828837 Tel No: 1800-6049999

3 of 3 Report No. T/20190516/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report F / Staff Sgt TAN WEILONG, JONATHAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: \\ 16/05/2019 13:42
Officer In Charge Of Case: TP / AEIT / SSI 2 YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:
Authentication Stamp	

		1 . 1
		Not Anthornel
		Llela
FASTECT AU	IOPIELID	1.1.0
BLK1 KAKI BU		17/5/1
#01-46,48,50		1 = 12 600
SINGAPORE		1/5 412,600
VEHICLE NO:SL	N 122R	7
QTY	PARTICULAR	2 11 20
1 PCS	BOOTLID 1782	30dy, DO \$2,400.00
1 PCS	BOOTLID REAR LOGO \$16	Nu \$199.00
1 PCS	BOOTLID 'AVANTE' EMBLEM 3 2	200 \$85.00
1 PCS	BOOTLID LOCK STRIKER # 35	7~1 \$85.00
1 PCS	BOOTLID WEATHERSTRIP 159	Tul \$219.00
1 PCS 2 PCS	BOOTLID INNER LOCK //6	Tul \$155.00
1 PCS	BOOTLID REFLECTORS@\$450.00 284.90 x 2 = 1 69.80	\$900.00
1 SET	BOOTLID INNER TRIM	De regel \$245.00
2 PCS	BOOTLID INNER TRIM CLIPS	\$50.00
1 SET	BOOTLID HINGES @\$165.00	N → \$330.00 ×
1 PCS	BOOTLID REVERSE CAMERA 450 REAR BUMPER (4.67.)	\$650.00
1 PCS	REAR BUMPER CENTRE GARNISH 3.54	\$1,150.00
2 PCS	[그 그 대한 프리마일(1) 10 10 10 10 10 10 10 10 10 10 10 10 10	
2 PCS	REAR BUMPER SIDE RETAINERS @\$52.00 26x2=404	Twi/cne \$600.00
1 SET	REAR BUMPER CLIPS	34 \$104.00
1 PCS	REAR BUMPER LOWER TRAY 35-4	Nec \$50.00
1 PCS	REAR BUMPER REINFORCEMENT 29	\$495.00
5 PCS	REAR BUMPER REINFORCEMENT TOP& BOTTOM BRACKETS@\$18.00	0 \$399.00 / 0 \$90.00 /
2 PCS	REAR BUMPER REINFORCEMENT STAYS @\$95.00	
1 PCS	REAR BUMPER INNER LOCK SENSOR 195	\$190.00
1 SET	REAR BUMPER LICENCE LAMP	11 \$102.00 X
1 PCS	REAR END PANEL 45-4	150dy 30 \$665.00
1 PCS	REAR END PANEL TOP GARNISH 160	Tul \$188.00
2 PCS	TAILLAMPS @\$505.00 362-50 x 2 = 725	(ne \$1,010.00
2 PCS	TAILLAMP HOUSING PANELS@\$195.00	37/34 \$390.00
1 PCS	REAR FLOOR PANEL 928	5-45.0/sic \$1,128.00 _
1 PCS	REAR FLOOR PANEL TOP BOARD	EU \$433.00
2 PCS	REAR FENDERS @\$1768.00	↑ \$3,536.00 ×
2 PCS	REAR FENDER INNER TRIM BOARDS @\$255.00	0/s De \$510.00 16 C
1 PCS	REAR EXHAUST	✓ \$993.00 X
2 PCS	REAR EXHAUST MOUNTINS @\$28.00	1 ↑ \$56.00 ×
1 PCS	REAR EXHAUST HEAT SHIELD	Sef \$159.00
1 PCS	BONNET	√ \$1,999.00  ✓
1 PCS 2 PCS	BONNET LUNGS COST CO	17 \$195.00 ×
1 PCS	BONNET HINGES @\$85.00	17 \$170.00 X
1 SET	BONNET INSULATOR	17 \$221.00 X
1 PCS	BONNET INSULATOR CLIPS FRONT BUMPER	1,7 \$50.00 €
2 PCS	[14] [15] [15] [15] [15] [15] [15] [15] [15	De/71m \$966.00
1 PCS	FRONT BUMPER SIDE RETAINERS @\$45,00	171 \$90.00
1 SET	FRONT BUMPER GENTRE GARNISH / DWL/ FRONT BUMPER CLIPS	30/De \$185.00_
1 PCS	FRONT BUMPER REINFORCEMENT 675	re \$50.00
1 PCS	FRONT BUMPER SPONGE ///	sey \$755.00_
1 PCS	FRONT GRILLE	7910 \$199.00
2 PCS	HEADLAMPS @\$1500.00 //98 x 2= 2396 (287)	Cre \$1,082.00
6519.55	200	(/a \$3,000.00

1 PCS	FRONT SUPPORT PANEL	1 1,455.00 X
1 PCS	FRONT SUPPORT PANEL GARNISH	1 → \$139.00 ×
1 PCS	FRONT LICENECE PLATE HOLDER 69	Tum \$136.00
2 PCS	FRONT BUMPER FOG LAMPS @\$330.00 2 95 X2 = 190	cre \$660.00_
1 PCS	FRONT BUMPER LOWER SKIRTING	1 → \$385.00 ×
2 PCS	HEADLAMP LOWER BRACKETS @\$45.00	cm \$90.00 -
1 PCS	AIR CON CONDENSER	, 17 \$1,132.00 X
2 PCS	AIR CON CONDENSER SIDE GARNISHS @\$85.00 65	MS To-1 \$170.00 12 C
1 PCS	RADIATOR	1 1,575.00 ×
1 PCS	RADIATOR FAN ASSY	1 7 \$568.00 X
2 PCS	FRONT FENDERS @\$966.00	7 \$1,932.00 ℃
1 PCS	AIR DUCT	17 \$148.00 X
1 PCS	AIR CLEANER BOX ASSY	n 1 \$388.00 ×
1 PCS	FRONT BUMPER LOWER RETAINER	Sey \$118.00_
	S.NETT	\$36,148.00
1 SET	REAR BUMPER REVERSE SENSOR	Sholl \$380.00 200
1 PCS	REAR END PANL SEALANT	266 \$50.0C U
1 PCS	REAR WINDSCREEN SEALANT	11 \$50.00 X
1 PCS	REAR LICENCE PLATE W/HOLDER	Sy \$50.00 40
1 SET	REAR FLOOR PANEL INSULATOR	ner \$280.00 /20
1 PCS	FRONT LICENECE PLATE W/HOLDER	Bul \$50.00 40
1 BOT	RADIATOR COOLANT	11 \$50.00 ×
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00 50
	TO TRANSFER BOOTLID MECHANISM	\$100.00 60
	TO DISMANTLE & REFIX REAR EXHAUST	\$100.00 60
	TO DISMANTLE & REFIX PETROL TANK	11 \$100.00 ×
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$120.00 80
	TO REFILL AIR CON GAS	A ↑ \$150.00 X
	TO SPRAY RUST PROOFING	\$150.00 /00
	TO MOUNT VEHICLE ON CAR O-LINER	∧^ \$380.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$2,800.00 /500
	TO PUTTY & SPRAY PAINTING	\$2,500.00 /gvo
		TOTAL \$43,618.00

.

LICK Ando Connectioning transce notify
the Regulator of the followings

\* To extract habitables spay purellay

\* To extract habitables spay purellay

\* To extract habitables spay purellay

\* Particular are expect to constantion

\* Things are extracted constantion

\* This extract habitable spay

\* No extract habitable spay

\* Advantaged by Persons

Significant

Significant

Significant

Significant

\* The extraction of the spay of the

1484.5 11987.84 4W 3380 15917-84 12654

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

CC3/MSG19008783/UQD3N2 Our File No:

Date: 29/07/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80459583

Claimant

SLN122R

Insured Vehicle No:

SLL3002U

Vehicle No: Date of Loss:

16/05/2019

Nature of Claim:

TP

Claim No: 593768

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLN122R

HYUNDAI AVANTE, 1.6 (A)

Engine No:

G4FGJU044798

Reg. Date:

Make & Model:

08/01/2019 (Man. Year: 2018)

Chassis No: Odometer:

KMHD841CMKU816157 12388 km

Colour:

Silver 1591 cc

**Engine Capacity:** Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

Nexen 7 mm

Rear Left Side: Rear Right Side: Nexen 7 mm Nexen 7 mm

Nexen 7 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,058.00	12,437.84	24,620.16	66.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,560.00	3,380.00	3,180.00	48.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,618.00	15,817.84	27,800.16	63.74
Approved Total (Overridden) (S\$)		12,600.00		10.000
(S\$)	43,618.00	12,600.00	31,018.00	71.11
+ GST 7.00/7.00% (S\$)	3,053.26	882.00	2,171.26	71.11
Nett Amount (S\$)	46,671.26	13,482.00	33,189.26	71.11

INSPECTION

Date of Assignment:

24/05/2019

Date Inspected:

17/05/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

12.0 days

Manager: SHIAU CHAN Adjuster: MARCUS CHUA

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

Referen	ce		
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)	
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code	(Lineubmitted	no print-code for SI N122R)	

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	2,400.00 F	*1,782.00 FI
2	1		*BOOTLID REAR LOGO	Necessary	199.00 F	*96.00 FI
3	1		*BOOTLID AVANTE EMBLEM	Necessary	85.00 F	*32.00 FI
4	1		*BOOTLID LOCK STRIKER	Twisted	85.00 F	*35.00 FI
5	1		*BOOTLID WEATHERSTRIP	Twisted	219.00 F	*159.00 FI
6	1		*BOOTLID INNER LOCK	Twisted	155.00 F	*116.00 FL
7	2		*BOOTLID REFLECTORS	Cracked	900.00 F	*569.80 FL
8	1		*BOOTLID INNER TRIM	Deformed / Warped	245.00 F	*245.00 FL
9	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
10	2		*BOOTLID HINGES	Not Necessary	330.00 F	*- Fl
11	1		*SET BOOTLID REVERSE CAMERA	Shorted	650.00 F	*450.00 FL
12	1		*REAR BUMPER	Distorted	1,150.00 F	*451.00 FL
13	1		*REAR BUMPER CENTRE GARNISH	Distorted	499.00 F	*354.00 FL
14	2		*REAR BUMPER LAMPS	Twisted / Cracked	600.00 F	*404.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Bent	104.00 F	*52.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*REAR BUMPER LOWER TRAY	Torn	495.00 F	*354.00 FL
18	1		*REAR BUMPER REINFORCEMENT	Distorted	399.00 F	*294.00 FL
19	5		*REAR BUMPER REINFORCEMENT TOP & BOTTOM BRACKETS	Twisted	90.00 F	*90.00 FL
20	2		*REAR BUMPER REINFORCEMENT STAYS	Bent	190.00 F	*190.00 FL
21	1		*REAR BUMPER INNER LOCK SENSOR	Cracked	225.00 F	*195.00 FL
22	1		*SET REAR BUMPER LICENCE LAMP	Not Necessary	102.00 F	*-Fl
23	1		*REAR END PANEL	Badly Dented	665.00 F	*454.00 FI
24	1		*REAR END PANEL TOP GARNISH	Twisted	188.00 F	*160.00 FL
25	2		*TAILLAMPS	Cracked	1,010.00 F	*725.00 FI
26	2		*TAILLAMP HOUSING PANELS	Dented / Bent	390.00 F	*390.00 FI
27	1		*REAR FLOOR PANEL	Badly Dented / Buckled	1,128.00 F	*928.00 FI
28	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	433.00 F	*-Fl
29	2		*REAR FENDERS	Repair	3,536.00 F	*-Fl
30	1		*REAR FENDER INNER TRIM BOARDS	O/s Deformed	510.00 F	*255.00 FL
31	1		*REAR EXHAUST	Repair	993.00 F	*-FI
32	2		*REAR EXHAUST MOUNTINGS	Not Necessary	56.00 F	*-Fl
33	1		*REAR EXHAUST HEAT SHIELD	Bent	159.00 F	*159.00 FI
34	1		*BONNET	Repair	1,999.00 F	*- Fl
35	1		*BONNET LOCK	Not Necessary	195.00 F	*-FI
36	2		*BONNET HINGES	Not Necessary	170.00 F	*- Fl
37	1		*BONNET INSULATOR	Not Necessary	221.00 F	*-FI
38	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*-FI
39	1		*FRONT BUMPER	Deformed / Torn	966.00 F	*494.00 FI
40	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*-FI
41	1		*FRONT BUMPER LOWER GARNISH	Dented / Deformed	185.00 F	*185.00 FI

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
43	1		*FRONT BUMPER REINFORCEMENT	Bent	755.00 F	*695.00 FL
44	1		*FRONT BUMPER SPONGE	Torn	199.00 F	*111.00 FL
45	1		*FRONT GRILLE	Cracked	1,082.00 F	*1,082.00 FL
46	2		*HEADLAMPS	Cracked	3,000.00 F	*2,396.00 FL
47	1		*FRONT SUPPORT PANEL	Not Necessary	1,455.00 F	*-FL
48	1		*FRONT SUPPORT PANEL GARNISH	Not Necessary	139.00 F	*-FL
49	1		*FRONT LICENCE PLATE HOLDER	Torn	136.00 F	*69.00 FL
50	2		*FRONT BUMPER FOG LAMPS	Cracked	660.00 F	*590.00 FL
51	1		*FRONT BUMPER LOWER SKIRTING	Not Necessary	385.00 F	*-FL
52	2		*HEADLAMP LOWER BRACKETS	Cracked	90.00 F	*90.00 FL
53	1		*AIR CON CONDENSER	Not Necessary	1,132.00 F	*-FL
54	1		*AIR CON CONDENSER SIDE GARNISHS	N/s Torn	170.00 F	*65.00 FL
55	1		*RADIATOR	Not Necessary	1,575.00 F	*-FL
56	1		*RADIATOR FAN ASSY	Not Necessary	568.00 F	*-FL
57	2		*FRONT FENDERS	Repair	1,932.00 F	*-FL
58	1		*AIR DUCT	Not Necessary	148.00 F	*-FL
59	1		*AIR CLEANER BOX ASSY	Not Necessary	388.00 F	*-FL
60	1		*FRONT BUMPER LOWER RETAINER	Bent	118.00 F	*118.00 FL
61	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
62	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
63	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*-FS
64	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
65	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	280.00 FS	*120.00 FS
66	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
67	1	nort C-1	*BOT RADIATOR COOLANT SpcNett. L=ListItemDisc.	Not Necessary	50.00 FS	*-FS
E-1116	arichise	part. 3-	Sperior E-Electronia de	Sub Total (S\$)	27 059 00	15,434.80
			- List Item Discount on I	Litems 0.00/20.00% (S\$)	0.00	2,996.96
				Total Parts (S\$)	37,058.00	12,437.84

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

lo.	Particulars	Lab.Type	Repairer's	Amount
abo	ur Items			
	TO CHECK WIRING.	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR.	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM.	New	100.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST.	New	100.00	60.00
,	TO DISMANTLE & REFIX PETROL TANK.	New	100.00	0.00
;	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	New	120.00	80.00
	TO REFILL AIR CON GAS.	New	150.00	0.00
3	TO SPRAY RUST PROOFING.	New	150.00	100.00
)	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS.	New	2,800.00	1,500.00
1	TO PUTTY & SPRAY PAINTING.	New	2,500.00	1,500.00
	Gross Labou	r Cost (S\$)	6,560.00	3,380.00

< END OF ESTIMATES >