

(08/11/13)

Surveyor: KalvinREF: CC3/TM19008786/K19d3n2**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: G2 7566TPolicy No. MD005079Claims No. M1903640

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHF 662M Yr Regn: 30 Jun 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 1995Make: Renault Latitude c.c. 1995Colour: M-Red/White A/C: Insured / Std / NI / NASp. Reading: 64463 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF1ABL15A4C2787X6

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ALU / Rim or

Tyre Size: F: 215 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hiti

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 16/5/19 D.O.I. 17/5/19Survey held at Transab

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHF-662M-CC4/AXA/700083/THH39.2 DOA: 3/1/17 To Ki
	G2 7566T-X 4,
7/5/19 @ 1.49pm	Email GIA & estimate to TMU.
28/5/19	Chd 45\$4650/4th, (Rox to 75980.10, 85%)

RECEIVED 28 MAY 2019

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 4.

1) 12/8/5 transit

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) \$ + RS. \$ \_\_\_\_\_

Transportation:

Photos

Others

TOTAL

Report Format: MER-TPLump Sum / I.B.I. (\$) 4650

250

10

260

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, 21 May 2019 1:49 PM  
**To:** Motor Claims  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 16/05/2019, SHF 662M (TP VEHICLE), GZ 7566T (OI VEHICLE)  
**Attachments:** SHF662 EST.pdf; SHF662 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHF 662M at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 17/05/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Kalvin Ang (LKKAUTO)**

---

**From:** weichunkong <weichunkong@transcab.com.sg>  
**Sent:** Thursday, 23 May 2019 9:55 AM  
**To:** 'Candy Kong'  
**Cc:** Calvin Ang (LKKAUTO)  
**Subject:** RE: SHF 662M  
**Attachments:** image002.emz; image007.wmz

Hi all,

SHF662M Net book value is \$45,509.64

Thanks  
Best regards

CK



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Candy Kong [<mailto:candy.kong@transcab.com.sg>]  
**Sent:** Thursday, 23 May, 2019 8:57 AM  
**To:** 'weichunkong' <weichunkong@transcab.com.sg>  
**Cc:** [kalvinang@lkkauto.com](mailto:kalvinang@lkkauto.com)  
**Subject:** SHF 662M

Hi CK,

Kindly provide me the Book Value of the taxi SHF 662M (Tokio Marine).  
DOA : 16/5/2019

*Thks & Rdgs*  
*Candy Kong*  
*Claims Service Assistant*



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Calvin Ang (LKKAUTO) [<mailto:kalvinang@lkkauto.com>]  
**Sent:** Thursday, 23 May, 2019 8:02 AM  
**To:** Candy Kong <[candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)> ([candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)) <[candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)>  
**Subject:** SHF 662M

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHF662M

Vehicle to be Exported: Yes

Intended Deregistration Date: 16 May 2019

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001712

Chassis No.: VF1ABL15AUC278746

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 30 Jun 2014

First Registration Date: 30 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jun 2022

PARF Rebate Amount: \$9,373.00

**Intended COE Rebate Details**

COE Expiry Date: 29 Jun 2022

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$57,338.00

COE Rebate Amount: \$22,357.00

**Total Rebate Amount: \$31,730.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/05/2019 16:25
Date Of Accident	16/05/2019 15:10
Exact Location Of Accident	KENT VALE BLK E 109 DROP OFF POINT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF662M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	OH SOI PIEW
NRIC No	S1221044B
Date Of Birth	29/02/1956
Occupation	OUTDOOR
Date Of Driving Pass	19/09/1979
Driving Experience	39 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98533309
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 507C WELLINGTON CIRCLE #08-110
Postcode	753507
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : MISS LEE - 86063658 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 16.05.2019 at about 1510hours, I was stationary along Kent Vale, Blk E 109 drop off point to alight my passenger. While stationary, collecting money from passenger, suddenly I felt an impact. Vehicle B (GZ7566T) making a reverse without checking his rear and hit onto my taxi front portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ7566T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	CHUA LEE SHYANG
NRIC/Passport Number	S2591005B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN

Kent Vale  
B16 E 109  
Drop at point  
A= SHF 662m  
B= GZ 7566T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GAT Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd****AAD1905-138**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 662M**

US \$4650/ 4/21

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHF 662M**

VF1ABL15AUC278746

RENAULT

LATITUDE

16.5.19

**TOKIO MARINE**

30/6/2014

		<b>PART</b>		<b>LIST</b>	
1	1	BUMPER COVER FRT	— <i>Reh</i>	\$	1,259.42
2	1	BUMPER SPOILER FRT	X <i>su</i>	\$	181.75
3	1	BUMPER ABSORBER FRT	X <i>su</i>	\$	394.68
4	1	BUMPER RETAINER FRT LH	X <i>su</i>	\$	151.41
5	1	BUMPER SUPPORT FRT	X <i>su</i>	\$	123.88
6	1	BUMPER RETAINER FRT RH	X <i>su</i>	\$	150.77
7	1	BUMPER SUPPORT FRT	X <i>su</i>	\$	123.88
8	1	BUMPER UNDERTRAY FRT	X <i>su</i>	\$	472.83
9	1	BUMPER GRILLE LOWER FRT	X <i>su</i>	\$	266.80
10	1	BUMPER FOG LAMP GRILLE LH	X <i>su</i>	\$	207.21
11	1	BUMPER FOG LAMP GRILLE RH	X <i>su</i>	\$	207.21
12	1	BUMPER BEAM FRT	X <i>su</i>	\$	914.08
13	1	TOW COVER FRT	X <i>su</i>	\$	28.61
14	1	FRONT BRACE PANEL	X <i>su</i>	\$	177.22
15	1	RADIATOR GRILLE	— <i>su</i>	\$	1,707.78
16	1	RADIATOR GRILLE BADGE 'RENAULT'	— <i>su</i>	\$	225.36
17	1	RADIATOR GRILLE FRAME	— <i>su</i>	\$	1,353.75
18	1	FRAME FULL SUPPORT PANEL	X <i>su</i>	\$	615.90
19	1	FRAME FULL SUPPORT BRACKET	X <i>su</i>	\$	89.79
20	1	HEADLAMP LH	X <i>su</i>	\$	1,184.43
21	1	HEADLAMP RH	X <i>su</i>	\$	1,184.43
22	1	HEADLAMP PANEL FRT LH	X <i>su</i>	\$	152.15
23	1	HEADLAMP PANEL FRT RH	X <i>su</i>	\$	152.15
24	1	BONNET	X <i>Rep. 2</i>	\$	1,941.63
25	1	BONNET INSULATOR	X <i>su</i>	\$	405.73
26	1	BONNET STRUT LH	X <i>su</i>	\$	88.61
27	1	BONNET STRUT RH	X <i>su</i>	\$	88.61
28	1	BONNET HINGE LH	X <i>su</i>	\$	348.31
29	1	BONNET HINGE RH	X <i>su</i>	\$	348.31

**Trans-cab Auto Services Pte Ltd****AAD1905-138**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 662M**

30	1	BONNET CABLE COVER	X sm	\$	161.03
31	1	BONNET SEAL OUTER	X sm	\$	92.36
32	1	BONNET SEAL INNER	X sm	\$	157.28
33	1	BONNET LOCK	X sm	\$	305.48
34	1	BONNET CABLE	X sm	\$	119.19
35	1	FENDER PANEL FRT LH	X sm	\$	783.83
36	1	WHEELARCH FRT LH	X sm	\$	278.84
37	1	FENDER BRACKET LOWER LH	X sm	\$	15.79
38	1	FENDER INSULATOR LH	X sm	\$	130.84
39	1	FENDER PANEL FRT RH	X sm	\$	783.83
40	1	WHEELARCH FRT RH	X sm	\$	278.84
41	1	FENDER BRACKET LOWER RH	X sm	\$	15.79
42	1	FENDER INSULATOR RH	X sm	\$	130.84
43	1	WIPER RESERVOIR	X sm	\$	348.25
44	1	WIPER RESERVOIR NECK	X sm	\$	136.11
45	1	WIPER RESERVOIR MOTOR	X sm	\$	270.06
46	1	AIR CLEANER BOX	X sm	\$	464.20
47	1	AIR CLEANER HOSE	X sm	\$	175.85
48	1	AIR CLEANER LOWER	X sm	\$	271.26

**TOTAL \$ 19,466.36****10% \$ 1,946.64****\$ 17,519.72****Special Nett**

1	1SET	RADIATOR GRILLE FRAME CLIP	— sm	\$	52.00
2	1SET	BUMPER CLIP FRT	— sm	\$	66.00
3	1SET	BUMPER BRACKET CLIP FRT LH	— sm	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	X sm	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	— sm	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	X sm	\$	10.50
7	1	TOW COVER FRT	X sm	\$	14.50
8	1	RADIATOR GRILLE SCREW	— sm	\$	16.00
9	1SET	BUMPER GRILLE LOWER CLIP	X sm	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	X sm	\$	70.00
11	1SET	FRAME FULL SUPPORT PANEL NUT	X sm	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	X sm	\$	30.00
13	1	Windscreen moulding	X sm	\$	120.00

**Trans-cab Auto Services Pte Ltd**

AAD1905-138

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 662M**

14	1	FRONT WINDSCREEN SEALANT	X 22	\$	253.80
15	1	FRONT WINDSCREEN INNER SPONGE SEAL	X 23	\$	100.00
16	1	Front licence plate with holder	But	\$	<del>35 80.00</del>
17	1SET	WHEELARCH CLIP FRT LH	X 27	\$	30.50
18	1SET	WHEELARCH CLIP FRT RH	X 27	\$	30.50
19	6	BONNET INSULATOR CLIP L70Y	X 27	\$	7.30
20	2	BONNET STRUT L70Y	X 27	\$	88.61
21	2	BONNET CABLE CLIP L70Y	X 27	\$	6.31
22	2	BONNET CABLE COVER SCREW L70Y	X 27	\$	10.85
<b>TOTAL</b>				<b>\$</b>	<b>1,110.38</b>

<b>TOTAL PARTS</b>	<b>\$</b>	<b>18,630.10</b>
--------------------	-----------	------------------

**Labour**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<del>380.00</del> X 27
To check steering geometry and computer wheel alignment	\$	<del>220.00</del> X 27
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<del>4,500.00</del> 600
To apply paint protection system (PPS) maintain and enhancement	\$	<del>380.00</del> X 27
To rust-proofing of the affected areas.	\$	<del>170.00</del> X 27
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<del>380.00</del> X 27
To transfer of tire, rim and on wheel balancing.	\$	<del>170.00</del> X 27

**Trans-cab Auto Services Pte Ltd****AAD1905-138**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 662M**

To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<del>170.00</del> X 3
To Check Electrical Lighting Concerned.	\$	<del>170.00</del> X 3
Putty and spray painting of the affected portion.	\$	<del>4,500.00</del> X 50
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<del>380.00</del> X 3
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<del>380.00</del> X 3
To transfer of front windscreen fittings and conduct water seepage test	\$	<del>200.00</del> X 3

**TOTAL \$ 12,000.00****Over All Total \$ 30,630.10****(LUMP SUM) Repair Days****15 DAYS***Ka/lin 10/11/19**17/5/19 1700h.**4 Dps.**4/5**After Repair pls*

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey (before/after spray painting)
- To display damaged part(s) during resurvey
- Repairs shall be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal responsibility is allowed
- Supplementary survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer:  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19008786/K1QD3N2

Date: 31/05/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MD005029
Claimant Vehicle No :	SHF662M	Insured Vehicle No :	GZ7566T
Date of Loss:	16/05/2019	Nature of Claim:	TP
		Claim No:	M1903640

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHF662M	Engine No:	M9R8839C001712
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC278746
Reg. Date:	30/06/2014 (Man. Year: 2014)	Odometer:	644613 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,630.09	4,838.99	13,791.10	74.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,000.00	1,000.00	11,000.00	91.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,630.09</b>	<b>5,838.99</b>	<b>24,791.10</b>	<b>80.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,650.00</b>		
(S\$)	30,630.09	4,650.00	25,980.09	84.82
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,144.11</b>	<b>325.50</b>	<b>1,818.61</b>	<b>84.82</b>
<b>Nett Amount (S\$)</b>	<b>32,774.20</b>	<b>4,975.50</b>	<b>27,798.70</b>	<b>84.82</b>

## INSPECTION

Date of Assignment:	21/05/2019	
Date Inspected:	17/05/2019	Inspected At: Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF662M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER FRT	Deformed	1,259.42 FL	*1,259.42 FL
2	1	*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1	*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1	*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1	*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1	*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1	*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
12	1	*BUMPER BEAM FRT	Serviceable	914.08 FL	*- FL
13	1	*TOW COVER FRT	Serviceable	28.61 FL	*- FL
14	1	*FRONT BRACE PANEL	Serviceable	177.22 FL	*- FL
15	1	*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
16	1	*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
17	1	*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
18	1	*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
19	1	*FRAME FULL SUPPORT BRACKET	Serviceable	89.79 FL	*- FL
20	1	*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
21	1	*HEADLAMP RH	Serviceable	1,184.43 FL	*- FL
22	1	*HEADLAMP PANEL FRT LH	Serviceable	152.15 FL	*- FL
23	1	*HEADLAMP PANEL FRT RH	Serviceable	152.15 FL	*- FL
24	1	*BONNET	Repair	1,941.63 FL	*- FL
25	1	*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
26	1	*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
27	1	*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
28	1	*BONNET HINGE LH	Serviceable	348.31 FL	*- FL
29	1	*BONNET HINGE RH	Serviceable	348.31 FL	*- FL
30	1	*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
31	1	*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
32	1	*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
33	1	*BONNET LOCK	Serviceable	305.48 FL	*- FL
34	1	*BONNET CABLE	Serviceable	119.19 FL	*- FL
35	1	*FENDER PANEL FRT LH	Serviceable	783.83 FL	*- FL
36	1	*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
37	1	*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
38	1	*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
39	1	*FENDER PANEL FRT RH	Serviceable	783.83 FL	*- FL
40	1	*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
41	1	*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
42	1	*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
43	1	*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
44	1	*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
46	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
47	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
48	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
49	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
50	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
51	1		*BUMPER BRACKET CLIP FRT LH SET	Necessary	12.00 FS	*12.00 FS
52	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
53	1		*BUMPER BRACKET CLIP FRT RH	Necessary	12.00 FS	*12.00 FS
54	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
55	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
56	1		*RADIATOR GRILLE SCREW	Necessary	16.00 FS	*16.00 FS
57	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
58	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
59	1		*SET FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
60	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
61	1		*WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
62	1		*FRONT WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
63	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
64	1		*FRONT LICENSE PLATE WITH HOLDER	Bent	80.00 FS	*35.00 FS
65	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
66	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
67	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
68	2		*BONNET STRUT CLIP L70Y	Not Necessary	88.61 FS	*- FS
69	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
70	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>20,576.73</b>	<b>5,355.21</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,946.64</b>	<b>516.22</b>
<b>Total Parts (\$\$)</b>	<b>18,630.09</b>	<b>4,838.99</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.	New	4,500.00	600.00
4	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	New	170.00	0.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	0.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,500.00	400.00
11	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,000.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >