

ASS. REC. BY:

REF:

CS/FCI19008791/Usd3

n2

Special Instruction:

Assigner:

CWS

Marcus

ASSIGNMENT (Office)

From (Person):

Sylvia

of

PEI

Date/Time:

2:41pm @ 17/5/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN3115B

Insured:

SHC 0952S

at Workshop m/s

Pestech

Tel:

67465405

of

1 Kaki Bukit Ave 6 #01-46 Autobuy

Policy No:

Claim No:

D190032751PSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/05/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 2:41pm @ 17/5/19

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

SGN 3115B-X

SHC 0952S - CS/FCI16000971/Usd1

D.O.A.: 14/1/2016

21/5 @ 11:54am - sent email we are pending estimate.

ASSIGNMENT

From: Date: 17.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGN 3153

at Workshop n/s

of MD 1 Kala Bukit Axi 6

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SGN 315B Yr Regn: 419

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Toyota Vios C.C 1496

Colour: s. blue A/C: Insured / Std / NI / NA

Sp. Reading: 2006 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR2B23F3601171716

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 16/5/19 D.O.I. 17/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have G.M. LTA 35873

10/6/19 L/S # 8400 confirmed with Ahs.

(\$ 11,949.35 Red - 59%)

RECEIVED 11 JUN 2019

Date/Time, File Pass to?

11/06/19

1) Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 8.400/- L/S)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

OSR

TOTAL

11/6/19

10x15: 150

170+150

50

50+50

157

627

MOTOR SURVEY ASSIGNMENT

Date	16-05-2019	Our Ref No. D19003275MFSH
Accident Date	16-05-2019	Claim Type. Third Party
Insured Vehicle	SHC0952S	Third Party Vehicle. SGN3115B
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 21 May 2019 11:54 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003275MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGN 3115B on 17/5/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 17 May 2019 3:13 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003275MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 May 2019 2:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003275MFSH/1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5042E
Vehicle Details	
Vehicle No.:	SGN3115B
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	2NRX433206
Chassis No.:	MR2B23F3601171716
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,936.00
Original Registration Date:	10 Apr 2019
First Registration Date:	10 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$13,936.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Apr 2029
PARF Rebate Amount:	\$10,452.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,689.00
COE Rebate Amount:	\$25,421.00
Total Rebate Amount:	\$35,873.00

The information contained herein is correct as at 17 May 2019

OK

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
HKK
17/5/18
4/5 \$400/-
Sht.

VEHICLE NO:SGN 3115B

QTY	PARTICULAR		
1 PCS	BOOTLID	851.90	10/Buc \$951.90
1 PCS	BOOTLID REAR LOGO		ru \$65.90
1 PCS	BOOTLID 'VIOS' EMBLEM		ru \$66.90
1 PCS	BOOTLID 'E' EMBLEM		ru \$41.90
2 PCS	BOOTLID REFLECTORS @\$178.85		one \$357.70
1 PCS	BOOTLID LICENCE LAMP		11 \$95.60 X
1 PCS	BOOTLID HANDLE GARNISH		11 \$169.60 X
1 PCS	BOOTLID INNER LOCK	495.10	twi \$816.95
1 PCS	BOOTLID INNER TRIM		11 \$579.50 X
1 SET	BOOTLID INNER TRIM CLIPS		11 \$50.00 X
1 PCS	BOOTLID WEATHERSTRIP		twi \$196.95
2 PCS	BOOTLID HINGES @\$128.60		hnt/twi \$257.20
1 PCS	REAR BUMPER		dis \$762.90
2 PCS	REAR BUMPER REFLECTORS @\$101.50		one \$203.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$69.50		best \$139.00
1 SET	REAR BUMPER CLIPS		ru \$50.00
2 PCS	REAR BUMPER SENSORS @\$385.10	225 x 2 = 450	one/shld \$770.20 270
1 PCS	REAR BUMPER REINFORCEMENT		dis \$361.95
1 PCS	REAR REVERSE CAMERA		shld \$680.00 3505.2
1 PCS	REAR END PANEL		30500 \$691.80
1 PCS	REAR END PANEL TOP GARNISH		twi \$269.10
2 PCS	TAILLAMPS @\$491.60		one \$983.20
2 PCS	TAILLAMP HOUSING PANELS @\$299.50		10/21 \$599.00
2 PCS	REAR FENDERS @\$955.80		ru \$1,911.60 X
2 PCS	REAR FENDER INNER TRIMS @\$484.10		De 17.1 \$968.20
1 PCS	REAR FLOOR PANEL		crushed/buc \$675.60
1 PCS	REAR FLOOR PANEL TOP BOARD		11 \$381.90
2 PCS	REAR FLOOR PANEL TOOLS SPONGES @\$250.00		10.1 \$500.00
1 PCS	REAR EXHAUST		ru \$598.60 X
2 PCS	REAR EXHAUST MOUNTINGS @\$65.00		11 \$130.00 X
1 PCS	REAR WINDSCREEN MOULDING		11 \$118.20 X
1 PCS	REAR BOOT LOCK SENSOR		one \$325.00 ✓
			\$14,769.35
1 SET	S.NETT	4698.4	
1 PCS	REAR FLOOR PANEL INSULATOR	7270.65	ru \$380.00 150
1 PCS	REAR END PANEL SEALANT		ru \$50.00 ✓
1 PCS	REAR WINDSCREEN SEALANT		11 \$50.00 X
1 PCS	REAR LICENCE PLATE W/HOLDER		11 \$50.00 X
	LABOUR CHARGES:		
	TO CHECK WIRING		\$80.00 30
	TO DISMANTLE & REPLACING PDC SENSOR		\$80.00 50
	TO TRANSFER BOOTLID MECHANISM		\$100.00 60
	TO SPRAY RUST PROOFING		\$150.00 80
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY		\$150.00 80

TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00	X
TO DISMANTLE & REFIX PETROL TANK		\$100.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	X
TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS		\$2,080.00	1500
TO PUTTY & SPRAY PAINTING		\$1,680.00	1200
TOTAL		\$20,349.35	

10530.65
8424.52

LKK Auto Consultants have notify
the Reparer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No 2nd opinion allowed
- Supplementary part(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Reparer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008791/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 952S	Veh. Inspected	SGN 3115B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003275MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	17/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MR2B23F3601171716	Colour	SILVER	
Odometer	2006	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DUNLOP	9 mm	
L/H Front Tyre	185/60 R15	DUNLOP	9 mm	
R/H Rear Tyre	185/60 R15	DUNLOP	9 mm	
L/H Rear Tyre	185/60 R15	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/05/2019	Inspection Date	17/05/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 3115B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	DENTED / BUCKLED	951.90	851.90
1	BOOTLID REAR LOGO	NECESSARY	65.90	65.90
1	BOOTLID "VIOS" EMBLEM	NECESSARY	66.90	66.90
1	BOOTLID "E" EMBLEM	NECESSARY	41.90	41.90
2	BOOTLID REFLECTORS @\$178.85	CRACKED	357.70	357.70
1	BOOTLID LICENCE LAMP	NOT NECESSARY	95.60	-
1	BOOTLID HANDLE GARNISH	NOT NECESSARY	169.60	-
1	BOOTLID INNER LOCK	TWISTED	816.95	495.10
1	BOOTLID INNER TRIM	NOT NECESSARY	579.50	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
1	BOOTLID WEATHERSTRIP	TWISTED	196.95	196.95
2	BOOTLID HINGES @\$128.60	BENT / TWISTED	257.20	257.20
1	REAR BUMPER	DISTORTED	762.90	762.90
2	REAR BUMPER REFLECTORS @\$101.50	CRACKED	203.00	203.00
2	REAR BUMPER SIDE RETAINERS @\$69.50	BENT	139.00	139.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SENSORS @\$385.10	CRACKED / SHORTED	770.20	450.00
1	REAR BUMPER REINFORCEMENT	DISTORTED	361.95	361.95
1	REAR END PANEL	BADLY DENTED	691.80	691.80
1	REAR END PANEL TOP GARNISH	TWISTED	269.10	269.10
2	TAILLAMPS @\$491.60	CRACKED	983.20	983.20
2	TAILLAMP HOUSING PANELS @\$299.50	DENTED / BENT	599.00	599.00
2	REAR FENDERS @\$955.80	TO REPAIR SEE LABOUR	1,911.60	-
2	REAR FENDER INNER TRIMS @\$484.10	DEFORMED / TORN	968.20	968.20
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	675.60	675.60
1	REAR FLOOR PANEL TOP BOARD	TORN	381.90	381.90
2	REAR FLOOR PANEL TOOLS SPONGES @\$250.00	TORN	500.00	500.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	598.60	-

Report Ref No. CS/FCI19008791/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST MOUNTINGS @\$65.00	NOT NECESSARY	130.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	118.20	-
1	REAR BOOT LOCK SENSOR	CRACKED	325.00	325.00
	LESS 25% DISCOUNT		-	-2,423.55
			14,089.35	7,270.65
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE CAMERA (SN)	SHORTED	680.00	350.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	380.00	150.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
			1,210.00	550.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		150.00	80.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX PETROL TANK.		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDERS AND REAR EXHAUST.		2,080.00	1,500.00
	TO PUTTY & SPRAY PAINTING.		1,680.00	1,200.00
	-		-	-
	-		-	-
	-		-	-
			5,050.00	3,060.00
	GRAND TOTAL		20,349.35	10,880.65

Report Ref No. CS/FC119008791/Usd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,400.00
---	--	--	----------

Report Ref No. CS/FCI19008791/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.