

ASS. REC. BY:

REF: CS / FC1 / 9008792 / G5d3n2 Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): MAY Chua of FC1 Date/Time: 17.5.19 3.03p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBP 4135K Insured: SHC 8970L

at Workshop m/s Bike Dynamic Centre Tel: 67496637

of Blk 6 Dafa Lane 10 #01-554

Policy No: Claim No: D19003289 MFSH

Sum Insured: Excess:

Make of Vch: D.O.A. 11.05.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 17.5.19 3.57p.m. Person Contacted: Lemon Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBK 4135K - X
	SHC 8970L - X
7/5/19 @ 3.19pm	informed May Chua, we are pending estimate from repairer.

357

MOTOR SURVEY ASSIGNMENT

Date	17-05-2019	Our Ref No. D19003289MFSH
Accident Date	11-05-2019	Claim Type. Third Party
Insured Vehicle	SHC8970L	Third Party Vehicle. FBP4135K
Survey Location	BLK 6 DEFU LANE 10 #01-554	
Contact Person.	SALLY GOH	
Contact No.	67496637/ 0	Fax No. 67496120
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BIKE DYNAMIC CENTRE	Attention. NIL
Cc : TP Solicitor	CATHERINE LIM LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 21 May 2019 3:19 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'May Chua Hui Chin'
Subject: RE: SURVEY ASSESSMENT - D19003289MFSH/1

Dear May,

Please be informed that we have inspected the motorbike FBP 4135K.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 17 May 2019 4:01 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003289MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 May, 2019 3:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003289MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	4991E
Vehicle No.:	FBP4135K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2019
Vehicle Make:	YAMAHA
Vehicle Model:	MX KING T150 MANUAL
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G3E6E0470536
Chassis No.:	MH3UG0750KK009639
Maximum Power Output:	-
Open Market Value:	\$2,345.00
Original Registration Date:	03 Apr 2019
First Registration Date:	03 Apr 2019
Transfer Count:	1
Actual ARF Paid:	\$352.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	02 Apr 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,469.00
COE Rebate Amount:	\$3,422.00
Total Rebate Amount:	\$3,422.00

The information contained herein is correct as at 20 May 2019

OK

QUOTATION FOR REPAIR : FBP4135K

Qty	Description	Repairer's Estimate
1 pc	Handle bar / BT	68.00 /
1 pc	Handle bar bracket X NN	45.00 X
1 set	Handle bar balancer / Cut	36.00 95 /
1 set	View mirror X / Cut	56.00 /
X1 pc	Head lamp assy X MT / Cut	105.00 X
1 pc	Head lamp cowling X / Cut	90.00 /
1 pc	Front signal cowling / Cut	130.00 /
1 pc	Front side fairing LH X NN	95.00 X
1 pc	Front mudguard X	68.00 X
1 pc	Front foot rest bracket / BT	95.00 /
1 set	Footrest rubber / Cut	20.00 /
1 pc	Gear shifter / BT	85.00 /
1 pc	Pillion footrest LH X	28.00 X
1 pc	Pillion footrest bracket LH X NN	65.00 X
X1 pc	Rear sport rim X	250.00 X
1 pc	rear signal LH / Cut	85.00 /
1 PC	magnet cover LH / Cut	295.00 /
1 pc	clutch lever LH / Cut	45.00 /
1pc	Rear side fairing LH / Cut	190.00 /
		1,851.00 1195
		185.10
		1,665.90 1075.5
Less 10%		

2 bott	fork oil /	50.00 30
2 pc	fork oil seal /	50.00 30
1 set	Body sticker /	90.00 60
	Towing fees x 2	70.00
	Front rim realign	80.00
	Front fork realign	120.00
	Chassis frame realign	300.00
	Labour charges	280.00
		2,705.90 280
		5 days

2 Days.

ump sum repair.

After repair photos.

Gmo Qiap - 82880282

1455.5

2%: 1150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008798/Gsd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8970L	Veh. Inspected	FBP 4135K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003289MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	17/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA MX KING T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MH3UG0750KK009639	Colour	BLUE	
Odometer	2578	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/80-17	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70-17	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/05/2019	Inspection Date	17/05/2019	
Survey held at	BIKE DYNAMIC CENTRE BLK 6 DEFU LANE 10 #01-55 SINGAPORE 539187			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 4135K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	BENT	68.00	68.00
1	HANDLE BAR BRACKET	NOT NECESSARY	45.00	-
1	SET HANDLE BAR BALANCER	CUT	36.00	36.00
1	SET VIEW MIRROR	CUT	56.00	56.00
1	HEAD LAMP ASSY	NOT NECESSARY	105.00	-
1	HEAD LAMP COWLING	CUT	90.00	90.00
1	FRONT SIGNAL COWLING	CUT	130.00	130.00
1	FRONT SIDE FAIRING LH	NOT NECESSARY	95.00	-
1	FRONT MUDGUARD	NOT NECESSARY	68.00	-
1	FRONT FOOT REST BRACKET	BENT	95.00	95.00
1	SET FOOTREST RUBBER	CUT	20.00	20.00
1	GEAR SHIFTER	BENT	85.00	85.00
1	PILLION FOOTREST LH	NOT NECESSARY	28.00	-
1	PILLION FOOTREST BRACKET LH	NOT NECESSARY	65.00	-
1	REAR SPORT RIM	NOT NECESSARY	250.00	-
1	REAR SIGNAL LH	CUT	85.00	85.00
1	MAGNET COVER LH	CUT	295.00	295.00
1	CLUTCH LEVER LH	CUT	45.00	45.00
1	REAR SIDE FAIRING LH	CUT	190.00	190.00
	LESS 10% DISCOUNT		-185.10	-119.50
			1,665.90	1,075.50
SPECIAL NETT ITEMS				
2	BOTT FORK OIL (SN)	NECESSARY	50.00	30.00
2	FORK OIL SEAL (SN)	NECESSARY	50.00	30.00
1	SET BODY STICKER (SN)	NECESSARY	90.00	60.00
			190.00	120.00
LABOUR				
	TOWING FEEX2.		70.00	50.00
	FRONT RIM REALIGN	NOT NECESSARY	80.00	-
	FRONT FORK REALIGN		120.00	60.00

Report Ref No. CS/FCI19008798/Gsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHASSIS FRAME REALIGN.	NOT NECESSARY	300.00	-
	LABOUR CHARGES.		280.00	150.00
			850.00	260.00
GRAND TOTAL			2,705.90	1,455.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CS/FCI19008798/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.