

ASS. REC. BY:

REF: CS/FCI 19008803/ET d3n2 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Gileen

of

FCI

Date/Time: 4.5.19 3:16 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 7660C

Insured: SHB 6328K

at Workshop m/s MOVA Automotive

Tel: 62723892

of Block 1008 Bukit narah Lane 3 # 01-04/06

Policy No:

Claim No: D19003273MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.5.19 3:57 p.m.

Person Contacted: Mthd

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate.

SMH 7660C - X

SHB 6328K - CS/FCI 15010291 / Agbn2

DOA. 12/06/2015

30/5 @ 4:24pm Revised preli advise via email

ACC. REC. BY:

Steve

REF:

FCI

ASSIGNMENT

From:

Date:

28/5

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMH 7660C

at Workshop m/s Nova Auto

of BLK 1008 Bt Merah #01-04

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh: After 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 7660C

Yr Regn:

6/1/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier

C.C.

1986

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

57099

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

2 SU 6000 64325

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/60R18

R:

11

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

14/5/19

D.O.I.

28/5/19

Survey held at

Nova

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-9SK 4/9/19 Finalize Confir \$1800, 2 day (Red: 944 x5; 34%)

RECEIVED 05 SEP 2019

Date/Time, File Pass to?



: Preli. Report

1) 519 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Report Format:

Lump Sum / L.B.E: (\$)

1800/-

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

110

50

50

28

238



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003273MFSH

Date: 30/5/2019

Our Ref: CS/FCI19008803/Etd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SAH 7660C

Please be informed that we had conducted the inspection of the abovementioned vehicle
28/05/2019 at the premises of M/s Mova Automobile have the following to report: -

Workshop Estimate Amount	: S\$ <u>2,744.75</u>
Revised Estimate Amount	: S\$ <u>1,015.27</u>
"Check" Items Amount	: S\$ <u>234.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Steve

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-05-2019	Our Ref No. D19003273MFSH
Accident Date	14-05-2019	Claim Type. Third Party
Insured Vehicle	SHB6328K	Third Party Vehicle. SMH7660C
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Jacelyn <jacelyn@movacom.sg>
Sent: Wednesday, 4 September 2019 5:23 PM
To: Steve Chen (LKK Auto)
Cc: Denise Tay (LKKAUTO)
Subject: RE: FINALIZATION: SMH7660C - TP/FCI - TOYOTA HARRIER (DOA 14.05.2019)

Noted

Best Regards,
Jacelyn Ooi
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Wednesday, 4 September 2019 4:49 PM
To: Jacelyn
Cc: Denise Tay (LKKAUTO)
Subject: FINALIZATION: SMH7660C - TP/FCI - TOYOTA HARRIER (DOA 14.05.2019)

Dear Jacelyn,

Reconfirm repair day is 2 day.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jacelyn [mailto:jacelyn@movacom.sg]
Sent: Wednesday, September 04, 2019 12:06 PM
To: Steve Chen (LKK Auto)
Cc: Denise Tay (LKKAUTO)
Subject: RE: FINALIZATION: SMH7660C - TP/FCI - TOYOTA HARRIER (DOA 14.05.2019)

Dear Steve,

Amount confirmed.

Best Regards,
Jacelyn Ooi

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 30 May 2019 4:28 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Eileen Lee'
Subject: RE: SURVEY ASSESSMENT - D19003273MFSH/1
Attachments: PRELI ADVISED SMH 7660C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMH 7660C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 17 May 2019 4:00 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003273MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 May, 2019 3:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003273MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6159G
Vehicle Details	
Vehicle No.:	SMH7660C
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM STYLE MAUVE 2.0 CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB679078
Chassis No.:	ZSU600064325
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$30,946.00
Original Registration Date:	06 Jan 2016
First Registration Date:	06 Jan 2016
Transfer Count:	1
Actual ARF Paid:	\$35,325.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2026
PARF Rebate Amount:	\$26,493.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$40,357.00
Total Rebate Amount:	\$66,850.00

The information contained herein is correct as at 28 May 2019

OK

Steve (LKK) 30/5/19 L/S 2 days RY AL SPY 28/5/19, 2.30 PM



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

16/05/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1

Veh # :- SMH7660C

Veh Model :- TOYOTA HARRIER

Estimate# :- CK419160

Claim # :-

ACC. Date :- 14/05/19

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	1,458.00	1,458.00
2.	REAR BUMPER LOWER (ROUGH BLACK)	1 PC	489.00	489.00
3.	REAR BUMPER SPONGE	1 PC	142.00	142.00
4.	REAR BUMPER SIDE RETAINER LH	1 PC	82.00	82.00
5.	REAR BUMPER LOWER BRACKET LH	1 PC	85.00	85.00
6.	REAR BUMPER LOWER BRACKET RH	1 PC	85.00	85.00
7.	REAR BUMPER CLIPS	10 PC	5.00	50.00
8.	REAR BUMPER SIDE RETAINER RH	1 PC	82.00	82.00
LIST TOTAL S\$				2,473.00
25% DISCOUNT S\$				-618.25
				1,854.75
SPECIAL NET ITEMS :				
1.	REVERSE SENSOR	1 PC	280.00	280.00
SPECIAL NET TOTAL S\$				280.00
LABOUR :				
TO INSTALL REAR PARKING SENSOR & DIAGNOSE FUNCTION				50.00
TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION				280.00
TO SPRAY PAINT ON REPAIRED AREAS				280.00
LABOUR TOTAL S\$				610.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) to be resurveyed and price is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E

MOVA AUTOMOTIVE PTE LTD

NON-TAX AMOUNT S

AMOUNT S\$ 2,744.75

GST @ 7 % 192.13

AMOUNT DUE S\$ 2,936.88



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008803/Etd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6328K	Veh. Inspected	SMH 7660C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003273MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	17/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600064325	Colour	BLACK	
Odometer	57099	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	DUNLOP	7 mm	
L/H Front Tyre	235/60 R18	DUNLOP	7 mm	
R/H Rear Tyre	235/60 R18	DUNLOP	7 mm	
L/H Rear Tyre	235/60 R18	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/05/2019	Inspection Date	28/05/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 7660C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,458.00	1,343.00
1	REAR BUMPER LOWER (ROUGH BLACK)	CUT	489.00	489.00
1	REAR BUMPER SPONGE	BROKEN	142.00	142.00
1	REAR BUMPER SIDE RETAINER LH	BROKEN	82.00	82.00
1	REAR BUMPER LOWER BRACKET LH	NOT NECESSARY	85.00	-
1	REAR BUMPER LOWER BRACKET RH	NOT NECESSARY	85.00	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER SIDE RETAINER RH	BROKEN	82.00	82.00
	LESS 25% DISCOUNT		-618.25	-542.00
			1,854.75	1,626.00
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	<u>LABOUR</u>			
	TO INSTALL REAR PARKING SENSOR & DIAGNOSE FUNCTION.		50.00	30.00
	TO REPLACE DAMAGED ITEMS.REALIGN CONNECTION.		280.00	200.00
	TO SPRAY PAINT ON REPAIRED AREAS.		280.00	200.00
			610.00	430.00
	GRAND TOTAL		2,744.75	2,256.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00

Report Ref No. CS/FCI19008803/Etd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.