

LC AUTOMOTIVE

Block 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @KB (S)417800
Tel : (65) 65250431 HP: 92712214
Email : chris_chanbebe@hotmail.com

CR425006413 13rd MAY 2019

ZIRCOM NETWORKS PTE LTD
Bk 25 KAKI BUKIT RD 4
05-26 SYNERGY @KB
Singapore 417800

TPAYA
Poh Kin

Accident date: 12nd MAY 2019
Estimated repair cost for vehicle no: GX9699R TOYOTA LITEACE '03

S/n	Qty	Items	U/price	Amount
1	1	Front headlamp assy-LH		\$301.10 +
2	1	Front headlamp grille-LH		\$211.20 +
3	1	Front side lamp-LH		\$151.70 +
4	1	Front bumper		\$511.80
5	8	Front bumper clips	\$8.20	\$65.60 374 30
6	1	Front bumper beam	\$156.40	\$211.10 +
7	2	Front bumper bracket		\$312.80 +
8	1	Front L/H fender	\$5.00	\$462.20 +
9	8	Front L/H fender cowling clips		\$40.00 +
10	1	Front tyre -LH		\$250.00 +
11	1	Front RIM -LH		\$350.00 +
12	1	Front L/H Lower Arm		\$381.50 +
13	1	Front R/H knuckle arm		\$361.40 +
14	1	Front L/H Knuckle Arm Bearing		\$182.25 +
Subtotal :-				\$3,792.15

866.20

649.65

Labour charges

To remove & Refix front undercarriage

Wheel alignment (computer)

To Check Wiring System

Tuff Kote

Panel beating

Spray painting

\$200.00 X

\$120.00 X

~~\$50.00~~ 30

\$120.00 X

~~\$800.00~~ 300

~~\$800.00~~ 250

580

Subtotal :- \$2,090.00

Total:- \$5,882.15

total: 1225.65

A/S: 950

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: