

Sheet1
LC AUTOMOTIVE

Block 25 KAKI BUKIT ROAD 4 #05-26 SYNERG @KB (S)417800
Tel : (65) 65250431 HP: 92712214
Email : chris_chanbebe@hotmail.com

CR425006413 13rd MAY 2019

ZIRCOM NETWORKS PTE LTD
Bk 25 KAKI BUKIT RD 4
05-26 SYNERGY @KB
Singapore 417800

TPAYA
Poh Kin

Accident date: 12nd MAY 2019

Estimated repair cost for vehicle no: GX9699R TOYOTA LITEACE '03

| S/n | Qty | Items | U/price | Amount |
|-------------|-----|--------------------------------|----------|---------------------------|
| 1 | 1 | Front headlamp assy-LH | | \$301.10 + |
| 2 | 1 | Front headlamp grille-LH | | \$211.20 + |
| 3 | 1 | Front side lamp-LH | | \$151.70 + |
| 4 | 1 | Front bumper | | \$511.30 |
| 5 | 8 | Front bumper clips | \$8.20 | \$65.80 374 30 |
| 6 | 1 | Front bumper beam | | \$211.10 + |
| 7 | 2 | Front bumper bracket | \$156.40 | \$312.80 + |
| 8 | 1 | Front L/H fender | | \$462.20 + |
| 9 | 8 | Front L/H fender cowling clips | \$5.00 | \$40.00 + |
| 10 | 1 | Front tyre -LH | | \$250.00 + |
| 11 | 1 | Front RIM -LH | | \$350.00 + |
| 12 | 1 | Front L/H Lower Arm | | \$381.50 + |
| 13 | 1 | Front R/H knuckle arm | | \$361.40 + |
| 14 | 1 | Front L/H Knuckle Arm Bearing | | \$182.25 + |
| Subtotal :- | | | | \$3,792.15 |

866.20

649.65

Labour charges

To remove & Refix front undercarriage

\$200.00 +

WHeel alignment (computer)

\$120.00 X

To Check Wiring System

~~\$50.00~~ 30

Tuff Kote

580

\$120.00 X

Panel beating

~~\$800.00~~ 300

Spray painting

~~\$800.00~~ 250

Subtotal :- \$2,090.00

Total:- \$5,882.15

total: 1225.65

H/S: 950

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: