

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
18 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9060 FAX: 6346 7400

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0262/19

DATE : 16-MAY-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : SHINYO ENGINEERING & CONSTRUCTION PTE LTD
ADDRESS : 1 YISHUN STREET 23
#01-30 YS-ONE
S(768441)
TELEPHONE NO : 68623039

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1900082937
VEHICLE NO : GBJ3595D
MODEL CODE : MVL2RDKE26KW3JBT-D
MODEL/YEAR : NISSAN NV350 PANEL VAN 5DR 2.5 5AT MY2018
ENGINE NO : YD25046253B
CHASSIS NO : JN1MC2E26Z0031009
MILEAGE : 2206 KM
DATE IN : 16/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 15/05/2019

Not Authorized
Halter
22/5/19
Tahap H. Dehery
Sdy.

— 9645 0084 elmer@tanchang.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBJ3595D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR BOTH CORNER OUTER PANEL, RENEW FRONT CAP OUTER CENTER PANEL	1000.00	875
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	600.00	500
3 ZZ/003	RENEW BOTH HEADLAMP AND FOCUS	48.00	✓
4 ZZ/004	REMOVE AND INSTALL FRT BUMPER TO FACILITATE FRONT CAP PANEL REPLACEMENT	ny 125.00	✗
5 ZZ/005	SUPPLY FRT LICENSE PLATE		
TOTAL LABOUR CHARGES		1773.00	

Supplementary 22/05/2019 11:34

Refill front GAS 120 ✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBJ3595D

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	FRT LICENCE PLATE	FLP		11	60.00 X
2	SUNDRIES	NPN			50.00 ?
3	LH HEADLAMP	26060-5YE6B	17 363.30	X	
4	RH HEADLAMP	26010-5YE6B	17 363.30	X	
5	EMBLEM-RADIATOR NISSAN	62889-1JA0A	ner 73.60	—	
6	GRILLE-RADIATOR	62310-5YE0B	cm 565.90	—	
7	LH INNER FRT PANEL	61211-5YE0A	315.00	?	
8	FRONT CENTER INNER PANEL	F1203-3XAMA	58.10	?	
9	LOWER RH INNER FRT PANEL	61210-5YE1D	315.00	7	
10	INSULATOR CENTER INNER FRT PANEL	61280-VW100	57.40	7	
11	OUTER CENTER FRONT CAP PANEL	F1202-3XAMA	So 1229.50	—	
SUB TOTAL			2111.60	0.00	1339.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			422.32	0.00	0.00
GRAND TOTAL			1689.28	0.00	1339.50
OVERALL TOTAL			3028.78		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBJ3595D

TOTAL LABOUR CHARGES	1773.00
TOTAL SPARE PARTS CHARGES	3028.78

GRAND TOTAL	4801.78 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.