

Surveyor: Kohn

REF:

Estimate No: _____
 To Inspected Vehicle No: _____
 at Workshop n/s _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal or Market Value: _____
 IDAQ Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Luni-Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction

PLP \$2,261.45
 CRD: \$21,607.18 (90%)

SHB 7952B

29 Mar 2019

Type: M. Car / M. Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or

Make: Toyota Prius cc 1798
 Colour: Red / White A/C: Ins d / Std / N / NA
 Sp. Reading: 11186 T/Radio: Ins d / Std / N / NA

Eng/No: _____
 C/No: J70RB3F4403079542

Gen. Cond: Good / ☒ Poor / Burnt
 Steering: Inord / ☒ Jammed / Leaked / Burnt or
 Brake: Inord / ☒ Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/B or

Tyre Size: F: 175/65R45
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm	
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm	
D.O.A. <u>14/5/11</u>		D.O.L. <u>16/5/11</u>	

Survey held at Truscob
 Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or
Rear o/s.

The UIC / Chassis frame / Body Structure affected due to collision.

AR

Date/Time File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Site + RS

Phone

Print

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Other (\$

☐ : Other (\$

10734

Trans-cab Auto Services Pte Ltd

AAD1905-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7952B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7952B

JTDKB3FU403079542

TOYOTA

PRIUS

14.5.2019

Ath

29/3/2019

PART**LIST**

1	1 REAR BUMPER	de	\$	458.60✓
2	1 REAR BUMPER RE-INFORCEMENT	2 de	\$	318.80✓
3	1 REAR BUMPER TOWING COVER	misslug	\$	14.70✓
4	1 REAR BUMPER UNDER COVER (BLACK)	de	\$	552.60✓
5	1 REAR BUMPER SIDE RETAINER LH	x un	\$	112.70
6	1 REAR BUMPER SIDE RETAINER RH	ucc	\$	112.70✓
7	1 REAR TAILGATE	X	\$	1,547.27
8	1 REAR TAILGATE OUTER GARNISH	X Rlyr	\$	905.10
9	1 COVER, REAR COMBINATION LAMP, RH	X	\$	54.70
10	1 COVER, REAR COMBINATION LAMP, RH	X	\$	54.70
11	1 GARNISH, BACK DOOR SIDE, LH	X	\$	93.60
12	1 GARNISH, BACK DOOR SIDE, RH	X	\$	93.60
13	1 BOARD ASSY, BACK DOOR TRIM	X	\$	254.40
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	X	\$	51.20
15	1 REAR TAILGATE WEATHERSTRIP	X	\$	365.20
16	1 REAR END PANEL	X	\$	602.10
17	1 TAILLAMP LOWER RH	X	\$	548.40
18	1 TAILLAMP UPPER RH	X	\$	557.90
19	1 REAR BUMPER SIDE RH	X	\$	232.00
20	1 REAR BUMPER SIDE LH	X	\$	232.00
21	1 TAILLAMP LOWER LH	X	\$	548.40
22	1 TAILLAMP UPPER LH	X	\$	557.90

\$ 8,268.82
25% \$ 2,067.21

\$ 6,201.62

Trans-cab Auto Services Pte Ltd

AAD1905-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7952B

Special Nett

1	1SET PARKING AID	/	\$	700.00 ²⁰⁰ - okayed
2	1SET REAR BUMPER CLIP	/	\$	22.00 - wee
3	2 REAR WINDSCREEN SELANT	X	\$	80.00
4	1 WINDSCREEN MOULDING	X	\$	100.00
5	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
6	1 REAR TAILGATE TOYOTA LOGO	X	\$	47.00
7	1 REAR TAILGATE WORDING 'PRIUS'	/	\$	52.90 - wee
8	1 REAR TAILGATE WORDING 'HYBRID'	/	\$	53.50 - wee
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	/	\$	80.00 - wee
10	1 REAR TAILGATE STICKER '6555-3333'	/	\$	80.00 - wee
11	1 REAR BUMPER PROTECTOR	/	\$	100.00 ⁵⁰ wee

TOTAL \$ 1,415.40

TOTAL PARTS \$ 7,617.02**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00 ⁴⁰⁰
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 ³⁰⁰
To Rust-Proofing Of The Affected Areas.	\$	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 30
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1905-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7952B

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	170.00 X
TOTAL	\$	10,150.00

Over All Total	\$	23,968.63
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days**20 DAYS**

Kahin (Kk)

16/5/19 1700h

3 By,

P/P

Before Part photo

967/9299



Jay

L

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1905-122

Your Ref : SKR2673U

Date : 13.June 2019

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHB7952B AND SKR2673U ON 14/05/19 07:15 PM ALONG BARTLEY ROAD TOWARDS THOMSON

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	2,526.75
2.	Loss of Rental for <u>3</u> days @ <u>\$117.40</u> per day	\$	340.20
3.	Loss of Income for <u>3</u> days @ <u>\$50</u> per day	\$	150.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	3,024.44

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

15 JULY 2019

WAYNE WILLIAM CHENG CHIEN LOONG
16 UPPER SERANGOON VIEW
#11-09
SINGAPORE 534201

Dear Sir/Madam,

OUR REF : CC3/AIG19008808/Kha3
YOUR REF : SKR 2673U
ACCIDENT INVOLVING SKR 2673U AND SHB 7952B ALONG BARTLEY ROAD ON
14.05.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SHB 7952B against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SHB 7952B. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHB7952B and SKR2673U along BARTLEY ROAD TOWARDS THOMSON on 14/05/19 07:15 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 13 (day) of June 2019

Yours Faithfully
Trans-Cab Services Pte Ltd

Jasmine Tan
General Manager



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **TRANS-CAB AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,526.75** (Repair Cost), **S\$490.20** (Loss of Rental/Use), **S\$7.49** (Disbursement) for vehicle no. **SHB 7952B** that was damaged pursuant to the accident which occurred on **14/05/2019** (date) along **BARTLEY ROAD TOWARDS THOMSON** (location) involving vehicle no/s **SKR 2673U**. This is pursuant to the inspection conducted on **16/05/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TRANS-CAB SERVICES PTE LTD** ("the third party claimant") of vehicle no. **SHB 7952B** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHB 7952B** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of July (month) 2019 (year)

 Kec

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AIG ASIA PACIFIC INSURANCE PTE LTD 78 Shenton Way #07-16 CHARTIS Building 079120 Singapore ATTENTION:	INVOICE NO. : INV1906-059 DATE : 12. June 2019 REFERENCE NO : AAD1905-122 TERMS : Net 30 Days DUE DATE : 12. July 2019 PAGE : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHB7952B; DOA 14.05.19(PART-BY-PART-19)	1	2,526.75	2,526.75

Total SGD Excl. GST :	2,361.45
7% GST :	165.30
Total SGD Incl. GST :	2,526.75

****** TWO THOUSAND FIVE HUNDRED TWENTY SIX AND SEVENTY FIVE SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

13 June, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 14/05/19 07:15 PM at BARTLEY ROAD TOWARDS THOMSON

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHB7952B. The taxi was hired to KANG LIN FUI a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$113.4 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan
General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

14-05-2019

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1905-122	Accident Date 14-05-2019
5/15/2019 10:45	5/17/2019 15:00	SHB7952B

Yours Faithfully,

Trans-Cab Services Pte Ltd**Jasmine Tan****General Manager**

[> Back to OneMotoring](#)**Vehicle Insurance Particulars Result**

Vehicle No.	Incident Date/Time	Insurance Company Name
GBD4859T	10 May 2019 / 12:00:00	EQ INSURANCE COMPANY LTD
SKX5827S	15 May 2019 / 11:15:00	NTUC INCOME INS CO-OP LTD
SKR2673U	14 May 2019 / 19:15:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.
SDS3318S	15 May 2019 / 13:55:00	NTUC INCOME INS CO-OP LTD
SKZ103U	15 May 2019 / 12:25:00	AXA INSURANCE PTE LTD

[Print](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019 Edit Reg		16 May 2019 00:00 Edit Adj Rpt	S\$2,361.45 Edit Estimates	S\$2,361.45 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: WAYNE-WILLIAM CHENG CHIEN LOONG , ID: S77001223, Tel: +6591074856									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.: SHB7952B		Date of Loss: 14/05/2019 19:00 - :59 [1 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3441113287SG		Policy/Cover Note No.: 1800086942 (Comprehensive)							
Vehicle Reg. No. (Insured): SKR2673U		Policy No. (Claimant): VPX/P1680520							
		Excess:							
Repairer: Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 29/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (21/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB7952B (3441113287SG)
 [SKR2673U]
 TP
 TRANS-CAB SERVICES PTE LTD
 May 14 2019 7:00PM
 [WAYNE-WILLIAM CHENG CHIEN LOONG]
 Trans-cab Auto Services Pte Ltd

Upload Documents
Upload Photos
Compose New Letter
Upload Video
Upload Audio

View View in Browser

Letters/Correspondences

1 per page ⌵ ✓

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Photos/Images

3 per page ⌵ ✓

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/19 09:01	General View	Load JPG ✓	✓
2	21/05/19 09:01	General View	Load JPG ✓	✓
3	21/05/19 09:01	General View	Load JPG ✓	✓
4	21/05/19 09:01	General View	Load JPG ✓	✓
5	21/05/19 09:01	General View	Load JPG ✓	✓
6	21/05/19 09:01	General View	Load JPG ✓	✓
7	21/05/19 09:01	General View	Load JPG ✓	✓
8	21/05/19 09:01	General View	Load JPG ✓	✓
9	21/05/19 09:01	General View	Load JPG ✓	✓
10	21/05/19 09:01	General View	Load JPG ✓	✓
11	21/05/19 09:01	General View	Load JPG ✓	✓
12	21/05/19 09:01	General View	Load JPG ✓	✓
13	21/05/19 09:01	General View	Load JPG ✓	✓
14	21/05/19 09:01	General View	Load JPG ✓	✓
15	21/05/19 09:01	General View	Load JPG ✓	✓
16	21/05/19 09:01	General View	Load JPG ✓	✓
17	21/05/19 09:01	General View	Load JPG ✓	✓
18	21/05/19 09:01	General View	Load JPG ✓	✓
19	21/05/19 09:01	General View	Load JPG ✓	✓
20	21/05/19 09:01	General View	Load JPG ✓	✓
21	21/05/19 09:01	General View	Load JPG ✓	✓
22	21/05/19 09:01	General View	Load JPG ✓	✓
23	21/05/19 09:01	General View	Load JPG ✓	✓
24	21/05/19 09:01	General View	Load JPG ✓	✓
25	21/05/19 09:08	General View	Load JPG ✓	✓
26	21/05/19 09:08	General View	Load JPG ✓	✓
27	21/05/19 09:08	General View	Load JPG ✓	✓
28	21/05/19 09:08	General View	Load JPG ✓	✓
29	21/05/19 09:08	General View	Load JPG ✓	✓
30	21/05/19 09:08	General View	Load JPG ✓	✓
31	21/05/19 09:08	General View	Load JPG ✓	✓
32	21/05/19 09:08	General View	Load JPG ✓	✓
33	21/05/19 09:08	General View	Load JPG ✓	✓

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/19 19:55	TP ESTIMATE - MARKED	Load PDF	
2	21/05/19 19:55	TP GIA REPORT	Load PDF	
3	15/07/19 13:24	LETTER TO OI	Load PDF	
4	25/07/19 08:38	WORKSHOP INVOICE	Load PDF	
5	25/07/19 08:38	AUTHORISATION TO ACT FORM	Load PDF	
6	25/07/19 08:38	Release Voucher	Load PDF	
7	25/07/19 08:38	RENTAL RECEIPT	Load PDF	
8	25/07/19 08:38	RENTAL MILEAGE	Load PDF	
9	25/07/19 08:38	LTA SEARCH	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/05/19 11:12	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKR2673U (Insd veh)	Model:	TOYOTA PRIUS 1.8 5DR
	SHB7952B (TP veh)		HATCHBACK (A)
Date of Accident:	14/05/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	19,010.51
Final Repair Cost	:	\$	2,526.75
Loss of Use	:	\$	150.00
Rental (if any)	:	\$	340.20
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,024.44

3.00 days at \$50.00 per day
3 days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	:	\$ 3,024.44
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

25 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19008808/K1HA3Q2
Date: 25/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800086942
Claimant Vehicle No: SHB7952B Insured Vehicle No: SKR2673U
Date of Loss: 14/05/2019 Nature of Claim: TP Claim No: 3441113287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7952B
Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C02618
Reg. Date: 29/03/2019 (Man. Year: 2018) Chassis No: JTDKB3FU403079542
Colour: Metallic White/Red Odometer: 11186 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,616.83	1,631.45	5,985.38	78.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,150.00	730.00	9,420.00	92.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,766.83	2,361.45	15,405.38	86.71
+ GST 7.00/7.00% (S\$)	1,243.68	165.30	1,078.38	86.71
Nett Amount (S\$)	19,010.51	2,526.75	16,483.76	86.71
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$113.40/day) (S\$)		340.20		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,024.44		

INSPECTION

Date of Assignment: 16/05/2019
Date Inspected: 16/05/2019 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Deformed	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Missing	14.70 FL	*14.70 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Deformed	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	112.70 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Necessary	112.70 FL	*112.70 FL
7	1		*REAR TAILGATE	Not Necessary	1,547.27 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	905.10 FL	*- FL
9	1		*COVER,REAR COMBINATION LAMP ,RH	Not Necessary	54.70 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP ,RH	Not Necessary	54.70 FL	*- FL
11	1		*GARNISH ,BACK DOOR SIDE ,LH	Not Necessary	93.60 FL	*- FL
12	1		*GARNISH ,BACK DOOR SIDE ,RH	Not Necessary	93.60 FL	*- FL
13	1		*BOARD ASSY ,BACK DOOR TRIM	Not Necessary	254.40 FL	*- FL
14	1		*PANEL ASSY ,BACK DOOR TRIM ,UPPER	Not Necessary	51.20 FL	*- FL
15	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	365.20 FL	*- FL
16	1		*REAR END PANEL	Not Necessary	602.10 FL	*- FL
17	1		*TAILLAMP LOWER RH	Not Necessary	548.40 FL	*- FL
18	1		*TAILLAMP UPPER RH	Not Necessary	557.90 FL	*- FL
19	1		*REAR BUMPER SIDE RH	Not Necessary	232.00 FL	*- FL
20	1		*REAR BUMPER SIDE LH	Not Necessary	232.00 FL	*- FL
21	1		*TAILLAMP LOWER LH	Not Necessary	548.40 FL	*- FL
22	1		*TAILLAMP UPPER LH	Not Necessary	557.90 FL	*- FL
23	1		*SET PARKING AID	Shorted	700.00 FS	*200.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
25	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
27	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
28	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
29	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*52.90 FS
30	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*53.50 FS
31	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*80.00 FS
32	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*80.00 FS
33	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,683.97	1,995.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,067.14	364.35

Total Parts (\$\$)	7,616.83	1,631.45
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	400.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,200.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	30.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			10,150.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >