

Trans-cab Auto Services Pte Ltd**AAD1905-122**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7952B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7952B

JTDKB3FU403079542

TOYOTA

PRIUS

14.5.2019

All

29/3/2019

PART**LIST**

1	1 REAR BUMPER ✓	\$	458.60
2	1 REAR BUMPER RE-INFORCEMENT ?	\$	318.80
3	1 REAR BUMPER TOWING COVER ✓	\$	14.70
4	1 REAR BUMPER UNDER COVER (BLACK) ✓	\$	552.60
5	1 REAR BUMPER SIDE RETAINER LH ✕	\$	112.70
6	1 REAR BUMPER SIDE RETAINER RH ✓	\$	112.70
7	1 REAR TAILGATE ✕	\$	1,547.27
8	1 REAR TAILGATE OUTER GARNISH ✕/Myr	\$	905.10
9	1 COVER, REAR COMBINATION LAMP, RH ✕	\$	54.70
10	1 COVER, REAR COMBINATION LAMP, RH ✕	\$	54.70
11	1 GARNISH, BACK DOOR SIDE, LH ✕	\$	93.60
12	1 GARNISH, BACK DOOR SIDE, RH ✕	\$	93.60
13	1 BOARD ASSY, BACK DOOR TRIM ✕	\$	254.40
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER ✕	\$	51.20
15	1 REAR TAILGATE WEATHERSTRIP ✕	\$	365.20
16	1 REAR END PANEL ✕	\$	602.10
17	1 TAILLAMP LOWER RH ✕	\$	548.40
18	1 TAILLAMP UPPER RH ✕	\$	557.90
19	1 REAR BUMPER SIDE RH ✕	\$	232.00
20	1 REAR BUMPER SIDE LH ✕	\$	232.00
21	1 TAILLAMP LOWER LH ✕	\$	548.40
22	1 TAILLAMP UPPER LH ✕	\$	557.90

	\$	8,268.82
25%	\$	2,067.21
	\$	6,201.62

Trans-cab Auto Services Pte Ltd

AAD1905-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7952B

Special Nett

1	1SET PARKING AID	✓	\$	700.00 ²⁰⁰
2	1SET REAR BUMPER CLIP	✓	\$	22.00
3	2 REAR WINDSCREEN SELANT	X	\$	80.00
4	1 WINDSCREEN MOULDING	X	\$	100.00
5	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
6	1 REAR TAILGATE TOYOTA LOGO	X	\$	47.00
7	1 REAR TAILGATE WORDING 'PRIUS'	✓	\$	52.90
8	1 REAR TAILGATE WORDING 'HYBRID'	✓	\$	53.50
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	✓	\$	80.00
10	1 REAR TAILGATE STICKER '6555-3333'	✓	\$	80.00
11	1 REAR BUMPER PROTECTOR	✓	\$	100.00 ⁵⁰

TOTAL \$ 1,415.40**TOTAL PARTS \$ 7,617.02****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00 ⁴⁰⁰
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 ³⁰⁰
To Rust-Proofing Of The Affected Areas.	\$	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 ³⁰
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-122**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7952B

To drop rear exhaust box, renew the same, to repair and
realign centre exhaust pipe.

\$ ~~170.00~~ X

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ ~~170.00~~ X

To transfer of rear windscreen fittings and conduct water
seepage test.

\$ ~~170.00~~ X

To check steering geometry and computer wheel
alignment

\$ ~~220.00~~ X

To transfer of Rear fender fittings, attachments and
perform water seepage test.

\$ ~~170.00~~ X

TOTAL \$ 10,150.00

Over All Total \$ 23,968.63

(PART-BY-PART) Repair Days**20 DAYS**

Ka Lun (KK)

16/5/19 1700h

3 Ry,

P/P

Before Paint photo

96719299

LKK Auto Consultant's hereby notify
the Repairer of the following:

- To retain any damaged parts as a spare part only
- To retain any damaged parts as a spare part only
- Parts provided are subject to availability
- Third party's involvement is subject to basis
- No illegal modification to the vehicle
- Supplemental temporary to the original and
is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: