

To LKK Auto Consultants Pte Ltd
Ref no. CC3/AIG19008808/Kha3

Accident Involving SKR 2673U and SHB 7952B along Bartley Road on
14.05.19

Damage

SHB 7952B –Rear bumper cover
dislodged from main body of car



Minimal damage to rear main bumper,
all lights and indicators working.

SKR 2673U – Damage at Licence
plate area (Cracked)

