

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

17, May 2019

AXA Insurance PL
143 Cecil Street #01-01 GB Building
S 069542

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SJJ2226G

Accident involving vehicle no: SJU1697D/SJJ2226G

DOA: 12/05/2019 AT Along Sentosa Gateway twds the U-turn

Not Authorized
L1 Imp @ 7500L
Passing After Point

11 days

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SJU1697D

To supply—

Description	Qty	Amount
Front bumper	1	481.80 ✓
Bumper retainer @172.25	1	172.25 ✓
Bumper foglamp cover, Lh	1	181.90 X
Headlamp, Lh 1222.20	1	1,712.10 ✓
Fender, front Lh	1	731.35 ✓
Fender cowl	1	274.45 ✓
Cowling clip	1	42.00 ✓
Front door, Lh	1	1,217.10 ✓
Front door hinge @172.45	2	344.90 ✓
Front door checker	1	181.90 ✓
Front door lock	1	561.60 X
Front door outer handle-big	1	274.45 X
Front door outer handle-small	1	171.10 X
Rear door, Lh	1	1,217.85 ✓
Rear door hinge @172.10	2	344.20 ✓
Rear door lock	1	561.60 X
Rear door outer handle	1	175.25 X
Rocker panel, Lh	1	581.90 ✓
Side skirt, Lh	1	971.35 ✓
Front absorber	1	577.10 ✓
Tie rod, Lh	1	172.55 X
Brake disc roto, Lh	1	361.60 X
Nuckle arm	1	374.50 ✓
Lower arm	1	381.90 ✓
Tyre, Lh	1	220.00 3085m 665m
Rim, Lh	1	280.00 250m
Stabilizer linkage 161.20	1	395.30 ✓
Rad end	1	140.00 X

photo attached

Drive shaft,Lh	1	1,499.80	✓
Fender lamp	1	46.20	X
Center pillar	1	450.50	X

To remove/replace front triangle glass and rear fender glass.	250.00	1801
To remove/transfer front n rear door power window mechanism,doorboard, Door glass to new door.	280.00	1201
To remove center pillar garnish, safety belt,front fender inner garnish,enable Repair works carry out,reinstall after job done.	180.00	1001
To remove damaged parts and attachments.		
Straighten left side chassis where necessary.		
Cut n weld damaged panel.		
Repair/reshape damaged panel/dented areas.		
Replace/align all parts into position.	1,600.00	14001
To spray paint.	1,800.00	14001
To repair/replace undercarriage parts.	450.00	2801
Computer alignment.	80.00	601
Tow fee	80.00	501