

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

17, May 2019

AXA Insurance PL
143 Cecil Street #01-01 GB Building
S 069542

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SJJ2226G
Accident involving vehicle no: SJU1697D/SJJ2226G
DOA: 12/05/2019 AT Along Sentosa Gateway twds the U-turn

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SJU1697D
To supply—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Description	Qty	Acknowledged by Repairer	Amount	
Front bumper	1	Signature: <i>BL</i>	481.80	✓
Bumper retainer @172.25	1	Date: <i>17/5/19</i>	172.25	✓
Bumper foglamp cover, Lh	1	<i>Sn</i>	181.90	X
Headlamp, Lh	1	<i>my DIT</i>	1,712.10	✓
Fender, front Lh	1	<i>B</i>	731.35	—
Fender cowl	1	<i>CM</i>	274.45	—
Cowling clip	1	<i>MC</i>	42.00	—
Front door, Lh	1	<i>B</i>	1,217.10	✓
Front door hinge @172.45	2	<i>B</i>	344.90	✓
Front door checker	1		181.90	?
Front door lock	1	<i>R</i>	561.60	X
Front door outer handle-big	1	<i>Sn</i>	274.45	X
Front door outer handle-small	1	<i>Sn</i>	171.10	X
Rear door, Lh	1	<i>B</i>	1,217.85	✓
Rear door hinge @172.10	2		344.20	?
Rear door lock	1	<i>R</i>	561.60	X
Rear door outer handle	1	<i>Sn</i>	175.25	X
Rocker panel, Lh	1	<i>B</i>	581.90	✓
Side skirt, Lh	1	<i>CM / B</i>	971.35	—
Front absorber	1	<i>B</i>	577.10	✓
Tie rod, Lh	1		172.55	?
Brake disc roto, Lh	1		361.60	?
Nuckle arm	1	<i>B</i>	374.50	—
Lower arm	1	<i>B</i>	381.90	—
Tyre, Lh	1	<i>AT</i>	220.00	308mm @154
Rim, Lh	1	<i>— 800</i>	280.00	250mm
Stabilizer linkage	1		395.30	?
Rad end	1		140.00	?

Not Authorized
L1 Sup & ?
Resurvey After Paint

11 days

Drive shaft,Lh	1	1,499.80	?
Fender lamp	1	46.20	X
Center pillar	1	450.50	X

To remove/replace front triangle glass and rear fender glass.

250.00 1801

To remove/transfer front n rear door power window mechanism,doorboard,
Door glass to new door.

280.00 1201

To remove center pillar garnish, safety belt,front fender inner garnish,enable
Repair works carry out,reinstall after job done.

180.00 1001

To remove damaged parts and attachments.

Straighten left side chassis where necessary.

Cut n weld damaged panel.

Repair/reshape damaged panel/dented areas.

Replace/align all parts into position.

1,600.00 14001

To spray paint.

1,800.00 14001

To repair/replace undercarriage parts.

450.00 2801

Computer alignment.

80.00 601

Tow fee

80.00 501