

REF:

AIG CCB/AIG19008810/Ayd307

Mennen

ASSIGNMENT

From:

Date:

17/5/19

Estimated Cost:

☒ QD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ RV / ☐ MV

To inspect Vehicle No.

SKT9762P

at Workshop no.

Premium

of

55 ubi Rd 1

Insured:

Policy No.

2100419561-03

Claims No.

068449273456

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

NIS	QIS

Est. or Market Value:

IDAC Accident Report

Consistent? Yes or No

GIA / PH Status:

Consistent? Yes or No

Est. Repairs:

days:

Rm: Yes or No

Lump Sum:

%

1 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKT9762P-

Veh Insp:

2015, June

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan.

cc 1395

Colour:

Black

ABC Insured / Std / Nil / NA

Sp Reading:

42298

T/Saler, Insured / Std / Nil / NA

Eng/No:

Chassis:

WAUZZZSV1F1044350

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: Nil / ☒ SB3m / ☐ STD A/Rim or

Tyre Size:

F:

225/45 R17.

R:

225/45 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A.

08/5/19

D.O.A.

17/05/19

Survey held at

Premium.

Des. of Damages: ☐ Fit / ☐ Rear / ☒ QIS / ☐ NIS / ☒ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ODAIG.

Total Loss.

7/5/19

SKT9762P-CCB/AIG19001513/Uph3g2
@ 11.18am revert to Prasanna Srin in Mennen.

DOR/17/5/2019

MV: 72K

PV: 51.9K

Nett: 20.1K.

RECEIVED 23 MAY 2019

7/5/19

Submit Uniconomical Total Loss report.

Date/Time, File Pass to?

☐

: Prel. Report

11/5/19

☐

: Final Report

Date/Time, File Return to?

29

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format:

AIGR-00/74/1

Lump Sum / I.B.E. (\$)

Survey Fee:

Transportation:

2 + 100 = 102

Photos

Others

TOTAL

200

10

210

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 21 May 2019 11:22 AM
To: Sim, Priscilla-LK
Cc: SUR
Subject: OD VEHICLE SKT 9762P (YOUR REF: 06844927345G)

Dear Ms Sim,

Please be informed owner that the vehicle not economical for repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 May 2019

Preliminary Advice

Vehicle No.	: SKT9762P	Accident Date	: 08/05/2019
Make	: AUDI A3	Policy No.	: 2100419561-03
Assignment Date	: 17/05/2019	Excess	: S\$0.00
Date of Inspection	: 17/05/2019	Est. Duration of Repair	: 28.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s & n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	94,465.00
Revised Amount	:S\$	60,789.00
Check Items (Estimated)	:S\$	11,984.00
Total	:S\$	72,773.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	51,909.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,091.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	9643J
Vehicle Details	
Vehicle No.:	SKT9762P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI AMBIENTE (NAV) MY 15
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CZC209981
Chassis No.:	WAUZZZ8V1F1044350
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$30,396.00
Original Registration Date:	26 Jun 2015
First Registration Date:	26 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$19,555.00
PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2025
PARF Rebate Amount:	\$14,666.00
COE Details	
COE Expiry Date:	25 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$37,243.00
Total Rebate Amount:	\$51,909.00

The information contained herein is correct as at 17 May 2019

OK

FOR SALE BY OWNER
 **Post an Advertisement**
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Jan 2010. Tip Top Condition. 50k Mileage Only!!
 Super Rural Efficient And Super Low Mileage.
 Call Us Today StarAd

P PRIME MOTOR & LEASING
 (RENTAL FLEET) CHIEF EXECUTIVE OFFICER'S FLEET MANAGER (COMMERCIAL)
 With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

[Browse by Category](#)
[Save Search](#)
[Print](#)
[Sort by Date Posted](#)
[20 results/page](#)

8 vehicles | **Search** Audi A3

Search Selection	Audi A3	Any	Any	2015	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----------

 ☐ Audi A3 Sedan 1.4A TFSI Ambiente (OPC) \$62,000 \$9,290 /yr 26-Mar-2015 1,395 cc 55,000 km Luxury Available

Fully Maintained And Serviced By Agent Premium Automobiles Since The Very First Day, 1 Owner Unit. Kept In Pristine Condition Inside Out. 100% Accident Free. STA Checks Welcome. Loan And Trade-In Avail...

Monster Motors Pte Ltd

 Protect 24-Mar-2015 Tags: 2015-audi-a3, 2015-audi-a3-1.4tfsi, 2015-audi-a3-1.4tfsi-ambiente, 2015-audi-a3-1.4tfsi-ambiente-opc

 ☐ Audi A3 Sedan 1.4A TFSI Ambiente \$72,800 \$11,140 /yr 26-Mar-2015 1,395 cc 62,500 km Luxury Available

Enjoy Low Interest Rates Offer Till This Month End! High Trade In! Full Agent Serviced By Premium Auto. Flexible Loan Packages With Low Interest And Monthly Instalments! Comes With Original 53 18" RL...

Euro Performance Asia Pte Ltd

☆ Posted: 24-Mar-2015 Tags: 2015 Audi A3, 2015 audi a3, Audi A3, audi a3, Audi, A3, a3, Used Audi



☐ Audi A3 Sedan 1.4A TFSI Ambiente

\$71,700

\$10,950 /yr

26-Mar-2015

1,395 cc

43,600 km

Luxury

Available

1 Owner Fully Maintained By Agent Premium Automobiles Since Day 1. Option To Extend Agent Warranty. Excellent Condition With Black On Black Combination. STA Checks Welcome. Buy With A Peace Of Mind. Hi...

Monster Motors Pte Ltd


 Posted: 15-Mar-2015
 Topic: 2015 Audi A3, 2015 audi a3, Audi A3, audi a3, Audi A3, a3, Used Audi

 ☐ Audi A3 Sedan 1.4A TFSI Ambiente \$69,800 \$10,620 /yr 27-Mar-2015 1,395 cc 58,000 km Luxury Available

1 Owner, Black On Black Combination, Fully Maintained And Serviced By Premium Automobiles! View To Believe! Call Us Now To Arrange Viewing!

 Posted: 14-May-2019 Tags: 2015 Audi A3, 2015 audi a3, Audi A3, audi a3, Audi, A3, a3, Used Audi

 Car Buying •
  Car Selling •
  Car Ownership •
  Car Aftermarket •
  On The Move •
  Lifestyle •
  **Buying a pre-owned car, but Unsure of its Condition?**
Get [STP CarCheck](#)

 ☐ Audi A3 Sedan 1.4A TFSI Ambiente \$77,800 \$10,950 /yr 15-Jul-2015 1,395 cc 58,195 km Luxury Available

Low-Interest Rate. 1 Year Warranty. Maintained By Premium Automobiles. Balloon Scheme, In-House Financing Options Available. Buy With A Peace Of Mind. 1 Owner. Low Mileage. 100% Genuine Mileage. No Ch...

Go Wheeler Pte Ltd

★ Posted: 13-May-2019 Tags: 2015 Audi A3, 2015 audi A3, Audi A3, audi A3, Audi A3, A3, A3, Used Audi

 ☐ Audi A3 Sedan 1.4A TFSI Ambiente **\$75,800** **\$10,490 /yr** **12-Aug-2015** **1,395 cc** **73,138 km** **Luxury** **Available**
\$800 Warranty Workshop Credits, 1 Year Warranty Cover Engine And Gear Box By Our Authorized Workshop, Full Servicing Records, Can Arrange For STA Evaluation, Well Maintained By Previous Owner, Drive W...
 Accendore Autolution Pte Ltd
 Posted: 16-May-2019 Page: 2015 Audi A3, 2015 audi a3, Audi A3, audi a3, Audi A3, a3, Used Audi

Model	Price	Lease	Year	Engine	Km	Body	Availability
☐ Audi A3 Sportback 1.4A TFSI S-tronic Ambiente	\$76,800	\$10,660 /yr	27-Aug-2015	1,395 cc	47,000 km	Hatchback	Available



High Loan Available, Low Interest Rate At 2.28%! Full Agent Maintained, Low Mileage, Flexible Bank/In House Loan Available, Excellent Fuel Efficiency, Up To 18km/L, Immaculate Condition, 100% Accident...

PREMIUM AD

Autotraders Traders Pte Ltd

☆ Posted: 15-May-2019 Tags: 2015 Audi A3, 2015 audi a3, Audi A3, audi a3, Audi A3, a3, Used Audi



☐ Audi A3 Sedan 1.4A TFSI Ambiente

\$81,999

\$11,100 /yr

30-Oct-2015

1,395 cc

46,000 km

Luxury

Available

Audi Approved Plus (Unit) Low Mileage. Flexible Financing And Trade In Are Available, Low Interest 2.28%. Pls Call/ SMS For More Detail And Viewing Appointment Before Is Sold!

PREMIUM AD

Premium Automobiles

☆ Posted: 05-May-2019 Tags: 2015 Audi A3, 2015 audi a3, Audi A3, audi a3, Audi A3, a3, Used Audi

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make ▼ Model ▼ Price ▼ Depreciation ▼ Reg Date ▼ Eng Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

For old advertisements, view Expired ads

20 ▼ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A3, Audi A3 Singapore, used Audi A3 Singapore, used Audi A3, used vehicles Singapore or even buy used Audi A3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, shower, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



Download on the
App Store



GET IT ON
Google play

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 21:41
Date Of Accident	08/05/2019 01:45
Exact Location Of Accident	PIE TOWARDS TUAS (ADAM ROAD EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9762P
Insured/Policyholder	
Name Of Registered Owner	AUYONG SZE LINDA
NRIC No	S1239643J
Email Address	LINDADORNEL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98248183
Alternative Phone No	OTHERS-91236231

Vehicle Particulars

Manufacturer	AUDI
Model	A3-1.4 SEDAN TFSI (AMBIENTE) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100419561-03
Cover Note Number	

Driver

Name of Driver	JONATHAN MING AUYONG DORNEL
NRIC No	S9890661D
Date Of Birth	08/07/1998
Occupation	INDOOR
Date Of Driving Pass	08/08/2018
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91236231
Fax Number	
Contact Number	
Email Address	JONATHAN.D98@HOTMAIL.COM

Address	3 TAMAN WARNA #D1-05
Postcode	276340
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SHAWN TAN FU YU GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT 145 AM ON 8/5/19, WHILE ON THE CURVE OF ADAM RD EXIT ON PIE, THE ROAD WAS WET AND DURING THE TURN, THE TIRE DISENGAGED. THE LAST WARNING LIGHT I SAW A MOMENT BEFORE THE INCIDENT WAS THE BREAK PADS WARNING. I WAS TRAVELLING AT ROUGHLY 60 KM/H DURING THE INCIDENT. EMAS TOWED THE VEHICLE TO TURF CITY AND FROM THERE AUDI HELPED TO TOW THE VEHICLE TO UBI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Chang Chee Sing
NRIC/VIN No.:

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 145 AM^{25/11} while on the curve of Adam Rd exit on PIE, the road was wet and during the turn, the tire disengaged. The last warning light I saw & moment before the incident was the brake pads warning. I was travelling at roughly 60 km/h during the incident. EMAS towed the vehicle to the city and from there outside helped to tow the vehicle to Uai.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Chang Choe Sing
NRIC/ID No:

Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #04-03 Singapore 048640
 Tel: (65) 6224 6000 Fax: (65) 6224 0000
 Operating hours: Monday to Friday, 09:00 - 17:00
 UEN: S46639900 / GST Reg. No.: M480017781

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 119052292 Vehicle Registration No: SKT 9762P
 Name (as shown in NRIC): Anyang Sze Linda NRIC/FIN/Passport No: S1239643J
 (* Vehicle Driver / Vehicle Owner) (* Please delete as appropriate)
 Address: 3 Temasek, Wema, #01-05 Singapore: 276340
 Contact (Tel): _____ Mobile No: 98248183
 Email Address: lindaadornel@gmail.com
 Date of Accident: 08/05/2019 Time of Accident: 01:15
 Place of Accident: PTE towards Tuas (Adam Road exit)
 Insurance Company: ACB Asia Pacific Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

1) To amend "reporting only" to "Own Damage".

2) To amend Type of Accident from "Collided with property" to "No collision".

3) To add in Passenger information.

Passenger is Mr. Shawn Tan. Fu Yu S8922903E

Policyholder/Owner's Signature
 Date: 16/5/19

Reporting Centre Personnel's Signature
 Name: Chang Chee Sing
 NRIC/FIN No: S224817101
 Date: 15/5/19



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : AUYONG SZE LINDA
 Period of Insurance : 26 Jun 2018 To 25 Jun 2019
 Engine No. : C2C209981
 Chassis No. : WAUZZZ8V1F1044350

Vehicle No. : SKT9762P
 Policy No. : 2100419561-03
 Endorsement No. : 000000000201474
 Issued Date : 18 May 2018

ABOUT THE COVER

Make/Model : AUDI A3 SEDAN 1.4 TFSI (AMBIENTE PLUS)
 Engine Capacity/Tonnage : 1,395.00 CC Sum Insured : Market Value First Year of Registration : 2015
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

AUYONG SZE LINDA - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9890661D



Name

JONATHAN MING AUYONG
DORNEL

歐陽錦

Race

EURASIAN

Date of birth

08-07-1998 M

Country of birth

HONG KONG SAR

S9890661D

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S9890661D

JONATHAN MING AUYONG DORNEL

Birth Date: 08 Jul 1998

Issue Date: 08 Aug 2018



002833045G



4863118

NRIC No: S9890661D



Date of issue
18-04-2013

3 TAMAN WARNA #01-05
SINGAPORE 276340

NRIC No: S9890661D

Date: 23/11/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 08 Aug 2018



Licence No: S9890661D

NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0628/2019/DY/CCS
Date	:	15-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Auyong Sze Linda
Address	:	3 Taman Warna #01-05 Singapore 276340
Telephone	:	HP +65 98248183
Type of Claim	:	Own Damage Claims
Policy No.	:	2100419561-03
Vehicle No	:	SKT 9762 P
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	Jun-15
Engine No	:	CZC 209981
Chassis No	:	WAUZZZ8V1F1044350
Mileage	:	42298 KM
Date In	:	8-May-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-May-19
Place of Accident	:	PIE towards Tuas (Adam Rd Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 9762 P

S/N	Nature of Jobs		Estimated Charges	Surveyor Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	TBC	✓
2	To carry out first measurement test on car o-liner.	S/N \$	800.00	?
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓
4	To remove and reinstall rear parking aid. Check function.	S/N \$	280.00	✓
5	To renew front windscreen.	S/N \$	480.00	✓
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 1,920.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 9762 P

S/N	Nature of Jobs		Estimated Charges	Surveyor Recommendation
6	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N	\$ 600.00	✓
7	To dislodge and reinstall RHS A-pillar, door harness, rear wire harness, battery manager, fuse and relay trays, audio and electrical components.	S/N	\$ 1,800.00	✓
8	To remove and reinstall centre console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N	\$ 3,200.00	✓
9	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 560.00	✓
10	To remove and reinstall front and rear seat assy, back rest, ABCD pillar trims, safety belts, carpets and sill trims, etc. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,800.00	✓
SUB-TOTAL LABOUR CHARGES		:	\$ 9,880.00	

7960

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 9762 P

S/N	Nature of Jobs		Estimated Charges	Surveyor Recommendation
11	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N	\$ 2,800.00	?
12	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,800.00	✓
13	To remove and reinstall exhaust system and rear suspension assembly. Renew accordingly.	S/N	\$ 2,400.00	✓
14	To remove and renew fuel tank assy.	S/N	\$ 600.00	✓
15	To set-up vehicle on car o-liner for repair.	S/N	\$ 2,400.00	?
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 22,800.00</u>	

11000

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 9762 P

S/N	Nature of Jobs	Estimated Charges	Surveyor Recommendation
16	To dismantle front bumper, rhs front fender, rhs headlight, rhs front door, rhs rear door, rear bumper and rear lid. Cut out and reweld rhs A-pillar, rhs sill pannel and rhs rear fender. To renew front bumper, rhs front fender, rhs headlight, rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 12,250.00	5000
17	To respray front bumper, both front fenders, rhs A-pillar, rhs sill panel, rhs front door, rhs rear door, rhs rear fender, rear bumper, door entrance, roof channel, drain channel and end panelling. To carry out joint sealant work and stone chip treatment.	\$ 9,300.00	4400
18	To renew rhs front rim and tyre and rhs rear rim and tyre. To carry out wheel alignment.	S/N \$ 320.00	✓
19	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 45,054.00	43134

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	+
3	FRONT BUMPER COVER TRIM - LH/RH <i>2nd Dmgd</i>	2 \$ 296.00	198-
4	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	\$ 148.00	✓
5	FRONT BUMPER PULL STRAP <i>new</i>	\$ 187.00	+
6	FRONT BUMPER GUIDE - RH <i>Dmgd</i>	\$ 35.00	✓
7	FRONT BUMPER AIR GRILLE - RH <i>Missing</i>	\$ 99.00	✓
8	FRONT BUMPER AIR GRILLE - LH <i>new</i>	\$ 99.00	+
9	RADIATOR GRILLE <i>new</i>	\$ 637.00	+
10	RADIATOR GRILLE BACK COVER <i>new</i>	\$ 89.00	+
11	SIGN 'CAUTION' STICKER <i>new</i>	\$ 13.00	+
12	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 7.00	+
13	FRONT REINFORCEMENT BEAM <i>3</i>	\$ 660.00	+
14	FRONT BUMPER FOAM - INNER <i>new</i>	\$ 125.00	+
15	FRONT BUMPER FOAM COVER	\$ 51.00	+
16	FRONT FENDER - RH <i>Distorted</i>	\$ 778.00	✓
17	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 65.00	✓
18	FRONT FENDER BRACKET - RH REAR <i>2 distorted</i>	\$ 25.00	✓
19	FRONT FENDER BRACKET - RH FRONT	\$ 35.00	✓
20	FRONT FENDER RIVET SET <i>new</i>	\$ 15.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 5,364.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACE - RH <i>bet</i>	\$ 88.00	✓
22	FRONT FENDER CLOSING ELEMENT - RH	\$ 30.00	✓
23	FRONT FENDER INSULATION - RH	\$ 38.00	✓
24	FRONT WHEEL HOUSING LINER SEAL - RH	\$ 31.00	✓
25	FRONT WHEEL HOUSING LINER - RH	\$ 158.00	✓
26	WHEEL HOUSING LINER ATTACHMENT PARTS <i>me</i>	\$ 81.00	✓
27	HEADLIGHT - RH <i>cancel</i>	\$ 1,825.00	✓
28	HEADLIGHT GAS DISCHARGE BULB	\$ 398.00	+
29	POWER MODULE FOR DAY DRIVING LIGHT	\$ 522.00	+
30	DISCHARGE LAMP CONTROL UNIT	\$ 1,051.00	+
31	HEADLIGHT WASHER CYLINDER	\$ 181.00	+
32	HEADLIGHT WASHER HOSE	\$ 170.00	+
33	SIDE BODY PANEL FRAME - RH <i>distorted</i>	\$ 3,273.00	✓
34	RIVETTED CAP NUT <i>me</i>	4 \$ 6.00	✓
35	FRONT WINDSCREEN <i>not me</i>	\$ 988.00	+
36	FRONT WINDACREEN GEL FOIL <i>me</i>	\$ 128.00	+
37	SPRING CLIP <i>me</i>	\$ 20.00	+
38	REAR WINDSCREEN <i>not me</i>	\$ 742.00	✓
39	REAR SIDE 1/ GLASS - RH <i>not me</i>	\$ 520.00	✓
40	FRONT DOOR - RH <i>distorted</i>	\$ 2,279.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 12,529.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FRONT DOOR SEAL - RH <i>per</i>	\$ 146.00	✓
42	BONDING AGENT ?	\$ 45.00	?
43	CLEANING SOLUTION ?	\$ 65.00	?
44	DOOR APPLICATOR ?	\$ 7.00	?
45	FRONT DOOR ATTACHMENT PARTS ? <i>per</i>	\$ 218.00	?
46	FRONT DOOR CATCH - RH <i>per</i>	\$ 96.00	✓
47	FRONT DOOR HINGE - RH <i>per</i>	\$ 75.00	✓
48	FRONT DOOR CORNER TRIM - RH <i>per</i>	\$ 41.00	✓
49	FRONT WINDOW GUIDE CHROME TRIM - RH <i>per</i>	\$ 235.00	✓
50	FRONT WINDOW SLOT CHROME TRIM - RH <i>per</i>	\$ 282.00	✓
51	DATA PLATE FOR TYRE PRESSURE <i>per</i>	\$ 26.00	✓
52	VEHICLE CHASSIS DATA TAG <i>per</i>	\$ 423.00	✓
53	FRONT DOOR WINDOW GLASS - RH <i>per</i>	\$ 211.00	✓
54	REAR DOOR - RH <i>Revised</i>	\$ 2,279.00	✓
55	REAR DOOR SEAL - RH <i>per</i>	\$ 146.00	✓
56	BONDING AGENT ?	\$ 45.00	?
57	CLEANING SOLUTION ?	\$ 65.00	?
58	DOOR APPLICATOR ?	\$ 7.00	?
59	REAR DOOR ATTACHMENT PARTS ?	\$ 118.00	?
60	FRONT DOOR ENTRANCE SILL TRIM - RH <i>per</i>	\$ 115.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,645.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	REAR DOOR ENTRANCE SILL TRIM - RH <i>new</i>	\$ 63.00	✓
62	REAR WHEEL HOUSING LINER - RH <i>new</i>	\$ 223.00	✓
63	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 81.00	✓
64	REAR BUMPER GUIDE - RH <i>new</i>	\$ 60.00	✓
65	ENGINE UNDERBODY NOISE INSULATION - FRONT <i>lot</i>	\$ 239.00	✓
66	UNDERBODY TRIM - RH <i>torn</i>	\$ 160.00	✓
67	FUEL TANK <i>lot</i>	\$ 2,396.00	✓
68	FUEL TANK SEAL RING <i>3 new</i>	\$ 39.00	✓
69	FUEL TANK BOLT SET	\$ 31.00	✓
70	FUEL TANK SEAL RING	\$ 24.00	✓
71	FUEL TANK TENSIONING STRAP <i>new</i>	\$ 70.00	✓
72	REAR EXHAUST SILENCER	\$ 663.00	✓
73	REAR EXHAUST SILENCER BRACKET <i>2 new</i>	\$ 75.00	✓
74	REAR EXHAUST SILENCER DUAL CLIP	\$ 55.00	✓
75	FRONT EXHAUST SILENCER <i>new</i>	\$ 452.00	✓
76	FRONT SUSPENSION SUPPROT CARRIER <i>Best</i>	\$ 940.00	✓
77	SUPPORT CARRIER BOLT SET <i>?</i>	\$ 114.00	?
78	SUPPORT CARRIER RUBBER BUSER SET <i>new</i>	\$ 151.00	✓
79	ALUMINIUM RIM - RH FRONT / RH REAR <i>lot of</i>	\$ 1,408.00	✓
80	FRONT TRACK CONTROL ARM - RH <i>Best</i>	\$ 336.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 7,580.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	FRONT TRACK CONTROL ARM BOLT SET <i>Best</i>	\$ 43.00	✓
82	FRONT STABILIZER BAR <i>Best</i>	\$ 372.00	✓
83	FRONT STABILIZER BAR BOLT SET <i>Best</i>	\$ 16.00	✓
84	FRONT WHEEL BEARING HOUSING - RH <i>2nd</i>	\$ 532.00	✓
85	FRONT WHEEL BEARING - RH <i>re</i>	\$ 442.00	✓
86	FRONT WHEEL BEARING BOLT SET <i>Best</i>	\$ 15.00	✓
87	FRONT GUIDE JOINT - RH <i>Best</i>	\$ 117.00	✓
88	FRONT GUIDE JOINT BOLT SET <i>Best</i>	\$ 10.00	✓
89	FRONT COUPLING ROD - RH <i>Best</i>	\$ 88.00	✓
90	FRONT GAS SHOCK ABSORBER - RH <i>Best</i>	\$ 251.00	✓
91	GAS SHOCK ABSORBER BOLT SET <i>Best</i>	\$ 25.00	✓
92	FRONT GAS ABSORBER BEARING - RH UPPER <i>new</i>	\$ 43.00	✓
93	FRONT GAS ABSORBER STRUT STORAGE - RH <i>Best</i>	\$ 114.00	✓
94	STRUT STORAGE BOLT SET <i>Best</i>	\$ 25.00	✓
95	FRONT DRIVE SHAFT - RH <i>Best</i>	\$ 2,005.00	✓
96	FRONT DRIVE SHAFT BOLT SET <i>2nd</i>	\$ 52.00	✓
97	STEERING GEAR <i>Best</i>	\$ 4,649.00	✓
98	STEERING GEAR TIE ROD END - RH <i>Best</i>	\$ 118.00	✓
99	STEERING GEAR TRACK ROD - RH <i>Best</i>	\$ 86.00	✓
100	FRONT BRAKE LINE <i>Distorted</i>	\$ 86.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 9,089.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	FRONT BRAKE VACUUM PIPE - RH ?	\$ 124.00 ?	
102	FRONT BRAKE SERVO - RH ?	\$ 559.00 ?	
103	FRONT BRAKE SERVO SEAL ?	\$ 17.00 ?	
104	FRONT BRAKE HEAT SHIELD - RH ?	\$ 93.00 ?	
105	FRONT BRAKE CALIPER HOUSING - RH <i>nd</i>	\$ 370.00 ✓	
106	FRONT BRAKE CALIPER BOLT SET <i>set</i>	\$ 22.00 ✓	
107	FRONT BRAKE CARRIER - RH <i>nd</i>	\$ 268.00 ✓	
108	FRONT BRAKE PAD SET - RH <i>na</i>	\$ 217.00 ✓	
109	FRONT BRAKE DISC - RH <i>nd</i>	\$ 153.00 ✓	
110	FRONT BRAKE DISC BOLT SET <i>set</i>	\$ 24.00 ✓	
111	FRONT BRAKE DISC COVER PLATE - RH <i>set</i>	\$ 59.00 ✓	
112	REAR BRAKE CALIPER HOUSING - RH ?	\$ 394.00 ?	
113	REAR BRAKE CALIPER BOLT SET ?	\$ 20.00 ?	
114	BRAKE CALIPER LUBRICATING GREASE ?	\$ 144.00 ?	
115	REAR BRAKE CALIPER CARRIER - RH <i>could</i>	\$ 154.00 ✓	
116	REAR BRAKE CALIPER SERVOMOTOR - RH ?	\$ 1,001.00 ?	
117	REAR BRAKE DISC - RH ?	\$ 130.00 ?	
118	REAR SERVOMOTOR ASSEMBLY PARTS ?	\$ 16.00 ?	
119	REAR BRAKE DISC COVER PLATE - RH ?	\$ 59.00 ?	
120	REAR BRAKE DISC COVER PLATE BOLT SET ?	\$ 20.00 ?	
SUB-TOTAL SPARE PARTS CHARGES		\$ 3,844.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
121	REAR SUSPENSION SUPPORT FRAME ?	\$ 1,325.00	?
122	REAR TRACK ROD - RH Bent	\$ 84.00	✓
123	REAR TRACK ROD BOLT SET Bent	\$ 25.00	✓
124	REAR COUPLING ROD - RH Bent	\$ 72.00	✓
125	REAR COUPLING ROD BOLT SET Bent	\$ 12.00	✓
126	REAR ANTI-ROLL BAR new	\$ 229.00	x
127	REAR SUSPENSION BRACKET - RH ?	\$ 133.00	?
128	REAR COVER CAP FOR BEARING SUPPORT - RH ?	\$ 6.00	?
129	REAR SUSP. BRACKET BOLT SET ?	\$ 59.00	?
130	REAR AXLE GUIDE - RH Bent	\$ 405.00	✓
131	REAR WISHBONE - RH LOWER Bent	\$ 263.00	✓
132	REAR WISHBONE BOLT SET Bent	\$ 28.00	✓
133	REAR WISHBONE RUBBER BUSH m	\$ 27.00	✓
134	REAR WISHBONE - RH UPPER Bent	\$ 259.00	✓
135	REAR WHEEL BEARING HOUSING - RH Bent	\$ 662.00	✓
136	REAR WHEEL BEARING - RH m	\$ 452.00	✓
137	REAR WISHBONE STONE CHIP GUARD - RH m	\$ 8.00	✓
138	REAR GAS SHOCK ABSORBER - RH Bent	\$ 228.00	✓
139	REAR SHOCK ABSORBER BOLT SET Bent	\$ 33.00	✓
140	REAR STOP BUFFER m	\$ 56.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,366.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9762 P

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
141	REAR SHOCK ABSORBER BEARING - RH <i>me</i>	\$ 94.00	✓
142	FRONT NO. PLATE <i>me</i>	S/N \$ 40.00	X
143	ACRYLIC SEALER <i>2</i>	S/N \$ 360.00	✓
144	CAVITY WAX <i>me</i>	S/N \$ 280.00	✓
145	STONE CHIP	S/N \$ 360.00	✓
146	METAL FILLER POWDER <i>me</i>	S/N \$ 280.00	✓
147	FRONT WINDSCREEN SEALANT <i>me</i>	S/N \$ 200.00	X
148	REAR WINDSCREEN SEALANT <i>2</i>	S/N \$ 200.00	✓
149	REAR 1/4 GLASS SEALANT <i>me</i>	S/N \$ 100.00	✓
150	PIRELLI TYRE - RH FRONT / RH REAR <i>Front</i>	2 \$ 800.00	<i>400</i>
151	SUNDRIES <i>?</i> <i>Resolved</i>	\$ 1,200.00	<i>?</i>
TOTAL SPARE PARTS CHARGES		\$ 51,331.00	
TOTAL LABOUR CHARGES		\$ 45,054.00	<i>43134</i>
GRAND TOTAL		\$ 96,385.00	<i>94465</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 17/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 28 Days.

LOR Auto Consultants hence notify the Employer of the following:

- To survey below after survey starting
- To survey damaged parts during survey
- To survey parts are subject to confirmation
- To survey survey is on a "Without Prejudice" basis
- To sign survey report is issued
- To sign survey report must be surveyed and approved by the appropriate Insurance Company

Authorised by Reparer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main:	14 May 2019		17 May 2019 17:05 Edit Adj Rpt	S\$60,789.00 Edit Estimates	S\$60,789.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AUYONG SZE LINDA, ID: S12396431, Tel: +6598248183		
Vehicle Reg. No.:	SKT9762P	Date of Loss:	08/05/2019 01:00 - :59 [46 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 0684492734SG	Policy/Cover Note No.:	2100419561-03 (Comprehensive)
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Sim, Priscilla-LK - 6419 1755] Priscilla-lk.sim@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/05/2019]		
Driver/Custodian:	JONATHAN MING AUYONG DORNEL (20 / Male) , NRIC: S9890661D, Tel: +6591236231 Email: JONATHAN.D98@HOTMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKT9762P (0684492734SG)
OD**

**May 8 2019 1:45AM
[AUYONG SZE LINDA]
Premium Automobiles Pte Ltd**

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	21/05/19 11:17	Adjuster Immediate Advice	Load HTML		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	21/05/19 09:32	General View	Load JPG	☒	
2	21/05/19 09:32	Chassis Number	Load JPG	☒	
3	21/05/19 09:32	General View	Load JPG	☒	
4	21/05/19 09:32	General View	Load JPG	☒	
5	21/05/19 09:32	General View	Load JPG	☒	
6	21/05/19 09:32	General View	Load JPG	☒	
7	21/05/19 09:32	General View	Load JPG	☒	
8	21/05/19 09:32	General View	Load JPG	☒	
9	21/05/19 09:32	General View	Load JPG	☒	
10	21/05/19 09:32	General View	Load JPG	☒	
11	21/05/19 09:32	General View	Load JPG	☒	
12	21/05/19 09:32	General View	Load JPG	☒	
13	21/05/19 09:32	General View	Load JPG	☒	
14	21/05/19 09:32	General View	Load JPG	☒	
15	21/05/19 09:32	General View	Load JPG	☒	
16	21/05/19 09:32	General View	Load JPG	☒	
17	21/05/19 09:32	General View	Load JPG	☒	
18	21/05/19 09:32	General View	Load JPG	☒	
19	21/05/19 09:32	General View	Load JPG	☒	
20	21/05/19 09:32	General View	Load JPG	☒	
21	21/05/19 09:32	General View	Load JPG	☒	
22	21/05/19 09:32	General View	Load JPG	☒	
23	21/05/19 09:32	General View	Load JPG	☒	
24	21/05/19 09:32	General View	Load JPG	☒	
25	21/05/19 09:32	General View	Load JPG	☒	
26	21/05/19 09:32	General View	Load JPG	☒	
27	21/05/19 09:32	General View	Load JPG	☒	
28	21/05/19 09:32	General View	Load JPG	☒	
29	21/05/19 09:32	General View	Load JPG	☒	
30	21/05/19 09:32	General View	Load JPG	☒	
31	21/05/19 09:32	General View	Load JPG	☒	
32	21/05/19 09:32	General View	Load JPG	☒	
33	21/05/19 09:32	General View	Load JPG	☒	
34	21/05/19 09:32	General View	Load JPG	☒	
35	21/05/19 09:32	General View	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	21/05/19 09:32	General View	 Load JPG	☒
37	21/05/19 09:32	General View	 Load JPG	☒
38	21/05/19 09:32	General View	 Load JPG	☒
39	21/05/19 09:32	General View	 Load JPG	☒
40	21/05/19 09:32	General View	 Load JPG	☒
41	21/05/19 09:32	General View	 Load JPG	☒
42	21/05/19 09:32	General View	 Load JPG	☒
43	21/05/19 09:32	General View	 Load JPG	☒
44	21/05/19 09:32	General View	 Load JPG	☒
45	21/05/19 09:32	General View	 Load JPG	☒
46	21/05/19 09:32	General View	 Load JPG	☒
47	21/05/19 09:32	General View	 Load JPG	☒
48	21/05/19 09:32	General View	 Load JPG	☒
49	21/05/19 09:32	General View	 Load JPG	☒
50	21/05/19 09:32	General View	 Load JPG	☒
51	21/05/19 09:32	General View	 Load JPG	☒
52	21/05/19 09:32	General View	 Load JPG	☒
53	21/05/19 09:32	General View	 Load JPG	☒
54	21/05/19 09:32	General View	 Load JPG	☒
55	21/05/19 09:32	General View	 Load JPG	☒
56	21/05/19 09:32	General View	 Load JPG	☒
57	21/05/19 09:32	General View	 Load JPG	☒
58	21/05/19 09:32	General View	 Load JPG	☒
59	21/05/19 09:32	General View	 Load JPG	☒
60	21/05/19 09:32	General View	 Load JPG	☒
61	21/05/19 09:32	General View	 Load JPG	☒
62	21/05/19 09:32	General View	 Load JPG	☒
63	21/05/19 09:32	General View	 Load JPG	☒
64	21/05/19 09:32	General View	 Load JPG	☒
65	21/05/19 09:32	General View	 Load JPG	☒
66	21/05/19 09:32	General View	 Load JPG	☒
67	21/05/19 09:32	General View	 Load JPG	☒
68	21/05/19 09:32	General View	 Load JPG	☒
69	21/05/19 09:32	General View	 Load JPG	☒
70	21/05/19 09:32	General View	 Load JPG	☒
71	21/05/19 09:32	General View	 Load JPG	☒
72	21/05/19 09:32	General View	 Load JPG	☒
73	21/05/19 09:32	General View	 Load JPG	☒
74	21/05/19 09:32	General View	 Load JPG	☒
75	21/05/19 09:32	General View	 Load JPG	☒
76	21/05/19 09:32	General View	 Load JPG	☒
77	21/05/19 09:32	General View	 Load JPG	☒
78	21/05/19 09:32	General View	 Load JPG	☒
79	21/05/19 09:32	General View	 Load JPG	☒
80	21/05/19 09:32	General View	 Load JPG	☒
81	21/05/19 09:32	General View	 Load JPG	☒
82	21/05/19 09:32	General View	 Load JPG	☒
83	21/05/19 09:32	General View	 Load JPG	☒
84	21/05/19 09:32	General View	 Load JPG	☒
85	21/05/19 09:32	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	21/05/19 09:32	General View	 Load JPG	☒
87	21/05/19 09:32	General View	 Load JPG	☒
88	21/05/19 09:32	General View	 Load JPG	☒
89	21/05/19 09:32	General View	 Load JPG	☒
90	21/05/19 09:32	General View	 Load JPG	☒
91	21/05/19 09:32	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/19 09:31	Singapore Accident Statement	 Load PDF	
2	21/05/19 09:31	Certificate of Insurance	 Load PDF	
3	21/05/19 09:31	Driver's Driving License	 Load PDF	
4	21/05/19 09:32	ESTIMATE	 Load PDF	
5	21/05/19 09:32	Log card (if available)	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/05/19 22:55	Accident Statement	 Load HTM	
2	16/05/19 17:56	Addendum Sheet	 Load JPG	☒
3	16/05/19 17:57	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/05/19 22:20	Accident Photo	 Load JPG	☒
2	13/05/19 22:20	Accident Photo	 Load JPG	☒
3	13/05/19 22:20	Accident Photo	 Load JPG	☒
4	13/05/19 22:20	Accident Photo	 Load JPG	☒
5	13/05/19 22:20	Accident Photo	 Load JPG	☒
6	13/05/19 22:20	Accident Photo	 Load JPG	☒
7	13/05/19 22:20	Accident Photo	 Load JPG	☒
8	13/05/19 22:20	Accident Photo	 Load JPG	☒
9	13/05/19 22:20	Accident Photo	 Load JPG	☒
10	13/05/19 22:20	Accident Photo	 Load JPG	☒
11	13/05/19 22:20	Accident Photo	 Load JPG	☒
12	13/05/19 22:20	Accident Photo	 Load JPG	☒
13	13/05/19 22:20	Accident Photo	 Load JPG	☒
14	13/05/19 22:20	Accident Photo	 Load JPG	☒
15	13/05/19 22:20	Accident Photo	 Load JPG	☒
16	13/05/19 22:20	Accident Photo	 Load JPG	☒
17	13/05/19 22:20	Accident Photo	 Load JPG	☒
18	13/05/19 22:20	Accident Photo	 Load JPG	☒
19	13/05/19 22:20	Accident Photo	 Load JPG	☒
20	13/05/19 22:20	Accident Photo	 Load JPG	☒
21	13/05/19 22:20	Accident Photo	 Load JPG	☒
22	13/05/19 22:21	Accident Photo	 Load JPG	☒
23	13/05/19 22:21	Accident Photo	 Load JPG	☒
24	13/05/19 22:21	Accident Photo	 Load JPG	☒
25	13/05/19 22:21	Accident Photo	 Load JPG	☒
26	13/05/19 22:21	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
27	13/05/19 22:21	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/05/19 22:41	Sketch Plan	 Load JPG	☒
2	13/05/19 22:41	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19008818/AQD3E2

Date: 31/05/2019

REFERENCE

Insured/Claimant: AUYONG SZE LINDA

Policy No: 2100419561-03

Date of Loss: 08/05/2019

Nature of Claim: OD

Claim No: 0684492734SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT9762P

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)

Engine No: CZC209981

Reg. Date: 26/06/2015 (Man. Year: 2014)

Chassis No: WAUZZZ8V1F1044350

Colour: Black

Odometer: 42298 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$72,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	51,331.00	36,285.00	15,046.00	29.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	43,134.00	24,504.00	18,630.00	43.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	94,465.00	60,789.00	33,676.00	35.65

INSPECTION

Date of Assignment: 17/05/2019

Date Inspected: 17/05/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$11,984.00 NETT)

TOTAL LOSS ASPECT

Market Value : \$72,000.00
OMV : \$30,396.00
PARF Rebate (1) : \$14,666.00
Quota Premium Paid : \$61,000.00
COE Rebate (2) : \$37,243.00
Total Rebate (1) + (2) = : \$51,909.00

The total amount incurred will be Market Value \$72,000.00 minus Total Rebate \$51,909.00 = \$20,091.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,830.00 FS	*1,830.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER COVER TRIM - LH / RH	O/S Damaged	296.00 FS	*148.00 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Cut	148.00 FS	*148.00 FS
5	1		*FRONT BUMPER PULL STRAP	Not Necessary	187.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE - RH	Damaged	35.00 FS	*35.00 FS
7	1		*FRONT BUMPER AIR GRILLE - RH	Missing	99.00 FS	*99.00 FS
8	1		*FRONT BUMPER AIR GRILLE - LH	Not Necessary	99.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	637.00 FS	*- FS
10	1		*RADIATOR GRILLE BACK COVER	Not Necessary	89.00 FS	*- FS
11	1		*SIGN CAUTION STICKER	Not Necessary	13.00 FS	*- FS
12	1		*STICKER FOR AIR CONDITIONER	Not Necessary	7.00 FS	*- FS
13	1		*FRONT REINFORCEMENT BEAM	Not Necessary	660.00 FS	*- FS
14	1		*FRONT BUMPER FOAM - INNER	Not Necessary	125.00 FS	*- FS
15	1		*FRONT BUMPER FOAM COVER	Not Necessary	51.00 FS	*- FS
16	1		*FRONT FENDER - RH	Distorted	778.00 FS	*778.00 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	65.00 FS	*65.00 FS
18	1		*FRONT FENDER BRACKET - RH REAR	Distorted	25.00 FS	*25.00 FS
19	1		*FRONT FENDER BRACKET - RH FRONT	Distorted	35.00 FS	*35.00 FS
20	1		*SET FRONT FENDER RIVET	Necessary	15.00 FS	*15.00 FS
21	1		*FRONT FENDER BRACE - RH	Bent	88.00 FS	*88.00 FS
22	1		*FRONT FENDER CLOSING ELEMENT - RH	Distorted	30.00 FS	*30.00 FS
23	1		*FRONT FENDER INSULATION - RH	Distorted	38.00 FS	*38.00 FS
24	1		*FRONT WHEEL HOUSING INNER SEAL - RH	Distorted	31.00 FS	*31.00 FS
25	1		*FRONT WHEEL HOUSING LINER - RH	Distorted	158.00 FS	*158.00 FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	81.00 FS	*81.00 FS
27	1		*HEADLIGHT - RH	Cracked	1,825.00 FS	*1,825.00 FS
28	1		*HEADLIGHT GAS DISCHARGE BULB	Not Necessary	398.00 FS	*- FS
29	1		*POWER MODULE FOR DAY DRIVING LIGHT	Not Necessary	522.00 FS	*- FS
30	1		*DISCHARGE LAMP CONTROL UNIT	Not Necessary	1,051.00 FS	*- FS
31	1		*HEADLIGHT WASHER CYLINDER	Not Necessary	181.00 FS	*- FS
32	1		*HEADLIGHT WASHER HOSE	Not Necessary	170.00 FS	*- FS
33	1		*SIDE BODY PANEL FRAME - RH	Distorted	3,273.00 FS	*3,273.00 FS
34	4		*RIVETTED CAP NUT	Necessary	6.00 FS	*6.00 FS
35	1		*FRONT WINDSCREEN	Not Necessary	988.00 FS	*- FS
36	1		*FRONT WINDSCREEN GEL FOIL	Not Necessary	128.00 FS	*- FS
37	1		*SPRING CLIP	Not Necessary	20.00 FS	*- FS
38	1		*REAR WINDSCREEN	Necessary	742.00 FS	*742.00 FS
39	1		*REAR SIDE 1/GLASS - RH	Necessary	520.00 FS	*520.00 FS
40	1		*FRONT DOOR - RH	Dented	2,279.00 FS	*2,279.00 FS
41	1		*FRONT DOOR SEAL - RH	Necessary	146.00 FS	*146.00 FS
42	1		*BONDING AGENT	* Check	45.00 FS	*- FS
43	1		*CLEANING SOLUTION	* Check	65.00 FS	*- FS
44	1		*DOOR APPLICATOR	* Check	7.00 FS	*- FS
45	1		*FRONT DOOR CATCH - RH	Not Necessary	96.00 FS	*- FS
46	1		*FRONT DOOR HINGE - RH	Not Necessary	75.00 FS	*- FS
47	1		*FRONT DOOR CORNER TRIM - RH	Not Necessary	41.00 FS	*- FS
48	1		*FRONT WINDOW GUIDE CHROME TRIM - RH	Not Necessary	235.00 FS	*- FS
49	1		*FRONT WINDOW SLOT CHROME TRIM - RH	Not Necessary	282.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*DATA PLATE FOR TYRE PRESSURE	Necessary	26.00 FS	*26.00 FS
51	1		*VEHICLE CHASSIS DATA TAG	Necessary	423.00 FS	*423.00 FS
52	1		*FRONT DOOR WINDOW GLASS - RH	Not Necessary	211.00 FS	*- FS
53	1		*REAR DOOR - RH	Dented	2,279.00 FS	*2,279.00 FS
54	1		*REAR DOOR SEAL - RH	Necessary	146.00 FS	*146.00 FS
55	1		*BONDING AGENT	* Check	45.00 FS	*- FS
56	1		*CLEANING SOLUTION	* Check	65.00 FS	*- FS
57	1		*DOOR APPLICATOR	* Check	7.00 FS	*- FS
58	1		*REAR DOOR ATTACHMENT PARTS	* Check	118.00 FS	*- FS
59	1		*FRONT DOOR ENTRANCE SILL TRIM - RH	Necessary	115.00 FS	*115.00 FS
60	1		*REAR DOOR ENTRANCE SILL TRIM - RH	Necessary	63.00 FS	*63.00 FS
61	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	223.00 FS	*- FS
62	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
63	1		*REAR BUMPER GUIDE - RH	Not Necessary	60.00 FS	*- FS
64	1		*ENGINE UNDERBODY NOISE INSULATION - FRONT	Cut	239.00 FS	*239.00 FS
65	1		*UNDERBODY TRIM - RH	Torn	160.00 FS	*160.00 FS
66	1		*FUEL TANK	Cut	2,396.00 FS	*2,396.00 FS
67	1		*FUEL TANK SEAL RING	Necessary	39.00 FS	*39.00 FS
68	1		*SET FUEL TANK BOLT	Necessary	31.00 FS	*31.00 FS
69	1		*FUEL TANK SEAL RING	Necessary	24.00 FS	*24.00 FS
70	1		*FUEL TANK TENSIONING STRAP	Necessary	70.00 FS	*70.00 FS
71	1		*REAR EXHAUST SILENCER	Not Necessary	663.00 FS	*- FS
72	2		*REAR EXHAUST SILENCER BRACKET	Not Necessary	75.00 FS	*- FS
73	1		*REAR EXHAUST SILENCER DUAL CLIP	Not Necessary	55.00 FS	*- FS
74	1		*FRONT EXHAUST SILENCER	Not Necessary	452.00 FS	*- FS
75	1		*FRONT SUSPENSION SUPPORT CARRIER	Bent	940.00 FS	*940.00 FS
76	1		*SET SUPPORT CARRIER BOLT	* Check	114.00 FS	*- FS
77	1		*SET SUPPORT CARRIER RUBBER BUSHER	Necessary	151.00 FS	*151.00 FS
78	2		*ALUMINIUM RIM - RH FRONT / RH REAR	Cracked	1,408.00 FS	*1,408.00 FS
79	1		*FRONT TRACK CONTROL ARM - RH	Bent	336.00 FS	*336.00 FS
80	1		*SET FRONT TRACK CONTROL ARM BOLT	Bent	43.00 FS	*43.00 FS
81	1		*FRONT STABILIZER BAR	Bent	372.00 FS	*372.00 FS
82	1		*SET FRONT STABILIZER BAR BOLT	Bent	16.00 FS	*16.00 FS
83	1		*FRONT WHEEL BEARING HOUSING - RH	Damaged	532.00 FS	*532.00 FS
84	1		*FRONT WHEEL BEARING - RH	Necessary	442.00 FS	*442.00 FS
85	1		*SET FRONT WHEEL BEARING BOLT	Bent	15.00 FS	*15.00 FS
86	1		*FRONT GUIDE JOINT - RH	Bent	117.00 FS	*117.00 FS
87	1		*SET FRONT GUIDE JOINT BOLT	Bent	10.00 FS	*10.00 FS
88	1		*FRONT COUPLING ROD - RH	Bent	88.00 FS	*88.00 FS
89	1		*FRONT GAS SHOCK ABSORBER - RH	Bent	251.00 FS	*251.00 FS
90	1		*SET GAS SHOCK ABSORBER BOLT	Bent	25.00 FS	*25.00 FS
91	1		*FRONT GAS ABSORBER STRUT STORAGE - RH	Bent	114.00 FS	*114.00 FS
92	1		*SET STRUT STORAGE BOLT	Bent	25.00 FS	*25.00 FS
93	1		*FRONT DRIVE SHAFT - RH	Bent	2,005.00 FS	*2,005.00 FS
94	1		*SET FRONT DRIVE SHAFT BOLT	Damaged	52.00 FS	*52.00 FS
95	1		*STEERING GEAR	Bent	4,649.00 FS	*4,649.00 FS
96	1		*STEERING GEAR TIE ROD END - RH	Bent	118.00 FS	*118.00 FS
97	1		*STEERING GEAR TRACK ROD - RH	Bent	86.00 FS	*86.00 FS
98	1		*FRONT BRAKE LINE	Distorted	86.00 FS	*86.00 FS
99	1		*FRONT BRAKE VACUUM PIPE - RH	* Check	124.00 FS	*- FS
100	1		*FRONT BRAKE SERVO - RH	* Check	559.00 FS	*- FS
101	1		*FRONT BRAKE SERVO SEAL	* Check	17.00 FS	*- FS
102	1		*FRONT BRAKE HEAT SHIELD - RH	* Check	93.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
103	1		*FRONT BRAKE CALIPER HOUSING - RH	Damaged	370.00 FS	*370.00 FS
104	1		*SET FRONT BRAKE CALIPER BOLT	Bent	22.00 FS	*22.00 FS
105	1		*FRONT BRAKE CARRIER - RH	Damaged	268.00 FS	*268.00 FS
106	1		*FRONT BRAKE PAD SET - RH	Necessary	217.00 FS	*217.00 FS
107	1		*FRONT BRAKE DISC - RH	Damaged	153.00 FS	*153.00 FS
108	1		*SET FRONT BRAKE DISC BOLT	Bent	24.00 FS	*24.00 FS
109	1		*FRONT BRAKE DISC COVER PLATE - RH	Bent	59.00 FS	*59.00 FS
110	1		*REAR BRAKE CALIPER HOUSING - RH	* Check	394.00 FS	*- FS
111	1		*SET REAR BRAKE CALIPER BOLT	* Check	20.00 FS	*- FS
112	1		*BRAKE CALIPER LUBRICATING GREASE	* Check	144.00 FS	*- FS
113	1		*REAR BRAKE CALIPER CARRIER - RH	Cracked	154.00 FS	*154.00 FS
114	1		*REAR BRAKE CALIPER SERVOMOTOR - RH	* Check	1,001.00 FS	*- FS
115	1		*REAR BRAKE DISC - RH	* Check	130.00 FS	*- FS
116	1		*REAR SERVOMOTOR ASSEMBLY PARTS	* Check	16.00 FS	*- FS
117	1		*REAR BRAKE DISC COVER PLATE - RH	* Check	59.00 FS	*- FS
118	1		*SET REAR BRAKE DISC COVER PLATE BOLT	* Check	20.00 FS	*- FS
119	1		*REAR SUSPENSION SUPPORT FRAME	* Check	1,325.00 FS	*- FS
120	1		*REAR TRACK ROD - RH	Bent	84.00 FS	*84.00 FS
121	1		*SET REAR TRACK ROD BOLT	Bent	25.00 FS	*25.00 FS
122	1		*REAR COUPLING ROD - RH	Bent	72.00 FS	*72.00 FS
123	1		*SET REAR COUPLING ROD BOLT	Bent	12.00 FS	*12.00 FS
124	1		*REAR ANTI-ROLL BAR	Not Necessary	229.00 FS	*- FS
125	1		*REAR SUSPENSION BRACKET - RH	* Check	133.00 FS	*- FS
126	1		*REAR COVER CAP FOR BEARING SUPPORT - RH	* Check	6.00 FS	*- FS
127	1		*SET REAR SUSP. BRACKET BOLT	* Check	59.00 FS	*- FS
128	1		*REAR AXLE GUIDE - RH	Bent	405.00 FS	*405.00 FS
129	1		*REAR WISHBONE - RH LOWER	Bent	263.00 FS	*263.00 FS
130	1		*SET REAR WISHBONE BOLT	Bent	28.00 FS	*28.00 FS
131	1		*REAR WISHBONE RUBBER BUSH	Necessary	27.00 FS	*27.00 FS
132	1		*REAR WISHBONE - RH UPPER	Bent	259.00 FS	*259.00 FS
133	1		*REAR WHEEL BEARING HOUSING - RH	Damaged	662.00 FS	*662.00 FS
134	1		*REAR WHEEL BEARING - RH	Necessary	452.00 FS	*452.00 FS
135	1		*REAR WISHBONE STONE CHIP GUARD - RH	Necessary	8.00 FS	*8.00 FS
136	1		*REAR GAS SHOCK ABSORBER - RH	Bent	228.00 FS	*228.00 FS
137	1		*SET REAR SHOCK ABSORBER BOLT	Bent	33.00 FS	*33.00 FS
138	1		*REAR STOP BUFFER	Necessary	56.00 FS	*56.00 FS
139	1		*REAR SHOCK ABSORBER BEARING - RH	Necessary	94.00 FS	*94.00 FS
140	1		*FRONT NO. PLATE	Not Necessary	40.00 FS	*- FS
141	1		*ACRYLIC SEALER	Necessary	360.00 FS	*360.00 FS
142	1		*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
143	1		*STONE CHIP	Necessary	360.00 FS	*360.00 FS
144	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
145	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
146	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
147	1		*REAR 1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
148	1		*PIRELLI TYRE - RH FRONT / RH REAR	Front Punctured	800.00 FS	*400.00 FS
149	1		*SUNDRIES	* Check	1,200.00 FS	*- FS
150	1		*FRONT DOOR ATTACHMENT PARTS	* Check	218.00 FS	*- FS
151	1		*FRONT GAS ABSORBER BEARING - RH UPPER	Necessary	43.00 FS	*43.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 51,331.00 36,285.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER (*Check)	New	800.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	0.00
5	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
6	TO DISLodge AND REINSTALL RHS A-PILLAR, DOOR HARNESS, REAR WIRE HARNESS, BATTERY MANAGER, FUSE AND RELAY TRAYS, AUDIO AND ELECTRICAL COMPONENTS	New	1,800.00	1,800.00
7	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	3,200.00
8	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	560.00
9	TO REMOVE AND REINSTALL FRONT AND REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, SAFETY BELTS, CARPETS AND SILL TRIMS, ETC. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	1,800.00
10	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS (*Check)	New	2,800.00	0.00
11	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,800.00	2,800.00
12	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY	New	2,400.00	2,400.00
13	TO REMOVE AND RENEW FUEL TANK ASSY	New	600.00	600.00
14	TO SET-UP VEHICLE ON CAR O-LINER FOR REPAIR (*Check)	New	2,400.00	0.00
15	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS HEADLIGHT, RHS FRONT DOOR, RHS REAR DOOR, REAR BUMPER AND REAR LID. CUT OUT AND REWELD RHS A-PILLAR, RHS SILL PANNEL AND RHS REAR FENDER. TO RENEW FRONT BUMPER, RHS FRONT FENDER, RHS HEADLIGHT, RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	12,250.00	5,000.00
16	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, RHS A-PILLAR, RHS SILL PANEL, RHS FRONT DOOR, RHS REAR DOOR, RHS REAR FENDER, REAR BUMPER, DOOR ENTRANCES, ROOF CHANNEL, DRAIN CHANNEL AND END PANELLING. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	9,300.00	4,400.00
17	TO RENEW RHS FRONT RIM AND TYRE AND RHS REAR RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
18	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
	Gross Labour Cost (S\$)		43,134.00	24,504.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >