



**STUTTGART AUTO PTE LTD**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**FINALIZATION COST OF REPAIRS**



**PORSCHE**

<b>SINGAPORE POLICE FORCE</b>		<b>NAME :</b> Mr Song Hwee Tiong	<b>WIP :</b> 45730
		<b>ADDRESS :</b> 2A Ramsgate Road Singapore 437472	<b>EXCESS :</b>
<b>ATTN. :</b> MOTOR CLAIMS		<b>TEL :</b>	<b>DATE:</b> 13.05.2019
<b>FAX :</b>			

<b>VEH NO :</b>	<b>SFA69B</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	EVA	63310683
<b>CHASSIS NO :</b>	WP1ZZZ9YZKDA03818	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	TP	
<b>MODEL :</b>	Cayenne E3	<b>DATE REG.:</b>	27.08.2018	<b>POLICY NO. :</b>		

**NATURE OF WORKS**

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	P9Y0-807-417-D -G2X	\$ 1,935.50	\$ 1,935.50
2	REAR BUMPER SOUND MAT LOWER LH	1	P9Y0-807-573- -	\$ 88.90	\$ 50.80
3	REAR BUMPER SOUND MAT LOWER RH	1	P9Y0-807-574- -	\$ 88.90	\$ 50.80
4	REAR BUMPER SOUND MAT UPPER LH	1	P9Y0-807-247- -	\$ 85.00	\$ 85.00
5	REAR BUMPER SOUND MAT UPPER RH	1	P9Y0-807-248- -	\$ 85.00	\$ 85.00
6	REAR BUMPER SPOILER	1	P9Y0-807-543- -OK1	\$ 1,205.10	\$ 1,205.10
7	REAR BUMPER SPOILER LOWER TRIM	1	P9Y0-807-834-B -OK1	\$ 840.00	\$ 840.00
8	TAIL PIPE TRIM COVER LH	1	P9Y0-807-837-A -OK1	\$ 137.00	\$ 137.00
9	TAIL PIPE TRIM COVER RH	1	P9Y0-807-838- -OK1	\$ -	\$ 127.00
10	REAR BUMPER BLIND RIVET	6	PN -908-550-01-	\$ 9.00	\$ 9.00
11	SENSOR GASKET	2	P5Q0-919-133- -9B9	\$ 5.20	\$ 5.20
12	SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	\$ -	\$ 477.00
13	TOW COVER	1	P9Y0-807-499- -OK1	\$ -	\$ 72.90
14	REINFORCEMENT	1	P9Y0-807-309-A -	\$ 1,872.70	\$ 1,070.10
15	REAR BUMPER ATTACHEMENT STRIPE CENTER	1	P9Y0-807-863- -	\$ 159.90	\$ 159.90
16	REAR BUMPER EXPANDER NUT	8	PN -106-213-01-	\$ 12.80	\$ 12.80
17	TAILGATE	1	P958-827-025-00-GRV	\$ 3,256.40	\$ 3,256.40
18	TAILGATE DAMPER	2	P9Y0-827-851-A -	\$ -	\$ 1,485.00
19	BLIND RIVET NUT	8	PN -906-481-02-	\$ 34.40	\$ 34.40
20	TAILGATE DRAIN BUSH	2	P958-502-899-00-	\$ -	\$ 21.80
21	BLIND RIVET	8	PN -016-206-1 -	\$ 44.00	\$ 44.00
22	STOPPER	1	P958-971-908-00-	\$ -	\$ 7.10
23	P000-043-305-51-/CAVITY PRESERVATION (AK	1	P000-043-210-97-	\$ -	\$ 75.30
24	DRAIN BUSH SPARE-WHEEL WEL	2	P958-502-899-00-	repeated	\$ 21.80
25	STOPPER	1	P958-971-908-00-	repeated	\$ 7.10
26	TAILGATE ADHESIVE. TAPE	4	P9Y0-827-379- -	\$ 48.00	\$ 48.00
27	REAR TOP SPOILER SEAL TAPE	1	P9Y0-898-003- -	\$ 119.30	\$ 119.30
28	REAR WINDSCREEN GASKET	1	P9Y0-845-571- -	\$ 115.90	\$ 115.90
29	LOGO "CAYENNE"	1	P9Y0-853-675- -	\$ 117.80	\$ 117.80
30	TAIL PIPE LH	1	P9Y0-253-823- -	\$ 693.40	\$ 693.40
			<b>TOTAL PARTS</b>	\$ 10,954.20	\$ 12,370.40
			<b>LESS 10%</b>	\$ 1,095.42	\$ 1,237.04
			<b>TOTAL PARTS COST</b>	\$ 9,858.78	\$ 11,133.36

	<b>Labour Description</b>		
1	TO REPLACE REAR BUMPER, TAILGATE & TO REPAIR REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.	\$ 3,120.00	\$ 7,020.00
2	TO RESPRAY REAR BUMPER, TAILGATE & REAR END PANEL.	\$ 2,400.00	\$ 3,800.00
3	TO TRANSFER THE TAILGATE MECHANISM.	\$ 780.00	\$ 780.00
4	TO REPLACE TAIL PIPE LH & CHECK FOR LEAKAGE.	\$ 780.00	\$ 780.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	\$ 560.00	\$ 560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	\$ 195.00	\$ 195.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
9	SUNDRIES.	\$ 30.00	\$ 50.00
		<b>TOTAL LABOUR</b>	<b>\$ 8,665.00 \$ 13,985.00</b>
		<b>TOTAL PARTS</b>	<b>\$ 9,858.78 \$ 11,133.36</b>
		<b>TOTAL</b>	<b>\$ 18,523.78 \$ 25,118.36</b>
		<b>LESS EXCESS</b>	<b>\$ - \$ -</b>
		<b>TOTAL AFTER EXCESS</b>	<b>\$ 18,523.78</b>
		<b>GST 7%</b>	<b>\$ 1,296.66 \$ -</b>
		<b>GRAND TOTAL</b>	<b>\$ 19,820.44 \$ -</b>

**NUMBER OF DAYS: 7 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)**