

2/2/2008

ASS. REC. BY:

REF: CS/SPF19008227/Tlvd30 Special Instruction:

Agency: TAUFEK

ASSIGNMENT (Office)

From (Person): Frankie they of SPF Date/Time: 17/5/19 @ 3pm

Estimated Cost: Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: SFA 69B Insured: GBC 759E

at Workshop m/s TransautoKars Tel: 63310683

of 27A Tenjong Penjuru @ 5th floor

Policy No: Claim No: AEMD/105/009/2019/062

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 7.5.2014

CA / REV / REP. / REV 24 HRS 22/5/2019 @ 2pm

Date/Time: 4:30pm @ 17/5/2019 Person Contacted: EVA Vehicle IN/OUT

Date/Time Action/Instruction Estimate

16/7/19 @ 2:49 pm Eva said vehicle has not send in for repair

26/7/19 Submit preli revised

Do Not Finalise

21/8/19 final fig \$ 18,523.78 (Red 7385.50, 2990) , 7 days (2 weekends) = 9 days

Upper range 918K - \$20K


22/8/19 To re-open and submit final report, pls pass to typist (Eva) 23/8/19

26/8/19 1st close date 16/8/19, reopen ref only

ASS. REC. BY: *Tan Jiah*

ASSIGNMENT

From: _____ Date: 22.5.2019
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SFA 69B
 at Workshop m/s Transurokar S
 of 27A Tanjong Pagar Rd @ 5 floor
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 200 pm



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS *awp'*
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFA 69B Yr Regn: 2018, Bay
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Porsche Cayenne E3 c.c. 2995
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 11719 T/Radio: Insured / Std / NI / NA
 Eng/No: WP122794JKD A05818
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 285 / 40 R21
 R: 315 / 35R21
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

<u>Front</u>	<u>Rear</u>
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>22/5/19 @ 230</u>

 Survey held at Transurokar
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	RECEIVED 26 JUL 2019
	RECEIVED 15 AUG 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 26/7 - typist
 Report Format: TP
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 8
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<u>220</u>
Transportation:	_____ \$ + RS, _____ SI
Photos	_____
Others	_____
TOTAL	<u>220</u>

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 August 2019 8:27 AM
To: jessicahs@eurokars.com.sg; rickteo@eurokars.com.sg; Taufikh (LKKAuto)
Cc: eva.kok@eurokars.com.sg; janice.syn@porsche.com.sg; SUR; stephanie.loke@eurokars.com.sg
Subject: RE: FINALIZATION TP SPF SFA69B
Attachments: STANLEY_EMAIL_20.12.18.pdf

Dear Jessica,

Please refer our email for previous case.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Wednesday, 21 August 2019 6:05 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; rickteo@eurokars.com.sg; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: eva.kok@eurokars.com.sg; janice.syn@porsche.com.sg; SUR <sur@lkkauto.com>; stephanie.loke@eurokars.com.sg
Subject: RE: FINALIZATION TP SPF SFA69B

Dear Veron,

We are unable to close this case without your confirmation.

Thanks & Regards,
Jessica

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: 21 August 2019 5:59 PM
To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Eva Kok <eva.kok@eurokars.com.sg>; Janice Syn <janice.syn@porsche.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION TP SPF SFA69B

Dear Jessica,

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>

Sent: Wednesday, 21 August 2019 3:58 PM

To: rickteo@eurokars.com.sg; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: eva.kok@eurokars.com.sg; janice.syn@porsche.com.sg

Subject: FINALIZATION TP SPF SFA69B

Dear Taufikh,

Please find our computation attached for your agreement.

COR: \$ 18,523.78 Before GST

7 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case urgently.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Rick Teo <rickteo@eurokars.com.sg>

Sent: 29 July 2019 9:41 AM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: Jessica Harry Shastri <jessicahs@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>

Subject: SFA69B PHOTOS

Hi Taufikh,

Herewith attached photos for your perusal.

Thank you.

Best Regards.



Rick Teo

Insurance Claims Executive

EUROKARS SERVICES
27A Tanjong Perjuru
Singapore 609042
DID : (+65) 63310697
Email : rickteo@eurokars.com.sg



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

SINGAPORE POLICE FORCE		NAME : Mr Song Hwee Tiong	WIP : 45730
ATTN : MOTOR CLAIMS		ADDRESS : 2A Ramsgate Road Singapore 437472	EXCESS :
FAX :		TEL :	DATE: 13.05.2019
VEH NO :	SFA69B	DATE IN :	CONTACT PERSON :
CHASSIS NO :	WP1ZZZ9YZKDA03818	MILEAGE :	EVA 63310683
MODEL :	Cayenne E3	DATE REG.:	TP
		27.08.2018	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY		REVISED	PRICES
1	REAR BUMPER	1	P9Y0-807-417-D -G2X	de	\$ 1,935.50 ✓
2	REAR BUMPER SOUND MAT LOWER LH	88.90	P9Y0-807-573- -	rel / X nn	\$ 50.80 ✓
3	REAR BUMPER SOUND MAT LOWER RH	88.90	P9Y0-807-574- -	rel / X nn	\$ 50.80 ✓
4	REAR BUMPER SOUND MAT UPPER LH	1	P9Y0-807-247- -	? rel	\$ 85.00 ✓
5	REAR BUMPER SOUND MAT UPPER RH	1	P9Y0-807-248- -	? rel	\$ 85.00 ✓
6	REAR BUMPER SPOILER	1	P9Y0-807-543- -OK1	de	\$ 1,205.10 ✓
7	REAR BUMPER SPOILER LOWER TRIM	1	P9Y0-807-834-B -OK1	cut	\$ 840.00 ✓
8	TAIL PIPE TRIM COVER LH	1	P9Y0-807-837-A -OK1	cut	\$ 137.00 ✓
9	TAIL PIPE TRIM COVER RH	1	P9Y0-807-838- -OK1	X nn	\$ 127.00 ✓
10	REAR BUMPER BLIND RIVET	6	PN -908-550-01-	rel	\$ 9.00 ✓
11	SENSOR GASKET	2	P5Q0-919-133- -9B9	rel	\$ 5.20 ✓
12	SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	X nn	\$ 477.00 X
13	TOW COVER	1	P9Y0-807-499- -OK1	X nn	\$ 72.90 ✓
14	REINFORCEMENT	1	P9Y0-807-309-A -	? bt	\$ 1,070.10 ✓
15	REAR BUMPER ATTACHEMENT STRIPE CENTER	1	P9Y0-807-863- -	? ds	\$ 159.90 ✓
16	REAR BUMPER EXPANDER NUT	8	PN -106-213-01-	rel	\$ 12.80 ✓
17	TAILGATE	1	P958-827-025-00-GRV	bt	\$ 3,256.40 ✓
18	TAILGATE DAMPER	2	P9Y0-827-851-A -	X nn	\$ 1,485.00 ✓
19	BLIND RIVET NUT	8	PN -906-481-02-	rel	\$ 34.40 ✓
20	TAILGATE DRAIN BUSH	2	P958-502-899-00-	X nn	\$ 21.80 ✓
21	BLIND RIVET	8	PN -016-206-1 -	rel	\$ 44.00 ✓
22	STOPPER	1	P958-971-908-00-	X nn	\$ 7.10 ✓
23	P000-043-305-51-/CAVITY PRESERVATION (AK	1	P000-043-210-97-	X nn	\$ 75.30 ✓
24	DRAIN BUSH SPARE-WHEEL WEL	2	P958-502-899-00-	repeated	\$ 21.80 ✓
25	STOPPER	1	P958-971-908-00-	repeated	\$ 7.10 ✓
26	TAILGATE ADHESIVE. TAPE	4	P9Y0-827-379- -	rel	\$ 48.00 ✓
27	REAR TOP SPOILER SEAL TAPE	1	P9Y0-898-003- -	rel	\$ 119.30 ✓
28	REAR WINDSCREEN GASKET	1	P9Y0-845-571- -	rel	\$ 115.90 ✓
29	LOGO "CAYENNE"	1	P9Y0-853-675- -	rel	\$ 117.80 ✓
30	TAIL PIPE LH	1	P9Y0-253-823- -	? bt	\$ 693.40 ✓
TOTAL PARTS					\$ 12,370.40
LESS 10%					\$ 1,237.04
TOTAL PARTS COST					\$ 11,133.36

	Labour Description			
1	TO REPLACE REAR BUMPER, TAILGATE & TO REPAIR REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.	1560	✓	3120 \$ 7,020.00
2	TO RESPRAY REAR BUMPER, TAILGATE & REAR END PANEL.		✓	2400 \$ 3,800.00
3	TO TRANSFER THE TAILGATE MECHANISM.		✓	NETT ✓ \$ 780.00
4	TO REPLACE TAIL PIPE LH & CHECK FOR LEAKAGE.		✓	NETT ✓ \$ 780.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.		✓	NETT ✓ \$ 560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.		✓	NETT ✓ \$ 195.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		✓	NETT ✓ \$ 200.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		✓	NETT ✓ \$ 600.00
9	SUNDRIES.		✓	NETT 30 \$ 50.00

TOTAL LABOUR	\$ -	\$ 13,985.00
TOTAL PARTS	\$ -	\$ 11,133.36
TOTAL	\$ -	\$ 25,118.36
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

25,909.28

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

M. M. M. M.
23/5/19

Taylor 97495749
WP
22/5/19 @ 230pm

Resurvey before paint.
suv@lkkauto.com.

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

SINGAPORE POLICE FORCE		NAME : Mr Song Hwee Tiong	WIP : 45730
ATTN. : MOTOR CLAIMS		ADDRESS : 2A Ramsgate Road Singapore 437472	EXCESS :
FAX :		TEL :	DATE : 13.05.2019
VEH NO :	SFA69B	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ9YZKDA03818	MILEAGE :	TYPE OF CLAIM : TP
MODEL :	Cayenne E3	DATE REG.: 27.08.2018	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY		REVISED PRICES	
1	REAR BUMPER	1	P9Y0-807-417-D -G2X	\$ 1,935.50	\$ 1,935.50
2	REAR BUMPER SOUND MAT LOWER LH	1	P9Y0-807-573- -	\$ 88.90	\$ 50.80
3	REAR BUMPER SOUND MAT LOWER RH	1	P9Y0-807-574- -	\$ 88.90	\$ 50.80
4	REAR BUMPER SOUND MAT UPPER LH	1	P9Y0-807-247- -	\$ 85.00	\$ 85.00
5	REAR BUMPER SOUND MAT UPPER RH	1	P9Y0-807-248- -	\$ 85.00	\$ 85.00
6	REAR BUMPER SPOILER	1	P9Y0-807-543- -OK1	\$ 1,205.10	\$ 1,205.10
7	REAR BUMPER SPOILER LOWER TRIM	1	P9Y0-807-834-B -OK1	\$ 840.00	\$ 840.00
8	TAIL PIPE TRIM COVER LH	1	P9Y0-807-837-A -OK1	\$ 137.00	\$ 137.00
9	TAIL PIPE TRIM COVER RH	1	P9Y0-807-838- -OK1	\$ -	\$ 127.00
10	REAR BUMPER BLIND RIVET	6	PN -908-550-01-	\$ 9.00	\$ 9.00
11	SENSOR GASKET	2	P5Q0-919-133- -9B9	\$ 5.20	\$ 5.20
12	SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	\$ -	\$ 477.00
13	TOW COVER	1	P9Y0-807-499- -OK1	\$ -	\$ 72.90
14	REINFORCEMENT	1	P9Y0-807-309-A -	\$ 1,872.70	\$ 1,070.10
15	REAR BUMPER ATTACHEMENT STRIPE CENTER	1	P9Y0-807-863- -	\$ 159.90	\$ 159.90
16	REAR BUMPER EXPANDER NUT	8	PN -106-213-01-	\$ 12.80	\$ 12.80
17	TAILGATE	1	P958-827-025-00-GRV	\$ 3,256.40	\$ 3,256.40
18	TAILGATE DAMPER	2	P9Y0-827-851-A -	\$ -	\$ 1,485.00
19	BLIND RIVET NUT	8	PN -906-481-02-	\$ 34.40	\$ 34.40
20	TAILGATE DRAIN BUSH	2	P958-502-899-00-	\$ -	\$ 21.80
21	BLIND RIVET	8	PN -016-206-1 -	\$ 44.00	\$ 44.00
22	STOPPER	1	P958-971-908-00-	\$ -	\$ 7.10
23	P000-043-305-51-/CAVITY PRESERVATION (AK	1	P000-043-210-97-	\$ -	\$ 75.30
24	DRAIN BUSH SPARE-WHEEL WEL	2	P958-502-899-00-	repeated	\$ 21.80
25	STOPPER	1	P958-971-908-00-	repeated	\$ 7.10
26	TAILGATE ADHESIVE. TAPE	4	P9Y0-827-379- -	\$ 48.00	\$ 48.00
27	REAR TOP SPOILER SEAL TAPE	1	P9Y0-898-003- -	\$ 119.30	\$ 119.30
28	REAR WINDSCREEN GASKET	1	P9Y0-845-571- -	\$ 115.90	\$ 115.90
29	LOGO "CAYENNE"	1	P9Y0-853-675- -	\$ 117.80	\$ 117.80
30	TAIL PIPE LH	1	P9Y0-253-823- -	\$ 693.40	\$ 693.40
TOTAL PARTS				\$ 10,954.20	\$ 12,370.40
LESS 10%				\$ 1,095.42	\$ 1,237.04
TOTAL PARTS COST				\$ 9,858.78	\$ 11,133.36



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19008827/T1vd3e2

ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 16-08-2019



ATTN : FRANKIE THAY

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 759E	Veh. Inspected	SFA 69B
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/062	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	17/05/2019

2. Vehicle Particulars & Condition

Make & Model	PORSCHE CAYENNE E3	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WP1ZZZ9YZKDA03818	Colour	BLACK
Odometer	11719	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	285/40 R21	PIRELLI	6 mm
L/H Front Tyre	285/40 R21	PIRELLI	6 mm
R/H Rear Tyre	315/35 R21	PIRELLI	6 mm
L/H Rear Tyre	315/35 R21	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2019	Inspection Date	22/05/2019
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFA 69B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,935.50	1,935.50
1	REAR BUMPER SOUND MAT LOWER LH	NECESSARY	88.90	88.90
1	REAR BUMPER SOUND MAT LOWER RH	NECESSARY	88.90	88.90
1	REAR BUMPER SOUND MAT UPPER LH	NECESSARY	85.00	85.00
1	REAR BUMPER SOUND MAT UPPER RH	NECESSARY	85.00	85.00
1	REAR BUMPER SPOILER	DEFORMED	1,205.10	1,205.10
1	REAR BUMPER SPOILER LOWER TRIM	CUT	840.00	840.00
1	TAIL PIPE TRIM COVER LH	CUT	137.00	137.00
1	TAIL PIPE TRIM COVER RH	NOT NECESSARY	127.00	-
6	REAR BUMPER BLIND RIVET	NECESSARY	9.00	9.00
2	SENSOR GASKET	NECESSARY	5.20	5.20
2	SENSOR PARKASSIST	NOT NECESSARY	477.00	-
1	TOW COVER	NOT NECESSARY	72.90	-
1	REINFORCEMENT	BENT	1,872.70	1,872.70
1	REAR BUMPER ATTACHMENT STRIPE CENTER	DISTORTED	159.90	159.90
8	REAR BUMPER EXPANDER NUT	NECESSARY	12.80	12.80
1	TAILGATE	BENT	3,256.40	3,256.40
2	TAILGATE DAMPER	NOT NECESSARY	1,485.00	-
8	BLIND RIVET NUT	NECESSARY	34.40	34.40
2	TAILGATE DRAIN BUSH	NOT NECESSARY	21.80	-
8	BLIND RIVET	NECESSARY	44.00	44.00
1	STOPPER	NOT NECESSARY	7.10	-
1	P000-043-305-51-/CAVITY PRESERVATION (AK	NOT NECESSARY	75.30	-
2	DRAIN BUSH SPARE-WHEEL WEL	REPEATED	21.80	-
1	STOPPER	REPEATED	7.10	-
4	TAILGATE ADHESIVE. TAPE	NECESSARY	48.00	48.00
1	REAR TOP SPOILER SEAL TAPE	NECESSARY	119.30	119.30
1	REAR WINDSCREEN GASKET	NECESSARY	115.90	115.90
1	LOGO "CAYENNE"	NECESSARY	117.80	117.80
1	TAIL PIPE LH	BENT	693.40	693.40

Report Ref No. CS/SPF19008827/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,324.92	-1,095.42
			11,924.28	9,858.78
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, TAILGATE & TO REPAIR REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.		7,020.00	3,120.00
	TO RESPRAY REAR BUMPER, TAILGATE & REAR END PANEL.		3,800.00	2,400.00
	TO TRANSFER THE TAILGATE MECHANISM.		780.00	780.00
	TO REPLACE TAIL PIPE LH & CHECK FOR LEAKAGE.		780.00	780.00
	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.		195.00	195.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	200.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			13,935.00	8,635.00
	GRAND TOTAL		25,909.28	18,523.78
RECOMMENDED COST OF REPAIRS				18,523.78

Report Ref No. CS/SPF19008827/T1vd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$18,000-\$20,000

RECOMMENDED REPAIR DAYS : 7

WEEKEND : 2

TOTAL DAYS : 9

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.