

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: YP684X190513

Estimate**Customer**

Name: EQ Insurance Company Limited

Address: Motor Claims Department

5 Maxwell Road #17-00

Tower Block MND Complex Singapore 069110

Date: 17-05-19

Vehicle No: YP684X

Model/Make: Mitsubishi

Canter FEB71GR4SDED

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Back Door Pillar	\$ 400.00	X
2	Back Door Pillar Aluminium Panel	\$ 1,800.00	1200 S.W
3	"Corporate" Advertisement & Artwork	\$ 550.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc's	\$ 800.00	300
	To putty & spray painting & including touch up paint on accident affected area	\$ 400.00	300
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	11X
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 100.00	11X

Total Parts & Labour of estimate for damaged vehicle

\$ 4,150.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Authorized
dhl
21/5/19

4/5 @ 1400
300

1500

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: