***	ASS. REC. BY:	REF: (S/MSG 190	REF: CS/MSG 1900885 4AG+d3p2 Special Instruction:					
MINM	From (Person): Chia Muli Estimated Cost:	ASSIGNME	NT (Office)		Date/Time: 17.5.19	20:29 p.W		
			3		51×4405× 67455783			
	of BIT 3021A, vbi a Policy No: 80456815 GM	oud 1 +01-59	Claim No:		61439783	Ξ,		
	Sum Insured:  Make of Veh: (Client's Record)		Excess:		D.O.A. 151572019			
	CA / REV / REP. / REV Date/Time; 2 -5.17  0-			V	H.O.D. Endorsement:ehicle IN /OUT			
<i>j</i> =		z - NA / NC 400 908			DOA-16/017 A	014		
		compose mail	pending	j estimate.				

Final Report

Others

TOTAL

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
1ain	15 May 2019		17 May 2019 20:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Create	d by insurer]
Insured:	ANG PEI XIONG, ID: S	8737519F		
Main Claimant:	LIM TOW JIN, ID: S18	187011		
Vehicle Reg. No.:	SCV5211Z	Date of Loss:	15/05/2	019 06:00 - :59
Claim Type:	ТР	Policy/Cover Note No.:		.5QMX (Comprehensive) e: 30/04/2018 - 019
Vehicle Reg. No. (Insured):	SLX4405X	Policy No. (Claimant):		
		Excess:		
Repairer:	Sin Hwee Motor Pte Ltd	(HQ) Blk 3023A, Ubi Road 1, #01	-59, 408717 Ubi - Te	1: 67455783
Handling Insurer:	MSIG Insurance (Singa 6594 2521]	pore) Pte. Ltd. (HQ) - Tel: +65 6	827 7888 [Handle	d by Chhia Nyuk Pui -
Adjuster:	LKK Auto Consultants P	te Ltd (HQ) - Tel: 6256-3561	Imm.Advice due	18/05/20191
Driver/Custodian (Insured):		e) , NRIC: S8737519F Email:		
Adj Asg. Remarks:	SJE Case, assigned to LKK			
	D		View All	Compose Case Mail
ASSOCIATED MAIL RECEIVE				
ASSOCIATED MAIL RECEIVE There are no mail for this case.				

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	87011	
Vehicle Details		13
Vehicle No.:	SCV5211Z	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	17 May 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	WISH 1.8 A	
Primary Colour:	Grey	
Manufacturing Year:	2006	
Engine No.:	1ZZ2651836	
Chassis No.:	ZNE100318576	
Maximum Power Output:	97.0 kW (130 bhp)	
Open Market Value:	\$18,824.00	
Original Registration Date:	15 Aug 2006	
First Registration Date:	15 Aug 2006	
Transfer Count:	0	
Actual ARF Paid:	\$20,707.00	
Intended PARE Rebate Details		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	•	
PARF Rebate Amount:	\$0.00	
Intended GOE Rebate Details		
COE Expiry Date:	30 Jun 2021	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	5	
PQP Paid:	\$24,240.00	
COE Rebate Amount:	\$10,275.00	
Total Rebate Amount:	\$10,275.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 May 2019

## **View Sent Message**

This mail is associated with:

\*SCV5211Z [SLX4405X]

TP LIM TOW JIN May 15 2019 6:00AM [ANG PEI XIONG] Sin Hwee Motor Pte Ltd

Resend View Recipients Print Message Delete Message Forward

LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 21/05/2019 12:12 PM. From

nyukpui\_cchia@sg.msig-asia.com

SCV5211Z [SLX4405X] Subject

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SCV 5211Z on 17/5/2019 We are pending estimate from repairer.

Best Regards, **Denise Tay** | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### **DOCUMENTS SUMMARY**

There are no documents.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Mobile Number

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresald.	
	ACCIDENT STATEMENT
Date Of Report	15/05/2019 20:05
Date Of Accident	15/05/2019 06:50
Exact Location Of Accident	ALONG CHOA CHU KANG DR TOWARDS KJE
Country/State of Loss	SINGAPORE
C	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SCV5211Z
Insured/Policyholder	
Name Of Registered Owner	LIM TOW JIN
NRIC No	S1818701I
Email Address	SINAI.MOUNT@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-94872050
Alternative Phone No	OFFICE-94872050
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	A WISH 1.8 1794CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10523551
Cover Note Number	
Driver	
Name of Driver	LIM TOW JIN
NRIC No	S1818701I
Date Of Birth	24/12/1967
Occupation	INDOOR
Date Of Driving Pass	01/11/1991
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE

(LOCAL) +65-94872050

SINAI.MOUNT@YAHOO.COM.SG

OFFICE-94872050

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

MANUAL CONTROL OF THE PARTY OF

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: ELEANOR LIM RUI EN

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I was driving my car along Chua Chu Kang Drive. The traffic was moderate. When I was stationary, suddenly vehicle SLX4405X hit onto my car rear side position. Damages of my car rear side position. No injuries were involved.

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SLX4405X

Vehicle Make/Model/Colour

HYUNDAI / FD I30 CW 1.6 A

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

ANG PEI XIONG

NRIC/Passport Number

S8737519F

Contact Number

92960604


Address

Postcode

Insurance Company Name

Nature Of Damage

11 . 1



## **ACCIDENT STATEMENT (2000 characters)**

I was driving my car along Chua Chu Ka was stationary, suddenly vehicle SLX440 Damages of my car rear side position. No	
Taxi Voucher No.:	
DECLARATION  I/We declare that the above particulars & information provide  VERIFIED BY AJAX MARS REPORTING OFFICER -	ed above are true in every aspect
JOHNNY VOO CHEON YEE	
MARS Officer	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
15 May 2019 at 12:03 PM	15 May 2019 at 12:03 PM

# SIN HWEE MOTOR PTE LTD

# **ESTIMATE**

\*\*\* Main Workshop \*\*\*

Blk 3023A Ubi Road 1 #01-59 S(408717)

\*\*\* Spray Paint Workshop @ Autobay \*\*\*

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

70ms16

MR LIM TOW JIN BLK 42 CHOA CHU KANG STREET 84 # 02-14 (S) 689104 Derise 1

DATE 16/5/2019

VEHICLE NO: SCV 5211 Z

MAKE: TOYOTA

MODEL: WISH 1.8

ZNE 100318576

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	REAR BUMPER De-Land	845.90	545 845.90 -
PC	DEAD DUMBED CINE DETAINED L/U 2	50.20	50.20
I PC	REAR BUMPER SIDE RETAINER R/H	50.20	50.20
PC	END PANEL Devec	527.60	527.60
PC	INNER MEMBER Papis	365.80	365.80 ₹
PC	WEATHER STRIP Let	299.30	299.30
PC	END PANEL TOP GARNISH Dela	245.00	245.00
PC	BOOTLID Deuted	1,272.30	1,272.30
PC	WINDSCREEN MOULDING	210.60	210.60
PC		309.10	309.10
PCS	BOOTLID INNER LOCK 2000 3 878.22		313.40
	BOOTED BAILED TABLE AND A CO.	156.70	
I PC	BOOTLD INNER TRIM ALC ALL BOOTLING CENTER LOGO AND	345.00	345.00 +
I PC	BOOTEID CENTER LOGIO	43.77	43.77
PC		287.59	287.59
PC	REAR FENDER INNER TRIM R/H Coulded.	425.15	425.15
	SUBTOTAL		5,590.91
LESS 25%	LESS 25%	-25.00%	-1,397.73
SET	NUMBER PLATE AND HOLDER ALL MAR	90.00	90.00
SET	REVERSE SENSOR TO INSTALL AND CALIBRATE REVERSE SENSOR	280.00 60.00	280.00 3 60.00 5
ē	TO SUPPLY FITTINGS AND INSTALL REVERSE CAMERA	120.00	120:00 5
5	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILILATE REPAIR WORK	150.00	159.06 17
	TO SUPPLY WINDSCREEN SEALANT	80.00	80.00 6
	TO REPLACE INNER TRIMS, FITTINGS AND LEATHER SEAT TO FACILITATE REPAIR WORK	150.00	150,00 6
	TO TRANSFER BOOTLID MECHANISM, FITTINGS AND TRIM TO NEW BOOTLID	150.00	159.00 80
	TO REPLACE REAR END PANEL INCLUDE KNOCKING, CUTTING, WELDING. TO INSTALL / ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	1,500.00	1,500.00 8
	TO SPRAY PAINT REAR END PANEL , BOOTLID AND BUMPER	1,500.00	1,500.00 &

Tel: 6745 5783 Fax: 6744 9582 Email: sinhweemotor@gmail.com Website: www.sinhweemotor.com

TOTAL

# SIN HWEE MOTOR PTE LTD

## **ESTIMATE**

\*\*\* Main Workshop \*\*\*
Blk 3023A Ubi Road 1 #01-59 S(408717)
\*\*\* Spray Paint Workshop @ Autobay \*\*\*
1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

MR LIM TOW JIN BLK 42 CHOA CHU KANG STREET 84 # 02-14 (S) 689104

DATE	16/5/2019
VEHICLE NO:	SCV 5211 Z
MAKE:	TOYOTA
MODEL:	WISH 1.8

QUANTITY	DESCRIPTION	UNIT	AMOUNT
-	TO SUPPLY AND TUFF KOTE ON AFFECTED AREA	150.00	150:00 60
-	TO CARRY OUT WIRE CHECKING ON AFFECTED AREA	80.00	80.00 30
	TO INSTALL REAR BOOTLID SPOILED AND SUPPLY FITTINGS Percented	80.00	80.00 +

2310

117/05/18 4/s. 06 Rays. total: 5253:66 LS: 42K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tel: 6745 5783 Fax: 6744 9582 Email: sinhweemotor@gmail.com Website: www.sinhweemotor.com

TOTAL

\$8,583.18

Merimen e-Claims

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case N	otified	Est Submitted	Adj Assigned	Adj Rpt	Adi	Submitted	Ins Auth'ed	Status	
	5 May 2019		17 May 2019 20:29 Edit Adj Rpt	S\$4,200.00 Edit Estimat	5\$4	9,200.00 ew Rpt		Pending for Survey Report Cancel Case	
м	ain	R	eference	Claim	Details		Documents		Show All
CLAIM SUB	FOLDER DE	TAILS				[Created l	oy insurer]		
Insured:	ANG PEI	KIONG, ID: S87	37519F						
Main Claimant:	LIM TOW	LIM TOW JIN, ID: S18187011							
Vehicle Reg. No.:	SCV521	SCV5211Z			e of Loss:		06:00 - :59 is From LTA Reg D	ate (Man Yr)]	
Claim Type:	<b>TP</b> / 593	TP / 593749			cy/Cover e No.:				
Vehicle Reg. No. (Insured):	SLX4405)	•			cy No. imant):		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Repairer:	Sin Hwee	Motor Pte Ltd (	HQ) Blk 3023A, Ubi	Road 1, #01-59	, 408717	Ubi - Tel: 67	455783		
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65 682	7 7888	[Handled by	Chhia Nyuk Pui -	6594 2521]	
Adjuster:	18/05/20		Ltd (HQ) - Tel: 62	56-3561 [Hai	ndled by X	ING GUO Q	IANG] [Imm.	Advice due	
Driver/Custo dian (Insured):	ANG PEI X	IONG (31 / Male)	, NRIC: S8737519	F Email:					
Adj Asg. Remarks:	SJE Case,	assigned to LKK	2						
ASSOCIATE	D MAIL RE	CEIVED					Viev	v All Compo	se Case Mail
There are no	mail for this	case.							
ALL ASSOC	IATED TAS	ks⊟			1	View All S	earch Tasks Ci	reate New Task	Complete
Due Date No results.	Priority	Type Task	Group Subjec	t Handler	Assign	ned By	Completed On	Created O	n Done

Merimen e-Claims Page 1 of 2

### Claim Documents

Pho	otos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	I Print
1	17/06/19 18:06	General View	£ Load JPG	☑
2	17/06/19 18:06	General View	Load JPG	<b>✓</b>
3	17/06/19 18:06	General View	Load JPG	V
4	17/06/19 18:06	General View	Load JPG	V
5	17/06/19 18:06	General View	Load JPG	V
6	17/06/19 18:06	General View	Load JPG	✓
7	17/06/19 18:06	General View	Load JPG	V
8	17/06/19 18:06	General View	Load JPG	V
9	17/06/19 18:06	General View	Load JPG	V
10	17/06/19 18:06	General View	Load JPG	V
11	17/06/19 18:06	General View	Load JPG	☑
12	17/06/19 18:06	General View	1 Load JPG	✓
13	17/06/19 18:06	General View	Load JPG	V
14	17/06/19 18:06	General View	6 Load JPG	V
15	17/06/19 18:06	General View	Load JPG	V
16	17/06/19 18:06	General View	Load JPG	✓
17	17/06/19 18:06	General View	Load JPG	V
18	17/06/19 18:06	General View	Load JPG	☑
19	17/06/19 18:06	General View	Load JPG	V
20	17/06/19 18:06	General View	Load JPG	V
21	17/06/19 18:06	General View	Load JPG	✓
22	17/06/19 18:06	General View	Load JPG	☑
23	17/06/19 18:06	General View	6 Load JPG	☑
24	17/06/19 18:06	General View	Load JPG	<b>✓</b>
25	17/06/19 18:06	General View	Load JPG	✓
26	17/06/19 18:06	General View	Load JPG	V
27	17/06/19 18:06	General View	Load JPG	V
28	17/06/19 18:06	General View	1 Load JPG	V
29	17/06/19 18:06	General View	Load JPG	✓
30	17/06/19 18:06	General View	Load JPG	☑
31	17/06/19 18:06	General View	⑥ Load JPG	V
32	17/06/19 18:06	General View	1 Load JPG	☑
33	17/06/19 18:06	General View	1 Load JPG	<b>▼</b>
34	17/06/19 18:06	Reinspection Photo	Load JPG	<b>V</b>
35	17/06/19 18:06	Reinspection Photo	1 Load JPG	₹
36	17/06/19 18:06	Reinspection Photo	♠ Load JPG	<b>▼</b>
37	17/06/19 18:06	Reinspection Photo	1 Load JPG	V

Merimen e-Claims Page 2 of 2

Pho	otos/Images		3 per p	age 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	17/06/19 18:06	Reinspection Photo	Ð	Load JPG	<b>V</b>
39	17/06/19 18:06	Reinspection Photo	Ð	Load JPG	V
40	17/06/19 18:06	Reinspection Photo	0	Load JPG	☑
41	17/06/19 18:06	Reinspection Photo	0	Load JPG	<b>V</b>
42	17/06/19 18:06	Reinspection Photo	0	Load JPG	☑
43	17/06/19 18:06	Reinspection Photo	0	Load JPG	V
44	17/06/19 18:06	Reinspection Photo	0	Load JPG	☑
45	17/06/19 18:06	Reinspection Photo	0	Load JPG	☑
46	17/06/19 18:06	Reinspection Photo	0	Load JPG	<b>V</b>

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To:  Handling Insurer  Note: Remarks are private unless you show it to other parties.			

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19008853/AGTD3E2

Date:

27/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80456815

Claimant Vehicle

SCV5211Z

Insured Vehicle No:

SLX4405X

No: Date of Loss:

15/05/2019

Nature of Claim:

TP

593749 Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SCV5211Z

Make & Model:

TOYOTA WISH, 1.8 (A)

Engine No:

1ZZ2651836

Reg. Date: Colour:

15/08/2006 (Man. Year: 2006) Silver

Chassis No: Odometer:

ZNE100318576 314464 km

Engine Capacity:

1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Front Right Side: Continental 6 mm Continental 6 mm Rear Left Side: Rear Right Side: Continental 6 mm Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,563.18	3,183.66	1,379.52	30.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,110.00	1,910.00	47.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,583.18	5,293.66	3,289.52	38.33
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	8,583.18	4,200.00	4,383.18	51.07

INSPECTION

Date of Assignment:

17/05/2019

Date Inspected:

17/05/2019

Inspected At:

Sin Hwee Motor Pte Ltd (HQ)

Blk 3023A, Ubi Road 1, #01-59

Singapore 408717

Estimated Period of Repair:

6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

### REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 25 Jun 2019)

Parts:

M1-MPV

TOYOTA WISH 1.8 (A) (Catalogue: Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCV5211Z)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	845.90 FL	*545.00 FL
2	1		*REAR BUMPER SIDE RETAINER L/H	Necessary	50.20 FL	*50.20 FL
3	1		*REAR BUMPER SIDE RETAINER R/H	Necessary	50.20 FL	*50.20 FL
4	1		*END PANEL	Dented	527.60 FL	*527.60 FL
5	1		*INNER MEMBER	Repair	365.80 FL	*-FL
6	1		*WEATHER STRIP	Cut	299.30 FL	*299.30 FL
7	1		*END PANEL TOP GARNISH	Deformed	245.00 FL	*245.00 FL
8	1		*BOOTLID	Dented	1,272.30 FL	*1,272.30 FL
9	1		*WINDSCREEN MOULDING	Necessary	210.60 FL	*210.60 FL
10	1		*BOOTLID INNER LOCK	Damaged	309.10 FL	*309.10 FL
11	2		*BOOTLID DAMPER	Not Necessary	313.40 FL	*-FL
12	1		*BOOTLID INNER TRIM	Not Necessary	345.00 FL	*-FL
13	1		*BOOTLID CENTER LOGO	Necessary	43.77 FL	*43.77 FL
14	1		*TAIL LAMP R/H	Not Necessary	287.59 FL	*-FL
15	1		*REAR FENDER INNER TRIM R/H	Cracked	425.15 FL	*425.15 FL
16	1		*SET NUMBER PLATE AND HOLDER	Not Necessary	90.00 FS	*-FS
17	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	5,960.91	4,178.22
			- List Item Discount on L Item	s 25.00/25.00% (S\$)_	1,397.73	994.56
				Total Parts (S\$)	4,563.18	3,183.66

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO INSTALL AND CALIBRATE REVERSE SENSOR.	New	60.00	50.00
2	TO SUPPLY FITTINGS AND INSTALL REVERSE CAMERA.	New	120.00	50.00
3	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIR WORK.	E New	150.00	120.00
4	TO SUPPLY WINDSCREEN SEALANT.	New	80.00	60.00
5	TO REPLACE INNER TRIMS, FITTINGS AND LEATHER SEAT TO FACILITATE REPAIR WORK.	New	150.00	60.00
6	TO TRANSFER BOOTLID MECHANISM, FITTINGS AND TRIM TO NEW BOOTLID.	New	150.00	80.00
7	TO REPLACE REAR END PANEL INCLUDE KNOCKING, CUTTING, WELDING. TO INSTALL / ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.	New	1,500.00	800.00
8	TO SPRAY PAINT REAR END PANEL, BOOTLID AND BUMPER.	New	1,500.00	800.00
9	TO SUPPLY AND TUFF KOTE ON AFFECTED AREA.	New	150.00	60.00
10	TO CARRY OUT WIRE CHECKING ON AFFECTED AREA.	New	80.00	30.00
11	TO INSTALL REAR BOOTLID SPOILED AND SUPPLY FITTINGS.	New	80.00	0.00
	Gross Labou	ır Cost (S\$)	4,020.00	2,110.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.