

# Vision Autowork Pte.Ltd.

( ROC / GST Reg. No. 201500371E)  
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
 Singapore 415875  
 Tel : 6341 6789 Fax: 6341 6778  
 E-mail:visionautowork@gmail.com

DATE : 16.05.19

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SDW7070H  
 MODEL : VOLKSWAGEN SCIROCCO  
 DATE OF ACCIDENT : 16.05.19  
 TIME OF ACCIDENT : 09:00HRS

WVWZZZ1B2BV015272

Cecilia

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                          | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|------------------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT DOOR LH <i>Distorted</i>                       | 1   | \$ 1,575.45     | \$ 1,575.45      |
| 2   | FRONT DOOR OUTER MOULDING LH <i>Distorted</i>        | 1   | \$ 176.75       | \$ 176.75        |
| 3   | FRONT DOOR HINGE LH <i>2</i>                         | 2   | \$ 106.75       | \$ 213.50        |
| 4   | FRONT DOOR CHECKER LH <i>for</i>                     | 1   | \$ 145.99       | \$ 145.99        |
| 5   | FRONT DOOR FRAME WEATHER STRIP LH                    | 1   | \$ 198.15       | \$ 198.15        |
| 6   | FRONT DOOR POWER WINDOW CONTROL SWITCH LH <i>new</i> | 1   | \$ 202.72       | \$ 202.72        |
| 7   | FRONT DOOR OUTER MOULDING LOWER LH <i>cut</i>        | 1   | \$ 246.41       | \$ 246.41        |
| 8   | FRONT DOOR GLASS CHANNEL LH <i>new</i>               | 1   | \$ 287.50       | \$ 287.50        |
| 9   | FRONT DOOR INNER LOCK LH <i>Distorted</i>            | 1   | \$ 414.40       | \$ 414.40        |
| 10  | FRONT DOOR LOCK CATCH LH <i>new</i>                  | 1   | \$ 63.68        | \$ 63.68         |
| 11  | FRONT DOOR OUTER HANDLE LH <i>Distorted</i>          | 1   | \$ 349.61       | \$ 349.61        |
| 12  | FRONT DOOR INNER TRIM BOARD LH <i>for</i>            | 1   | \$ 956.35       | \$ 956.35        |
| 13  | FRONT DOOR REGULATOR LH <i>for</i>                   | 1   | \$ 473.38       | \$ 473.38        |
| 14  | FRONT DOOR POWER WINDOW MOTOR LH <i>new</i>          | 1   | \$ 496.73       | \$ 496.73        |
| 15  | FRONT DOOR SPEAKER LH <i>new</i>                     | 1   | \$ 178.53       | \$ 178.53        |
| 16  | REAR BUMPER <i>Distorted</i>                         | 1   | \$ 950.17       | \$ 950.17        |
| 17  | REAR BUMPER SIDE GARNISH LH <i>cut</i>               | 1   | \$ 48.15        | \$ 48.15         |
| 18  | REAR BUMPER CENTER BRACKET <i>new</i>                | 1   | \$ 160.11       | \$ 160.11        |
| 19  | REAR BUMPER SIDE BRACKET <i>LH new</i>               | 2   | \$ 100.30       | \$ 200.60        |
| 20  | TAIL LAMP LH <i>cut</i>                              | 1   | \$ 569.80       | \$ 569.80        |
| 21  | REAR FENDER LH <i>Distorted</i>                      | 1   | \$ 1,279.60     | \$ 1,279.60      |
| 22  | REAR FENDER INNER TRIM LH <i>crushed</i>             | 1   | \$ 596.41       | \$ 596.41        |
| 23  | REAR FENDER INNER PANEL LH <i>Byis</i>               | 1   | \$ 477.65       | \$ 477.65        |
| 24  | REAR FENDER INNER PANEL SPEAKER LH <i>new</i>        | 1   | \$ 396.41       | \$ 396.41        |
| 25  | REAR FENDER COWLING LH <i>Torn</i>                   | 1   | \$ 221.33       | \$ 221.33        |
| 26  | REAR FENDER OUTER MOULDING (LOWER) LH <i>cut</i>     | 1   | \$ 162.42       | \$ 162.42        |
| 27  | REAR FENDER 1/4 GLASS WITH MOULDING LH <i>new</i>    | 1   | \$ 496.37       | \$ 496.37        |
| 28  | REAR ABS SENSOR LH <i>Not New</i>                    | 1   | \$ 287.55       | \$ 287.55        |

100.30  
322

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SDW7070H  
 MODEL : VOLKSWAGEN SCIROCCO  
 DATE OF ACCIDENT : 16.05.19  
 TIME OF ACCIDENT : 09:00HRS

|    |                                       |   |             |             |    |
|----|---------------------------------------|---|-------------|-------------|----|
| 29 | REAR CROSSMEMBER <i>Neu</i>           | 1 | \$ 1,064.71 | \$ 1,064.71 | x. |
| 30 | REAR LOWER ARM LH <i>Best</i>         | 1 | \$ 499.77   | \$ 499.77   | 2  |
| 31 | REAR SWING ARM LH <i>Best</i>         | 1 | \$ 451.61   | \$ 451.61   | 2  |
| 32 | REAR SHOCK ABSORBER LH <i>Best</i>    | 1 | \$ 369.62   | \$ 369.62   | 2  |
| 33 | REAR WHEEL HUP LH <i>Best</i>         | 1 | \$ 647.81   | \$ 647.81   | 2  |
| 34 | REAR WHEEL HUP BEARING LH <i>Best</i> | 1 | \$ 500.33   | \$ 500.33   | 2  |
| 35 | REAR UPPER ARM LH <i>Best</i>         | 1 | \$ 481.21   | \$ 481.21   | 2  |
| 36 | REAR ADJUSTABLE ARM LH <i>Best</i>    | 1 | \$ 598.72   | \$ 598.72   | 2  |
| 37 | REAR KNUCKLE ARM LH <i>Best</i>       | 1 | \$ 799.75   | \$ 799.75   | 2  |
| 38 | REAR LINKAGE LH <i>Neu</i>            | 1 | \$ 170.71   | \$ 170.71   | +  |

11288.19.  
10159.37.

TOTAL PRICE \$ 17,409.96  
 LESS 10% \$ 1,741.00  
 SUB TOTAL PRICE \$ 15,668.96

#### SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                        | QTY | UNIT S/NETT | TOTAL S/NETT |     |
|-----|----------------------------------------------------|-----|-------------|--------------|-----|
| 1   | FRONT DOOR SEALANT LH <i>Neu</i>                   | 1   | \$ 150.00   | \$ 150.00    | x.  |
| 2   | FRONT DOOR STEP GARNISH CLIP RH (SET) <i>Neu</i>   | 1   | \$ 30.00    | \$ 30.00     | x.  |
| 3   | FRONT DOOR OUTER MOULDING CLIP RH (SET) <i>Neu</i> | 1   | \$ 30.00    | \$ 30.00     | x.  |
| 4   | FRONT DOOR TRIM BOARD CLIP (SET) <i>Neu</i>        | 1   | \$ 50.00    | \$ 50.00     | 30  |
| 5   | TAILLAMP CLIP(SET) <i>Neu</i>                      | 1   | \$ 30.00    | \$ 30.00     | 10. |
| 6   | REAR BUMPER CLIP (SET) <i>Neu</i>                  | 1   | \$ 80.00    | \$ 80.00     | 30. |
| 7   | REAR FENDER SEALANT LH <i>Neu</i>                  | 1   | \$ 150.00   | \$ 150.00    | x   |
| 8   | REAR FENDER INNER TRIM CLIP (SET) LH <i>Neu</i>    | 1   | \$ 80.00    | \$ 80.00     | 30. |
| 9   | REAR FENDER COWLING CLIP (SET) <i>Neu</i>          | 1   | \$ 50.00    | \$ 50.00     | 30  |
| 10  | REAR FENDER INNER PANEL SEALANT LH <i>Neu</i>      | 1   | \$ 150.00   | \$ 150.00    | x   |
| 11  | REAR FENDER 1/4 GLASS SEALANT LH <i>Neu</i>        | 1   | \$ 80.00    | \$ 80.00     | 40  |
| 12  | REAR FENDER 1/4 GLASS INNER SHIELD LH <i>Neu</i>   | 1   | \$ 60.00    | \$ 60.00     | x   |
| 13  | REAR WHEEL RIM LH <i>lit</i>                       | 1   | \$ 1,200.00 | \$ 1,200.00  | 500 |
| 14  | REAR WHEEL TYRE LH <i>Neu</i>                      | 1   | \$ 450.00   | \$ 450.00    | x.  |
| 15  | BRAKE OIL <i>Neu</i>                               | 1   | \$ 30.00    | \$ 30.00     | +   |
| 16  | WHEEL CAP (SET) <i>Neu</i>                         | 1   | \$ 180.00   | \$ 180.00    | +   |

700

TOTAL \$ 2,800.00

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| S/N | JOB DESCRIPTION                         | PRICE       | ADJUSTED COST |
|-----|-----------------------------------------|-------------|---------------|
| 1   | TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK | \$ 1,800.00 | 800           |

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SDW7070H**  
 MODEL : **VOLKSWAGEN SCIROCCO**  
 DATE OF ACCIDENT : 16.05.19  
 TIME OF ACCIDENT : 09:00HRS

|    |                                                                                                |             |     |
|----|------------------------------------------------------------------------------------------------|-------------|-----|
| 2  | TO SPRAY PAINT                                                                                 | \$ 1,600.00 | 700 |
| 3  | TUFF COAT                                                                                      | \$ 250.00   | 60  |
| 4  | WIRING, BULB CHECKING                                                                          | \$ 180.00   | 30  |
| 5  | REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR                      | \$ 350.00   | 100 |
| 6  | REMOVE & REFIX AUDIO SPEAKER                                                                   | \$ 120.00   | X   |
| 7  | REMOVE & REFIX REAR QUARTER GLASS RH                                                           | \$ 100.00   | 60  |
| 8  | TRANSFER FRONT DOOR MECHANISM RH                                                               | \$ 80.00    | 40  |
| 9  | REMOVE & REINSTALL FRONT WINDOW GLASS RH                                                       | \$ 80.00    | 40  |
| 10 | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 120.00   | X   |
| 11 | REMOVE AND REFIX REAR UNDERCARRIAGE                                                            | \$ 650.00   | 220 |
| 12 | TO PRESS REAR WHEEL BEARING                                                                    | \$ 80.00    | X   |
| 13 | FOUR WHEEL ALIGNMENT                                                                           | \$ 120.00   | 80  |
| 14 | REMOVE AND REFIX REAR FENDER GLASS                                                             | \$ 120.00   | X   |
| 15 | RESET ABS LIGHT                                                                                | \$ 350.00   | X   |
| 16 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 250.00   | X   |

TOTAL **2130** \$ 6,250.00

#### ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,468.96  
 TOTAL LABOUR COST : \$ 6,250.00  
 TOTAL REPAIR COST : \$ 24,718.96

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**ABBY**  
 SERVICE ADVISOR  
 ABBY  
 HP : 9856 4815

the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Ling.  
 17/05/19.

08 Days.  
 total: 12989.37  
 1/5: 91K  
 (Nett Value)