

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0648/2019/DY/KK  
**Date** : 22-May-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle : GBE 6742 C**

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

**Attn: Motor Claims Dept**

**Tel: 6880 4602 - Fax 6880 4838**

**Owner's Name** : Mr. Rajan Raghupathy  
**Address** : Blk 205 Jurong East Street 21  
#02-157  
Singapore 600205  
**Telephone** : HP +65 90091672  
**Type of Claim** : Third Party Claim  
**Policy No.** : 1700022197-01  
**Vehicle No** : **SLQ 1900 P**  
**Model Code** : Audi A4 SEDAN 1.4 TFSI S  
**Model / Year** : Jun-17  
**Engine No** : CVN 039075  
**Chassis No** : WAUZZZF48HA165258  
**Mileage** : -  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 16-May-19  
**Place of Accident** : Jurong East St 21 Blk 205 Carpark

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLQ 1900 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ <del>1,050.00</del> 700	
3	To respray rear bumper.	\$ <del>900.00</del> 700.	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLQ 1900 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Del</i>	\$ 2,015.00	✓
2	REAR BUMPER FIXING PARTS	\$ 66.00	X
3	REAR PARKING SENSOR SECURING STRIP	\$ 203.00	X
4	REAR LIGHT REFLECTOR - LH	\$ 38.00	X
5	REAR LIGHT REFLECTOR - RH	\$ 38.00	X
6	REAR BUMPER CARRIER	\$ 819.00	X
7	REAR BUMPER GUIDE SECTION - LH	\$ 20.00	X
8	REAR BUMPER SENSOR - INNER/OUTER	2 \$ 462.00	X
9	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS		\$ 4,161.00	
TOTAL LABOUR		\$ 2,502.00	
GRAND TOTAL		\$ 6,663.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 22/05/19  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant