

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0648/2019/DY/KK
Date : 22-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : GBE 6742 C

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Rajan Raghupathy
Address : Blk 205 Jurong East Street 21
#02-157
Singapore 600205
Telephone : HP +65 90091672
Type of Claim : Third Party Claim
Policy No. : 1700022197-01
Vehicle No : **SLQ 1900 P**
Model Code : Audi A4 SEDAN 1.4 TFSI S
Model / Year : Jun-17
Engine No : CVN 039075
Chassis No : WAUZZZF48HA165258
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-May-19
Place of Accident : Jurong East St 21 Blk 205 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLO 1900 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00	
3	To respray rear bumper.	\$ 900.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 1900 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR PARKING SENSOR SECURING STRIP	\$ 203.00	
4	REAR LIGHT REFLECTOR - LH	\$ 38.00	
5	REAR LIGHT REFLECTOR - RH	\$ 38.00	
6	REAR BUMPER CARRIER	\$ 819.00	
7	REAR BUMPER GUIDE SECTION - LH	\$ 20.00	
8	REAR BUMPER SENSOR - INNER/OUTER	2 \$ 462.00	
9	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS		\$ 4,161.00	
TOTAL LABOUR		\$ 2,502.00	
GRAND TOTAL		\$ 6,663.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant