

22/03/2019

ASS. REC. BY:

REF: CS/CTI19008875/K1 + d367

Special Instruction:

Surveyor: Kalun

ASSIGNMENT (Office)

From (Person): Irene Tay Hin Ping

of CTI

Date/Time: 21.5.19 9:00 a.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SBS 6527J

Insured: PC 1204 J

at Workshop m/s Go Ahead Loyang

Tel: 90296574

of 2 Loyang Way

Policy No: DMBISN30608918000

Claim No: SMM1911262158C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10.05.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.5.19 2:30 p.m.

Person Contacted: Yong Shun

Vehicle (IN) OUT

Date/Time	Action/Instruction
	Estimate (✓) Contact Person WSP - 97377634 Sara
	SBS 6527J - x
	PC 1204 J - CCB/CTI19006755/Ahb3
	D.O.A. 11/04/2019

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SBS 6527J Yr Regn: 2 Feb, 2015Type: M.Car / M.Cycle / B / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C-Class C.C. 6374Colour: Green A/C: Insured / Std / NI / NASp. Reading: 251509 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF B62808323127672Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 275/70 R22-5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Conti

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4.4 mmL/Bal. 4 mm L/Bal. 4.4 mmD.O.A. 10/5/19 D.O.I. 21/5/19Survey held at Go-Ahead

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/6/19	Chk L/S \$11800 / 5 Bs. (Red: 8719-30: 42%) <u>CT2</u>
	<u>4</u>

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

☐ : Prel. Report

1) 18/6 Typst

☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 220

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

220Report Format: TPLump Sum / I.B.I. (\$ 11,800)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2019		21 May 2019 09:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	RFL MART, Co. Reg. No.: 53347427B			
Main Claimant:	GO AHEAD SINGAPORE PTE LTD, Co. Reg. No.: 201541900C			
Vehicle Reg. No.:	SBS6527J	Date of Loss:	10/05/2019 05:00 - :59 [51 Months and 8 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D202158C02	Policy/Cover Note No.:	DMB1SN30608918000 (Comprehensive)	
Vehicle Reg. No. (Insured):	PC1207J	Policy No. (Claimant):	D-18091603MFBP	
		Excess:	S\$3,000.00	
Repairer:	Go Ahead Loyang Pte. Ltd. (HQ) 2 Loyang Way, 508776 Loyang - Tel: 68126469			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2019]			
Driver/Custodian (Insured):	MUHAMMAD RAFI BIN SULAIM (33 / Male) , NRIC: S8602745C Email:			
Adj Asg. Remarks:	to contact Yong Shun at 9029 6574 to arrange for TP survey. thank you.			

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

26th May 2019

Quotation No.: Q19-OPS-0667

China Taiping Insurance Singapore Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

By Email : claimsdept@sg.cntaiping.com

Attn: Claims Department

Dear Sir/Mdm

Estimated Cost of Repair job for SBS 6527J (Accident on 10/05/19, along TPE 65191 – Bef Punggol Rd involving SBS6527J & PC1207J)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour & sealant to replace 2 pcs x RHS Glass panel	4 day	\$880.00	\$3,520.00 1760
2	Supply skilled labour to Cut-weld & repair RHS structure accordingly to MB repair directive, apply anti-rust coating on affected structure. Supply skilled labour & sealant to install RHS bodypanel (above battery panel)	4 day	\$880.00	\$3,520.00 1760
3	Supply skilled painter & paint material to spraypaint RHS body panel & battery panel (3- color, White / Silver / Green)	2 portion	\$500.00	\$1,000.00 800
4	RHS Glass Panel (P1:09)	1 pc	\$2,245.82	\$2,245.82
5	RHS Glass Panel (P1:11)	1 pc	\$1,501.98	\$1,501.98
6	RHS bodypanel (P2:600)	1 pc	\$1,504.37	\$1,504.37
7	RHS battery panel (P3:700)	1 pc	\$4,315.22	\$4,315.22 3600
8	RHS battery panel – Gas spring (P3:728)	1 pc	\$159.98	\$159.98
9	RHS battery panel – Pivot Pin (P3:740)	1 pc	\$9.06	\$9.06
10	RHS battery panel – Plate (P3:718)	1 pc	\$155.78	\$155.78

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R

S/N	Description	Qty.	Unit Price	Total Price
11	RHS battery panel – LHS Bracket hinge (P3:722)	1 pc	\$113.96	\$113.96 ✓
12	RHS battery panel – RHS Bracket hinge (P3:724)	1 pc	\$113.96	\$113.96 ✓
13	RHS battery panel – LHS Bracket hinge Bushing (P3:738)	2 pcs	\$5.96	\$11.92 ✓
14	RHS battery panel – LHS Bracket hinge screw (P3:726)	4 pcs	\$5.96	\$23.84 ✓
15	RHS battery panel – lock (P3:734)	2 pcs	\$63.42	\$126.84 ✓
16	RHS battery panel – handle (P3:720)	1 pc	\$38.15	\$38.15 ✓
17	RHS battery panel – stopper (P3:721)	2 pcs	\$5.96	\$11.92 ✓
18	RHS Body structure (P4:560)	2 pcs	\$282.75	\$565.50 ✓
19	RHS Body structure (P4:526)	1 pc	\$232.75	\$232.75 ✓
20	RHS Body structure (P4:574)	1 pc	\$565.50	\$565.50 ✓
21	RHS Body structure (P4:571)	1 pc	\$282.75	\$282.75 ✓
22	Advertisement sticker	1 lot	\$500.00	\$500.00 400
Total				\$20,519.30

Terms and Conditions:

Payment Terms : 30 days upon invoice
 Quotation Validity : 30 days
 Lead-Time : 8 working day
 Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive

Kalvin 16/6/19
21/5/19 1436
5 Days
L/S
After Report photo

Approval by

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2019 16:11
Date Of Accident	10/05/2019 05:40
Exact Location Of Accident	TPE 65191 - BEF P'GGOL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBS6527J
Insured/Policyholder	
Name Of Registered Owner	GO AHEAD SINGAPORE PTE LTD
Co Reg No	201541900C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63847169
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	CITARO O530-6.4 L AT TURBO ABS (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-18091603MFBP
Cover Note Number	
Driver	
Name of Driver	ANTHONY RAJ S/O GEORGE
NRIC No	S7280672G
Date Of Birth	18/06/1972
Occupation	OUTDOOR
Date Of Driving Pass	04/09/2016
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98539697
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	175B P'GGOL FIELD #05-559
Postcode	822175
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILST I WAS TRAVELLING OFF-SERVICE ON MY WAY TOWARDS P'GGOL INT @ P'GGOL PL VIA TPE, A WHITE GOLDEN DRAGON MINI BUS THAT WAS TRYING TO OVERTAKE MY BUS FROM THE ADJACENT LANE SKIDDED & COLLIDED ON TO THE REAR RIGHT WINDOW GLASS & BODY PANEL OF MY BUS

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DIFFERENT FORMAT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC1207J
Vehicle Make/Model/Colour	WHITE GOLDEN DRAGON XML6770J18
Details Of Properties	FRONT LEFT BUMPER
Vehicle Category	BUS
Name of Driver	MUHAMMAD RAFI BIN SULAIMAN
NRIC/Passport Number	S8602745C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)


Sketch Plan



Accident Photo



Accident Photo



26th May 2019

Quotation No.: Q19-OPS-0667

China Taiping Insurance Singapore Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

By Email : claimsdept@sg.cntaiping.com

Attn: Claims Department

Dear Sir/Mdm

Estimated Cost of Repair job for SBS 6527J (Accident on 10/05/19, along TPE 65191 – Bef Punggol Rd involving SBS6527J & PC1207J)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour & sealant to replace 2 pcs x RHS Glass panel	4 day	\$880.00	\$3,520.00 1760
2	Supply skilled labour to Cut-weld & repair RHS structure accordingly to MB repair directive, apply anti-rust coating on affected structure. Supply skilled labour & sealant to install RHS bodypanel (above battery panel)	4 day	\$880.00	\$3,520.00 1760
3	Supply skilled painter & paint material to spraypaint RHS body panel & battery panel (3- color, White / Silver / Green)	2 portion	\$500.00	\$1,000.00 800
4	RHS Glass Panel (P1:09) <i>Shutland -10%</i>	1 pc	\$2,245.82	\$2,245.82
5	RHS Glass Panel (P1:11) <i>Shutland -10%</i>	1 pc	\$1,501.98	\$1,501.98
6	RHS bodypanel (P2:600) <i>Bentley -10%</i>	1 pc	\$1,504.37	\$1,504.37
7	RHS battery panel (P3:700) <i>Bentley -10%</i>	1 pc	\$4,315.22	\$4,315.22 3600
8	RHS battery panel – Gas spring (P3:728) <i>Mitsubishi -10%</i>	1 pc	\$159.98	\$159.98
9	RHS battery panel – Pivot Pin (P3:740) <i>me -10%</i>	1 pc	\$9.06	\$9.06
10	RHS battery panel – Plate (P3:718) <i>Bent -10%</i>	1 pc	\$155.78	\$155.78

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R

S/N	Description	Qty.	Unit Price	Total Price
11	RHS battery panel – LHS Bracket hinge (P3:722) <i>But -10%</i>	1 pc	\$113.96	\$113.96 ✓
12	RHS battery panel – RHS Bracket hinge (P3:724) <i>But -10%</i>	1 pc	\$113.96	\$113.96 ✓
13	RHS battery panel – LHS Bracket hinge Bushing (P3:738) <i>me -10%</i>	2 pcs	\$5.96	\$11.92 ✓
14	RHS battery panel – LHS Bracket hinge screw (P3:726) <i>me -10%</i>	4 pcs	\$5.96	\$23.84 ✓
15	RHS battery panel – lock (P3:734) <i>me -10%</i>	2 pcs	\$63.42	\$126.84 ✓
16	RHS battery panel – handle (P3:720) <i>me -10%</i>	1 pc	\$38.15	\$38.15 ✓
17	RHS battery panel – stopper (P3:721) <i>me -10%</i>	2 pcs	\$5.96	\$11.92 ✓
18	RHS Body structure (P4:560) <i>But -10%</i>	2 pcs	\$282.75	\$565.50 ✓
19	RHS Body structure (P4:526) <i>But -10%</i>	1 pc	\$232.75	\$232.75 ✓
20	RHS Body structure (P4:574) <i>But -10%</i>	1 pc	\$565.50	\$565.50 ✓
21	RHS Body structure (P4:571) <i>But -10%</i>	1 pc	\$282.75	\$282.75 ✓
22	Advertisement sticker <i>me</i>	1 lot	\$500.00	\$500.00 400 ✓
Total				\$20,519.30

Terms and Conditions:

Payment Terms : 30 days upon invoice
 Quotation Validity : 30 days
 Lead-Time : 8 working day
 Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore
738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com

Kalvin 16/11/19
21/5/19 143h
5 Days
4/5
After Report photo

Approval by



ROC / CR / GST Reg No: 200004370R

































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2019		21 May 2019 09:26 Edit Adj Rpt	S\$11,800.00 Edit Estimates	S\$11,800.00 View Rpt		Pending for Survey Report Cancel Case





Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RFL MART , Co. Reg. No.: 53347427B								
Main Claimant:	GO AHEAD SINGAPORE PTE LTD , Co. Reg. No.: 201541900C								
Vehicle Reg. No.:	SBS6527J	Date of Loss:	10/05/2019 05:00 - :59 [51 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202158C02	Policy/Cover Note No.:	DMB1SN30608918000 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC1207J	Policy No. (Claimant):	D-18091603MFBP						
		Excess:	S\$3,000.00						
Repairer:	Go Ahead Loyang Pte. Ltd. (HQ) 2 Loyang Way, 508776 Loyang - Tel: 68126469								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 30/05/2019]								
Driver/Custodian (Insured):	MUHAMMAD RAFI BIN SULAIM (33 / Male), NRIC: S8602745C Email:								
Adj Asg. Remarks:	to contact Yong Shun at 9029 6574 to arrange for TP survey. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBS6527J (SNM19D202158C02)
[PC1207J]
TP
GO AHEAD SINGAPORE PTE LTD
May 10 2019 5:00AM
[RFL MART]
Go Ahead Loyang Pte. Ltd.

Upload Documents Upload Photos Compose New Letter			View View In Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Go Ahead Loyang Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 11:45	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/06/19 15:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/06/19 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	18/06/19 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	18/06/19 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	18/06/19 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	18/06/19 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	18/06/19 15:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/05/19 09:25	INSD PC1207J GIA Report	 Load PDF	<input type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Go Ahead Loyang Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 11:45	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Go Ahead Loyang Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 11:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/05/19 11:31	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Go Ahead Loyang Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 11:44	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19008875/K1TD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN30608918000

Claimant Vehicle
No: SBS6527JInsured Vehicle
No: PC1207J

Date of Loss: 10/05/2019

Nature of Claim: TP

Claim
No: SNM19D202158C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6527J**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A) Engine No: 902926C1071134

Reg. Date: 02/02/2015 (Man. Year: 2014) Chassis No: WEB62808323127672

Colour: Green Odometer: 251509 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Continental 4 mm Rear Left Side: Continental 4/4 mm

Front Right Side: Continental 4 mm Rear Right Side: Continental 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,479.30	10,537.67	1,941.63	15.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,040.00	4,320.00	3,720.00	46.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,519.30	14,857.67	5,661.63	27.59
Approved Total (Overridden) (S\$)		11,800.00		
Nett Amount (S\$)	20,519.30	11,800.00	8,719.30	42.49

INSPECTION

Date of Assignment: 21/05/2019

Date Inspected: 21/05/2019 Inspected At:

Go Ahead Loyang Pte. Ltd. (HQ)
2 Loyang Way
Singapore 508776

Estimated Period of Repair: 5.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2019)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6527J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS GLASS PANEL (P1:09)	Shattered	2,245.82 F	*2,245.82 FL
2	1		*RHS GLASS PANEL (P1:11)	Shattered	1,501.98 F	*1,501.98 FL
3	1		*RHS BODY PANEL (P2:600)	Buckled	1,504.37 F	*1,504.37 FL
4	1		*RHS BATTERY PANEL (P3:700)	Buckled	4,315.22 F	*3,600.00 FL
5	1		*RHS BATTERY PANEL - GAS SPRING (P3:728)	Missing	159.98 F	*159.98 FL
6	1		*RHS BATTERY PANEL - PIVOT PIN (P3:740)	Necessary	9.06 F	*9.06 FL
7	1		*RHS BATTERY PANEL - PLATE (P3:718)	Bent	155.78 F	*155.78 FL
8	1		*RHS BATTERY PANEL - LHS BRACKET HINGE (P3:722)	Bent	113.96 F	*113.96 FL
9	1		*RHS BATTERY PANEL - RHS BRACKET HINGE (P3:724)	Bent	113.96 F	*113.96 FL
10	2		*RHS BATTERY PANEL - LHS BRACKET HINGE BUSHING (P3:738)	Necessary	11.92 F	*11.92 FL
11	4		*RHS BATTERY PANEL - LHS BRACKET HINGE SCREW (P3:726)	Necessary	23.84 F	*23.84 FL
12	2		*RHS BATTERY PANEL - LOCK (P3:734)	Cracked	126.84 F	*126.84 FL
13	1		*RHS BATTERY PANEL - HANDLE (P3:720)	Cracked	38.15 F	*38.15 FL
14	2		*RHS BATTERY PANEL - STOPPER (P3:721)	Necessary	11.92 F	*11.92 FL
15	2		*RHS BODY STRUCTURE (P4:560)	Bent	565.50 F	*565.50 FL
16	1		*RHS BODY STRUCTURE (P4:526)	Bent	232.75 F	*232.75 FL
17	1		*RHS BODY STRUCTURE (P4:574)	Bent	565.50 F	*565.50 FL
18	1		*RHS BODY STRUCTURE (P4:571)	Bent	282.75 F	*282.75 FL
19	1		*ADVERTISEMENT STICKER	Necessary	500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **12,479.30** **11,664.08**
 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00 1,126.41

Total Parts (S\$) **12,479.30** **10,537.67**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY SKILLED LABOUR & SEALANT TO REPLACE 2PCS X RHS GLASS PANEL.	New	3,520.00	1,760.00
2	SUPPLY SKILLED LABOUR TO CUT-WELD & REPAIR RHS STRUCTURE ACCORDINGLY TO MB REPAIR DIRECTIVE, APPLY ANTI-RUST COATING ON AFFECTED STRUCTURE. SUPPLY SKILLED LABOUR & SEALANT TO INSTALL RHS BODY PANEL (ABOVE BATTERY PANEL)	New	3,520.00	1,760.00
3	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO SPRAYPAINT RHS BODY PANEL & BATTERY PANEL. (3-COLOR, WHITE/SILVER/GREEN)	New	1,000.00	800.00
Gross Labour Cost (S\$)			8,040.00	4,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >