

INSURANCE OWNER:

DORIAN

CC 4/11/1900 8878 / B7854

IDAC

Surveyor:

Mr Lim

DOI:

ASSIGNMENT

2/15/19

Date / Time:

2/15/19

Registered in Malaysia:

2/15/19

Pre-assign / CCU / FTE

SMG 630SR

Insured Vehicle No.:

UN FUN

Claim No.:

049333435806

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

12/05/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJN 4542J

INSRS:

WSP:

Tel:

Liability:

RMKS:

Lehm AutoPro

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SJN 4542J - NALIN 1107 27431 ; 01/14/2011

SMG 630SR - X

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OE

After call ltr to OE: 17/10/19 - JIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

17/10/19

- BLUE REVIEWED. OLD RATE - ENDED TP.
SEND LETTER 4 EMAIL TO OI TO NOTIFY
TEP DRAW 4 NOC ISSUES.

- MINUSSED

- TP LOD IN BY EMAIL

22/10/19

- TYPE REPORT FOR MANDATE APPROVAL
- REPORT DONE

04/11/19

- SEND MANDATE APPROVAL TO AG

12/11/19

- AG APPROVED MANDATE

13/11/19

- SEND 1ST OFFER TO TP.

- TP ACCEPTED OFFER.

- ALL BOOK IN ORDER.

- TO CLOSE.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L9

S\$ 9,700.00 (11 days) Reduction: 4A %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Assessed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 9,700.00

(OLD RATE - ENDED TP)

Loss of Rental (LOR):

S\$ 2,750.00 (15 days) X \$150

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 36.45

Medical:

S\$ -

Disbursement: TOWING

S\$ 180.00

(e.g. Tow / Independent)

Legal Cost

S\$ -

Total:

S\$ 12,166.45

Global Sum S\$: 12,165.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 12,165.00

Name 1:

TOMI AUTOPRO PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

REF: AIG

Jag

ASSIGNMENT

From: Date: 2/15/19

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SJN 4542J**

at Workshop no: **Team Autopro**

of: **160 Sn Ming Drive # 01-14**

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record):

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bot. or Market Value:

IDAC Accident Report:

Confirmed? : Yes or No

GIA / PIR Source:

Confirmed? : Yes or No

Est. Repairs:

11 days Res: Yes or No

Lump Sum:

3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: **SJN 4542J** Yr / Mo: **16/2/2009**

Type: **Car** / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Joyta 1515** cc: **1794**

Color: **White** Alt: Insured / Std / TH / NA

Op. Reading: T/Alder Insured / Std / TH / NA

Eng No: **12Z3131836** 200

C/Mc: **SNM/00056334** 7/30

Gen Cond: Good / Fair / Poor / Burnt

Steering: **Order** / Jammed / Leaked / Burnt or

Brake: **Order** / Jammed / Leaked / Burnt or

Mod: **Nil** / **SRM** / STD A/Rim or

Tyre Size: F: **195/65/15** Yokohama

R: **195/65/15** Lingling

DS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Yoko Frt, Lingling Rear**

Front: Rear

R/Ral: **6** mm R/Ral: **6** mm

L/Ral: **6** mm L/Ral: **6** mm

D.O.A: **17/5/19** D.O.I: **21/5/19**

Survey held at: **Team Autopro**

Des. of Damages: Frt / Rear / Q/S / NS / UIC / Rollover or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/3 9700.00 **Team Lin**

• **CR00: 07.662.00 (Aik)** 17/10/19

MV 36,360/2

PV 15,126/2

NV 21,174/2

Team Lin

22/5/19

Date/Time, File Pass to?

☐ : Prelim. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)

Survey Fee:

Transportation

) 3 x 100.00

) Photos

) Others

TOTAL

Report Format:

Lump Sum / L.B.E. (\$)

☐ Interview (\$)☐ Tech. Ins (\$)☐ Weekend (\$)

Parts Sub Total : \$ 9859.41 15,149.45

25%

Discount

\$ 2464.85 3,787.36

PARTS TOTAL :

\$ 7394.56 11,362.09

360.75
SUPP

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ 60.00
2	Rear no plate	1	\$ 60.00	\$ 60.00
3	Rear bumper reverse sensor	2	\$ 150.00	\$ 300.00
4	Tail lamp inner seal	2	\$ 60.00	\$ 120.00
5	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00
6	Tailgate windscreen inner seal	1	\$ 120.00	\$ 120.00
7	Tailgate windscreen moulding	1	\$ 120.00	\$ 120.00
8	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
9	Rear end panel sealant	1	\$ 100.00	\$ 100.00
10	Rear floor panel sealant	1	\$ 100.00	\$ 100.00
SPECIAL NETT TOTAL :				\$ 620.00 1,160.00

NH
BT
DL
NEX
NECV
NECV
NECV
NDMA
NECV
?NECV

Nos.	LABOUR	S\$
1	R&R upholstery	\$ 120.00 200.00
2	R&R tailgate component	\$ 80.00 100.00
3	R&R Exhaust pipe	\$ 120.00 180.00
4	R&R under carriage	\$ 200.00 300.00
5	R&R tailgate windscreen	\$ 180.00 200.00
6	R&R reverse sensor and test function	\$ 60.00 80.00
7	R&R rear tyre	\$ 60.00 80.00
8	Check wiring	\$ 50.00 80.00
9	Panel beat	\$ 1300.00 1,600.00
10	Rust proofing	\$ 100.00 300.00
11	Spray painting	\$ 1400.00 1,600.00
12	Conduct 4 wheels alignment	\$ 80.00 120.00
LABOUR TOTAL :		\$ 3750.00 4,840.00

PARTS TOTAL : \$ 11,362.09
SPECIAL NETT TOTAL : \$ 1,160.00
LABOUR TOTAL : \$ 4,840.00
GRAND TOTAL : \$ 17,362.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

? photo
Lump sum repair
Repair days 11

Torim Lim
21/5/19
1600 hr

Resurvey
on 22/5/19

Torim Lim
14 30 hrs

Parts 7,755.31
SN 620.00
Labour 3,750.00

12,125.31
@20% 2,425.06
9,700.25

L/s 9700/2

TG Lim
24/5/19

SJE : _____ Vehicle Nos : SJN 4542J
 Date of Survey : _____ Model : _____
 Date of ReSurvey: _____ After-Paint: _____ Year : _____
 Contacts : _____ Chassis No : _____

Supplementary Report

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear floor panel insulator pad	1	\$ 500.00	\$ 481.00 500.00
			Amt	\$ -500.00
			Discount(0.00%)	\$ -
			Subtotal	\$ 481.00 500.00

✓ NEC

Nos.	LABOUR	S\$
1		\$ -
	LABOUR TOTAL :	\$ -

Resurvey on 22/5/19
 Ttlim lile
 1430 hrs

MOTORCAR (Rear)

Vehicle No:

SUN 4542J

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	DL	✓	2
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	DL	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	?		
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DL	✓	
1159	993327	Rear End Panel	DL	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim	?		
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	?		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	?		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler	?		
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	NEC	✓	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	?		
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor	?		
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	DIS	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	DL	✓	

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board	?		
1203	994328	Spare Tyre Panel	?		
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw	?		
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	?		
1213	993357	Rear Exhaust Chrome Pipe	?		
1214	993361	Rear Exhaust Mounting	?		
1215	993358	Rear Exhaust Heat Shield	?		
1216	995223	Rear LH Chassis Member	?		
1217	993165	Rear RH Chassis Member	?		
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	DD	✓	2
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim	RR	✓	
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre	RUN	✓	
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NEC	✓	
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items:

42

Assessor:

TTCM

22/5/19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2974A
Vehicle Details	
Vehicle No.:	SJN4542J
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ISIS 1.8LX A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1ZZ3131836
Chassis No.:	ZNM100056334
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,733.00
Original Registration Date:	16 Feb 2009
First Registration Date:	16 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$17,733.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Feb 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$15,967.00
COE Rebate Amount:	\$15,126.00
Total Rebate Amount:	\$15,126.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 May 2019

OK

avg dep 7480/yr

MV 36,300/2

PV 15,126/2

NV 21,174/2

TTC my kin
22/5/19

Lake View Credit Pte Ltd

Posted: 06-Apr-2019 Tags: 2009 Toyota ISIS, 2009 toyota isis, Toyota ISIS, toyota isis, Toyota, ISIS, isis, Used Toyota



Toyota ISIS 1.8A LX (COE till 02/2029) - N.A 12-Mar-2009 1,794 cc - MPV **SOLD**

Just Arrived! 1 Owner Only! New 10 Years COE With Full Loan Available! New Leather Seats! Beautiful Interior And Exterior Condition Assured! Guaranteed Accident-Free! All Trade In Welcome! Call Now Fo...

Creative Auto

Posted: 17-Mar-2019 Tags: 2009 Toyota ISIS, 2009 toyota isis, Toyota ISIS, toyota isis, Toyota, ISIS, isis, Used Toyota



Toyota ISIS 1.8A LX (COE till 03/2024) \$34,800 \$7,250 /yr 09-Mar-2009 1,794 cc - MPV **Available**

Full Loan Available At \$700 Plus, We Can Help To Convert To \$10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Loan Approval! We Are sgCarMart Premium D...

Premium D...

88 Motor Trading

Posted: 15-May-2019 Tags: 2009 Toyota ISIS, 2009 toyota isis, Toyota ISIS, toyota isis, Toyota, ISIS, isis, Used Toyota



Toyota ISIS 1.8A LX (New 5-yr COE) - N.A 26-Nov-2008 1,794 cc - MPV **SOLD**

AA Trust Automotive

Posted: 03-Mar-2019 Tags: 2008 Toyota ISIS, 2008 toyota isis, Toyota ISIS, toyota isis, Toyota, ISIS, isis, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota, Toyota Singapore, used Toyota Singapore, used Toyota, used vehicles Singapore or even buy used Toyota Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

PRE-REPAIR INSPECTION REQUEST – SJN4542J vs SMG6305R (OI) on D.O.A.: 17/05/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 5/21/2019 8:56:53 AM
Attachments:  draft.pdf  2days.pdf

Hi,

Please refer to the enclosed request from **Team AutoPro Pte Ltd**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rui, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

903um@ 21/5/19
person @ Zack
vehicle in
SUK @ Mr Lim

From: TeamAutoPro North [mailto:teamautopl@gmail.com]
Sent: Saturday, May 18, 2019 5:00 PM
To: Chan, Yoke Shi; Chin, Lee-Ying; Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Supramaniam, Darshene; Tan, Lily (AIG)
Subject: [EXTERNAL] 2 Days Notice: SJN 4542 J (Our Ref) and SMG 6305 R (Your Ref) Dated 17th May 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,
Road Traffic Accident Involving SJN 4542 J (Our Ref) and SMG 6305 R (Your Ref)
Dated 17th May 2019, Time around 20:49
@ BKE TOWARDS WOODLANDS AFTER MANDAI EXIT

We represent our client; Mohammad Dhamshique Bin Mohamed Said, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SJN 4542 J and your insured's vehicle registration number: SMG 6305 R.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors**, via email to the following personnel:-

Contact Person	Alan Koh	9092 7279
	Frederick Lim	9674 6635
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--
The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,
Michelle Lim
Team AutoPro Pte Ltd
Tel: 6258 1955
Fax: 6258 1956

385 Sin Ming Drive
#01-02 Vicom Inspection Centre
Singapore 575718
IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SJN4542J (0493334358SG)**

[SMG6305R]

TP

MOHAMMAD DHAMSHIQUEBIN MOHAMED SAID

May 17 2019 8:40PM

[LIN KUN]

Team Autopro Pte Ltd (sin Ming)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 12/11/2019 08:47 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12166.45) - SJN4542J - Claim Handler: MdNoor, Norsiah

Approved:12166.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2019 Edit Reg		03 May 2019 00:00 Edit Adj Rpt	\$49,700.00 Edit Estimates	\$49,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIN KUN, ID: S84746013								
Main Claimant:	MOHAMMAD DHAMSHIQUEBIN BIN MOHAMED SAID, ID: S7532974A								
Vehicle Reg. No.:	SJN4542J	Date of Loss:	17/05/2019 20:00 - :59 [123 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0493334358SG	Policy/Cover Note No.:	1800154686 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMG6305R	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 30/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (12/11/2019): Alert - Adj Mandate Approved (\$12166.45) - SJN4542J - Claim Handler: MdNoor, No...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN4542J (0493334358SG)

[SMG6305R]

TP

MOHAMMAD DHAMSHIQUEBIN BIN MOHAMED SAID

May 17 2019 8:40PM

[LIN KUN]

Team Autopro Pte Ltd (sin Ming)

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown																Edit		
Photos/Images															1 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	19/10/19 13:44	General View																Load JPG ☒		
2	19/10/19 13:44	General View																Load JPG ☒		
3	19/10/19 13:44	General View																Load JPG ☒		
4	19/10/19 13:44	General View																Load JPG ☒		
5	19/10/19 13:44	General View																Load JPG ☒		
6	19/10/19 13:44	General View																Load JPG ☒		
7	19/10/19 13:44	General View																Load JPG ☒		
8	19/10/19 13:44	General View																Load JPG ☒		
9	19/10/19 13:44	General View																Load JPG ☒		
10	19/10/19 13:44	General View																Load JPG ☒		
11	19/10/19 13:44	General View																Load JPG ☒		
12	19/10/19 13:44	General View																Load JPG ☒		
13	19/10/19 13:44	General View																Load JPG ☒		
14	19/10/19 13:44	General View																Load JPG ☒		
15	19/10/19 13:44	General View																Load JPG ☒		
16	19/10/19 13:44	General View																Load JPG ☒		
17	19/10/19 13:44	General View																Load JPG ☒		
18	19/10/19 13:44	General View																Load JPG ☒		
19	19/10/19 13:44	General View																Load JPG ☒		
20	19/10/19 13:44	General View																Load JPG ☒		
21	19/10/19 13:44	General View																Load JPG ☒		
22	19/10/19 13:44	General View																Load JPG ☒		
23	19/10/19 13:44	General View																Load JPG ☒		
24	19/10/19 13:44	General View																Load JPG ☒		
25	19/10/19 13:44	General View																Load JPG ☒		
26	19/10/19 13:44	General View																Load JPG ☒		
27	19/10/19 13:44	General View																Load JPG ☒		
28	19/10/19 13:44	General View																Load JPG ☒		
29	19/10/19 13:44	General View																Load JPG ☒		
30	19/10/19 13:44	General View																Load JPG ☒		
31	19/10/19 13:44	General View																Load JPG ☒		
32	19/10/19 13:44	General View																Load JPG ☒		
33	19/10/19 13:44	General View																Load JPG ☒		
34	19/10/19 13:44	General View																Load JPG ☒		
35	19/10/19 13:44	General View																Load JPG ☒		
36	19/10/19 13:44	General View																Load JPG ☒		
37	19/10/19 13:44	General View																Load JPG ☒		
38	19/10/19 13:44	General View																Load JPG ☒		
39	19/10/19 13:44	General View																Load JPG ☒		
40	19/10/19 13:44	General View																Load JPG ☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	19/10/19 13:44	General View	 Load JPG	☒
42	19/10/19 13:44	General View	 Load JPG	☒
43	19/10/19 13:44	General View	 Load JPG	☒
44	19/10/19 13:44	General View	 Load JPG	☒
45	19/10/19 13:44	General View	 Load JPG	☒
46	19/10/19 13:44	General View	 Load JPG	☒
47	19/10/19 13:44	General View	 Load JPG	☒
48	19/10/19 13:44	General View	 Load JPG	☒
49	19/10/19 13:44	General View	 Load JPG	☒
50	19/10/19 13:44	General View	 Load JPG	☒
51	19/10/19 13:44	General View	 Load JPG	☒
52	19/10/19 13:44	General View	 Load JPG	☒
53	19/10/19 13:44	General View	 Load JPG	☒
54	19/10/19 13:44	General View	 Load JPG	☒
55	19/10/19 13:44	General View	 Load JPG	☒
56	19/10/19 13:44	General View	 Load JPG	☒
57	19/10/19 13:44	General View	 Load JPG	☒
58	19/10/19 13:44	General View	 Load JPG	☒
59	19/10/19 13:44	General View	 Load JPG	☒
60	19/10/19 13:44	General View	 Load JPG	☒
61	19/10/19 13:44	General View	 Load JPG	☒
62	19/10/19 13:44	General View	 Load JPG	☒
63	19/10/19 13:44	General View	 Load JPG	☒
64	19/10/19 13:44	General View	 Load JPG	☒
65	19/10/19 13:44	General View	 Load JPG	☒
66	19/10/19 13:44	General View	 Load JPG	☒
67	19/10/19 13:44	General View	 Load JPG	☒
68	19/10/19 13:44	General View	 Load JPG	☒
69	19/10/19 13:44	General View	 Load JPG	☒
70	19/10/19 13:44	General View	 Load JPG	☒
71	19/10/19 13:44	General View	 Load JPG	☒
72	19/10/19 13:44	General View	 Load JPG	☒
73	19/10/19 13:44	General View	 Load JPG	☒
74	19/10/19 13:44	General View	 Load JPG	☒
75	19/10/19 13:44	General View	 Load JPG	☒
76	19/10/19 13:44	General View	 Load JPG	☒
77	19/10/19 13:44	General View	 Load JPG	☒
78	19/10/19 13:44	General View	 Load JPG	☒
79	19/10/19 13:44	General View	 Load JPG	☒
80	19/10/19 13:44	General View	 Load JPG	☒
81	19/10/19 13:44	General View	 Load JPG	☒
82	19/10/19 13:44	General View	 Load JPG	☒
83	19/10/19 13:44	General View	 Load JPG	☒
84	19/10/19 13:44	General View	 Load JPG	☒
85	19/10/19 13:44	General View	 Load JPG	☒
86	19/10/19 13:44	General View	 Load JPG	☒
87	19/10/19 13:44	General View	 Load JPG	☒
88	19/10/19 13:44	General View	 Load JPG	☒
89	19/10/19 13:44	General View	 Load JPG	☒
90	19/10/19 13:44	General View	 Load JPG	☒
91	19/10/19 13:44	General View	 Load JPG	☒
92	19/10/19 13:44	General View	 Load JPG	☒
93	19/10/19 13:44	General View	 Load JPG	☒
94	19/10/19 13:44	General View	 Load JPG	☒
95	19/10/19 13:44	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	19/10/19 13:44	General View	 Load JPG	☒
97	19/10/19 13:44	General View	 Load JPG	☒
98	19/10/19 13:44	General View	 Load JPG	☒
99	19/10/19 13:44	General View	 Load JPG	☒
100	19/10/19 13:44	General View	 Load JPG	☒
101	19/10/19 13:44	General View	 Load JPG	☒
102	19/10/19 13:44	General View	 Load JPG	☒
103	19/10/19 13:44	General View	 Load JPG	☒
104	19/10/19 13:44	General View	 Load JPG	☒
105	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
106	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
107	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
108	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
109	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
110	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
111	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
112	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
113	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
114	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
115	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
116	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
117	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
118	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
119	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
120	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
121	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
122	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
123	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
124	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
125	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
126	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
127	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
128	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
129	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
130	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
131	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
132	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
133	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
134	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
135	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
136	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
137	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
138	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
139	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
140	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
141	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
142	19/10/19 13:45	Reinspection Photo	Load JPG	☒
143	19/10/19 13:45	Reinspection Photo	Load JPG	☒
144	19/10/19 13:45	Reinspection Photo	Load JPG	☒
145	19/10/19 13:45	Reinspection Photo	Load JPG	☒
146	19/10/19 13:45	Reinspection Photo	Load JPG	☒
147	19/10/19 13:45	Reinspection Photo	Load JPG	☒
148	19/10/19 13:45	Reinspection Photo	Load JPG	☒
149	19/10/19 13:45	Reinspection Photo	Load JPG	☒
150	19/10/19 13:45	Reinspection Photo	Load JPG	☒
151	19/10/19 13:45	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
153	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
154	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
155	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
156	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
157	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
158	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
159	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
160	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
161	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
162	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
163	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
164	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
165	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
166	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
167	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
168	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
169	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
170	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
171	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
172	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
173	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
174	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
175	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
176	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
177	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
178	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
179	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
180	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
181	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
182	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
183	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
184	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
185	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
186	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
187	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
188	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
189	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
190	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
191	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
192	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
193	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
194	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
195	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
196	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
197	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
198	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
199	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
200	19/10/19 13:45	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/19 15:02	ACKNOWLEDGEMENT EMAIL TO AIG DD 21.05.19	 Load PDF	
2	21/05/19 15:02	EMAIL FROM AIG DD 21.05.2019	 Load PDF	
3	21/05/19 15:02	NOTIFICATION FROM WORKSHOP	 Load PDF	
4	21/05/19 15:02	TP GIA REPORT	 Load PDF	
5	26/05/19 09:53	TP ESTIMATE + SUPP	 Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
6	17/10/19 11:01	EMAIL TO OI		Load PDF	
7	17/10/19 11:01	LETTER TO OI		Load PDF	
8	21/10/19 17:49	TP LOD		Load PDF	
9	01/11/19 09:52	RENTAL RECEIPT		Load PDF	
10	01/11/19 09:52	LTA SEARCH		Load PDF	
11	01/11/19 09:52	LOD		Load PDF	
12	01/11/19 09:52	GIA SEARCH		Load PDF	
13	01/11/19 09:52	TOWING FEE		Load PDF	
AIG Asia Pacific Insurance Pte. Ltd. (SG)					
No	Finalized On			Thumbnail	Print
1	22/05/19 09:32	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMG6305R (Insd veh)	Model:	TOYOTA ISIS 1.8 LXA (A)
	SJN4542J (TP veh)		
Date of Accident:	17/05/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	17,737.09
Final Repair Cost	:	\$	12,165.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	15 days
LTA / GIA Search Fee	:	\$	
Others: Towing Fee	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	12,165.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 12,165.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

14 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19008878/BHA3Q2

Date: 14/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800154686
 Claimant: SJN4542J Insured Vehicle No: SMG6305R
 Vehicle No: SJN4542J
 Date of Loss: 17/05/2019 Nature of Claim: TP Claim No: 0493334358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN4542J
 Make & Model: TOYOTA ISIS, 1.8 LXA (A) Engine No: 1ZZ3131836
 Reg. Date: 16/02/2009 (Man. Year: 2008) Chassis No: ZNM100056334
 Colour: White Odometer: 0 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Linglong 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,897.09	8,435.31	4,461.78	34.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	3,750.00	1,090.00	22.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,737.09	12,185.31	5,551.78	31.30
Approved Total (Overridden) (\$\$)		9,700.00		
Nett Amount (\$\$)	17,737.09	9,700.00	8,037.09	45.31
+ Car Rental (15.0 x S\$150.00/day) (\$\$)		2,250.00		
+ Doc/Search Fee (\$\$)		36.45		
+ Other Costs (\$\$)		180.00		
Nett Liability (\$\$)		12,166.45		
Global Sum Settlement (\$\$)		12,165.00		

INSPECTION

Date of Assignment: 03/05/2019
 Date Inspected: 21/05/2019 Inspected At: Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN
 MING AUTOCITY
 Singapore 575722

Estimated Period of Repair: 11.0 days

Adjuster: Lim Teow Guan**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	1,482.00 FL	*1,331.00 FL
2	1	*TAILGATE LOGO	Necessary	68.00 FL	*68.00 FL
3	1	*TAILGATE CHROME MOULDING ISIS	Necessary	255.20 FL	*155.20 FL
4	1	*TAILGATE TRIMBOARD	Dislodged	494.00 FL	*442.90 FL
5	1	*TAILGATE TRIMBOARD CLIPS	Necessary	55.00 FL	*40.00 FL
6	1	*TAILGATE SIDE TRIMBOARD GARNISH	Dislodged	99.40 FL	*99.40 FL
7	1	*TAILGATE TOP CENTRE TRIMBOARD GARNISH	Broken	115.50 FL	*115.50 FL
8	1	*TAILGATE INNER HANDLE	Dislodged	64.30 FL	*64.30 FL
9	2	*TAILGATE RUBBER STOPPER	Missing	53.00 FL	*53.00 FL
10	1	*TAILGATE WINDSCREEN MOULDING	Necessary	122.70 FL	*122.70 FL
11	1	*TAILGATE WEATHERSTRIP	Distorted	247.00 FL	*247.00 FL
12	2	*TAILGATE HYDRAULIC DAMPER	Not Necessary	444.20 FL	*- FL
13	1	*TAILGATE LOCK	Bent	310.45 FL	*310.45 FL
14	1	*TAILGATE LOCK SENSOR	Damaged	187.20 FL	*187.20 FL
15	1	*TAILGATE WIPER MOTOR ASSY	No Damaged	488.25 FL	*- FL
16	2	*REAR NUMBER PLATE LAMP ASSY	Dislodged	123.00 FL	*123.00 FL
17	1	*REAR BUMPER	Dented	1,300.00 FL	*1,300.00 FL
18	1	*REAR BUMPER CLIP	Necessary	50.00 FL	*40.00 FL
19	2	*REAR BUMPER SIDE RETAINER	Necessary	176.90 FL	*105.80 FL
20	2	*REAR BUMPER BRACKET	Broken	177.80 FL	*130.00 FL
21	1	*REAR BUMPER TOW COVER	Cracked	42.00 FL	*42.00 FL
22	1	*REAR BUMPER TOW COVER BRACKET	Dented	165.00 FL	*140.40 FL
23	2	*REAR BUMPER LAMP	Broken	646.00 FL	*593.06 FL
24	1	*REAR END PANEL	Dented	462.30 FL	*462.30 FL
25	1	*REAR END PANEL TOP GARNISH	Dislodged	195.00 FL	*195.00 FL
26	1	*REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FL	*40.00 FL
27	1	*REAR FLOOR PANEL	Dented	1,150.00 FL	*1,150.00 FL
28	1	*SPARE TYRE BRACKET	Bent	95.50 FL	*438.10 FL
29	1	*SPARE TYRE BRACKET LOCK NUT	Bent	377.20 FL	*- FL
30	1	*EXHAUST SILENCER	Not Necessary	720.85 FL	*- FL
31	1	*EXHAUST HEAT SHIELD	No Damaged	122.00 FL	*- FL
32	2	*EXHAUST MOUNTING	No Damaged	104.00 FL	*- FL
33	2	*TAILLAMP	Broken	689.60 FL	*689.60 FL
34	1	*REAR AXLE	No Damaged	1,420.00 FL	*- FL
35	1	*REAR SHOCK ABSORBER RH	No Damaged	256.00 FL	*- FL
36	1	*WHEEL HUB BEARING RH	No Damaged	234.00 FL	*- FL
37	1	*REAR FENDER RH	Dented	753.50 FL	*753.50 FL
38	1	*REAR FENDER INNER GARNISH RH	Dented	422.70 FL	*380.00 FL
39	1	*REAR FENDER INNER GARNISH CLIPS RH	Necessary	50.00 FL	*40.00 FL
40	1	*REAR FENDER INNER SHIELD RH	No Damaged	75.00 FL	*- FL
41	1	*REAR FENDER INNER SHIELD CLIPS RH	No Damaged	50.00 FL	*- FL
42	1	*REAR WHEEL HOUSE PANEL RH	No Damaged	672.00 FL	*- FL
43	1	*REAR FENDER AIR VENT RH	No Damaged	82.90 FL	*- FL
44	1	*SUNDRIES	Not Necessary	60.00 FS	*- FS
45	1	*REAR NO PLATE	Bent	60.00 FS	*40.00 FS
46	2	*REAR BUMPER REVERSE SENSOR	Dislodged	300.00 FS	*200.00 FS
47	2	*TAIL LAMP INNER SEAL	Not Necessary	120.00 FS	*- FS
48	1	*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*80.00 FS
49	1	*TAILGATE WINDSCREEN INNER SEAL	Necessary	120.00 FS	*100.00 FS
50	1	*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FS	*120.00 FS
51	1	*TAILGATE WINDSCREEN PRIMER AND CLEANER	No Damaged	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*80.00 FS
53	1		*REAR FLOOR PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
54	1		*REAR FLOOR PANEL INSULATOR PAD	Necessary	500.00 FL	*481.00 FL
				Sub Total (\$\$)	16,809.45	11,020.41
				- List Item Discount on L Items 25.00/25.00% (\$\$)	3,912.36	2,585.10
				Total Parts (\$\$)	12,897.09	8,435.31

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R UPHOLSTERY	New	200.00	120.00
2	R&R TAILGATE COMPONENT	New	100.00	80.00
3	R&R EXHAUST PIPE	New	180.00	120.00
4	R&R UNDER CARRIAGE	New	300.00	200.00
5	R&R TAILGATE WINDSCREEN	New	200.00	180.00
6	R&R REVERSE SENSOR AND TEST FUNCTION	New	80.00	60.00
7	R&R REAR TYRE	New	80.00	60.00
8	CHECK WIRING	New	80.00	50.00
9	PANEL BEAT	New	1,600.00	1,300.00
10	RUST PROOFING	New	300.00	100.00
11	SPRAY PAINTING	New	1,600.00	1,400.00
12	CONDUCT 4 WHEELS ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			4,840.00	3,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >