

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____ After-Paint: _____
Contacts : _____

Vehicle Nos : **SJN 4542J**
Model : Toyota Isis
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,482.00	\$ 1,482.00
2	Tailgate logo	1	\$ 68.00	\$ 68.00
3	Tailgate chrome moulding " ISIS "	1	\$ 255.20	\$ 255.20
4	Tailgate trimboard	1	\$ 494.00	\$ 494.00
5	Tailgate trimboard clips	1	\$ 55.00	\$ 55.00
6	Tailgate side trimboard garnish @ SGD 99.40	1	\$ 99.40	\$ 99.40
7	Tailgate top centre trimboard garnish	1	\$ 115.50	\$ 115.50
8	Tailgate inner handle	1	\$ 64.30	\$ 64.30
9	Tailgate rubber stopper	2	\$ 26.50	\$ 53.00
10	Tailgate windscreen moulding	1	\$ 122.70	\$ 122.70
11	Tailgate weatherstrip	1	\$ 247.00	\$ 247.00
12	Tailgate hydraulic damper @ SGD 222.10	2	\$ 222.10	\$ 444.20
13	Tailgate lock	1	\$ 310.45	\$ 310.45
14	Tailgate lock sensor	1	\$ 187.20	\$ 187.20
15	Tailgate wiper motor assy	1	\$ 488.25	\$ 488.25
16	Rear number plate lamp assy @ SGD 61.50	2	\$ 61.50	\$ 123.00
17	Rear bumper	1	\$ 1,300.00	\$ 1,300.00
18	Rear bumper clip	1	\$ 50.00	\$ 50.00
19	Rear bumper side retainer @ SGD 88.45	2	\$ 88.45	\$ 176.90
20	Rear bumper bracket @ SGD 88.90	2	\$ 88.90	\$ 177.80
21	Rear bumper tow cover	1	\$ 42.00	\$ 42.00
22	Rear bumper tow cover bracket	1	\$ 165.00	\$ 165.00
23	Rear bumper lamp @ SGD 323.00	2	\$ 323.00	\$ 646.00
24	Rear end panel	1	\$ 462.30	\$ 462.30
25	Rear end panel top garnish	1	\$ 195.00	\$ 195.00
26	Rear end panel top garnish clip	1	\$ 50.00	\$ 50.00
27	Rear floor panel	1	\$ 1,150.00	\$ 1,150.00
28	Spare tyre bracket	1	\$ 95.50	\$ 95.50
29	Spare tyre bracket lock nut	1	\$ 377.20	\$ 377.20
30	Exhaust silencer	1	\$ 720.85	\$ 720.85
31	Exhaust heat shield	1	\$ 122.00	\$ 122.00
32	Exhaust mounting @ SGD 52.20	2	\$ 52.00	\$ 104.00
33	Taillamp	2	\$ 344.80	\$ 689.60
34	Rear axle	1	\$ 1,420.00	\$ 1,420.00
35	Rear shock absorber Rh	1	\$ 256.00	\$ 256.00
36	Wheel hub bearing Rh	1	\$ 234.00	\$ 234.00
37	Rear fender Rh	1	\$ 753.50	\$ 753.50
38	Rear fender inner garnish Rh	1	\$ 422.70	\$ 422.70
39	Rear fender inner garnish clips Rh	1	\$ 50.00	\$ 50.00
40	Rear fender inner sheild Rh	1	\$ 75.00	\$ 75.00
41	Rear fender inner sheild clips Rh	1	\$ 50.00	\$ 50.00
42	Rear fender air vent Rh	1	\$ 82.90	\$ 82.90
43	Rear wheel house panel Rh	1	\$ 672.00	\$ 672.00

9859.41

Parts Sub Total : \$ 9859.41 15,149.45
 25% Discount \$ 2464.95 3,787.36
PARTS TOTAL : \$7394.56 11,362.09 360.75
 SUPP

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ 60.00
2	Rear no plate	1	\$ 60.00	\$ 40.00 60.00
3	Rear bumper reverse sensor	2	\$ 150.00	\$ 200.00 300.00
4	Tail lamp inner seal	2	\$ 60.00	\$ 120.00
5	Tailgate windscreen sealant	1	\$ 100.00	\$ 80.00 100.00
6	Tailgate windscreen inner seal	1	\$ 120.00	\$ 100.00 120.00
7	Tailgate windscreen moulding	1	\$ 120.00	\$ 120.00
8	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
9	Rear end panel sealant	1	\$ 100.00	\$ 80.00 100.00
10	Rear floor panel sealant	1	\$ 100.00	\$ 60.00 100.00
SPECIAL NETT TOTAL :				\$ 620.00 1,160.00

Nos.	LABOUR	S\$
1	R&R upholstery	\$ 120.00 200.00
2	R&R tailgate component	\$ 80.00 100.00
3	R&R Exhaust pipe	\$ 120.00 180.00
4	R&R under carriage	\$ 200.00 300.00
5	R&R tailgate windscreen	\$ 180.00 200.00
6	R&R reverse sensor and test function	\$ 60.00 80.00
7	R&R rear tyre	\$ 60.00 80.00
8	Check wiring	\$ 50.00 80.00
9	Panel beat	\$ 1300.00 1,600.00
10	Rust proofing	\$ 100.00 300.00
11	Spray painting	\$ 1400.00 1,600.00
12	Conduct 4 wheels alignment	\$ 80.00 120.00
LABOUR TOTAL :		\$ 3750.00 4,840.00

PARTS TOTAL : \$ 11,362.09
 SPECIAL NETT TOTAL : \$ 1,160.00
 LABOUR TOTAL : \$ 4,840.00
GRAND TOTAL : \$ 17,362.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

? photo
 Lump sum repair
 Repair days 11
 TGLim Lim
 21/5/19
 1600 hr

Resurvey
 on 22/5/19

TGLim Lim
 14 30 hrs

Parts 7,755.31
 SN 620.00
 Labour 3,750.00

12,125.31
 @20% 2,425.06
 9700.25

L/s 9700/2

TGLim Lim
 24/5/19

SJE : _____ Vehicle Nos : **SJN 4542J**
 Date of Survey : _____ Model : _____
 Date of ReSurvey: _____ After-Paint: _____ Year : _____
 Contacts : _____ Chassis No : _____

Supplementary Report

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear floor panel insulator pad	1	\$ 500.00	\$ 481.00 500.00
			Amt	\$ -500.00
			Discount(0.00%)	\$ -
			Subtotal	\$ 481.00 500.00

✓ NEC

Nos.	LABOUR	S\$
1		\$ -
	LABOUR TOTAL :	\$ -

Resurvey on 22/5/19

TGtim line

1430 hrs