

7/23/2012

ASS. REC. BY:

Surveyor: Steve

REF:

CS/INC19008879/6713/12

Special Instruction:

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of

INC

Date/Time: 21/5/19 @ 9:35am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 3602

Insured:

SIN 9118T

at Workshop m/s

Thiam Heng Street

Tel:

82636295

of

176 Sing Ming Drive #05-14

96391626 Jenny

Policy No:

Claim No:

MT 11044243-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/05/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

9:45am @ 21/5/19

Person Contacted:

Steven

H.O.D. Endorsement:

Vehicle ID

UT

Date/Time

Action/Instruction

Estimate ☒

SMK 3602-X

SIN 9118T-NA/INC 11001577/WI

JOA 25/01/2011

C25/10-

Confirm Lump Sum \$8000/-, 10 days (Red: 14588.90: 64%)

RECEIVED 3 OCT 2019

Est. Repairs:

days

Res. Fee:

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Survey held at

Thiam Heng

2:48pm

Des. of Damages (Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s front & o/s rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 108K

Date/Time, File Pass to?

☐

Preli. Report

1) 30/10 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format:

TP

Lump Sum / I.B.E. (\$)

8000/-

Survey Fee:

Transportation:

) 3 + RS. \$1

) Photos

) Others

TOTAL

250