

22/03/2003

ASS. REC. BY:

REF: (S/SMD19008886 / ASD3N2)

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Melvin Ye of SMO Date/Time: 21-5-19 1451 P.M.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ 9633V Insured: GBH 5223A

at Workshop m/s NEW HOOT TCD Tel: 6747 9241

of 1 Kaki Bukit Ave 6, BIK C #01-43

Policy No: DIGINTHKE000185 Claim No: (MTD) 1902415

Sum Insured: Excess:

Make of Veh: D.O.A. 17-5-19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21-5-19 3:24pm Person Contacted: Suky Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	GZ 9633V - CS / EQ117000327 / Aqh3n2 D.O.A. - 05/01/2017
	GBH 5223A - X
28/05/19	@ 11:12 am revert pending estimate from reporter to Melvin via memo

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 629633U Yr Regn: 2006 Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Fiat Doblo cc 1910

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 292462 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZFA22300005446892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65HS

R: 185/65HS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Haide

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 22/05/17

Survey held at NHT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/06/19 TP Sample COE Expiry: 26/11/21
Confirmed Hs \$ 2,000/- @ 3 days with Advis
(\$ 14,030.20 Red - 88%)

MV: 15K

PV: 12.2K

Nett: 2.8K

RECEIVED 19 JUN 2019

Resurvey M. of Typ - 1

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1) 19/06/19

2) _____

IN

OUT

Basic & Add.

450

3) Typst

4) _____

S + RS, SI

11

5) _____

6) _____

Photos

Others

TOTAL

461

Prel. Report:

Final Report: \$ 2,000/- Hs

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 May 2019		21 May 2019 14:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		ETHOZ GROUP LTD, Co. Reg. No.: 198104531H							
Main Claimant:		VOGUST BOUTIQUE TRADING, Co. Reg. No.: 53050155D							
Vehicle Reg. No.:		GZ9633U	Date of Loss:	17/05/2019 09:00 - :59					
Claim Type:		TP / CMTD1902415	Policy/Cover Note No.:	D19MTHCVE000185 (Third Party Only)					
Vehicle Reg. No. (Insured):		GBH5223A	Policy No. (Claimant):						
			Excess:						
Repairer:		New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241							
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2019]							
Driver/Custodian (Insured):		ZAINAL BIN SA'AT (), NRIC: S8719261Z, Tel: +6597479325 Email:							
Adj Asg. Remarks:		WS: Reena/ Sukyl 67479241							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GZ9633U (CMTD1902415)
[GBH5223A]**

TP

VOGUST BOUTIQUE TRADING
May 17 2019 9:00AM
[ETHOZ GROUP LTD]
New Hock Teck Motor Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/05/2019 11:12 AM.
To Melvin.ye@sompo.com.sg
CC sur@lkkauto.com
Subject GZ9633U (CMTD1902415) [GBH5223A] TP

Dear Melvin,

Please be informed that we have inspected the vehicle GZ 9633U on 22/05/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.


Budget Direct
insurance


Car insurance due?

Pay Less or Get \$100*, even if you don't buy.

[Get a Quote >](#)

*Terms and conditions apply.

► **SEARCH** Price Range Depreciation > 10 year(s) Vehicle Type [Advanced Search](#)

Home » Used Cars » Hui Hua Credit Pte Ltd » Fiat Doblo 1.3JTD (COE till 01/2022)

► Fiat Doblo 1.3JTD (COE till 01/2022)

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

HUI HUA CREDIT PTE LTD



Price	\$16,300	Fuel Type	Diesel
Depreciation	\$6,170 /yr	Reg Date	12-Jan-2007 (2yrs 7mths 19days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$12,854 as of today (change)	OMV	\$18,737
COE	\$24,334	No. of Owners	5
Engine Cap	1,248 cc		
Curb Weight	1,300 kg		
Type of Vehicle	Van		

Description

Well Maintained. No Repair Needed. Call Our Friendly Sales Team For Viewing Now. In House Loan Available.

Category

COE Car

Status

Available

Resources**Car Valuation - Free**

Find out the market value of your existing car for free. Get started

**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	Hui Hua Credit Pte Ltd	
	» dealer's pricelist	
	» 92 vehs sold 36 vehs available	
Address	1 Bukit Batok Crescent #02-22/23	
	Search cars nearby this location	
Location	WCEGA Plaza	
Office No	64696611 / 64646611	
Contact Person(s)	Joey Ng	88110091
	Jian Rong	91830337
	Alex Chng	86661188
	Weisley	84888000



HUI HUA

view our [used car list](#) | [company info](#)

Posted on: 16-May-2019 | Last Updated on: 21-May-2019

Upfront Payment

» more Financial Info

Transfer Fee	\$25	
Down Payment	\$1,630 (change)	Maximum 90% Loan
1st Instalment	\$528	Based on 4.5% interest rate
Insurance	\$1,521 onwards	
	Not at fault? No upfront payment required! (Get a quote)	
	Quote assumes a standard profile. "Get a quote" for exact figure.	

Powered by

AVIVA

SHORTLISTED HISTORY

[Compare](#)[Rent](#)

\$3,704

Check with seller for exact figure

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 0155D

Vehicle Details

Vehicle No.: GZ9633U
Vehicle to be Exported: No
Intended Deregistration Date: 18 May 2019
Vehicle Make: FIAT
Vehicle Model: DOBLO CARGO 1.9MJTD
Primary Colour: Yellow
Manufacturing Year: 2006
Engine No.: 223B10005054176
Chassis No.: ZFA22300005446392
Maximum Power Output: -
Open Market Value: \$19,996.00
Original Registration Date: 27 Nov 2006
First Registration Date: 27 Nov 2006
Transfer Count: 0
Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Nov 2021
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$24,191.00
COE Rebate Amount: \$12,203.00
Total Rebate Amount: \$12,203.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 18 May 2019

OK

MSME19064730 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME 18/05/2019 14:49
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/05/2019 14:49
Date Of Accident	17/05/2019 09:40
Exact Location Of Accident	SLIP RD OF PIE (TOH TUCK FLYOVER) TWDS TOH TUCK AV
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ9633U
Insured/Policyholder	
Name Of Registered Owner	VOGUST BOUTIQUE TRADING
Co Reg No	53050155D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97875280

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5105459788
Cover Note Number	

Driver

Name of Driver	ALOYSIUS THOI WEI LIANG
NRIC No	S9312441C
Date Of Birth	12/04/1993
Occupation	OUTDOOR
Date Of Driving Pass	11/04/2013
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96357839
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 839 TAMPINES ST 83 #09-90
 Postcode 520839
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG THE SLIP ROAD TOWARDS TOH TUCK ROAD. I SLOWED DOWN AND STOPPED ALONG THE STOP LINE TO GIVE WAY TO ONCOMING TRAFFIC. SUDDENLY, I FELT AN IMPACT. VEHICLE B HIT ON THE REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH5223A
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along the slip road towards Tol Ruck Pond. I slowed down and stopped along the stop line to give ways to oncoming traffic.

Suddenly, I felt an impact. Vehicle B hit on the rear portion of my vehicle and caused damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

VOGUST BOUTIQUE TRADING

21/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Sampo

Shirley

ZFA22300005446392

Accident date: 17/05/2019

Estimated repair cost for vehicle no: GZ9633U FIAT DOBLO CARGO 1.9M '06

S/N	QTY	Items	U/PRICE	AMOUNT
1	1	Rear R/H Boot Lid <i>new</i>		\$1,920.00 <i>x</i>
2	1	Rear R/H Boot Lid 5 Pax Sticker		\$30.00 <i>x</i>
3	1	Rear R/H Boot Lid 70km/H Sticker		\$30.00 <i>x</i>
4	1	Rear R/H Boot Lid Inner Rubber		\$145.20 <i>x</i>
5	1	Rear R/H Boot Lid Upper Inner Lock		\$266.20 <i>x</i>
6	1	Rear R/H Boot Lid Lower Inner Lock		\$266.20 <i>x</i>
7	1	Rear R/H Boot Lid Windscreen Seal <i>xlt</i>		\$60.00 <i>x</i>
8	1	Rear L/H Boot Lid <i>xlt</i>		\$1,920.00 <i>x</i>
9	1	Rear L/H Boot Lid Fiat Logo		\$125.00 <i>x</i>
10	1	Rear L/H Boot Lid Doblo Logo		\$125.00 <i>x</i>
11	1	Rear L/H Boot Lid Number Plate		\$50.00 <i>x</i>
12	2	Rear L/H Boot Lid Number Plate Lamp	\$95.00	\$190.00 <i>x</i>
13	1	Rear L/H Boot Lid Inner Rubber		\$145.20 <i>x</i>
14	1	Rear L/H Boot Lid Upper Inner Lock		\$266.20 <i>x</i>
15	1	Rear L/H Boot Lid Lower Inner Lock		\$266.20 <i>x</i>
16	1	Rear L/H Boot Lid Windscreen Seal		\$60.00 <i>x</i>
17	1	Rear Bumper <i>deland</i>		\$590.00 <i>x</i>
18	8	Rear Bumper Clip <i>re</i>	\$6.50	\$52.00 <i>30</i>
19	2	Rear Bumper Side <i>LH deland</i>	\$300.00	\$600.00 <i>3w</i>
20	2	Rear Bumper Side Retainer <i>LH Mm</i>	\$55.00	\$110.00 <i>55</i>
21	2	Rear Bumper Side Reflector <i>LH curled</i>	\$38.00	\$76.00 <i>38</i>
22	1	Rear Bumper Reinforcement <i>Deated</i>		\$549.40 <i>x</i>
23	1	Rear Bumper Reverse Sensor (Special Nett) <i>xlt</i>		\$380.00 <i>x</i>
24	2	Rear Tail Lamp <i>LH curled</i>	\$380.00	\$760.00 <i>380</i>
25	2	Rear Tail Lamp Cover <i>LH curled</i>	\$303.60	\$607.20 <i>303.60</i>
26	1	Rear End Panel		\$855.00 <i>x</i>
27	1	Rear End Panel Inner Rubber <i>2 xlt</i>		\$118.40 <i>x</i>
28	1	Rear End Panel Top Garnish <i>1 re</i>		\$340.00 <i>x</i>

29	1	Rear Exhaust		\$655.00	
30	2	Rear Exhaust Mounting		\$38.50	\$77.00
31	1	Rear Exhaust Aluminium Cover			\$125.00

2246
2021.40

Subtotal:- \$11,760.20

Labour charges

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear & center exhaust

~~\$380.00~~ X

To remove & refit rear L/H & R/H boot lid windscreen

~~\$240.00~~ X

Gum

~~\$100.00~~ X

To check wiring

~~\$100.00~~ 30

Tuff kote

580

~~\$150.00~~ X

Panel beating

~~\$1,600.00~~ 300

Spray painting

~~\$1,600.00~~ 200

Subtotal:- \$4,270.00

Total:- \$16,030.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 260140

H/S: 21C ✓
03Days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008886/ASD3N2

Date: 24/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTHCVE000185
Claimant Vehicle No :	GZ9633U	Insured Vehicle No :	GBH5223A
Date of Loss:	17/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902415

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ9633U	Engine No:	223B10005054176
Make & Model:	FIAT DOBLO, 1.2 D 1.3M (M)	Chassis No:	ZFA22300005446392
Reg. Date:	27/11/2006 (Man. Year: 2006)	Odometer:	292462 km
Colour:	Yellow		
Engine Capacity:	1910 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Haida 6 mm	Rear Left Side:	Haida 6 mm
Front Right Side:	Haida 6 mm	Rear Right Side:	Haida 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,860.20	2,021.40	9,838.80	82.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	580.00	3,590.00	86.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,030.20	2,601.40	13,428.80	83.77
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	16,030.20	2,000.00	14,030.20	87.52
+ GST 7.00/7.00% (\$\$)	1,122.11	140.00	982.11	87.52
Nett Amount (\$\$)	17,152.31	2,140.00	15,012.31	87.52

INSPECTION

Date of Assignment:	21/05/2019	
Date Inspected:	22/05/2019 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
Parts:	M1-MPV	FIAT DOBLO 1.2 D 1.3M (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ9633U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR R/H BOOT LID	Not Necessary	1,920.00 F	*- FL
2	1		*REAR R/H BOOT LID 5 PAX STICKER	Not Necessary	30.00 F	*- FL
3	1		*REAR R/H BOOT LID 70KM/H STICKER	Not Necessary	30.00 F	*- FL
4	1		*REAR R/H BOOT LID INNER RUBBER	Not Necessary	145.20 F	*- FL
5	1		*REAR R/H BOOT LID UPPER INNER LOCK	Not Necessary	266.20 F	*- FL
6	1		*REAR R/H BOOT LID LOWER INNER LOCK	Not Necessary	266.20 F	*- FL
7	1		*REAR R/H BOOT LID WINDSCREEN SEAL	Not Necessary	60.00 F	*- FL
8	1		*REAR L/H BOOT LID	Not Necessary	1,920.00 F	*- FL
9	1		*REAR L/H BOOT LID FIAT LOGO	Not Necessary	125.00 F	*- FL
10	1		*REAR L/H BOOT LID DOBLO LOGO	Not Necessary	125.00 F	*- FL
11	1		*REAR L/H BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
12	2		*REAR L/H BOOT LID NUMBER PLATE LAMP	Not Necessary	190.00 F	*- FL
13	1		*REAR L/H BOOT LID INNER RUBBER	Not Necessary	145.20 F	*- FL
14	1		*REAR L/H BOOT LID UPPER INNER LOCK	Not Necessary	266.20 F	*- FL
15	1		*REAR L/H BOOT LID LOWER INNER LOCK	Not Necessary	266.20 F	*- FL
16	1		*REAR L/H BOOT LID WINDSCREEN SEAL	Not Necessary	60.00 F	*- FL
17	1		*REAR BUMPER	Deformed	590.00 F	*590.00 FL
18	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
19	1		*REAR BUMPER SIDE	N/s Deformed	600.00 F	*300.00 FL
20	1		*REAR BUMPER SIDE RETAINER	N/s Necessary	110.00 F	*55.00 FL
21	1		*REAR BUMPER SIDE REFLECTOR	N/s Cracked	76.00 F	*38.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	549.40 F	*549.40 FL
23	1		*REAR TAIL LAMP	N/s Cracked	760.00 F	*380.00 FL
24	1		*REAR TAIL LAMP COVER	N/s Cracked	607.20 F	*303.60 FL
25	1		*REAR END PANEL	Not Necessary	855.00 F	*- FL
26	1		*REAR END PANEL INNER RUBBER	Not Necessary	118.40 F	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	340.00 F	*- FL
28	1		*REAR EXHAUST	Not Necessary	655.00 F	*- FL
29	2		*REAR EXHAUST MOUNTING	Not Necessary	77.00 F	*- FL
30	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	125.00 F	*- FL
31	1		*REAR BUMPER REVERSES ENSOR	Not Necessary	380.00 FS	*- FS
32	1		*GUM	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,860.20	2,246.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	224.60
Total Parts (\$\$)	11,860.20	2,021.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	0.00
3	TO REMOVE & REFIT REAR L/H & R/H BOOT LID WINDSCREEN	New	240.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	0.00
6	PANEL BEATING	New	1,600.00	300.00
7	SPRAY PAINTING	New	1,600.00	200.00
Gross Labour Cost (S\$)			4,170.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >