

INSURANCE

INS. CASE OWNER:

CC³ /AIG1900 8891, A. *plax*

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

23/5/2019

Date / Time:

21/5/19

Registered in Merimen:

21/5/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLT 16724

Name of Insured:

YAP Kim WEE YE JIN (U)

Insured Tel No.:

HP:

17/5/19

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

127716406VSH

Policy No.:

8000680V5-01

Make / Model:

SUBARU

Place of Accident:

20 Hmly car with man GAKORN

If NO: Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Of GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLX 23034



INSRS:
WSP:
Tel:
Liability:
RMKS:

premium



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/5/19 - 2:30pm

Spoke to OI. Informed OI on IP claim, advised to settle by end of week with LWP. E-mailed IP with LWP.

PIC: Ashor

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler: Typist:

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

UTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

PIP

SS11,166.08

5 days

Reduction:

40 %

Email

Call

FINAL SETTLEMENT

Date/Time: 11-02-20

Confirm with: NADIA

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 23

If NO or B 2E, Ass. Lia:

(A) REVERSE (B) DOUBLE (C) REVERSE (D) DOUBLE (E) REVERSE (F) DOUBLE (G) REVERSE (H) DOUBLE (I) REVERSE (J) DOUBLE (K) REVERSE (L) DOUBLE (M) REVERSE (N) DOUBLE (O) REVERSE (P) DOUBLE (Q) REVERSE (R) DOUBLE (S) REVERSE (T) DOUBLE (U) REVERSE (V) DOUBLE (W) REVERSE (X) DOUBLE (Y) REVERSE (Z) DOUBLE

Repair Cost:

21/5/19

SS11,947.71

Loss of Rental (LOR):

SS 150.00

5 days

Reduction:

40 %

Loss of Use (LOU):

SS -

(5 days)

Reduction:

40 %

Loss of Income (LOI):

SS -

(5 days)

Reduction:

40 %

LOI only

LOU only

LOI + LOU

LOI + LOU

LOI + LOU

(Tick only one)

GIA/UTA Search:

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS12,097.71

Global Sum SS:

FINAL PAYMENT

Date/Time: 11-02-20

Confirm with: NADIA

Email

Call

Payee 1:

SS12,097.71

Name 1:

PREMIUM AUTOMOBILES PTE LTD

Payee 2 (Strike if N.A.):

SS

Name 2:

Payee 3 (Strike if N.A.):

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 230

COPY SENT 13/7/2020

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

DIAC / Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 888 days Res.: Yes or No

Lum Sum: 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX2303U Yr Regn: 2018, Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan cc 1984

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 20531 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAW222F4XJA070679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 245/55R19

R: 245/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 23/05/19

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP A16

PIP: 11,166.08 (RED: 7,593.32 40%)

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0653/2019/DY/TF
Date : 22-May-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLT 1672 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loo Seng Kong
Address : 2D Hong San Walk
#04-09
Singapore 689050
Telephone : (HP) +65 90078623
Type of Claim : Third Party Claims
Policy No. : 1800016639-01
Vehicle No : **SLX 2303 U**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 20/2/2018
Engine No : CVK 050074
Chassis No : WAUZZZF4XJA070674
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-May-19
Place of Accident : 2D Hong San Walk S(689050)-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 2303 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, rhs headlight and rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1250 ✓	✓
3	To respray front bumper and rhs front fender.	\$ 1,800.00 1100 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,922.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2303 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Replaced</i>	\$ 1,999.00 ✓	1,599.20
2	FRONT BUMPER FIXING PART <i>Not in</i>	\$ 258.00 +	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not in</i>	\$ 191.00 +	
4	FRONT BUMPER AIR GUIDE - RH <i>Not in</i>	\$ 56.00 +	
5	FRONT BUMPER SECURING STRIP <i>Not in</i>	\$ 32.00 +	
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not in</i>	\$ 123.00 +	
7	FRONT BUMPER CARRIER <i>Not in</i>	\$ 733.00 +	
8	FOAM FILLER PIECE <i>Not in</i>	\$ 113.00 +	
9	FRONT BUMPER GUIDE SECTION - RH <i>Damaged</i>	\$ 34.00 ✓	31.12
10	RADIATOR BRACKET HOLDER <i>Not in</i>	\$ 125.00 +	
11	FRONT BUMPER SUPPORT - RH & LH <i>Not in</i>	\$ 52.00 X	
12	FRONT BUMPER SENSOR <i>Not in</i>	2 \$ 462.00 +	
13	FRONT BUMPER SENSOR SEAL RING <i>Not in</i>	4 \$ 12.00 +	
14	HORN - LOW TONE <i>2 Not in</i>	\$ 262.00 +	
15	HORN BRACKET <i>Not in</i>	\$ 26.00 +	
16	FRONT FENDER - RH <i>Dented</i>	\$ 700.00 ✓	559.60
17	FRONT FENDER ATTACHMENT PARTS <i>Not in</i>	\$ 183.00 X	
18	FRONT FENDER CLOSING ELEMENT - RH <i>Not in</i>	\$ 45.00 X	
19	FRONT FENDER BRACKET - RH <i>Not in</i>	\$ 32.00 X	
20	POP RIVET <i>Not in</i>	\$ 18.00 ✓	14.40
SUB-TOTAL SPARE PARTS		\$ 5,456.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2303 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER BRACE - RH <i>Best</i>	\$ 107.00 ✓	85.60
22	FRONT WHEEL HOUSING LINER - RH <i>not in</i>	\$ 220.00 +	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>not in</i>	\$ 82.00 +	
24	FRONT WHEEL SPOILER - RH <i>cracked.</i>	TBC 65.10+	52.32
25	FRONT WHEEL SPOILER TRIM - RH <i>not in</i>	\$ 33.00 +	
26	FRONT FENDER STONE CHIP GUARD - RH <i>not in</i>	\$ 46.00 ✓	36.64
27	FRONT FENDER TOP COVER - RH <i>not in</i>	\$ 28.00 ✓	22.24
28	FRONT HEADLIGHT CORNER TOP COVER - RH <i>not in</i>	\$ 21.00 ✓	16.80
29	HEADLIGHT - RH <i>cut</i>	\$ 7,087.00 ✓	5,669.60
30	HEADLIGHT LIFT CYLINDER - RH <i>Not Nec</i>	\$ 192.00 X	
31	SUNDRIES <i>Nec</i>	\$ 500.00 ✓	61.20
TOTAL SPARE PARTS		\$ 13,772.00	
TOTAL LABOUR CHARGES		\$ 4,922.00	
GRAND TOTAL		\$ 18,694.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adnan King*
Surveyed Date : *23/05/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0653/2019/DY/TF
Date : 22-May-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SLT 1672 G**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 12 Jul 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loo Seng Kong
Address : 2D Hong San Walk
#04-09
Singapore 689050
Telephone : (HP) +65 9007 8623
Type of Claim : Third Party Claims
Policy No. : 1800016639-01
Vehicle No : **SLX 2303 U**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 20/2/2018
Engine No : CVK 050074
Chassis No : WAUZZZF4XJA070674
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-May-19
Place of Accident : 2D Hong San Walk S(689050)-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 2303 U

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs headlight and rhs front fender. Re-organise crash management components. Reinstall all parts removed.		\$ 2,450.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.		\$ 1,800.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,922.00</u>	<u>\$ 3,022.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2303 U

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER FIXING PART	\$ 258.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	
4	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	
5	FRONT BUMPER SECURING STRIP	\$ 32.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 123.00	
7	FRONT BUMPER CARRIER	\$ 733.00	
8	FOAM FILLER PIECE	\$ 113.00	
9	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	\$ 27.12
10	RADIATOR BRACKET HOLDER	\$ 125.00	
11	FRONT BUMPER SUPPORT - RH & LH	\$ 52.00	
12	FRONT BUMPER SENSOR	2 \$ 462.00	
13	FRONT BUMPER SENSOR SEAL RING	4 \$ 12.00	
14	HORN - LOW TONE	\$ 262.00	
15	HORN BRACKET	\$ 26.00	
16	FRONT FENDER - RH	\$ 700.00	\$ 559.60
17	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	
18	FRONT FENDER CLOSING ELEMENT - RH	\$ 45.00	
19	FRONT FENDER BRACKET - RH	\$ 32.00	
20	POP RIVET	\$ 18.00	\$ 14.40
SUB-TOTAL SPARE PARTS		\$ 5,456.00	\$ 2,200.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2303 U

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
		<i>c/f</i>	\$ 2,200.32
21	FRONT FENDER BRACE - RH	\$ 107.00	\$ 85.60
22	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	
24	FRONT WHEEL SPOILER - RH	\$ 65.40	\$ 52.32
25	FRONT WHEEL SPOILER TRIM - RH	\$ 33.00	
26	FRONT FENDER STONE CHIP GUARD - RH	\$ 46.00	\$ 36.64
27	FRONT FENDER TOP COVER - RH	\$ 28.00	\$ 22.24
28	FRONT HEADLIGHT CORNER TOP COVER - RH	\$ 21.00	\$ 16.16
29	HEADLIGHT - RH	\$ 7,087.00	\$ 5,669.60
30	HEADLIGHT LIFT CYLINDER - RH	\$ 192.00	
31	SUNDRIES	\$ 500.00	\$ 61.20
TOTAL SPARE PARTS		\$ 13,837.40	\$ 8,144.08
TOTAL LABOUR CHARGES		\$ 4,922.00	\$ 3,022.00
GRAND TOTAL		\$ 18,759.40	\$ 11,166.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 23 May 2019 3:08 PM
To: mastura@premiumauto.com.sg; claims@premiumauto.com.sg
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: ACCIDENT INVOLVING SLX 2303 U AND YOUR INSURED SLT1672G DATED ON 17/05/2019 ***LKK REF:CC3/AIG19008891/pb3

Tracking:	Recipient	Delivery
	mastura@premiumauto.com.sg	
	claims@premiumauto.com.sg	
	Hsiao Tong (LKKAuto)	Delivered: 23/5/2019 3:08 PM
	Admin A	
	Meikwan@lkkauto.com	Delivered: 23/5/2019 3:08 PM
	shupei@lkkauto.com	Delivered: 23/5/2019 3:08 PM
	olivialau@lkkauto.com	Delivered: 23/5/2019 3:08 PM

Without Prejudice
Our Ref: CC3/AIG19008891/pb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLT1672G[AIG] & SLX 2303U DATED ON 17/05/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna| Case Handler
LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Thursday, 23 May 2019 9:42 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>; mastura@premiumauto.com.sg

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Claims <claims@premiumauto.com.sg>

Subject: RE: ACCIDENT INVOLVING SLX 2303 U AND YOUR INSURED SLT1672G DATED ON 17/05/2019 ***LKK REF:CC3/AIG19008891/pb3

Dear All,

Attached are the repair estimate for your kind reference.

Best Regards,

Diyana

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, 21 May, 2019 4:43 PM

To: mastura@premiumauto.com.sg; Claims <claims@premiumauto.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SLX 2303 U AND YOUR INSURED SLT1672G DATED ON 17/05/2019 ***LKK REF:CC3/AIG19008891/pb3

Dear Sir /Madam,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeit@lkkauto.com | fax: 6741-4108

10k 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mastura <mastura@premiumauto.com.sg>

Sent: Friday, 17 May 2019 7:00 PM

To: Admin A <admin-a@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>

Subject: ACCIDENT INVOLVING SLX 2303 U AND YOUR INSURED SLT1672G DATED ON 17/05/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

TP is insured with AIG

Do take note, kindly arrange the survey on 23/5/2019, Thursday, 10 AM

Thank you.

Best Regards,

Mastura

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 10990277290)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. mastura@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	21 May 2019 16:10	Cim Dtl Modified	Claimant's Name: -> LOO SENG KONG. Claimant's ID: -> S6873931D.	[A] Lau Shu Pei
2	21 May 2019 16:10	Cim Veh Model Changed	(200040) AUDI A4 2.0 (A).	[A] Lau Shu Pei
3	21 May 2019 16:10	Cim Created	Reg No: SLX2303U. Acct Date: 2019/05/17. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. L td. (SG). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Premium Automobiles Pte L td (UBI)	[A] Lau Shu Pei
4	21 May 2019 16:10	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):: Suggested Adj. : LKK Auto Consultants Pte Ltd.	[A] Lau Shu Pei
5	21 May 2019 16:10	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2019/05/30	[A] Lau Shu Pei
6	21 May 2019 16:10	Adj Mandate Set	Approved: 8000.00. Reinsp: Adj decides.	[A] Lau Shu Pei
7	21 May 2019 16:10	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (E xpress)	[I] Merimen Administrator
8	21 May 2019 16:10	Label Added	(23): Express.	[A] Lau Shu Pei
9	21 May 2019 16:10	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
10	12 Dec 2019 18:06	Adj Rpt Initiated		[A] Asher Sng Rong Yi
11	12 Dec 2019 18:06	Insured Phone No Updated	[None] -> [+6593892076]	[A] Asher Sng Rong Yi
12	12 Dec 2019 18:06	Cim Dtl Modified	JPJ Reg. Date: -> 2018/02/20.	[A] Asher Sng Rong Yi
13	12 Dec 2019 18:06	Cim Details Notified		[A] Asher Sng Rong Yi
14	09 Jan 2020 12:39	Adj Mandate Request	Cur.Req: 12699.71: LIABILITY: 100% B: 23 OI REVERSED AND HIT TP PARKED VEH	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[23/05/2019 14:56] Khanchna Pothuraj:
23/5/2019 @2.40PM - Spoke to OI. Informed OI on TP claim, agreed to settle and aware of NCD will be affected if applicable. Sent e-mail to OI. - Khanchna

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Reason)	Ref 1	Ref 2	Amount
2375490	12 Dec 2019 18:06:10	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLX2303U	SLT1672G	11.77

Print Received Message

This mail is associated with :

***SLX2303U (1277164082SG)
[SLT1672G]**

TP
LOO SENG KONG
May 17 2019 8:00AM
[YAP KIM LEE (YE JINLI)]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 13/01/2020 14:54 PM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12649.71) - SLX2303U - Claim Handler: Lee, Ming-Yao

Approved:12649.71:May try to negotiateLOR up to S\$ 140.00/day

Print Received Message

This mail is associated with :

***SLX2303U (1277164082SG)**
[SLT1672G]

TP

LOO SENG KONG

May 17 2019 8:00AM

[YAP KIM LEE (YE JINLI)]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/02/2020 16:32 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12699.71) - SLX2303U - Claim Handler: Lee, Ming-Yao

Approved:12699.71:May try to negotiateLOR up to S\$ 140.00/day

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT1672G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/TP/0653/2019/SM
21ST June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 2.0 TFSI 8W
Vehicle Chassis No. : WAUZZZF4XJA070674
Vehicle Regn No. : SLX 2303 U
Vehicle Mileage : 23037 KM
Vehicle Owner : Mr. Loo Seng Kong
Liability : **Direct Settlement by Khanchna of
LKK Auto Consultant Pte Ltd via email
dated 23/05/2019 with LOR/LOU.**
Accident Date : 17th May 2019
Place : Basement Carpark 2D Hong San Walk S689050
Repair Cost : \$ 11,947.71
WIP No. : 53906
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


10:00 am
22/6/2019



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LOO SENG KONG
 Period of Insurance : 20 Feb 2019 To 19 Feb 2020
 Engine No. : CVK050074
 Chassis No. : WAUZZZF4XJA070674

Vehicle No. : SLX2303U
 Policy No. : 1800016639-01
 Endorsement No. :
 Issued Date : 07 Feb 2019

ABOUT THE COVER

Make/Model : AUDI A4 Sedan 2.0 TFSI S tronic
 Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LOO SENG KONG - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125277

PREMIUM LEASING - TKC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

55C235

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 May 2019 Edit Reg		23 May 2019 00:00 Edit Adj Rpt	S\$11,166.08 Edit Estimates	S\$11,166.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: YAP KIM LEE (YE JINLI) , ID: S7677065D, Tel: +6593892076									
Main Claimant: LOO SENG KONG , ID: S6873931D									
Vehicle Reg. No.: SLX2303U		Date of Loss: 17/05/2019 08:00 - :59 14 Months and 27 Days From LTA Reg Date (Man Yr)							
Claim Type: TP / 1277164082SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLT1672G		Policy No. (Claimant): 1800016639-01							
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (14/02/2020): Alert - Adj Mandate Approved (S\$12699.71) - SLX2303U - Claim Handler: Lee, Ming-... - AIG_SG_EXPRESS (13/01/2020): Alert - Adj Mandate Approved (S\$12649.71) - SLX2303U - Claim Handler: Lee, Ming-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX2303U (1277164082SG)
[SLT1672G]
TP
LOO SENG KONG
May 17 2019 8:00AM
[YAP KIM LEE (YE JINLI)]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	12/12/19 17:26	General View		Load JPG	☒
2	12/12/19 17:26	General View		Load JPG	☒
3	12/12/19 17:26	General View		Load JPG	☒
4	12/12/19 17:26	General View		Load JPG	☒
5	12/12/19 17:26	General View		Load JPG	☒
6	12/12/19 17:26	General View		Load JPG	☒
7	12/12/19 17:26	General View		Load JPG	☒
8	12/12/19 17:26	General View		Load JPG	☒
9	12/12/19 17:26	General View		Load JPG	☒
10	12/12/19 17:26	General View		Load JPG	☒
11	12/12/19 17:26	General View		Load JPG	☒
12	12/12/19 17:26	General View		Load JPG	☒
13	12/12/19 17:26	General View		Load JPG	☒
14	12/12/19 17:26	General View		Load JPG	☒
15	12/12/19 17:26	General View		Load JPG	☒
16	12/12/19 17:26	Reinspection Photo		Load JPG	☒
17	12/12/19 17:26	Reinspection Photo		Load JPG	☒
18	12/12/19 17:26	Reinspection Photo		Load JPG	☒
19	12/12/19 17:26	Reinspection Photo		Load JPG	☒
20	12/12/19 17:26	Reinspection Photo		Load JPG	☒
21	12/12/19 17:26	Reinspection Photo		Load JPG	☒
22	12/12/19 17:26	Reinspection Photo		Load JPG	☒
23	12/12/19 17:26	Reinspection Photo		Load JPG	☒
24	12/12/19 17:26	Reinspection Photo		Load JPG	☒
25	12/12/19 17:26	Reinspection Photo		Load JPG	☒
26	12/12/19 17:26	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	21/05/19 16:10	TP GIA REPORT		Load PDF	
2	23/05/19 14:56	EMAIL TO OI		Load PDF	
3	24/05/19 16:59	TP ESTIMATE- MARKED		Load PDF	
4	09/01/20 12:40	TP LOD		Load PDF	
5	20/01/20 14:23	EMAIL FROM WSP DD 200120		Load PDF	
6	18/02/20 10:23	WORKSHOP INVOICE		Load PDF	
7	18/02/20 10:23	AUTHORISATION TO ACT FORM		Load PDF	
8	18/02/20 10:23	Release Voucher		Load PDF	
9	18/02/20 10:23	RENTAL RECEIPT		Load PDF	
10	18/02/20 10:23	LOD		Load PDF	
11	18/02/20 10:23	GIA SEARCH		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	22/05/19 09:18	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLT1672G (Insd veh)	Model:	AUDI A4 2.0 (A)
	SLX2303U (TP veh)		
Date of Accident:	17/05/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	20,072.56
Final Repair Cost	:	\$	11,947.71
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	750.00 5 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	12,699.71
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
		23	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 12,699.71
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

18 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19008891/AES3Q2

Date: 18/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLX2303U

Insured Vehicle No : SLT1672G

Date of Loss: 17/05/2019

Nature of Claim: TP

Claim No: 1277164082SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX2303U

Make & Model: AUDI A4, 2.0 (A)

Engine No: CVK050074

Reg. Date: 20/02/2018 (Man. Year: 2018)

Chassis No: WAUZZZF4XJA070674

Colour: Silver

Odometer: 20531 km

Engine Capacity: 1984 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/55R19

Rear Tyre Size: 245/55R19

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,837.40	8,144.08	5,693.32	41.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,922.00	3,022.00	1,900.00	38.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,759.40	11,166.08	7,593.32	40.48
+ GST 7.00/7.00% (S\$)	1,313.16	781.63	531.53	40.48
Nett Amount (S\$)	20,072.56	11,947.71	8,124.85	40.48
+ Car Rental (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,699.71		

INSPECTION

Date of Assignment: 23/05/2019

Date Inspected: 23/05/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,999.00 FS	*1,599.20 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	191.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUILDE - RH	Not Necessary	56.00 FS	*- FS
5	1		*FRONT BUMPER SECURING STRIP	Not Necessary	32.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	123.00 FS	*- FS
7	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
8	1		*FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	34.00 FS	*27.12 FS
10	1		*RADIATOR BRACKET HOLDER	Not Necessary	125.00 FS	*- FS
11	2		*FRONT BUMPER SUPPORT - RH & LH	Not Necessary	52.00 FS	*- FS
12	2		*FRONT BUMPER SENSOR	Not Necessary	462.00 FS	*- FS
13	4		*FRONT BUMPER SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
14	1		*HORN - LOW TONE	Not Necessary	262.00 FS	*- FS
15	1		*HORN BRACKET	Not Necessary	26.00 FS	*- FS
16	1		*FRONT FENDER - RH	Dented	700.00 FS	*559.60 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
18	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	45.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH	Not Necessary	32.00 FS	*- FS
20	1		*POP RIVET	Necessary	18.00 FS	*14.40 FS
21	1		*FRONT FENDER BRACE - RH	Bent	107.00 FS	*85.60 FS
22	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	220.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
24	1		*FRONT WHEEL SPOILER - RH	Cracked	65.40 FS	*52.32 FS
25	1		*FRONT WHEEL SPOILER TRIM - RH	Not Necessary	33.00 FS	*- FS
26	1		*FRONT FENDER STONE CHIP GUARD - RH	Necessary	46.00 FS	*36.64 FS
27	1		*FRONT FENDER TOP COVER - RH	Necessary	28.00 FS	*22.24 FS
28	1		*FRONT HEADLIGHT CORNER TOP COVER - RH	Necessary	21.00 FS	*16.16 FS
29	1		*HEADLIGHT - RH	Cut	7,087.00 FS	*5,669.60 FS
30	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	192.00 FS	*- FS
31	1		*SUNDRIES	Necessary	500.00 FS	*61.20 FS
Total Parts (\$\$)					13,837.40	8,144.08

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS HEADLIGHT AND RHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,800.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,922.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >