

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0653/2019/DY/TF
Date : 22-May-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLT 1672 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loo Seng Kong
Address : 2D Hong San Walk
#04-09
Singapore 689050
Telephone : (HP) +65 90078623
Type of Claim : Third Party Claims
Policy No. : 1800016639-01
Vehicle No : **SLX 2303 U**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 20/2/2018
Engine No : CVK 050074
Chassis No : WAUZZZF4XJA070674
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-May-19
Place of Accident : 2D Hong San Walk S(689050)-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 2303 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs headlight and rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1250	
3	To respray front bumper and rhs front fender. ✓	\$ 1,800.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,922.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2303 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>del</i>	\$ 1,999.00	✓
2	FRONT BUMPER FIXING PART <i>me</i>	\$ 258.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>me</i>	\$ 191.00	+
4	FRONT BUMPER AIR GUIDE - RH <i>me</i>	\$ 56.00	+
5	FRONT BUMPER SECURING STRIP <i>me</i>	\$ 32.00	+
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>me</i>	\$ 123.00	+
7	FRONT BUMPER CARRIER <i>me</i>	\$ 733.00	+
8	FOAM FILLER PIECE <i>me</i>	\$ 113.00	+
9	FRONT BUMPER GUIDE SECTION - RH <i>me</i>	\$ 34.00	✓
10	RADIATOR BRACKET HOLDER <i>me</i>	\$ 125.00	+
11	FRONT BUMPER SUPPORT - RH & LH ?	\$ 52.00	?
12	FRONT BUMPER SENSOR <i>me</i>	2 \$ 462.00	+
13	FRONT BUMPER SENSOR SEAL RING <i>me</i>	4 \$ 12.00	+
14	HORN - LOW TONE <i>me</i>	\$ 262.00	+
15	HORN BRACKET <i>me</i>	\$ 26.00	+
16	FRONT FENDER - RH <i>Dented</i>	\$ 700.00	✓
17	FRONT FENDER ATTACHMENT PARTS ?	\$ 183.00	?
18	FRONT FENDER CLOSING ELEMENT - RH ?	\$ 45.00	?
19	FRONT FENDER BRACKET - RH ?	\$ 32.00	?
20	POP RIVET <i>me</i>	\$ 18.00	✓
SUB-TOTAL SPARE PARTS		\$ 5,456.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2303 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER BRACE - RH ?	\$ 107.00	?
22	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$ 220.00	+
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 82.00	+
24	FRONT WHEEL SPOILER - RH <i>new</i>	TBC	+
25	FRONT WHEEL SPOILER TRIM - RH <i>new</i>	\$ 33.00	+
26	FRONT FENDER STONE CHIP GUARD - RH <i>new</i>	\$ 46.00	✓
27	FRONT FENDER TOP COVER - RH <i>new</i>	\$ 28.00	✓
28	FRONT HEADLIGHT CORNER TOP COVER - RH <i>new</i>	\$ 21.00	✓
29	HEADLIGHT - RH <i>cut</i>	\$ 7,087.00	✓
30	HEADLIGHT LIFT CYLINDER - RH ?	\$ 192.00	?
31	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS		\$ 13,772.00	
TOTAL LABOUR CHARGES		\$ 4,922.00	
GRAND TOTAL		\$ 18,694.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan King
Surveyed Date : 03/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant