

Asher

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X**FINAL REPORT**

Estimate No. : b1 51242
 Date Estimated : 21/05/2019
 Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
 Kit Chui Jing (Jie CuiJing)
 268 Bukit Batok East Avenue 4
 #12-244

- ACCOUNT - 121
 AIG Asia Pacific Insurance Pte. Ltd.
 78 Shenton Way
 #08-16 Chartis Building
 Singapore 079120

Singapore 650268

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF1313D	LC94376	21/08/2018	X3 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear M bumper and attachments include knocking out dents caused by the accident	850.00		850.00 ✓
To spray paint rear bumper	934.00		934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (M/PMMA)	1,531.70	1.00		1,531.70 ✓
REAR BUMPER BOTTOM TRIM PANEL (M)	364.70	1.00		364.70 ✓
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00		20.20 ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,916.60
Total Labour & Parts :	3,930.60 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,930.60
GST @7%:	275.14
Grand Total :	4,205.74

BMW Dealer

LKK Auto Co. Ltd. notify
the Repairer as follows:
• To repair vehicle in spray painting

Performance Motors Limited
A Sime Darby Motors Company (Information)
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-free Number (1800-2255263) without Prejudice basis
legal motorist's price is allowed

303, Alexandra Road (must be authorised by Sime Darby Performance Centre)
Singapore 159944
Fax: 64747770

280, Kembangan Road
East Coast Centre
Singapore 159944
Fax: 63449773

Acknowledged by Repairer
Signature: _____
Date: _____

GST REG. NO : M2 - 0020081 - X

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time _____ Excess S\$ _____
Surveyor's Name _____ Sign _____
Surveyor's Tel _____ Authorised Yes / No _____
Authorised Date _____ Time _____

REGN. NO. M2-0020081-X PHOTO BY SURVEYOR Yes / No PML Yes / No
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (After Sales)
64796624 (Motorrad)
No. of Working Days Recommend _____

21 MAY 2019

ESTIMATE

Estimate No. : b1 51242 Page No. : 1 of 4
Date Estimated : 21/05/2019
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR - Kit Chui Jing (Jie CuiJing) 268 Bukit Batok East Avenue 4 #12-244 Singapore 650268	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF1313D	LC94376	21/08/2018	X3 sDrive20i	0

DESCRIPTION	VALUE
To replace rear M bumper and lower bumper trim and attachment include knocking cause by the accident .	850 1,700.00
Painting rear bumper .	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	80.00
Total Labour 1:	2,995.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER	1	739.80	739.80
LH SIDE GUIDE FOR BUMPER	1	61.50	61.50
RH SIDE GUIDE FOR BUMPER	1	61.50	61.50
REAR BUMPER BOTTOM REINFORCEMENT	1	70.90	70.90
REAR BUMPER PANEL PRIMED (M/PMA)	1	1,531.70	1,531.70
REAR BUMPER BOTTOM TRIM PANEL (M)	1	364.70	364.70
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
ULTRASONIC SENSOR ALPINWEISS (U300)	2	380.65	761.30
Supp- Bmt-4 bumper cut /			
Total Parts :			3,611.60

Steve (LKK) WKL P/P 10/6/19, 11 am	Labour 1	:	2,995.00
83228813	Parts	:	3,611.60
	Labour 2	:	0.00
	Excess	:	0.00
	Total GST @ 7%	:	462.46
	Grand Total	:	7,069.06

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **