

Kj
Not Authorized
Running Bk paint
2 days



ESTIMATE TO REPAIR

VEHICLE NO. : SLL 4881 S
MAKE : AUDI
MODEL : Q3 1.4 TFSI S TRONIC
YEAR : 2017
CHASSIS NO : WAUZZZ8U9HR060095

SURVEYOR NAME : Kenneth (LKK)
DATE OF SURVEY : 28th May 2019
TIME OF SURVEY :

DATE : 18-May-19
DATE OF ACCIDENT : 15-May-18
THIRD PARTY REF : SJV 7683 Z / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Bu 1pc	\$ 950.00 ✓
1 pc	Rear Bumper Reinforcement ✓			\$ Bu	\$ 450.00 ✓
1 pc	Rear Bumper Lower Garnish			\$ cm	\$ 350.00 ✓
2 pcs	Rear Bumper Sensor ✓			\$	\$ 400.00 ✓
	Less 10%		\$ 200.00	Short	\$ 2,150.00
					\$ 215.00
					\$ 1,935.00
	To putty and spray painting				\$ 300.00 2501
	To check rear wiring and replace sensor				\$ 120.00 601
	Labour Charges				\$ 250.00 ✓
	Part 8 \$2150.00				
	-10% \$215.00				
	\$1935.00				
	Labour \$560.00				
	\$2495.00				
	-20% \$499.00				
	\$1996.00				
	02 days				
	4/8 \$2000.00 ✓ ok				
TG/RA-	Total				\$ 2,605.00

Lim Tan Motor Pte Ltd

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd