

ESTIMATE TO REPAIR

VEHICLE NO. : SLL 4881 S
 MAKE : AUDI
 MODEL : Q3 1.4 TFSI S TRONIC
 YEAR : 2017
 CHASSIS NO : WAUZZZ8U9HR060095

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 18-May-19
 DATE OF ACCIDENT : 15-May-18
 THIRD PARTY REF : SJV 7683 Z / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 950.00
1 pc	Rear Bumper Reinforcement				\$ 450.00
1 pc	Rear Bumper Lower Garnish				\$ 350.00
2 pcs	Rear Bumper Sensor		\$ 200.00		\$ 400.00
					\$ 2,150.00
	Less 10%				\$ 215.00
					\$ 1,935.00
	To putty and spray painting				\$ 300.00
	To check rear wiring and replace sensor				\$ 120.00
	Labour Charges				\$ 250.00
TG/RA-	Total				\$ 2,605.00

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd