



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER:
Tan Teck Chye

India International Insurance Pte Ltd (HQ)

Singapore

L44 - Marcus

22/05/19 C 0955h

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	TP020052019
Policy No:		Date of Loss:	17/05/2019
Vehicle Reg. No.:	SLK2176M	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (Insured):	Tan Lee Hao		

Make/Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Vehicle Reg. Date:	10/01/2017
Vehicle Colour:	Silver	Chassis No:	GK81101390
Engine No:	L15B5001677		
Odometer:	0 KM		

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair (day) 6

Description of Accident/Loss ON 17.05.2019 AT ABOUT 1815 HRS, I WAS DRIVING IN MY VEHICLE (A: SLK2176M) ALONG SLIP ROAD OF SEAH STREET. UPON REACHING THE SLIP ROAD TO ENTER NORTH BRIDGE ROAD, I STOPPED TO GIVE WAY TO THE TRAFFIC ON THE MAIN ROAD. WHEN I WAS ABOUT TO MOVE OFF, I FELT A SUDDEN IMPACT FROM BEHIND AND REALIZED VEHICLE (B: SKW4073L) HAD HIT ONTO THE REAR PORTION OF MY VEHICLE. VEHICLE A (SLK2176M): NO PASSENGER ON BOARD. VEHICLE B (SKW4073L): NO PASSENGER ON BOARD.

Remarks:
Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	7,162.48
Labour	10.00
Paintwork Labour	1,450.00
Towing	1,200.00
	0.00

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Gross Total (\$\$)	9,822.48
+ GST 7.00% (\$\$)	687.57
Nett Amount (\$\$)	10,510.05

This claim is handled by: OW CAYMEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 May 2019)
 Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/SLK2176M/21/05/2019 14:12
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*tailgate lid <i>so 600</i>	20.00	0.00	*1,050.00 FL	—
2	1		*tailgate lid lock top <i>sef/tw</i>	20.00	0.00	*189.00 FL	—
3	1		*tailgate lid lock latch bottom <i>11</i>	20.00	0.00	*25.70 FL	X
4	1		*tailgate lid weatherstrip <i>tw</i>	20.00	0.00	*125.00 FL	—
5	1		*tailgate lid Shuttle badge <i>tw</i>	20.00	0.00	*65.20 FL	—
6	1		*tailgate lid outer chrome garnish <i>sef/cna</i>	20.00	0.00	*243.00 FL	—
7	1		*tailgate lid outer press opening switch <i>11</i>	20.00	0.00	*95.30 FL	X
8	1		*tailgate lid inner closing handle garnish <i>11</i>	20.00	0.00	*25.70 FL	X
9	2		*tailgate lid rubber stopper <i>11</i>	20.00	0.00	*43.00 FL	X
10	2		*rear licence plate <i>11</i>	20.00	0.00	*68.40 FL	X
11	1		*rear windscreen glass bottom weatherstrip <i>tw</i>	20.00	0.00	*125.60 FL	—
12	1		*rear end panel outer <i>so 5.00</i>	20.00	0.00	*365.80 FL	—
13	1		*rear bumper <i>so 70.12</i>	20.00	0.00	*860.00 FL	—
14	2		*rear bumper side retainer <i>2/K Bst</i>	20.00	0.00	*96.40 FL	12C
15	1		*rear windscreen glass sealant <i>tw</i> <i>405.2</i>	0	0.00	*150.00 FS	405.2
16	1		*rear windscreen glass sponge <i>tw</i> <i>305.2</i>	0	0.00	*100.00 FS	305.2
17	1	<i>sef</i>	*rear bumper parking sensor <i>shid</i> <i>2005.2</i>	0	0.00	*450.00 FS	2005.2
18	1		*rear licence plate <i>11</i>	0	0.00	*40.00 FS	X
19	1		*tailgate lid centre logo <i>tw</i>	20.00	0.00	*48.00 FL	—
20	1		*tailgate lid inner trim <i>se 70.12</i>	20.00	0.00	*320.00 FL	—
21	8		*tailgate lid inner trim clips <i>tw</i> <i>cna</i>	20.00	0.00	*34.40 FL	—
22	1		*rear lamp right (with body) <i>cna</i>	20.00	0.00	*597.20 FL	—
23	1		*rear lamp right (with tailgate) <i>2</i>	20.00	0.00	*395.00 FL	—
24	1		*rear bumper tow cover <i>cna</i>	20.00	0.00	*45.00 FL	X
25	1		*rear bumper reflector right <i>cna</i>	20.00	0.00	*47.30 FL	—
26	1		*rear bumper reflector garnish right <i>tw</i>	20.00	0.00	*45.00 FL	—
27	1		*rear bumper end splash cover right <i>11</i>	20.00	0.00	*129.60 FL	X
28	1		*rear end panel inner trim <i>se 70.12</i> <i>188.40</i>	20.00	0.00	*320.00 FL	—
29	6		*rear end panel inner trim clips <i>11</i>	20.00	0.00	*25.80 FL	X
30	1		*rear end panel extension trim right <i>11</i>	20.00	0.00	*155.50 FL	X
31	1		*rear fender inner trim lower right <i>se 70.12</i>	20.00	0.00	*489.60 FL	—
32	1		*reverse camera <i>11</i>	20.00	0.00	*1,041.60 FL	X
33	1		*rear luggage floor panel <i>2</i>	20.00	0.00	*956.00 FL	X

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 8,768.10
 - List Item Discount on L Items (S\$) 1,605.62
 Total Parts (S\$) 7,162.48

Tan Lim Motor Pte Ltd/SLK2176M/21/05/2019 14:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

7-5233.70
 202
 4186.96

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New	1,200.00
<u>Labour Items</u>			
2	To reinstall of rear bumper parking sensor.	New	80.00
3	To remove and refit rear windscreen glass.	New	120.00
4	To check electrical lighting concerned.	New	50.00
5	To rust-proofing of the affected areas.	New	100.00
6	To remove and install video camera & reverse camera.	New	200.00
7	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	900.00
Gross Labour Cost (S\$)			2,650.00

Tan Lim Motor Pte Ltd/SLK2176M/21/05/2019 14:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1 Defu Lane 6 Singapore 539365
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

6526.96