

11/03/2013

ASS. REC. BY:

REF: CS/MSG19008906/TIVd3/n2

Special Instruction:

Surveior: Taufik

ASSIGNMENT (Office)

From (Person): Elaine Ngai Sian Mei

of MSIG

Date/Time: 21.5.19 9.00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 3559E

Insured:

SLV 9100M

at Workshop m/s Borneo Motors

Tel:

98476171

of Toyota BodyCare Centre, No 2 Pandan Crescent

Policy No: 29070041

Claim No: 589476

Sum Insured:

Excess:

D.O.A. 31.3.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 21.5.19 01.51pm

Person Contacted: Thomas

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SME 3559E - NA/MSG19006528/r3	D.O.A. - 31/03/2019
23/5/19	Send preli: revised via merimen	
27/5/19	Final fig \$ 2644.02 confirmed by email (Ref 2336.34, 4713)	

Surveyor

Taufik

REF: MS19

ASSIGNMENT

From:

Date: 22-5-2019

Estimated Cost:

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SME 3559E

at Workshop n/s Borneo Motor
of 2 Pandan Crescent

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Refor 12.00 P.M

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"rup"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SME 3559E

Yr Regn:

2018, Sep.

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota Gamba

C.C

1496

Colour:

Orange

A/C: Insured / Std / NI / NA

Sp. Reading:

12774

T/Radio: Insured / Std / NI / NA

Eng/No:

12774
MHFZ28H3300056579

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

195/50R16

R:

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22/5/19 @ 1030

Survey held at

Borneo Pandan

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/5 - typist

Report Format:

Merimen

Lump Sum / I.B.I. (\$

2644.02

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

10

160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 23 May 2019

Preliminary Advice

Insured Vehicle No	: SLV9720M	Accident Date	: 31/03/2019
TP Vehicle No	: SME3559E	Assignment Date	: 21/05/2019
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 5.00
Date of Inspection	: 22/05/2019		
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD - (PANDAN) (HQ) TOYOTA BODYCARE CENTRE, NO. 2 PANDAN CRESENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,980.36
Revised Amount	:S\$	2,644.02
Check Items (Estimated)	:S\$	146.54
Total	:S\$	2,790.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2019		21 May 2019 09:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:	CHEE KHENG HOCK ROTHSCHILD, ID: S8128913A																							
Main Claimant:	TAN TENG CHORK, ID: S71299428																							
Vehicle Reg. No.:	SME3559E	Date of Loss:	31/03/2019 00:00 - :59 [6 Months and 4 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 589476	Policy/Cover Note No.:	29070041 (Comprehensive) Coverage: 24/01/2019 - 23/01/2020																					
Vehicle Reg. No. (Insured):	SLV9720M	Policy No. (Claimant):																						
Repairer:	Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/05/2019]																							
Adj Asg. Remarks:	MANUALLY ASSIGNED. CONTACT: THOMAS PANG @ 9847 6171 / 6631 1860.																							
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail																					
There are no mail for this case.																								
☐ ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 27 May 2019 9:34 AM
To: Thomas Pang PTCBC; Taufikh (LKKAUTO)
Cc: SUR; Admin A
Subject: RE: Finalize REport for SME3559E

Dear Thomas,

WITHOUT PREJUDICE

Confirmed amount \$2644.02 before GST @ 4 working days.

Kindly send Final invoice and all supporting documents directly to MSIG

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Friday, 24 May 2019 4:40 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Finalize REport for SME3559E

Dear Taufikh,

Attach finalize report for your perusal. 04 working days

Thank you

Regards

thomas

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

MSDh
ESTIMATE

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Teng Chork (Chen Dingzuo) 120 Lorong L Telok Kurau #05-01 Singapore 425553 Mobile: 81111800
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT	E3	NSP170R	27/09/2018	SME3559E	0	43024 72/DS/SME3559E
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFZ28H3300056579	2NRX361664	60	Thomas Pang W T	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: MSIG INSURANCE TP VEH: SLV9720M DATE OF ACC: 31.03.2019			✓	50 · 100.00
2	C	BP-LAB2 R/I REAR REVERSE SENSOR TO FAC REPAIR (N ETT)			X	164.00
3	C	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NET T)			✓	111.52
4	C	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)			✓	164.00
5	C	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS			✓	656 · 1968.00
6	C	BP-RES2 RESPRAY ACC AFFECTED AREAS			✓	1076 · 1614.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER & REAR TAILGATE)			✓	183.18
8	1	SPC507-OD014 70 BACK SENSOR (4R8, ORANGE ME)	1.00	172.40	15.00	146.54
9	2	S52151-OD010 EXTENSION, RR BUMPER	1.00	187.50	15.00	159.37
10	3	S52161-OD070 EXTENSION, RR BUMPER	1.00	127.40	15.00	108.29
11	4	S52162-OD040 EXTENSION, RR BUMPER	1.00	127.40	15.00	108.29
12	5	S52162-OD050 PLATE, RR BUMPER, NO	1.00	20.60	15.00	17.51

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour	Tanfiah 97495749 WP 22/5/19 21030 Resurvey before paint sur@lkkauto.com A-5 days
			Less
			Amount Due

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE 01/04/2019
TIME 17:38

3942676

3942676

TO SECURITY GUARD
PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES:

VEHICLE NO SME3559E

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	Mr Tan Teng Chork (Chen Dingzuo) 120 Lorong L Telok Kurau #05-01 Singapore 425553 Mobile: 81111800	
		Document No		
		0		
		Document Date		
		01/04/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT	E3	NSP170R	27/09/2018	SME3559E	0	43024 72/DS/SME3559E
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On	
MHFZ28H3300056579		2NRX361664	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	6	T90975-02086	1.00	72.20	15.00	Net 61.37 ✓
14	7	S75442-0D290	1.00	35.00	15.00	Net 29.75 ✓
15	8	S75441-0D070	1.00	52.40	15.00	Net 44.54 ✓
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 675.66	4,980.36
		Labour 4,121.52	GST 7.00% 348.63
		Materials 183.18	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 5,328.99

PLEASE TEAR ALONG PERFORATED LINE

3942677

TO SECURITY GUARD

3942677

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 01/04/2019
TIME 17:38

VEHICLE NO SME3559E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

INTERNAL INVOICE

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 118481
Tel No: 6631 1188

New Vehicle Preparation PDI
***** For use by BMS PDI *****
.
.
.

10100001 /NEWVEHIC

38028540

Mr TC Tan
120 Lorong L Telok Kurau
#05-01
Singapore 425553

04/10/2018

18 MYQKT EX	NSF170R 27/09/2018	SME3559E	1	36085	69INT/SME3559E
WHF228H3300050579	CHRX361664	00	Raymond Seah L M	--/--/----	0.00 00/--/---- 0.00

M D1068*-PLATINUM SHINEPRO
1 * PSPRO PDI LABOUR FOR PLATINUM SHINE PDI
D1068D) Platinum Shine Glass Coating
1 * PSPRO MAT PDI PLATINUM SHINE SET

0:00	GST 0.00%	0.00
0:00		0.00
0:00		
0:00		

04/10/2018
09:18

SME3559E



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 24/05/2019	Mr Tan Teng Chork (Chen Dingzuo) 120 Lorong L Telok Kurau #05-01 Singapore 425553 Mobile: 81111800

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT	E3	NSP170R	27/09/2018	SME3559E	0	43024
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MHFZ28H3300056579 2NRX361664 60 Thomas Pang W T 22/05/2019 8.00 22/05/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: MSIG INSURANCE				50.00
		TP VEH: SLV9720M				
		DATE OF ACC: 31.03.2019				183.16
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE				
		PER PANEL APPLICATION				111.52
		(REAR BUMPER & REAR TAILGATE)				
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NET				656.00
		T)				
4	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				1076.00
		AND STRAIGHTEN/REALIGN				164.00
		ACC AFFECTED AREAS				159.37
5	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				108.29
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				61.37
7	1	S52151-0D010 EXTENSION, RR BUMPER	1.00	187.50	15.00	29.75
8	2	S52161-0D070 EXTENSION, RR BUMPER	1.00	127.40	15.00	44.54
9	3	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	15.00	
10	4	S75442-0D290 PLATE, BACK DOOR NAM	1.00	35.00	15.00	
11	5	S75441-0D070 PLATE, BACK DOOR NAM	1.00	52.40	15.00	

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour 403.32 Materials 2,057.52 Lubrication/Fluid 183.18 Others 0.00 0.00	2,644.00 GST 7.00% 185.01 Less 0.00 Amount Due 2,829.10

396904

PLEASE TEAR ALONG PERFORATED LINE

396904

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 24/05/2019
TIME 15:48

VEHICLE NO

SME3559E

SIGNATURE



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19008906/T1VD3N2
Date: 28/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29070041
Claimant: SME3559E Insured Vehicle No: SLV9720M
Vehicle No: Nature of Claim: TP Claim No: 589476
Date of Loss: 31/03/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME3559E Engine No: 2NRX361664
Make & Model: TOYOTA SIENTA, 1.5 CVT ELEGANCE (A) Chassis No: MHFZ28H3300056579
Reg. Date: 27/09/2018 (Man. Year: 2018) Odometer: 12774 km
Colour: Orange
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Price: Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/50R16 Rear Tyre Size: 195/50R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	775.66	453.32	322.34	41.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,204.70	2,190.70	2,014.00	47.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,980.36	2,644.02	2,336.34	46.91
+ GST 7.00/7.00% (\$\$)	348.63	185.08	163.55	46.91
Nett Amount (\$\$)	5,328.99	2,829.10	2,499.89	46.91

INSPECTION

Date of Assignment: 21/05/2019
Date Inspected: 22/05/2019 Inspected At:

Borneo Motors (singapore) Pte Ltd -
(pandan) (HQ)
Toyota Bodycare Centre, No. 2 Pandan
Crescent
Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2019)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME3559E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BACK SENSOR (4R8,ORANGE ME)	Not Necessary	146.54 FS	*- FS
2	1		*EXTENSION,RR BUMPER	Deformed	159.37 FS	*159.37 FS
3	1		*EXTENSION,RR BUMPER RH	Deformed	108.29 FS	*108.29 FS
4	1		*EXTENSION,RR BUMPER LH	Not Necessary	108.29 FS	*- FS
5	1		*PLATE,RR BUMPER,NO	Not Necessary	17.51 FS	*- FS
6	1		*TOYOTA SYMBOL EMBLEM	Necessary	61.37 FS	*61.37 FS
7	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
8	1		*PLATE,BACK DOOR NAM	Necessary	29.75 FS	*29.75 FS
9	1		*PLATE,BACK DOOR NAM	Necessary	44.54 FS	*44.54 FS
Total Parts (S\$)					775.66	453.32

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R/I REAR REVERSE SENSOR TO FAC REPAIR	New	164.00	0.00
2	CHECK WIRING AND CONDUCT WATER TEST	New	111.52	111.52
3	TO RESET ECU AND REPROGRAMME	New	164.00	164.00
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	1,968.00	656.00
5	RESPRAY ACC AFFECTED AREAS	New	1,614.00	1,076.00
6	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER & REAR TAILGATE)	New	183.18	183.18
Gross Labour Cost (S\$)			4,204.70	2,190.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >