

ASS. REC. BY:

REF:

CS/EQT19008908/R1/d3

Special Instruction:

02

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

EQT

Date/Time:

21/5/19 @ 2:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

XE 3507A

Insured:

at Workshop m/s

Yee Keong Motor

Tel:

62620218

of

No. 14 Penjuru Road

Policy No.:

Claim No.:

DMH001244-JG

Sum Insured:

Excess:

5000.00 (no waiver)

Make of Veh:

(Client's Record)

D.O.A

30/4/2019

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:20pm @ 21/5/19

Person Contacted:

Yee Keong

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

XE3507A - (03/EQT18015930 / K1/hq3q2

D.O.A: 30/8/2018

22/5 @ 4:13pm - revert via email, repair on lump sum.

24/5/19 @ 5:37pm Joel Goh informed C/A to Ex: \$5000 by email.

24/5/19 @ 6:04pm Informed Yee Keong C/A on LS basis to Ex: \$5000 by email.

Rasu will go recovery for supplementary on 28/5/19.

Surveyor *Jason*

REF:


51976

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 (OD / TP / WS / TP RES / OD RES / EVA / INV / MV)  
 To Inspect Vehicle No: **XE 3507A**  
 at Workshop m/s **YEE KEONG**  
 of **NO. 14, PUNJAB RD**  
 Insured: **EQI**  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: **5000**  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **130k**  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / **REV** / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **XE 3507A** Yr Regn: **2017 / SEP**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 (Truck / Trailer or)  
 Make: **SCANIA P360 CB6X4MHZ** c.c. **12742**  
 Colour: **WHITE** A/C: Insured / Std / NI / NA  
 Sp. Reading: **87490** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **4S2P6X4000 54 760 20**  
 Gen. Cond: Good / **Fair** / Poor / Burnt  
 Steering: **In order** / Jammed / Leaked / Burnt or  
 Brake: **In order** / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **315/80R22.5**  
 R: **D/O**  
 (BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front Rear  
 R/Bal. **8** mm R/Bal. **8/8** mm  
 L/Bal. **8** mm L/Bal. **8/8** mm  
 D.O.A. **30/04/19** D.O.I. **21/05/19**  
 Survey held at **YEE KEONG**  
 Des. of Damages: **FR** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>Lump Sum \$36,250 / Cred: 37062.90 (50%)</b>
	<b>RECEIVED 10 SEP 2019</b>

Date/Time, File Pass to?

1) **10/9 Typst**

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ **36250**)

Days Of Repair: **10**

Resurvey No. of Trip: **1**

Add Fee:

☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

Photos

Others

TOTAL

<b>300</b>
<b>300</b>

## Nivitha (LKK Auto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Tuesday, 21 May 2019 2:43 PM  
**To:** assignments  
**Subject:** OD SURVEY FOR XE3507A (DM19HO01244-JG)  
**Attachments:** 21052019143850-0001.pdf; XE3507A (30.04.19).pdf

Dear LKK

Attached OD estimates and GIA report.  
Please assist on this OD survey.

Excess: \$5,000.00 (no waiver)  
Survey and revert.

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 24 May 2019 6:04 PM  
**To:** yeekeongmotorengineering@gmail.com  
**Cc:** SUR  
**Subject:** OD VEHICLE XE 3507A (DOA: 30/04/2019)

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **XE 3507A** at repair cost on **Lump Sum basis (excess \$5,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shiau Chan (LKKAuto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Friday, 24 May 2019 5:37 PM  
**To:** Shiau Chan (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: OD SURVEY FOR XE3507A (DM19HO01244-JG)

Dear Shiau Chan

Please proceed to authorize OD up to \$44,546.13 before excess of \$5,000.00.


Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t*

---

**From:** Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]  
**Sent:** Thursday, May 23, 2019 11:21 AM  
**To:** Joel Goh  
**Cc:** SUR  
**Subject:** RE: OD SURVEY FOR XE3507A (DM19HO01244-JG)

Dear Joel,

Please find the attached of estimate.

Sorry for the inconvenience caused.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Thursday, 23 May 2019 11:15 AM  
**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 22 May 2019 4:18 PM  
**To:** Admin-D (LKKAuto); 'Joel Goh'; assignments  
**Cc:** SUR  
**Subject:** RE: OD SURVEY FOR XE3507A (DM19HO01244-JG)  
**Attachments:** PRELI ADVISED XE 3507A.pdf; Estimates.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **XE 3507A**  
**We did not authorise repair.**

**Repair on lump sum.**

**Please let us have your authorization**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 21 May 2019 3:27 PM  
**To:** 'Joel Goh' <[joel.goh@eqinsurance.com.sg](mailto:joel.goh@eqinsurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: OD SURVEY FOR XE3507A (DM19HO01244-JG)

Dear Joel,

Thank you for the assignment.

Best Regards,

G.Nivitha| Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]  
**Sent:** Tuesday, 21 May 2019 2:43 PM  
**To:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** OD SURVEY FOR XE3507A (DM19HO01244-JG)

Your Ref: DM19HO01244-JG

Date: 7/3/2018

Our Ref: CS/EQ19008908/R1td3The Motor Claims Department  
EQ INSURANCE COMPANY LTD

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. XE 3507A.**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 22/05/2019 at the premises of M/s Yee Keong Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>68,217.92</u>
Revised Estimate Amount	: S\$ <u>23,433.54</u>
"Check" Items Amount	: S\$ <u>21,112.59</u>
Market Value	: S\$ <u>130,000.00</u>
LTA Reimbursement Value	: S\$ <u>39,153.00</u>
Nett Value	: S\$ <u>90,847.00</u>

**Description of Damage:**

The vehicle sustained damages at the front portion

**Comments/ Present Status:**

Damages Consistent.  
We have not authorized repair.

Yours faithfully

Rasul  
Automotive Assessor

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5197E
Vehicle Details	
Vehicle No.:	XE3507A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 May 2019
Vehicle Make:	SCANIA
Vehicle Model:	P360CB6X4MHZ
Primary Colour:	Multi-Colour
Manufacturing Year:	2017
Engine No.:	DC13114L017026818
Chassis No.:	YS2P6X40005476020
Maximum Power Output:	-
Open Market Value:	\$109,249.00
Original Registration Date:	29 Sep 2017
First Registration Date:	29 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,463.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,890.00
COE Rebate Amount:	\$39,153.00
<b>Total Rebate Amount:</b>	<b>\$39,153.00</b>

The information contained herein is correct as at 22 May 2019

OK

130,000  
39,153  

---

90,847



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2019 18:18
Date Of Accident	30/04/2019 11:10
Exact Location Of Accident	ALONG SLE TOWARDS EXIT WOODLANDS AVE 12
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE3507A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KL ENVIRO PTE. LTD.
Co Reg No	201525197E
Email Address	SOH@KLENIRO.COM
Mobile Phone No	(LOCAL) +65-97550037
Alternative Phone No	OFFICE-68610332

### Vehicle Particulars

Manufacturer	SCANIA
Model	P360CB6X4MHZ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-005903
Cover Note Number	

### Driver

Name of Driver	BIAN CHUNKE
NRIC No	G2742906N
Date Of Birth	18/03/1996
Occupation	OUTDOOR
Date Of Driving Pass	11/09/2017
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87436319
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	19, SUNGEI KADUT LOOP, SINGAPORE 729462
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20190430/2128

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD8343C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YM6102K  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number YQ448G  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name UNKNOWN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? YM6102K  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name UNKNOWN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? YQ448G  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

#### DETAILS OF INJURED PERSON 3

Name UNKNOWN  
Approximate Age

Injuries Sustain

Injured person in which vehicle?

YQ448G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, Invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to Police Report

- ☐ Claim own policy
- ☐ Claim third party
- ☒ Claim OD LTP at other works hop Jim Quan
- ☐ For record purpose

Policy No. DMCP1418-005903  
Insurer FQ Veh. No. XE3S07A

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190430/2128

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

1 of 3

Report No. T/20190430/2128

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/04/2019 16:23	Vide Report No.:	Station Diary No.: 118
--	------------------	---------------------------

## Informant's Particulars

Name of Informant: BIAN CHUNKE			Address: C/O APT BLK 52 Choa Chu Kang North 6 #18-15 Yew Mei Green SINGAPORE 689575	
ID Type / ID No.: FIN NO / G2742906N			Contact No.: Home/Office: Mobile: 8743 6319	
Nationality: CHINESE			Email:	
Sex: Male	Age: 23	Date of Birth: 18/03/1996	Type of Informant: Driver	
Race: Chinese			Language: Chinese	Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 3,4 Date of Expiry:	

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/04/2019 11:10	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SELETAR EXPRESSWAY WOODLANDS AVENUE 12 SLE(BKE) Exiting Woodlands Ave 12				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
XD8343C	Lorry	MAN			Slightly Damaged	0
XE3507A	Lorry	SCANIA			Slightly Damaged	0
YM6102K	Lorry	ISUZU			Slightly Damaged	0
YQ448G	Lorry	MITSUBISHI			Slightly Damaged	1

## POLICE REPORT Pg. 2



**SINGAPORE  
POLICE FORCE**



T/20190430/2128

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

2 of 3

Report No. T/20190430/2128

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	BIAN CHUNKE	ID No.	G2742906N
Related Vehicle	XE3507A (Lorry)	Contact No.	8743 6319
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 30/04/2019 at about 1110hrs, while I was proceeding to work, I was travelling on SLE towards BKE and exiting from Woodlands Ave 12. While I was on the slip road, the road was packed and moving slowly. When exiting the slip road, I did not take notice that the vehicles in front of me had stopped and proceeded as per normal. When I realized that the vehicles in front were stationary, I could not stop my vehicle in time. Due to my vehicle being too heavy, I needed a larger breaking distance to stop in time. Thus, I collided into another lorry bearing YQ448G which was in front of me. This caused a chain of collisions that followed after. The vehicle(YQ448G) that I collided into had further collided with 2 other lorries bearing YM6102K and XD8343C. After the collision, I together with the driver from XD8343C made a check on the other drivers and called for ambulance. At that point of time, did not manage to get hold of their particulars. Soon after, ambulance, traffic police as well as SCDF arrived. The ambulance then conveyed 03 of the injured drivers from the other vehicles. I was then given a case card by the traffic police and was advised to head to the police center to lodge a police report. There were several damages on the vehicles:

- 1) My vehicle, XE8343C - Small dent on the front bumper and cracked wind shield
- 2) XD8343C - Minor scratches on rear bumper
- 3) YQ448G - Dent on the rear and front bumper
- 4) YM6102K -Dent on the rear and front bumper, cracked wind shield



POLICE REPORT Pg. 3



**SINGAPORE  
POLICE FORCE**



T/20190430/2128

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

3 of 3



Report No. T/20190430/2128

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / TAN RUI JIE 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/04/2019 16:23
Officer In Charge Of Case: TP / GIT / SI ONG CHEE HIEN Contact No.: 65476437	Classification Of Case:

Authentication Stamp  
NP168



# YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125

TEL/FAX: 62620218 | MOBILE: 97808928

Motor Claim

EQ Insurance Company Ltd

VEHICLE NUMBER : XE 3507 A

POLICY NO. DMCPHQ18-005903

Date: 17 May 19

## PARTS SUPPLY - LIST ITEMS

1	1pc	Radiator <del>bt</del> ? <del>bt</del> ✓	3141.06 ✓
2	2pcs	Radiator top bracket @ \$274.15 <del>cr</del> ? <del>X</del> <del>su</del> ✓	548.30 X
3	2pcs	Radiator bracket link @ \$205.57 ? <del>X</del> <del>su</del> ✓	411.14 X
4	1pc	Radiator expansion tank <del>X</del> <del>su</del> ✓	972.87 X
5	1pc	Front bumper <del>bt</del> ✓	1293.79 ✓
6	1pc	Front bumper corner o/s <del>bt</del> ✓	1112.41 ✓
7	1pc	Front bumper end piece o/s <del>ne</del> ✓	92.31 ✓
8	1pc	Front bumper bracket o/s <del>bt</del> ? <del>bt</del> ✓	1171.99 ✓
9	1pc	Front bumper bracket, side o/s <del>bt</del> ✓	97.59 ✓
10	1pc	Front bumper tow beam <del>X</del> <del>su</del> ✓	2862.70 X
11	1pc	LH Hinge lock <del>bt</del> ✓	332.38 ✓
12	1pc	Front grille panel <del>CR</del> ✓	1676.63 ✓
13	1pc	Front grille logo <del>ne</del> ✓	78.01 ✓
14	1pc	Front grille 'Scania' emblem <del>ne</del> ✓	64.54 ✓
15	1pc	Front grille badge <del>ne</del> ✓	100.85 ✓
16	1pc	Front windscreen <del>Bro</del> ✓	1480.20 ✓
17	3pcs	Windscreen adhesive @ \$420.74 <del>ne</del> ? <del>CR</del> ✓	1262.22 ✓
18	1pc	Air blower motor ? <del>CR</del> ✓	1350.67 ✓
19	1pc	Aircon bracket ? <del>CR</del> ✓	480.00 ✓
20	1pc	Air Duct ? <del>X</del> <del>su</del> ✓	833.83 X
21	1pc	Air Flap housing ? <del>CR</del> ✓	657.09 ✓
22	1pc	Aircon condenser <del>bt</del> ✓	2179.96 ✓
23	1pc	Aircon receiver drier ? <del>ut</del> ✓	383.33 ✓
24	1pc	Aircon discharge pipe ? <del>bt</del> ✓	875.25 ✓
25	1pc	Aircon liquid pipe assy ? <del>bt</del> ✓	1364.72 ✓
26	1pc	Aircon suction pipe ? <del>bt</del> <del>X</del> <del>su</del> ✓	753.26 X
27	1pc	Aircon evaporator ? <del>X</del> <del>su</del> ✓	1110.53 X
28	1pc	Aircon coil ? <del>X</del> <del>su</del> ✓	3701.48 X
29	1pc	LH Headlamp <del>bt</del> ✓	636.42 ✓
30	1pc	LH Headlamp seal <del>at</del> ✓	214.22 ✓
31	1pc	LH Headlamp bracket <del>at</del> ? <del>CR</del> ✓	951.03 ✓
32	1pc	LH Headlamp housing <del>at</del> ✓	483.37 ✓
33	1pc	Front grille panel, lower <del>CR</del> ✓	2499.04 ✓
34	2pcs	Front panel top mesh @ \$297.77 <del>bt</del> ✓	595.54 ✓
35	2pcs	Front panel lower mesh @ \$287.03 <del>bt</del> ✓	574.06 ✓
36	1pc	Front panel bracket LH <del>X</del> <del>su</del> ✓	66.28 X
37	1pc	Front panel hinges LH <del>X</del> <del>su</del> ✓	388.16 X
38	1pc	Front LH Cab corner <del>X</del> <del>su</del> ✓	1938.94 X
39	1pc	Front grille panel <del>CR</del> ✓	1676.61 ✓
40	2pcs	Front panel lock @ \$332.38 <del>H</del> (1pc) ✓	664.76 332.28 ✓
41	2pcs	Front wheel arch fender garnish, front @ \$866.22 <del>ne</del> (1pc) ✓	1732.44 866.22 ✓
42	1pc	Front step bracket @ \$428.90 <del>X</del> <del>su</del> ✓	857.80 X
43	1pc	Front shielding net <del>bt</del> ✓	490.92 ✓
44	1pc	Shielding net mesh <del>bt</del> ✓	287.13 ✓
45	1pc	Aircon coil ? <del>bt</del> ✓	1208.44 ✓
46	1pc	Charge cooler <del>bt</del> ✓	3701.35 ✓
47	1pc	Cooler top bracket <del>CR</del> ✓	280.00 ✓

# YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125

TEL/FAX: 62620218 | MOBILE: 97808928

Date: 17 May 19

7566.17

VEHICLE NUMBER : XE 3507 A

POLICY NO. D-19092536MFVS/13

48	1pc	Wiper blade	cut
49	2pcs	Wiper arm	bt
50	2pcs	Wiper link	? bt
51	1pc	Air Filter assy	CR
52	1pc	Sun Visor	CR
53	1pc	Sun Visor bracket	? bt
54	1pc	Sun Visor, bottom o/s	? bt
55	1pc	RH Stepboard	X
56	1pc	RH side lamp	CR
57	1pc	Wiper panel garnish	CR
58	1pc	Mesh Shielding net	X
Total Spare Parts			

Rasul  
Hp 900w/68

10 days

43

21/05/19 @ 1700

74.18	
377.52	
1572.06	
3527.41	41497.90
450.00	102
460.00	
680.00	37348.1
650.00	
125.00	
240.00	
287.13	
58078.92	

1set	1set	Front windscreen sealant	CR
1pc	1pc	Front no. plate	bt
1pc	1pc	ERP bracket	CR
1pc	1pc	Logos & Letterings	CR
1tin	1tin	Radiator Coolant	CR
Towing ? receipt			
Remove the necessary affected parts, X cut/weld front outer cab panel, dashboard inner panel, wiper panel, straighten front floor panel, both front chassis, and door pillar, front bulkhead panel, rooftop panel, and replace parts Putty and Spraypaint			
Remove and refit dashboard and finishes			
Remove and refit aircon parts, pipings, and rooftop aircon system and refill freon gas			
Remove and refit air cleaner and hoses			
Remove and refit front windscreen Tuff Kote			
Remove and refit wiring harness, fuses relays, refocus both headlamp beam, and replace parts and reset complete system using Diagnostic Tools			
Remove and refit both front & rear shock absorbers, brackets, stopper and coil spring			
Remove and refit radiator with fittings and pressure test cooling system			

EXCESS: 8000

Revers  
Resin after  
repair

40.00	
30.00	
29.00	
400.00	200
40.00	
400.00	100

3800.00 1000 + 300 = 13  
2000.00 800  
800.00 400

900.00 500

300.00 X  
150.00  
150.00 100  
500.00 250

400.00 X

200.00 150

TOTAL 68217.92

37348.90

LKK Auto Consultancy  
The Repairer  
• To resurvey the vehicle  
• To display the vehicle  
• Parts prices  
• Third party  
• No any other work is allowed  
• Supplementary items must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125

TEL/FAX: 62620218 | MOBILE: 97808928

Policy No. DMCPHA

18-005903

XE 3507 A

Date 28-5-19

Supplementary items

Fan ring

# 747.58 X nn

Fan cover

# 580.00 scd /

TOTAL # 1327.58

Fan assy

# 3767.40 Jam /

4347.40

10%

3912.66

TOTAL # 5094.98

P - 37348.11

S/N - 439.00

L - 3650.00

Suppl - 3912.66

---

45349.77

T - 20%

361279.81

45 - 36,250

10 days



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQI19008908/R1td3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 02-10-2019	
		Code : EQI	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
	Insured Veh.	Veh. Inspected	XE 3507A
	Policy No. DMCPHQ18-005903	Coverage (\$)	0.00
	Claim No. DMHO01244-JG	Excess (\$)	5,000.00
	Assign From JOEL GOH	Assign Date	21/05/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
	Make & Model SCANIA P360CB6X4MHZ	c.c	12742
	Engine No. HIDDEN	Year of Reg.	2017
	Chassis No. YS2P6X40005476020	Colour	WHITE
	Odometer 87490	Steering	IN ORDER
	Brakes IN ORDER	Modification	NIL
	General FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
	Accident Date 30/04/2019	Inspection Date	21/05/2019
	Survey held at YEE KEONG MOTOR ENGINEERING NO: 14 PENJURU ROAD SINGAPORE 609125		
<b>5a. Remarks</b>			
A)THE MARKET VALUE IS S\$130,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 3507A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	RADIATOR	BENT	3,141.06	3,141.06
2	RADIATOR TOP BRACKET @\$274.15	SERVICEABLE	548.30	-
2	RADIATOR BRACKET LINK @\$205.57	SERVICEABLE	411.14	-
1	RADIATOR EXPANSION TANK	SERVICEABLE	972.87	-
1	FRONT BUMPER	BENT	1,293.79	1,293.79
1	FRONT BUMPER CORNER O/S	BENT	1,112.41	1,112.41
1	FRONT BUMPER END PIECE O/S	NECESSARY	92.31	92.31
1	FRONT BUMPER BRACKET O/S	BENT	1,171.99	1,171.99
1	FRONT BUMPER BRACKET, SIDE O/S	BENT	97.59	97.59
1	FRONT BUMPER TOW BEAM	SERVICEABLE	2,862.70	-
1	LH HINGE LOCK	BENT	332.38	332.38
1	FRONT GRILLE PANEL	CRACKED	1,676.63	1,676.63
1	FRONT GRILLE LOGO	NECESSARY	78.01	78.01
1	FRONT GRILLE 'SCANIA' EMBLEM	NECESSARY	64.54	64.54
1	FRONT GRILLE BADGE	NECESSARY	100.85	100.85
1	FRONT WINDSCREEN	BROKEN	1,480.20	1,480.20
3	WINDSCREEN ADHESIVE @\$420.74	CRACKED	1,262.22	1,262.22
1	AIRBLOWER MOTOR	CRACKED	1,350.67	1,350.67
1	AIRCON BRACKET	CRACKED	480.00	480.00
1	AIR DUCT	SERVICEABLE	833.83	-
1	AIR FLAP HOUSING	CRACKED	657.09	657.09
1	AIRCON CONDENSER	BENT	2,179.96	2,179.96
1	AIRCON RECEIVER DRIER	CUT	383.33	383.33
1	AIRCON DISCHARGE PIPE	BENT	875.25	875.25
1	AIRCON LIQUID PIPE ASSY	BENT	1,364.72	1,364.72
1	AIRCON SUCTION PIPE	SERVICEABLE	753.26	-
1	AIRCON EVAPORATOR	SERVICEABLE	1,110.53	-
1	AIRCON COIL	SERVICEABLE	3,701.48	-
1	RH HEADLAMP	BROKEN	636.42	636.42
1	RH HEADLAMP SEAL	CUT	214.22	214.22
1	RH HEADLAMP BRACKET	CRACKED	951.03	951.03

Report Ref No. CS/EQI19008908/R1td3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH HEADLAMP HOUSING	CUT	483.37	483.37
1	FRONT GRILLE PANEL, LOWER	CRACKED	2,499.04	2,499.04
2	FRONT PANEL TOP MESH @\$297.77	BENT	595.54	595.54
2	FRONT PANEL LOWER MESH @\$287.03	BENT	574.06	574.06
1	FRONT PANEL BRACKET LH	SERVICEABLE	66.28	-
1	FRONT PANEL HINGES LH	SERVICEABLE	388.16	-
1	FRONT LH CAB CORNER	SERVICEABLE	1,938.94	-
1	FRONT GRILLE PANEL	CRACKED	1,676.61	1,676.61
2	FRONT PANEL LOCK @\$332.38	BENT (1PC ONLY)	664.76	332.38
2	FRONT WHEEL ARCH FENDER GARNISH, FRONT @\$866.22	DEFORMED (1PC ONLY)	1,732.44	866.22
1	FRONT STEP BRACKET @\$428.90	SERVICEABLE	857.80	-
1	FRONT SHIELDING NET	BENT	490.92	490.92
1	SHIELDING NET MESH	BENT	287.13	287.13
1	AIRCON COIL	BENT	1,208.44	1,208.44
1	CHARGE COOLER	BENT	3,701.35	3,701.35
1	COOLER TOP BRACKET	CRACKED	280.00	280.00
1	WIPER BLADE	CUT	74.18	74.18
2	WIPER ARM	BENT	377.52	377.52
2	WIPER LINK	BENT	1,572.06	1,572.06
1	AIR FILTER ASSY	CRACKED	3,527.41	3,527.41
1	SUN VISOR	CRACKED	450.00	450.00
1	SUN VISOR BRACKET	BENT	460.00	460.00
1	SUN VISOR, BOTTOM O/S	BENT	680.00	680.00
1	RH STEPBOARD	SERVICEABLE	650.00	-
1	RH SIDE LAMP	CRACKED	125.00	125.00
1	WIPER PANEL GARNISH	DEFORMED	240.00	240.00
1	MESH SHIELDING NET	SERVICEABLE	287.13	-
1	FAN RING (ADDITIONAL)	NOT NECESSARY	747.58	-
1	FAN COVER (ADDITIONAL)	SCRATCHED	580.00	580.00
1	FAN ASSY (ADDITIONAL)	JAMMED	3,767.40	3,767.40
	LESS 10% DISCOUNT		-	-4,584.53
			63,173.90	41,260.77

Report Ref No. CS/EQI19008908/R1td3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	FRONT NO. PLATE (SN)	BENT	30.00	30.00
1	ERP BRACKET (SN)	NECESSARY	29.00	29.00
1	LOGOS & LETTERINGS (SN)	NECESSARY	400.00	200.00
1	TIN RADIATOR COOLANT (SN)	NECESSARY	40.00	40.00
			539.00	339.00
	<b><u>LABOUR</u></b>			
	TOWING.		400.00	100.00
	REMOVE THE NECESSARY AFFECTED PARTS, CUT / WELD FRONT OUTER CAB PANEL, DASHBOARD INNER PANEL, WIPER PANEL, STRAIGHTEN FRONT FLOOR PANEL, BOTH FRONT CHASSIS, AND DOOR PILLAR, FRONT BULKHEAD PANEL, ROOFTOP PANEL, AND REPLACE PARTS.		3,800.00	1,300.00
	PUTTY AND SPRAYPAINT.		2,000.00	800.00
	REMOVE AND REFIT DASHBOARD AND FINISHES.		800.00	400.00
	REMOVE AND REFIT AIRCON PARTS, PIPINGS, AND ROOFTOP AIRCON SYSTEM AND REFILL FREON GAS.		900.00	500.00
	REMOVE AND REFIT AIR CLEANER AND HOSES.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT FRONT WINDSCREEN.		150.00	150.00
	TUFF KOTE.		150.00	100.00
	REMOVE AND REFIT WIRING HARNESS, FUSES RELAYS, REFOCUS BOTH HEADLAMP BEAM, AND REPLACE PARTS AND RESET COMPLETE SYSTEM USING DIAGNOSTIC TOOLS.		500.00	250.00
	REMOVE AND REFIT BOTH FRONT & REAR SHOCK ABSORBERS, BRACKETS, STOPPER AND COIL SPRING.	NOT NECESSARY	400.00	-
	REMOVE AND REFIT RADIATOR WITH FITTINGS AND PRESSURE TEST COOLING SYSTEM.		200.00	150.00
			9,600.00	3,750.00
	<b>GRAND TOTAL</b>		<b>73,312.90</b>	<b>45,349.77</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>36,250.00</b>
	<b>LESS EXCESS</b>			<b>-5,000.00</b>

Report Ref No. CS/EQ19008908/R1td3e2





NETT LIABILITY			31,250.00
----------------	--	--	-----------

Report Ref No. CS/EQI19008908/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.