

22/03/2011

ASS. REC. BY:

REF: CS/PC119008912/R1+ d3ⁿ²

Special Instruction:

Surveyor: Kasul

ASSIGNMENT (Office)

From (Person): Hunny Kao

of PC1

Date/Time: 21.5.19 4.23p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLT 2517R

Insured: SHB 4800 B

at Workshop m/s Vifi Pte Ltd

Tel: 88111110

of 1 Butit Batak (Kscent #06-12

Policy No:

Claim No: D19003298MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.5.2019

CA / REV / REP. / REV 24 HRS

"w"

H.O.D. Endorsement:

Date/Time: 21.5.19 4.36p.m

Person Contacted: EZUwan

Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SLT 2517R-X	
	SHB 4800B - CS/PC11402468/Rqbk 3.	120A - 13/12/2014
	lump sum \$700f Cred: 2724.80179%	

MOTOR SURVEY ASSIGNMENT

Date	17-05-2019	Our Ref No. D19003298MFSH
Accident Date	13-05-2019	Claim Type. Third Party
Insured Vehicle	SHB4800B	Third Party Vehicle. SLT2517R
Survey Location	1 BUKIT BATOK CRESCENT #06-12WCEGA PLAZA	
Contact Person.	EZUWAN HUZAINI	
Contact No.	67670011/ 88111110	Fax No. 67677391
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VIFI PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 24 June 2019 3:10 PM
To: Denise Tay (LKKAuto)
Subject: FW: Finalise SLT2517R
Attachments: SLT2517R Finalise.pdf

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ezuwan@perfectpower.sg [mailto:ezuwan@perfectpower.sg]
Sent: Monday, 24 June 2019 11:06 AM
To: rasul@lkkauto.com
Subject: Finalise SLT2517R

Dear Rasul,

Finalise for SLT2517R

COR-\$706.24

Lumpsum

3 Day Repair

Thank you

Regards,

Ezuwan Huzaini

Service Advisor / Claims Advisor

+65 8811 1110

e-mail: ezuwan@perfectpower.sg



1 Bukit Batok Crescent
#06-12 WCEGA PLAZA

**VIFI PTE LTD**

REPAIRS WITH ETHICS

Your Ref: SHB4800B

Our Ref: SLT2517R

To: MS FIRST CAPITAL INSURANCE LIMITED

CC

Email

Fax

Date: 17-05-19

From: Ezuwan

Fax: 6659 0111

Contact: 8811 1110

Make / Model: HONDA HRV 1.5 DX CVT

Chassis No.: JHMRU1810GX203081

Engine No.: L15B4533082

Year of Make: 2017

Accident Date: 13-05-19

ESTIMATE FOR VEHICLE NO.: SLT2517R

DESCRIPTION	QTY	List Price
REAR BUMPER <i>repair</i>	1	\$ 880.00
REAR RIGHT WHEEL ARCH <i>SCA</i>	2	\$ 196.00
REAR BUMPER MOULDING <i>SCA - RH (parts name)?</i>	1	\$ 195 48.00
REAR RIGHT FENDER <i>repair</i>	1	\$ 210.00

Total: \$ 1,334.00

LESS 20% \$ (266.80)

Parts Total: \$ 1,067.20

SPECIAL NETT

ANTI RUST COATING <i>XX</i>	1	\$ 20 200.00
BODY SEALANT <i>XX</i>	1	\$ 180.00
FRONT NUMBER PLATE <i>XX</i>		\$ 60.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$ 250 500.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$ 12 100.00
TO SPRAY PAINTING ON THE AFFECTED AREA	\$ 300 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Please survey the vehicle at :-

1 Bukit Batok Crescent

#06-12, WCEGA PLAZA

SINGAPORE 658064

(Kindly contact Ezuwan @ 8811 1110)

Total: \$ 3424.80 3,307.20

7% GST: \$ 231.50

Grand Total: \$ 3,538.70

VIFI PTE LTD

1 BUKIT BATOK CRESCENT

#06-12, WCEGA PLAZA

t 67670011

Company Registration Number : 201315095D

**VIFI PTE LTD***REPAIRS WITH ETHICS*

Your Ref: SHB4800B

Our Ref: SLT2517R

To: MS FIRST CAPITAL INSURANCE LIMITED

CC

Email

Fax

Date: 17-05-19
From: Ezuwan
Fax: 6659 0111
Contact: 8811 1110
Make / Model: HONDA HRV 1.5 DX CVT
Chassis No.: JHMRU1810GX203081
Engine No.: L15B4533082
Year of Make: 2017
Accident Date: 13-05-19

FINALISE FOR VEHICLE NO. : SLT2517R

DESCRIPTION

REAR RIGHT WHEEL ARCH

REAR BUMPER MOULDING RH (side)

QTY		List Price
1	\$	196.00
1	\$	195.00
Total:		\$ 391.00
LESS 20%:		\$ (78.20)
Parts Total:		\$ 312.80

SPECIAL NETT

ANTI RUST COATING

1	\$	20.00
---	----	-------

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
TO SPRAY PAINTING ON THE AFFECTED AREA

312.80
570.00
882.80
20%
706.24

250.00
300.00
550.00
L/S-700

Total:	\$	882.80
Lumpsum 20% Minus:	\$	(176.56)
Total:	\$	706.24
7% GST:	\$	61.80
Grand Total:	\$	768.04

VIFI PTE LTD

1 BUKIT BATOK CRESCENT

#06-12, WCEGA PLAZA

t 67670011

Company Registration Number : 201315095D



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008912/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4800B	Veh. Inspected	SLT 2517R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003298MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	21/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HR-V 1.5 DX	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRU1810GX203081	Colour	BLUE	
Odometer	43496	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/05/2019	Inspection Date	28/05/2019	
Survey held at	1 BUKIT BATOK CRESCENT #06-12			
Repairer	VIFI PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 2517R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	880.00	-
2	REAR RIGHT WHEEL ARCH	SCRATCHED	196.00	196.00
1	REAR BUMPER MOULDING RH	SCRATCHED	195.00	195.00
1	REAR RIGHT FENDER	TO REPAIR SEE LABOUR	210.00	-
	LESS 20% DISCOUNT		-296.20	-78.20
			1,184.80	312.80
<u>SPECIAL NETT ITEMS</u>				
1	BODY SEALANT (SN)	NOT NECESSARY	180.00	-
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
			240.00	-
<u>LABOUR</u>				
	ANTI RUST COATING.		200.00	20.00
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR RIGHT FENDER.		500.00	250.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.	NOT NECESSARY	100.00	-
	TO SPRAY PAINTING ON THE AFFECTED AREA.		1,200.00	300.00
			2,000.00	570.00
GRAND TOTAL			3,424.80	882.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				700.00

Report Ref No. CS/FCI19008912/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.