



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LONPAC

LKK

EZ SWIFT CAR RENTAL & LEASING PTE LTD

16/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Con Pac
Joy.

Accident date: 08/05/2019

Estimated repair cost for vehicle no: GBG7341J NISSAN NV200 1.5 M '17

CHASSIS: VSKYBAM20Z0148311

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front L/H Head Lamp <i>wt</i>		\$486.40 ✓
2	1	Front L/H Head Lamp Bracket <i>Not new</i>		\$248.60 X
3	1	Front Bumper <i>torn</i>		\$589.70 ✓
4	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30 ✓
5	1	Front L/H Bumper Side Retainer <i>new</i>		\$35.20 ✓
6	1	Front L/H Bumper Top Side Cover <i>del</i>		\$362.20 ✓
7	1	Front L/H Fender <i>damaged</i>		\$564.80 ✓
8	1	Front L/H Fender Cowling <i>3 x 11</i>		\$122.00 X
9	6	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$39.00 X

2068.30
1861.47

Subtotal :- \$2,512.90

S/n	Qty	Items / Special Nett	U/price	Amount
10	1	Front L/H Hub Cap <i>cut</i>		\$186.70 60
11	1	Front L/H Tyre <i>Not new</i>		\$350.00 X

Subtotal :- \$536.70

60

Labour charges

To check wheel alignment

\$150.00 ~~80~~

To check wiring

\$100.00 ~~30~~

Tuff kote

\$150.00 ~~X~~

Panel beating

\$1,200.00 ~~400~~

Spray painting

810
\$1,200.00 ~~300~~

Subtotal :- \$2,800.00

Total:- \$5,849.60

total: 2731.47.

h/s: 2.1K ✓

04Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: