

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date Of Registration:

SHD 45E

VF1ABL15AUC281538

RENAULT

LATITUDE

10.5.19

EQ

23/3/2015

		PART			LIST
1	1	BUMPER COVER REAR ✓	\$		1,108.46
2	1	BUMPER LOWER REAR ✓	\$		768.84
3	1	BUMPER BRACKET CTR REAR ✓	\$		113.47
4	1	BUMPER BRACKET SIDE RH REAR ✗	\$		135.97
5	1	BUMPER RETAINER RH REAR ✗	\$		44.99
6	1	BUMPER REFLECTOR RH ✗ old Panay	\$		43.61
7	1	BUMPER BRACKET SIDE LH REAR ✗	\$		135.97
8	1	BUMPER RETAINER LH REAR ✗	\$		44.99
9	1	BUMPER REFLECTOR LH ✓	\$		43.61
10	1	BUMPER BEAM REAR ✓	\$		777.52
11	1	BUMPER BEAM BRACKET LH REAR ✓	\$		225.95
12	1	BUMPER BEAM BRACKET RH REAR ✓	\$		225.95
13	1	BOOT REAR ✓	\$		2,872.68
14	1	BOOT FINISHER ✗	\$		470.06
15	1	BOOT WHEATERSTRIP ✗	\$		323.05
16	1	BOOT REFLECTOR LAMP LH ✓	\$		493.35
17	1	BOOT REFLECTOR LAMP RH ✓	\$		493.35
18	1	BOOT BADGE 'RENAULT' ✓	\$		225.36
19	1	BOOT BADGE ✓	\$		225.36
20	1	BOOT STRUT LH ✗	\$		276.08
21	1	BOOT STRUT RH ✗	\$		276.08
22	1	BOOT HINGE LH ✗	\$		367.84
23	1	BOOT HINGE RH ✗	\$		367.84
24	1	BOOT INNER TRIM ✗	\$		586.45
25	1	BOOT SWITCH ✗	\$		168.13
26	1	BOOT LOCK ✗	\$		202.67
27	1	BOOT LOCK CATCH ✗	\$		74.40
28	2	LICENCE PLATE LAMP ✗	\$		50.52
29	2	BOOT RUBBER PLUG ✗	\$		221.81
30	1	FENDER PANEL INNER TRIM REAR RH ✗	\$		671.45

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

31	1	FENDER PANEL REAR RH	X	\$	3,299.13
32	1	WHEELARCH REAR RH	X	\$	543.47
33	1	FENDER PANEL REAR LH	X	\$	3,299.13
34	1	FENDER PANEL INNER TRIM REAR LH	X	\$	671.45
35	1	WHEELARCH REAR LH	X	\$	543.47
36	1	TAILLAMP RH	/	\$	552.55
37	1	TAILLAMP PANEL RH	X <i>ng</i>	\$	986.70
38	1	TAILLAMP LH	/	\$	552.55
39	1	TAILLAMP PANEL LH	X <i>ng</i>	\$	986.70
40	1	OUTER PANEL REAR (End Panel)	/	\$	1,471.77
41	1	OUTER PANEL REAR (End Panel)TRIM	/	\$	404.56
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X	\$	2,189.88
43	1	SPARE WHEEL PANEL TRIM	X	\$	612.21
44	1	EXHAUST REAR	X	\$	7,489.05
45	1	EXHAUST CAP REAR	X	\$	230.49

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET	PARKING AID	/	\$	700.00 ⁵⁰⁰
2	1SET	REAR BUMPER CLIP	/	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	/	\$	33.00
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	+	\$	10.00
5	1SET	BUMPER RETAINER RH CLIP RR	/	\$	20.00
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	+	\$	10.00
7	1SET	BUMPER RETAINER CLIP LH RR	/	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	/	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	/	\$	66.00
10	1	EXHAUST MOUNTING REAR	X	\$	17.82
11	1SET	BOOT FINISHER CLIP	X	\$	24.20
12	1	BOOT STICKER "Trans-cab"	/	\$	30.00
13	1	BOOT STICKER "6555-3333"	/	\$	30.00
14	1	BOOT INNER TRIM CLIP	X	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	X	\$	35.00
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X	\$	385.00
17	1	SPARE TYRE	X	\$	330.00

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

18	1	FENDER INNER TRIM CLIP RH	X	\$	28.00
19	1	TAILLAMP CLIP RH	—	\$	5.00
20	2	REAR WINDSCREEN SEALANT	X	\$	80.00
21	1	WINDSCREEN MOULDING	X	\$	100.00
22	1	REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
23	1	TAILLAMP CLIP LH	—	\$	5.00
24	1	FENDER INNER TRIM CLIP LH	X	\$	28.00
25	1SET	FENDER WHEELARCH REAR LH CLIP	X	\$	35.00
26	1	Rear left tyre	X	\$	330.00
27	1	Rear left tyre rim	X	\$	380.00
28	1	Rear right tyre	X	\$	330.00
29	1	Rear right tyre rim	X	\$	380.00
TOTAL				\$	3,645.02

TOTAL PARTS \$ 35,927.07**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 800
To reinstall rear bumper parking sensor.	\$	170.00 40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 50
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

To check steering geometry and computer wheel alignment	\$	220.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To repair and realign rear exhaust pipe.	\$	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X
To Check Electrical Lighting Concerned	\$	170.00 30
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X

TOTAL \$ 16,580.00**Over All Total \$ 52,507.07****(LUMP SUM) Repair Days 20 DAYS**

Kahin 11/11/19
17/5/19 1715L
5 hrs
4/5
After Repair p/te

LKK Auto Services hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- To resurvey prices and to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval by Insurance Company

Acknowledged by Repairer
Date: