

22/03/2019

ASS. REC. BY:

REF:

CS/CTI19008921/Jtd3

172

Special Instruction:

Surveyor: Three Sie

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

22/5/19 @ 1:11pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 7150H

Insured:

GBC 1286X

at Workshop m/s

My Car Consultant

Tel:

of

53 ubi Ave 1 # 01-25

Policy No:

DMCVSN30350818011

Claim No:

SNM19D202186C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:43pm @ 22/5/19

Person Contacted:

Hui Qin

Vehicle:

IN/OUT

Date/Time	Action/Instruction
	Teohmatt (✓)

Case No: Howe Jie

REF: CFI

# ASSIGNMENT

From: 22/5/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 7150H  
at Workshop n/s: My Car Consultant  
of: 53 ubi Ave L #01-25

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record):

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SMH 7150H Yr Regd: 30 Jan 2019

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey C.C. 2354

Colour: Blue A.C. Insured / Std / NI / NA

Sp. Reading: 4895 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRC1880KC200708

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / 5/8in / STD A/Rim or

Tyre Size: F: 215/55R17

R:

BS / DOT / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 16/5/19 D.O.I: 22/5/19

Survey held at: My Car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Waiting for workshop email estimate.

Continued L/S \$4950/- Delays of repair. Cred: 5344.40 :51%.

RECEIVED 21 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

2016 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

3 x 40.00 \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / L.B.E: (\$) 4950

220

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 22 May 2019 1:11 PM  
**To:** admin@mycar.sg  
**Cc:** 'assignments'  
**Subject:** RE: OUR REF: SNM19D202186 - GBC1286X - PRE-REPAIR INSPECTIONFORSMH7150H

### **WITHOUT PREJUDICE**

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### **Chong Boon Sen**

Claims Executive  
Department

### **China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** My Car Consultant [mailto:admin@mycar.sg]  
**Sent:** Wednesday, 22 May, 2019 12:39 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D202186 - GBC1286X - PRE-REPAIR INSPECTIONFORSMH7150H

### **WITHOUT PREJUDICE**

Hi Boon Sen,

OUR REF: SMH7150H  
YOUR REF: GBC1286X

We agree to your list of surveyor.

Best Regards,

**Huiqin**

Direct line: 88668832 | Fax: 69255219

### **My Car Consultant Pte Ltd**

53 Ubi Avenue 1  
Paya Ubi Industrial Park #01-33  
Singapore 408934

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: ??? Taiping SG 3 Anson Road  
#16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** My Car Consultant [<mailto:admin@mycar.sg>]  
**Sent:** Wednesday, 22 May, 2019 11:54 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Subject:** fw: OUR REF: SNM19D202186 - GBC1286X - PRE-REPAIR INSPECTION FORSMH7150H

**WITHOUT PREJUDICE**

Best Regards,

**Huiqin**

Direct line: 88668832 | Fax: 69255219

**My Car Consultant Pte Ltd**  
53 Ubi Avenue 1  
Paya Ubi Industrial Park #01-33  
Singapore 408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

---

**From:** "Claims Dept of CTI" <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Sent:** Friday, May 17, 2019 2:54 PM  
**To:** "Ong Chin Kiat" <[chinkiat.ong@sg.cntaiping.com](mailto:chinkiat.ong@sg.cntaiping.com)>, "Chong Boon Sen" <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>, "Alfred Toh" <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>, "Chee So Chow" <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>, "admin@mycar.sg" <[admin@mycar.sg](mailto:admin@mycar.sg)>, "Elaine Cheong" <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Subject:** OUR REF: SNM19D202186 - GBC1286X - PRE-REPAIR INSPECTION FORSMH7150H

Dear Elaine,

Please conduct PRS –SMH7150H soonest possible on behalf of Boon Sen

File with Elaine Cheong 6389 6530 and officer in charge –Chong Boon Sen -6389 6171.

Regards  
Angie Foo

**From:** My Car Consultant [<mailto:admin@mycar.sg>]  
**Sent:** Thursday, May 16, 2019 5:55 PM  
**To:** Claims Dept of CTI  
**Subject:** OUR REF: SMH7150H YOUR REF: GBC1286X PRE-REPAIR INSPECTION FOR SMH7150H

**WITHOUT PREJUDICE**

OUR REF: SMH7150H  
YOUR REF: GBC1286X

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SMH7150H  
ACCIDENT INVOLVING SMH7150H AND GBC1286X

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your

attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Warm Regards,  
**Kai Ling**

**My Car Consultant Pte Ltd**  
**53 Ubi Avenue 1**  
**Paya Ubi Industrial Park**  
**#01-33 S(408934)**

**Tel: +65 9868 6000 / Fax: 6925 5219**

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1704H
Vehicle Details	
Vehicle No.:	SMH7150H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	K24W72460599
Chassis No.:	JHMRC1880KC200708
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,220.00
Original Registration Date:	30 Jan 2019
First Registration Date:	30 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$31,508.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jan 2029
PARF Rebate Amount:	\$23,631.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,909.00
COE Rebate Amount:	\$31,178.00
<b>Total Rebate Amount:</b>	<b>\$54,809.00</b>

The information contained herein is correct as at 23 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/05/2019 17:04
Date Of Accident	16/05/2019 07:45
Exact Location Of Accident	BKE (SLE) TWDS KJE (PIE)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH7150H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO KAH SWEE
NRIC No	S8021704H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96746455
Alternative Phone No	OFFICE-96746455

### Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4 EX-S CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MS000833
Cover Note Number	

### Driver

Name of Driver	TEO KAH SWEE
NRIC No	S8021704H
Date Of Birth	23/07/1980
Occupation	INDOOR
Date Of Driving Pass	22/12/2003
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96746455
Fax Number	
Contact Number	OFFICE-96746455
Email Address	NOEMAIL

Address	BLK 347A YISHUN AVENUE 11 #16-515
Postcode	761347
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC1286X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MONOGARAN S/O VELU
NRIC/Passport Number	S1291285D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2



Passenger 1

NAME: :

GENDER: :

**DETAILS OF INJURED PERSON 1**

Name : TEO KAH SWEE

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SMH7150H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time: 16 MAY 19

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 16-10-2014

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## Estimation

Date: 23 May 19  
Vehicle: SMH7150H  
Make / Model: HOND/ODYSSEY  
Chassis:

No.	Description	Unit	Unit Price	Amount
<b>Parts Replacement:</b>				
1	TAILGATE <i>BVC /</i>	1	\$ 1,492.00	\$ 1,492.00 <i>1200</i>
2	TAILGATE GLASS MOULDING <i>nec /</i>	1	\$ 220.00	\$ 220.00
3	TAILGATE GLASS LOGO <i>nnx</i>	1	\$ 36.00	\$ 36.00 <i>x</i>
4	TAILGATE SIDE REFLECTOR LAMP <i>CRA /</i>	2	\$ 389.00	\$ 778.00 <i>nnx</i>
5	TAILGATE OUTER GARNISH WITH ABSOLUTE WORDING <i>A</i>	1	\$ 326.00	\$ 326.00
6	TAILGATE LOWER CHROME GARNISH <i>CRA /</i>	1	\$ 175.00	\$ 175.00
7	TAILGATE LOCK <i>Jam /</i>	1	\$ 255.00	\$ 255.00
8	TAILGATE STRIKER <i>nnx</i>	1	\$ 45.00	\$ 45.00 <i>x</i>
9	TAILGATE RUBBER <i>DEF /</i>	1	\$ 119.00	\$ 119.00
10	TAILGATE INNER TRIM <i>CRA /</i>	1	\$ 236.00	\$ 236.00
11	REAR BUMPER <i>DEF /</i>	1	\$ 658.00	\$ 658.00
12	REAR BUMPER RETAINER <i>nec /</i>	2	\$ 29.50	\$ 59.00
13	REAR BUMPER REFLECTOR <i>CRA /</i>	12	\$ 55.00	\$ 55 110.00
14	TAILGATE REFLECTOR CHROME <i>CRA /</i>	2	\$ 87.50	\$ 175.00
15	TAILLAMP <i>CRA /</i>	12	\$ 853.00	\$ 1,706.00 <i>496</i>
16	END PANEL <i>BVC /</i>	1	\$ 651.00	\$ 651.00
17	END PANEL TOP GARNISH <i>CRA /</i>	1	\$ 221.00	\$ 221.00
18	SPARE TYRE TOP BOARD <i>nnx</i>	1	\$ 115.00	\$ 115.00 <i>x</i>
19	PDC SENSOR <i>Shorted</i>	4	\$ 154.00	\$ 200 616.00
				\$ 7,993.00
			Less 20%	\$ 1,598.60
			<b>Total</b>	\$ 6,394.40
<b>S/Nett items:</b>				
27	REAR BUMPER CLIP <i>nec /</i>	1 SET	\$ 40.00	\$ 30 40.00
28	REAR FENDER INNER TRIM CLIP <i>nnx</i>	1 SET	\$ 30.00	\$ 30.00 <i>x</i>
29	WINDSCREEN SEALANT <i>nec /</i>	1	\$ 150.00	\$ 60 150.00
30	JOINT SEALANT <i>nec /</i>	1	\$ 150.00	\$ 40 150.00
				\$ 370.00
<b>Labour to:</b>				
32	TO CHECK REAR ELECTRICAL WIRING	1	\$ 60.00	\$ 30 60.00
33	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	1	\$ 200.00	\$ 40 200.00
34	REMOVE AND REFIT FUEL TANK	1	\$ 150.00	\$ 150.00 <i>x</i>
35	REMOVE AND RENEW FLOOR INSULATOR	1	\$ 150.00	\$ 20 150.00
36	REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 150.00	\$ 30 150.00
37	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 40 100.00
38	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 20 120.00
39	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00 <i>700</i>
40	LKK <i>AND</i> PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00 <i>800</i>
	the Repairer of the following:			\$ 3,530.00
	• To resurvey before and after spray painting			
	• To display damaged car after during resurvey			
	• Parts prices are subject to insurance company			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
			<b>Parts Replacement Amount</b>	\$ 6,764.40
			<b>Total Amount for Labour</b>	\$ 3,530.00
			<b>Total Amount</b>	\$ 10,294.40

Acknowledged by Repairer

Signature:

Date:

*Handwritten signature*  
4/6/19

Hwee Jie

4/6/19

L/S 5 days.

Total \$4950/-

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119008921/JTD3N2

Date: 25/06/2019

## REFERENCE

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMCVSN30350818011	
<b>Claimant Vehicle No :</b>	SMH7150H	<b>Insured Vehicle No :</b>	GBC1286X	
<b>Date of Loss:</b>	16/05/2019	<b>Nature of Claim:</b>	TP	<b>Claim No:</b> SNM19D202186C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SMH7150H	<b>Engine No:</b>	K24W72460599
<b>Make &amp; Model:</b>	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	<b>Chassis No:</b>	JHMRC1880KC200708
<b>Reg. Date:</b>	30/01/2019 (Man. Year: 2018)	<b>Odometer:</b>	4895 km
<b>Colour:</b>	Blue		
<b>Engine Capacity:</b>	2354 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

## CONDITION OF TYRES

<b>Front Tyre Size:</b>	215/55 R17	<b>Rear Tyre Size:</b>	215/55 R17
<b>Front Left Side:</b>	Dunlop 6 mm	<b>Rear Left Side:</b>	Dunlop 6 mm
<b>Front Right Side:</b>	Dunlop 6 mm	<b>Rear Right Side:</b>	Dunlop 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,764.40	4,528.40	2,236.00	33.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,680.00	1,850.00	52.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,294.40</b>	<b>6,208.40</b>	<b>4,086.00</b>	<b>39.69</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,950.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,294.40</b>	<b>4,950.00</b>	<b>5,344.40</b>	<b>51.92</b>

## INSPECTION

<b>Date of Assignment:</b>	22/05/2019	
<b>Date Inspected:</b>	22/05/2019	<b>Inspected At:</b>
		My Car Consultant Pte Ltd (Ubi)
		53 Ubi Ave 1, #01-33, Paya Ubi
		Industrial Park
		Singapore 408934

**Estimated Period of Repair:** 5.0 days**Adjuster:** ONG HWEE JIE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2019)
<b>Parts:</b>	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMH7150H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,492.00 FL	*1,200.00 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	220.00 FL	*220.00 FL
3	1		*TAILGATE GLASS LOGO	Not Necessary	36.00 FL	*- FL
4	2		*TAILGATE SIDE REFLECTOR LAMP	Cracked	778.00 FL	*778.00 FL
5	1		*TAILGATE OUTER GARNISH WITH ABSOLUTE WORDING	Not Necessary	326.00 FL	*- FL
6	1		*TAILGATE LOWER CHROME GARNISH	Cracked	175.00 FL	*175.00 FL
7	1		*TAILGATE LOCK	Jammed	255.00 FL	*255.00 FL
8	1		*TAILGATE STRIKER	Not Necessary	45.00 FL	*- FL
9	1		*TAILGATE RUBBER	Deformed	119.00 FL	*119.00 FL
10	1		*TAILGATE INNER TRIM	Cracked	236.00 FL	*236.00 FL
11	1		*REAR BUMPER	Deformed	658.00 FL	*658.00 FL
12	2		*REAR BUMPER RETAINER	Necessary	59.00 FL	*59.00 FL
13	1		*REAR BUMPER REFLECTOR (2 Pcs)	Cracked (1 pc only)	110.00 FL	*55.00 FL
14	2		*TAILGATE REFLECTOR CHROME	Cracked	175.00 FL	*175.00 FL
15	1		*TAILLAMP (2 Pcs)	Cracked (1 pc only)	1,706.00 FL	*496.00 FL
16	1		*END PANEL	Buckled	651.00 FL	*651.00 FL
17	1		*END PANEL TOP GARNISH	Cracked	221.00 FL	*221.00 FL
18	1		*SPARE TYRE TOP BOARD	Not Necessary	115.00 FL	*- FL
19	4		*PDC SENSOR	Shorted	616.00 FL	*200.00 FL
20	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
21	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
22	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
23	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,363.00</b>	<b>5,628.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,598.60</b>	<b>1,099.60</b>
<b>Total Parts (\$\$)</b>	<b>6,764.40</b>	<b>4,528.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING.	New	60.00	30.00
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.	New	200.00	40.00
3	REMOVE AND REFIT FUEL TANK.	New	150.00	0.00
4	REMOVE AND RENEW FLOOR INSULATOR.	New	150.00	20.00
5	REMOVE AND RENEW REAR REVERSE SENSOR.	New	150.00	30.00
6	TO RESPRAY UNDERCOATING.	New	100.00	40.00
7	APPLY ANTI RUST ON AFFECTED AREAS.	New	120.00	20.00
8	SPRAY PAINTING ON AFFECTED AREAS.	New	1,400.00	700.00
9	PANEL BEATING ON AFFECTED AREAS.	New	1,200.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,530.00</b>	<b>1,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >